

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO : 67038511
REFERENCE : 064/IC/TCAC/CCR/2019
DATE : 28-MAY-2019

ERGO INSURANCE PTE LTD
5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
S(038985)
TEL : 68299199
FAX : 68299247/9248
ATTN : CLAIM MANAGER

OWNER'S NAME : M/S SERVICE STATIONARY & TRADING PTE LTD
ADDRESS : 18 BOON LAY WAY
#04-142 TRADEHUB 21
S(609966)
TELEPHONE NO : 97979200 - MR RONNIE

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : 1700012219-01
VEHICLE NO : GBG891J
MODEL CODE : YTKARUM20TWL-CAAC
MODEL/YEAR : NISSAN NV200 1.5L DIESEL VAN (II)
ENGINE NO : K9KC400D056981
CHASSIS NO : VSKYBAM20Z0144964
MILEAGE : 28480 KM
DATE IN : 28/05/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SHAWN CHUA CHU RONG
ACCIDENT DATE : 28/05/2019

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO GBG891J

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	240.00	/
2	RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	55.00	/
3	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	200.00	100
4	WHI	CHECK & INSPECT WIRE HARNESS FOR DAMAGE & OPEN/ SHORT CIRCUIT, REPAIR WHEN NECESSARY	240.00	X
5	ZZ/001	REPLACE RIGHT SLIDING DOOR, REAR RIGHT PANEL, RIGHT TAIL LAMP, REAR BUMPER ETC. REPAIR PANELS 390	1950.00	/
6	ZZ/002	TRANSFER RIGHT SLIDING DOOR COMPONENTS TO FACILITATE REPAIR	120.00	/
7	ZZ/003	RESPRAY RIGHT SLIDING DOOR, REAR RIGHT PANEL ETC 250	750.00	500
8	ZZ/004	QC, RETUNE & CONSULT CHECK		
9	ZZ/005	COMPLIMENTARY WASH & VACUUM		
TOTAL LABOUR CHARGES			3555.00	

Steve (LKK) wr P/L 7/6/19, 2-03 pm
8 days
P/P
Rw Bel spy

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO GBG891J

		DAMAGED PARTS & PRICES			
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
1	RIGHT BUMPER BRACKET / <i>OK</i>	85228-BJ00A	22.70		
2	REAR BUMPER / <i>CNT</i>	H5022-3LGEH	632.70		
3	RIGHT SLIDING DOOR / <i>DD</i>	H2100-BJ1AC	1165.20		
4	REAR RIGHT FENDER / <i>DD</i>	78100-3LS0A	1554.30		
5	GROM-PTN PIPE / <i>CNT</i>	80874-WL00A	2.50		
6	SLIDING DOOR RAIL GUIDE / <i>CNT</i>	77760-BJ01A	154.40		
7	RIGHT TAIL LAMP / <i>CNT</i>	26550-BJ20A	254.90		
SUB TOTAL			3786.70	0.00	0.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			757.34	0.00	0.00
GRAND TOTAL			3029.36	0.00	0.00
OVERALL TOTAL			3029.36		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO GBG891J

TOTAL LABOUR CHARGES	3555.00
TOTAL SPARE PARTS CHARGES	3029.36

GRAND TOTAL	6584.36 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.