

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 1437S

DATE 29/5/2019 10:48

MAKE :

Like

CHINA

MODEL : HYUNDAI i40

LKK/Kahin

L/Sam

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid ✓			\$ 2,174.90
	Boot Lid Lock Upper ✗			\$ 102.60
	Boot Lid Lock Lower ✗			\$ 31.70
	Boot Lid 'H' Emblem ✓			\$ 28.70
	Boot Lid CRDI Plate ✓			\$ 27.90
	Bootlid Moulding ✓			\$ 85.00
	Bootlid i40 Emblem ✓			\$ 27.90
	Bootlid Lower Garnish ✓			\$ 227.90
	Rear Bumper ✓			\$ 553.00
	Rear Bumper Reinforcement ✓			\$ 428.40
	Rear Bumper Reinforcement Bracket (LH/RH) ?		\$ 80.30	\$ 160.60
	Rear Bumper Clip 10 pcs ✓			\$ 22.00
	Rear Bumper Bracket ?		\$ 35.60	\$ 71.20
	Rear Bumper Sponge ✓			\$ 103.50
	Rear Bumper Under Cover ✗			\$ 228.00
	Rear Panel ✓			\$ 526.70
	Rear Panel Garnish ?			\$ 57.70
	Rear Panel Lower Panel ✓			\$ 89.40
	SUB TOTAL			\$ 4,947.10
	LESS 20%			\$ 989.42
	DISCOUNTED TOTAL			\$ 3,957.68
	Boot Lid Comfort Logo & Tel No. Sticker ✓			\$ 30.00 Nett
	Boot Lid Advertisement Logo ✓			\$ 100.00 Nett
	Rear Bumper Reverse Sensor ✓			\$ 135.70 Nett
	Rear Bumper Rubber Mat ✓			\$ 50.00 Nett
	Rear Bumper Advertisement Logo ✓			\$ 50.00 Nett
	Rear Fender Advertisement Logo (LH/RH) ✓			\$ 200.00 Nett
	Labour Charge			
	Panel Beating			\$ 800.00 ⁶⁰⁰
	Spray Painting Charge			\$ 900.00 ⁸⁰⁰
	Wiring Charge			\$ 50.00 ^X
	Tuff Kote			\$ 50.00 ²⁰
	Remove/Refix Reverse Sensor			\$ 80.00 ³⁰
	TOTAL LABOUR			\$ 1,880.00
	ESTIMATE TOTAL			\$ 6,403.38

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Kahin (LKK)
 Signature: _____
 Date: 29/5/19 1240L
 4 Days
 4/5
Alfa Rep-p hls

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.