

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0672/2019/DY/TF
Date : 25-May-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Premium Leasing Pte Ltd
Address : 9 Leng Kee Road
Singapore 159090
Telephone : (HP) +65 90604226 (Drv.Mr Norbert)
Type of Claim : Own damage Claim
Policy No. : 999994451/100864021-00000
Vehicle No : **SLN 3559 U**
Model Code : A4 Avant 1.4 TFSI S
Model / Year : 28-04-17
Engine No : CVN 016063
Chassis No : WAUZZZF45HA014717
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 18-May-19

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLN 3559 U

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid. Calibrate park assistance.	S/N \$ 280.00 ✓	
2	To dismantle and renew rear bumper and lower spoiler. Re-organise rear crash management components. Reinstall all parts removed. Repair lhs rear fender, replace lhs tailamp.	\$ 1,500.00 500.	
3	To respray rear bumper, lhs rear fender.	\$ 1,500.00 1100.	
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		\$ 3,472.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLN 3559 U

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER	\$ 2,015.00	de ✓
2	REAR BUMPER FIXING PARTS	\$ 66.00	?
3	REAR BUMPER SPOILER	\$ 227.00	?
4	REAR BUMPER REFLECTOR - LH	\$ 38.00	int ✓
5	REAR BUMPER TAIL LIGHT - LH	\$ 931.00	int ✓
6	REAR BUMPER GUIDE SECTION - LH	\$ 40.00	?
7	REAR TAIL LIGHT TRIM - LH	\$ 27.00	?
8	SUNDRIES	\$ 300.00	?
TOTAL SPARE PARTS CHARGES		\$ 3,644.00	
TOTAL LABOUR CHARGES		\$ 3,472.00	
GRAND TOTAL		\$ 7,116.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name	:	Tanplun 97445744
Surveyed Date	:	Not Yet
Authorised Date	:	Ex: to be advise
Excess Cost	:	04 days
Liability	:	30/8/11 @ 1025
Remarks	:	Resing before point suve lhan to con.

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant