

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9884R**AAD1905-264**

Not Notified
1/1/1988

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHD 9884R

VF1ABL15AUC277540

RENAULT

LATITUDE

28.5.19

MSIG

9/5/2014

PART		LIST	
1	BUMPER COVER FRT	\$	<i>CM</i> 1,259.42 ✓
1	BUMPER SPOILER FRT	\$	<i>Ort</i> 181.75 ✓
1	BUMPER ABSORBER FRT	\$	<i>Tu</i> 394.68 ✓
1	BUMPER RETAINER FRT LH	\$	<i>CM</i> 151.41 ✓
1	BUMPER SUPPORT FRT	\$	<i>Sn</i> 123.88 X
1	BUMPER UNDERTRAY FRT	\$	<i>Sn</i> 472.83 X
1	BUMPER GRILLE LOWER FRT	\$	<i>Sn</i> 266.80 X
1	BUMPER FOG LAMP GRILLE LH	\$	<i>Sn</i> 207.21 X
1	BUMPER BEAM FRT	\$	<i>R</i> 914.08 X
1	HEADLAMP LH	\$	<i>CM</i> 1,184.43 ✓
1	HEADLAMP PANEL FRT LH	\$	<i>R</i> 152.15 X
1	FENDER PANEL FRT LH	\$	<i>R</i> 783.83 ✓
1	WHEELARCH FRT LH	\$	<i>Ort</i> 278.84 ✓
1	FENDER BRACKET LOWER LH	\$	<i>R</i> 15.79 X
1	FENDER INSULATOR LH	\$	<i>Sn</i> 130.84 X
1	FRONT BRACE PANEL	\$	<i>R</i> 177.22 X
1	RADIATOR GRILLE	\$	<i>MSIG</i> 1,707.78 ✓
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>R</i> 225.36 ✓
1	RADIATOR GRILLE FRAME	\$	<i>CM</i> 1,353.75 ✓
1	FRAME FULL SUPPORT PANEL	\$	<i>Sn</i> 615.90 X
1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i> 89.79 X
1	BONNET	\$	<i>R</i> 1,941.63
1	BONNET INSULATOR	\$	<i>Sn</i> 405.73
1	BONNET STRUT LH	\$	<i>Sn</i> 88.61
1	BONNET STRUT RH	\$	<i>Sn</i> 88.61
1	BONNET HINGE LH	\$	<i>R</i> 348.31
1	BONNET HINGE RH	\$	<i>R</i> 348.31
1	BONNET LOCK	\$	<i>R</i> 305.48
1	BONNET CABLE	\$	<i>Sn</i> 119.19

Trans-cab Auto Services Pte Ltd**AAD1905-264**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9884R

1	BONNET CABLE COVER	\$	161.03	X
1	BONNET SEAL OUTER	\$	92.36	
1	BONNET SEAL INNER	\$	157.28	
1	AIR CLEANER BOX	\$	464.20	
1	AIR CLEANER HOSE	\$	175.85	
1	AIR CLEANER LOWER	\$	271.26	
1	AUTO COMPUTER	\$	5,032.17	
1	INJECTION COMPUTER	\$	4,706.30	
1	RHD HYDRAULIC POWER(ROCK&PINION)	\$	5,154.52	
1	STEERING PUMP ELECTRIC L70Y	\$	2,306.90	
1	STEERING PINION RACK L70Y	\$	4,413.11	
1	SUBFRAME OUTER FRT	\$	2,652.45	
1	SUBFRAME BRACKET OUTER LH	\$	92.36	
1	SUBFRAME BRACKET OUTER RH	\$	92.36	
1	ENGINE UNDERTRAY	\$	564.98	
1	RADIATOR FAN COWLING	\$	820.54	X
1	RADIATOR FAN MOTOR LH	\$	967.36	
1	RADIATOR FAN MOTOR RH	\$	1,479.46	
1	DOOR PANEL FRT LH	\$	2,844.66	
1	DOOR HINGE UPPER LH	\$	261.28	
1	DOOR HINGE LOWER LH	\$	300.55	
1	DOOR CHECK FRT LH	\$	194.77	
1	DOOR LOCK FRT LH	\$	908.75	
1	DOOR CATCH FRT LH	\$	131.23	
1	DOOR HANDLE OUTER FRT LH	\$	477.76	
1	DOOR HANDLE COVER FRT LH	\$	13.22	
1	DOOR HANDLE MODULE FRT LH	\$	133.60	
1	DOOR REGULATOR FRT LH	\$	505.19	
1	DOOR REGULATOR MOTOR FRT LH	\$	796.46	
1	DOOR REGULATOR GUIDE FRT LH	\$	120.97	
1	DOOR MOULDING FRONT LH	\$	176.82	
1	DOOR FINISHER INNER FRONT LH	\$	323.44	
1	DOOR FINISHER FRONT LH	\$	423.10	
1	DOOR CASING FRONT LH	\$	1,509.06	
1	DOOR GRAB HANDLE FRONT LH	\$	210.96	
1	DOOR BLIND FRONT LH	\$	741.80	
1	DOOR WHEATHESTRIIP FRONT LH	\$	410.66	
1	DOOR SEAL FRONT LH	\$	162.02	

Trans-cab Auto Services Pte Ltd**AAD1905-264**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9884R

1	DOOR GLASS RUNNER SEAL FRONT LH	\$	Sh	229.31	}
1	DOOR WAIST SEAL OUTER FRONT LH	\$	Sh	334.69	
1	DOOR WAIST SEAL INNER FRONT LH	\$	Sh	115.64	
1	DOOR MIRROR ASSY LH	\$	Sh	1,483.40	
1	DOOR MIRROR GLASS LH	\$	Sh	148.20	
1	DOOR MIRROR BACK COVER LH	\$	Sh	218.46	
1	DOOR HARNESS WIRE LH	\$	Sh	2,670.00	
1	LOWER ARM LH L70Y	\$	Sh	685.76	
1	KNUCKLE ARM LH L70Y	\$	Sh	846.98	
1	ABSORBER FRT LH L70Y	\$	Sh	360.54	
1	DRIVESHAFT LH	\$	H	1,747.45	
1	STABILIZER BAR FRT	\$	Sh	604.65	
1	WHEEL HOUSING PANEL FRNT LH	\$	H	4,682.09	
TOTAL		\$		68,711.55	
10%		\$		6,871.16	
		\$		61,840.40	

Special Nett

1	BUMPER CLIP FRT	\$	na	66.00	}
1	BUMPER BRACKET CLIP FRT LH	\$	na	12.00	
1	BUMPER SUPPORT CLIP FRT LH	\$	na	10.50	
1	BUMPER GRILLE LOWER CLIP	\$	na	69.00	
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	na	70.00	
2	FRAME FULL SUPPORT PANEL NUT	\$	na	20.00	
2	FRAME FULL SUPPORT PANEL STUD	\$	na	30.00	
1	WHEELARCH CLIP FRT LH	\$	na	30.50	
1	FRONT LEFT TYRE	\$	Sh	300.00	
1	FRONT LEFT TYRE RIM	\$	na	380.00	
1SET	Front licence plate with holder	\$	Sh	80.00	}
1	WINDSCREEN SEALANT	\$	na	253.80	
1	FRONT WINDSCREEN MOULDING	\$	na	120.00	
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	
6	BONNET INSULATOR CLIP L70Y	\$	na	7.30	
2	BONNET STRUT L70Y	\$	Sh	88.61	
2	BONNET CABLE CLIP L70Y	\$	na	6.31	
2	BONNET CABLE COVER SCREW L70Y	\$	na	10.85	}
1SET	RADIATOR GRILLE FRAME CLIP	\$	na	52.00	

Trans-cab Auto Services Pte Ltd**AAD1905-264**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9884R

1SET	RADIATOR GRILLE SCREW	\$	na	16.00	X
1	FRONT RIGHT TYRE	\$	sn	300.00	X
1	FRONT RIGHT TYRE RIM	\$	na	380.00	✓
1	FRONT DOOR STICKER 'Trans-Cab'	\$	na	80.00	6012
1	FRONT DOOR STICKER 'Classic'	\$	na	80.00	X
1	DOOR CHECK BOLT	\$	sn	22.69	} X
1	DOOR GUIDE SCREW	\$	sn	10.85	
1	DOOR HINGE BOLT	\$	sn	10.85	
1	DOOR HINGE NUT LH	\$	sn	14.60	
1	DOOR CHECK BOLT	\$	sn	22.69	
1	DOOR CHECK NUT	\$	sn	3.75	
1	DOOR LOCK SCREW L70Y	\$	sn	6.12	
1	DOOR CATCH SCREW L70Y	\$	sn	10.06	
TOTAL		\$		2,664.51	
TOTAL PARTS		\$		64,504.90	

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 6,000.00 5001

To transfer of front bumper fittings, attachment and perform water seepage test.

\$ na 380.00 X

To transfer of front fender fittings, attachment and perform water seepage test.

\$ na 380.00 X

To transfer of front windscreen fittings and conduct water seepage test.

\$ na 170.00 X

To check steering geometry and computer wheel alignment

\$ 220.00 601

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ na 380.00 X

Trans-cab Auto Services Pte Ltd**AAD1905-264**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9884R

To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	nn 440.00 X
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	nn 380.00 X
To transfer of tire, rim and on wheel balancing.	\$	170.00 401
Putty and spray painting of the affected portion.	\$	6,000.00 8801
To Check Electrical Lighting Concerned.	\$	170.00 201
To rust-proofing of the affected areas.	\$	170.00 601
To apply paint protection system (PPS) maintain and enhancement	\$	nn 380.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00 X
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	nn 380.00 X
To remove and refit air bag system and reset vehicle warning indicators.	\$	nn 480.00 X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	nn 380.00 X
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	nn 380.00 X
To check ABS brake efficiency, final checking and testing.	\$	nn 380.00 X

LKK Auto Consultants hence notify

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplemental charges for parts and labour is subject to final approval from Insurance Company

Acknowledged by Reparer

TOTAL \$ 17,620.00**Over All Total \$ 82,124.90****LUMP SUM (REPAIR DAY)****20 days****4 days**