

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0714/2019/NK
Date : 3-Jun-19

Vehicle NOT in workshop. Kindly arrange for survey.

Your Insured Vehicle no SCM 4025 Z

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Christopher Andrew Brandon
Address : 27 Yarwood Avenue
Singapore 587999
Telephone : HP +65 97573597
Type of Claim : Third Party Claims
Policy No. : VPA/P1581539
Vehicle No : **SJZ 0184 Y**
Model Code : Audi RS5 4.2 QU
Model / Year : Oct-10
Engine No : CFC 002149
Chassis No : WAUZZZ8T6BA900806
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 24-May-19
Place of Accident : Bukit Timah Rd Open Carpark

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJZ 0184 Y

S/N	Nature of Jobs	Estimated Charges	Remarks
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy and front parking aid	s/n \$ 480.00	
2	To dismantle and renew front bumper. Reorganise front crash managements components. Reinstall all parts removed.	\$ 1,200.00	Sou
3	To rep spray front bumper.	\$ 1,000.00	S50
4	To carry out diagnostic check.	s/n \$ 192.00	
TOTAL LABOUR CHARGES		: \$ 2,872.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJZ 0184 Y

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>cm</i>	\$ 5,367.00	
2	FRONT BUMPER FIXING PARTS ?	\$ 234.00	
3	FRONT BUMPER SECURING STRIP - LH / RH ?	\$ 64.00	
4	FRONT BUMPER BLACK SPOILER X	\$ 542.00	
5	FRONT BUMPER SPOILER - LOWER X	\$ 1,301.00	
6	FRONT BUMPER CLOSING ELEMENT - CENTER X	\$ 207.00	
7	FRONT BUMPER SPOILER - CENTER X	\$ 209.00	
8	FRONT BUMPER AIR GRILLE - RH <i>cm</i>	\$ 355.00	
9	RADIATOR GRILLE X	\$ 4,024.00	
10	RSS EMBLEM X	NEC \$ 113.00	
11	FRONT RADIATOR GRILLE SENSOR SUPPORT X	NEC \$ 258.00	
12	FRONT LICENCE PLATE HOLDER X	\$ 390.00	
13	FRONT REINFORCEMENT BAR X	\$ 802.00	
14	FOAM FILLER PIECE X	\$ 246.00	
15	FRONT REINFORCEMENT BAR COVER X	\$ 194.00	
16	A/C STICKER X ?	NEC \$ 18.00	
17	FRONT BUMPER SENSOR -	2 \$ 419.00	
18	FRONT BUMPER SENSOR SEAL RING <i>ne</i>	\$ 5.00	
19	FRONT HEADLIGHT WASHER COVER - LH / RH X	2 \$ 104.00	
20	FRONT LIFT CYLINDER - RH X	\$ 251.00	
21	RADIATOR GRILLE AIR GUIDE - RH X	\$ 35.00	
22	FRONT NO. PLATE X	S/N \$ 40.00	
23	SUNDRIES ?	\$ 300.00	
TOTAL SPARE PARTS		: \$ 15,478.00	
TOTAL LABOUR CHARGES		: \$ 2,872.00	
GRAND TOTAL		: \$ 18,350.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : RASUL - Hp 90010068
Surveyed Date : 31/07/19 @ 1130
Authorised Date :
Excess Cost : 3 days
Liability :
Remarks : Resurvey before paint

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant