

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0714/2019/NK
Date : 03-Jun-19

Vehicle NOT in workshop. Kindly arrange for survey.

Your Insured Vehicle no SCM 4025 Z

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Christopher Andrew Brandon
Address : 27 Yarwood Avenue
Singapore 587999
Telephone : HP +65 97573597
Type of Claim : Third Party Claims
Policy No. : VPA/P1581539
Vehicle No : **SJZ 0184 Y**
Model Code : Audi RS5 4.2 QU
Model / Year : Oct-10
Engine No : CFC 002149
Chassis No : WAUZZZ8T6BA900806
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 24-May-19
Place of Accident : Bukit Timah Rd Open Carpak

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJZ 0184 Y

S/N	Nature of Jobs	Estimated Charges	Remarks
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy and front parkind aid	s/n \$ 480.00	
2	To dismantle and renew front bumper. Reorganise front crash managements components. Reinstall all parts removed.	\$ 1,200.00	
3	To rep spray front bumper.	\$ 1,000.00	
4	To carry out diagnostic check.	s/n \$ 192.00	
TOTAL LABOUR CHARGES		: \$ 2,872.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJZ 0184 Y

S/N	Parts Description	<u>Damage Parts & Prices</u>	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 5,367.00	
2	FRONT BUMPER FIXING SETS	\$ 234.00	
3	SECURING STRIP LH / RH	\$ 64.00	
4	FRONT BUMPER SPOILER	\$ 542.00	
5	FRONT BUMPER LOWER SPOILER	\$ 1,301.00	
6	CLOSING ELEMENT	\$ 207.00	
7	FRONT SPOILER	\$ 209.00	
8	AIR GUIDE GRILLE RH	\$ 355.00	
9	RADIATOR GRILLE	\$ 4,024.00	
10	"RS5" CHROME EMBLEM	NEC \$ 113.00	
11	SUPPORT INNER LH/ RH	NEC \$ 258.00	
12	LICENCE PLATE HOLDER	\$ 390.00	
13	REINFORCEMENT BEAM	\$ 802.00	
14	FOAM FILLER PC	\$ 246.00	
15	FRONT BUMPER COVER	\$ 194.00	
16	STICKER FOR AIR CONDITIONING	NEC \$ 18.00	
17	FRONT SENSOR	2 \$ 419.00	
18	SEAL RING FRONT	\$ 5.00	
19	COVER CAP FOR HEADLIGHT WASHER	2 \$ 104.00	
20	LIFT CYLINDER RH	\$ 251.00	
21	RADIATOR AIR GUIDE	\$ 35.00	
22	FRONT NO PLATE	S/N \$ 25.00	
23	SUNDRIES	\$ 300.00	
TOTAL SPARE PARTS		: \$ 15,463.00	
TOTAL LABOUR CHARGES		: \$ 2,872.00	
GRAND TOTAL		: \$ 18,335.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant