

INS. CASE OWNER:

Ahmad

CC 3/AIG1600

4063, 14/3/16

LKK:

IDAC:

AIG1600

Surveyor:

Kenneth

DOI:

ASSIGNMENT

28/2/16

Date / Time:

28/2/16

Registered in Merimen:

2/3/16

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKV 7054C

Name of Insured:

Lim H. San Angela

Insured Tel No.:

HP:

98915586

Excess Sec II :SS

D.O.A.:

28/2/16

Is driver the owner?

( YES / NO )

Nature of Accident:

Claim No.:

3031201131561

Policy No.:

2100421300

Make / Model:

Mazda Bute

Place of Accident:

Open carpark in front of BFL191

Lov Tan Payoh.

If NO, Driver Name / Age:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability:

%

Final ? Yes / No

SHF616y



INSRS:

WSP:

Tel:

Liability:

RMKS:

Trans-car



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

DATE / PIC

2/3/16

SHF616y - C/L TP 1402073 21/9/16 009 19/10/16

SKV 7054C - X

- PENDING

080416 @ 11:00AM

CALLED 01 NO RESPONSE.

110416 @ 11:00AM

CALLED 01 NO RESPONSE.

120416 @ 3:18PM

CALLED 01 NO RESPONSE.

14/02/16

Letter sent to OI

FOR BULK SETTLEMENT

- RETURN @ TC. KN FOR DOCS.

KIV

17-10-17

WHAT I DESCRIBED IS RIGHT I DON'T THINK I NEED TO CHANGE  
OR CUT LANE WHICH IS ONE WAY DRIVEWAY. 2 MINOR CONTS  
ON THE RIGHT ARE MEANT FOR EXISTING NO ENTRY. PLEASE  
CHECK WITH OI'S COUNTER CLAIM STATUS I BELIEVE STP AS BOTH  
PARTIES WITHOUT EVIDENCE & CONFLICTING VERSIONS.

17/10/17

- TEMP. CLOSE - TP INACTIVITY

STAGE	DATE / PIC
Non-Reporting ltr (1st)	
Non-Reporting ltr (2nd)	
Non-Reporting ltr (Final)	
Notification ltr (if non-pickup)	
Call OI	
After call ltr to OI	
Documentation Check List:	Handler Typist
Notification ltr (if non-pickup)	
After call ltr to OI	
Authorisation To Act:	
Release Voucher:	
Final Repair Bill:	
Car Rental Invoice:	
Towing Invoice:	
LTA / GIA:	
Medical Bill:	
PIR:	
Mandate/Reject Instruction:	
LOD:	
Payment Breakdown Form:	
Post-Repair Photos:	
Others:	

PRELIMINARY ADVICE	Date/Time:	Sent By:
--------------------	------------	----------

FINALIZATION	Date/Time:	Confirm with:	Confirm by:
--------------	------------	---------------	-------------

Repair Cost:	101	SS 744.82 ( 1.5 days) Reduction:	90 %	Email <input type="checkbox"/> Call <input type="checkbox"/>
--------------	-----	----------------------------------	------	--

FINAL SETTLEMENT	Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>
------------------	------------	---------------	--

Final Liability:	% 50	(Agreed / Assessed) BOLA S/N No.:	NIL	If NO or B 28, Ass. Lia:
------------------	------	-----------------------------------	-----	--------------------------

Repair Cost:	SS	(Guide only)		
--------------	----	--------------	--	--

Loss of Rental (LOR):	SS	( days)		
-----------------------	----	---------	--	--

Loss of Use (LOU):	SS	( \$ x days)		
--------------------	----	--------------	--	--

Loss of Income (LOI):	SS	( \$ x days)		
-----------------------	----	--------------	--	--

LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/> [Tick only one]				
---	--	--	--	--

GIA/LTA Search	SS			
----------------	----	--	--	--

Medical:	SS			
----------	----	--	--	--

Disbursement:	SS	(e.g. Tow/Independent)		
---------------	----	------------------------	--	--

Legal Cost	SS			
------------	----	--	--	--

Total:	SS	Global Sum SS:		
--------	----	----------------	--	--

FINAL PAYMENT	Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>
---------------	------------	---------------	--

Payee 1:	SS	Name 1:		
----------	----	---------	--	--

Payee 2: (Strike if N.A.)	SS	Name 2:		
---------------------------	----	---------	--	--

Payee 3: (Strike if N.A.)	SS	Name 3:		
---------------------------	----	---------	--	--

COPY SENT

1) Claim status: Normal/Reject/Private Settle

2) Report Format: WP REPORT

3) Survey fee: \$320.00

ASS. REC. BY:

REF: A/G/

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s Trans Cab

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 02 hr days Res.: Yes or NoLum Sum: 1.3% % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: S14F6164 Yr Regn: 06, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or AIMake: Renault Latitude c.c. 1995Colour M. white / Red A/C: Insured / Std / NI / NASp. Reading 300765 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: VFIABL 15AUC 278497Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim orTyre Size: F: Revelo 215/60R16R: Falken

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 8 mm R/Bal. 6 mmL/Bal. 8 mm L/Bal. 6 mmD.O.A. 28/2/16 D.O.I. 29/2/16

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S Frt

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
29/2	GIA & Est not ready
2/3	8744.82 Repair
4	File paid to Corbyline
14/7	8744.82 Car, Firmw Jasmine (2 X 132.68 + 100)
	KV (Neto: 7,019.65/90%)
	Global Rpt @ 590.00 /KV

Date/Time, File Pass to?

☐ : Prell. Report

Days Of Repair: \_\_\_\_\_

1)

☐ : Final Report

Resurvey No. of Trip: \_\_\_\_\_

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)

Survey Fee:

Transportation:

3 + R3 3

Photos

Others

TOTAL

Report Format: \_\_\_\_\_

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG16004063/Khg3

78 SHENTON WAY #08-16  
CHARTIS BUILDING  
SINGAPORE 079120

Date : 02-03-2016



Code : AIG

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKV 7054C	Veh. Inspected	SHF 616Y
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	02/03/2016

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer		Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	28/02/2016	Inspection Date	29/02/2016
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

**TRANS-CAB AUTO SERVICES PTE LTD**

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

**SHF 616Y - AIG**

*Not Authorised* **RIZA**  
*1.B.1* *8748.82*  
*DONE*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

**SHF 616Y - RIZA**

VF1ABL15AUC278497

RENAULT

LATITUDE

28.02.16

**AIG**

PART			LIST	
1	1	BUMPER COVER FRT	\$	<i>R</i> 968.78 <i>X</i>
2	1	BUMPER RETAINER FRT LH	\$	<i>D.I</i> 116.47 <i>✓</i>
3	1	HEADLAMP LH	\$	<i>Sm</i> 911.10 <i>X</i>
4	1	FENDER PANEL FRT LH	\$	<i>R</i> 602.95 <i>X</i>
5	1	FENDER WHEELARCH FRT LH	\$	<i>Sm</i> 107.33 <i>X</i>
6	1	FENDER PANEL FRT RH	\$	<i>R</i> 602.95 <i>X</i>
7	1	AIR CLEANER LOWER	\$	<i>Sm</i> 271.26 <i>X</i>
8	1	AIR CLEANER HOSE	\$	<i>Sm</i> 58.57 <i>X</i>

<b>TOTAL</b>	\$	<b>3,639.42</b>
--------------	----	-----------------

<b>10%</b>	\$	<b>363.94</b>
------------	----	---------------

	\$	<b>3,275.47</b>
--	----	-----------------

**Special Nett**

1	1SET	FRONT BUMPER CLIP	\$	<i>nn</i> 66.00 <i>X</i>
2	1SET	FRONT WHEELARCH CLIP LH	\$	<i>nn</i> 30.50 <i>X</i>
3	1SET	BUMPER RETAINER FRT CLIP LH	\$	<i>nn</i> 12.50 <i>X</i>
4	1	RIM RH FRT	\$	<i>Sm</i> 385.00 <i>X</i>
5	1	TYRE RH FRT	\$	<i>Sm</i> 330.00 <i>X</i>
6	1	CAP HUB RH FRT	\$	<i>Sm</i> 35.00 <i>X</i>

<b>TOTAL</b>	\$	<b>859.00</b>
--------------	----	---------------

<b>TOTAL PARTS</b>	\$	<b>4,134.47</b>
--------------------	----	-----------------

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$	1,400.00	<i>2001</i>
----	----------	-------------

To Check Electrical Lighting Concerned.

\$	<i>nn</i> 170.00	<i>X</i>
----	------------------	----------

Putty and spray painting of the affected portion.

\$	1,500.00	<i>4401</i>
----	----------	-------------

To rust-proofing of the affected areas.

\$	<i>nn</i> 170.00	<i>X</i>
----	------------------	----------

**TRANS-CAB AUTO SERVICES PTE LTD**

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

**SHF 616Y - AIG****RIZA**

To check steering geometry and computer wheel alignment

\$

220.00 X

To transfer of tire, rim and on wheel balancing.

\$

170.00 X

**TOTAL \$****3,630.00****Over All Total \$****7,764.47****(PARTS BY PARTS) Repair Days****5 Days****LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Text size + -

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 3878K

### Vehicle Details

Vehicle No.: SHF616Y

Vehicle to be Exported: Yes

Intended De-registration Date: 29 Feb 2016

Vehicle Make: RENAULT

Vehicle Model: LATITUDE 2.0L DCI AUTO D/AB 4DR

Primary Colour: Red

Manufacturing Year: 2014

Engine No.: M9R8839C001423

Chassis No.: VF1ABL15AUC278497

Maximum Power Output: 127.0 kW (170 bhp)

Open Market Value: \$19,998.00

Original Registration Date: 27 Jun 2014

First Registration Date: 27 Jun 2014

Transfer Count: 0

Actual ARF Paid: \$12,498.00

### Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 26 Jun 2022

PARF Rebate Amount: \$9,373.00

### Intended COE Rebate Details

COE Expiry Date: 26 Jun 2022

COE Category: A - Car (up to 1600cc & 97kW (130bhp))

COE Period(Years): 8

PQP Paid: \$57,338.00

COE Rebate Amount: \$45,312.00

**Total Rebate Amount: \$54,685.00**

### Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.  
The information contained herein is correct as at 29 Feb 2016

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.  
Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.  
Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution  
Copyright © 2016 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)

: (LKKAUTO)

---

**From:** Vic (LKKAUTO)  
**Sent:** Tuesday, 17 October, 2017 4:00 PM  
**To:** Dally Amri, Mimi Zarina  
**Cc:** Admin A; Vic (LKKAUTO); Laili, Shahzlan; Sukimin, Nurasikin  
**Subject:** Your Ref: 3031201131SG\_ACCIDENT INVOLVING VEHICLES SKV 7054C (OI) AND SHF 616Y (TP) ON 28/02/2016

Your Ref: 3031201131SG  
Our Ref: CC3/AIG16004063/Khb3

Dear Mi Mi,

ACCIDENT INVOLVING VEHICLES SKV 7054C (OI) AND SHF 616Y (TP) ON 28/02/2016

We refer to the above matter.

Please be informed that we had already finalized the COR and had already settled the matter with TP claimant at a 50% basis due to conflicting versions on 14/07/2016.

However, till date, no feedback and documents from TP repairer yet.

As such, we will proceed to temporarily close this matter and submit our Survey Report for your necessary action.

We will reopen the case should there be any further development.

Thank you.

Best Regards,

**Vic Alpeh** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2096 | email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



*Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

**Our Ref: CC3/AIG16004063/Khg3**

12 April 2016

**LIM LI SAN ANGELA**  
54 LAKESIDE DRIVE  
#15-22  
SINGAPORE 648317

Dear Sir/Madam,

**ACCIDENT INVOLVING SKV 7054C AND SHF 616Y ON 28/02/2016**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Kindly note that we have reviewed this matter and would like to advise that you and/or your authorized driver may not be absolved from blame for this accident.

If you have evidence/information to prove that we should not settle the third party claim, kindly let us have them in writing within the next 10 days, after we shall proceed with negotiation with Third Party claimant on the **without prejudice basis** and any settlement should not bind any claims whatsoever by you/your driver against the other party's insurer arising from this particular accident.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

  
Asher

Case Handler

DID: 6841 6051

FAX: 6741 4108

Email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)

c.c. AIG Asia Pacific Insurance Pte Ltd  
(Motor Claims Dept)



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Mar 2016 15:08 <a href="#">Edit Reg</a>		29 Feb 2016 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$744.82</b> <a href="#">Edit Estimates</a>	<b>S\$744.82</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
<b>Insured:</b> Lim Li San Angela, ID: 57714704G									
<b>Main Claimant:</b> TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K									
<b>Vehicle Reg. No.:</b> SHF616Y		<b>Date of Loss:</b> 28/02/2016 12:00 - :59							
<b>Claim Type:</b> TP / 3031201131SG		<b>Policy/Cover Note No.:</b> 2100431300							
<b>Vehicle Reg. No. (Insured):</b> SKV7054C		<b>Policy No. (Claimant):</b> VPX/P1680520							
<b>Excess:</b>									
<b>Repairer:</b> Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel: 62876666									
<b>Handling Insurer:</b> AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Suriamurthy, Visaline]									
<b>Claimant's Insurer:</b> AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288									
<b>Adjuster:</b> LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 11/03/2016]									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SHF616Y (3031201131SG)  
[SKV7054C]  
TP  
TRANS-CAB SERVICES PTE LTD  
Feb 28 2016 12:00PM  
[Lim Li San Angela]  
Trans-cab Auto Services Pte Ltd

Upload Documents	Upload Photos	Compose New Letter	Upload Video	Upload Audio	View	Use Viewer
------------------	---------------	--------------------	--------------	--------------	------	------------

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	02/03/16 17:10	Odometer Reading	1	Load JPG	<input checked="" type="checkbox"/>
2	02/03/16 17:10	Chassis Number	1	Load JPG	<input checked="" type="checkbox"/>
3	02/03/16 17:11	General View	1	Load JPG	<input checked="" type="checkbox"/>
4	02/03/16 17:11	General View	1	Load JPG	<input checked="" type="checkbox"/>
5	02/03/16 17:11	General View	1	Load JPG	<input checked="" type="checkbox"/>
6	02/03/16 17:11	General View	1	Load JPG	<input checked="" type="checkbox"/>
7	02/03/16 17:11	General View	1	Load JPG	<input checked="" type="checkbox"/>
8	02/03/16 17:11	General View	1	Load JPG	<input checked="" type="checkbox"/>

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	02/03/16 16:36	TP ESTIMATE - MARKED	1	Load PDF	
2	02/03/16 16:36	TP GIA REPORT & COE REBATE	1	Load PDF	
3	12/04/16 15:29	LETTER TO OI	1	Load PDF	
4	17/10/17 16:01	EMAIL TO AIG	1	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	02/03/16 16:04	oi gia	1	Load PDF	

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset Save Print
There are no document checklists configured.	

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:** ☐ Handling Insurer.

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG16004063/KHB3Q2

Date: 19/10/2017

## REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100431300
Claimant Vehicle No :	SHF616Y	Insured Vehicle No :	SKV7054C
Date of Loss:	28/02/2016	Nature of Claim:	TP
		Claim No:	3031201131SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SHF616Y	Engine No:	M9R8839C001423
Make & Model:	RENAULT LATITUDE, 2.0 D dCi (A)	Chassis No:	VF1ABL15AUC278497
Reg. Date:	27/06/2014 (Man. Year: 2014)	Odometer:	300765 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Rovelo 8 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Rovelo 8 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	4,134.47	104.82	4,029.65	97.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,630.00	640.00	2,990.00	82.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>7,764.47</b>	<b>744.82</b>	<b>7,019.65</b>	<b>90.41</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>543.51</b>	<b>52.14</b>	<b>491.37</b>	<b>90.41</b>
<b>Nett Amount (S\$)</b>	<b>8,307.98</b>	<b>796.96</b>	<b>7,511.02</b>	<b>90.41</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

## INSPECTION

Date of Assignment:	29/02/2016	
Date Inspected:	29/02/2016	Inspected At: Trans-cab Auto Services Pte Ltd NO. 2ANG MO KIO, ST 63 Singapore 569111
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER FRT	Repair	968.78 FL	*- FL
2	1		*BUMPER RETAINER FRT LH	Distorted	116.47 FL	*116.47 FL
3	1		*HEADLAMP LH	Serviceable	911.10 FL	*- FL
4	1		*FENDER PANEL FRT LH	Repair	602.95 FL	*- FL
5	1		*FENDER WHEELARCH FRT LH	Serviceable	107.33 FL	*- FL
6	1		*FENDER PANEL FRT RH	Repair	602.95 FL	*- FL
7	1		*AIR CLEANER LOWER	Serviceable	271.26 FL	*- FL
8	1		*AIR CLEANER HOSE	Serviceable	58.57 FL	*- FL
9	1		*SET FRONT BUMPER CLIP	Not Necessary	66.00 FS	*- FS
10	1		*SET FRONT WHEELARCH CLIP LH	Not Necessary	30.50 FS	*- FS
11	1		*SET BUMPER RETAINER FRT CLIP LH	Not Necessary	12.50 FS	*- FS
12	1		*RIM RH FRT	Serviceable	385.00 FS	*- FS
13	1		*TYRE RH FRT	Serviceable	330.00 FS	*- FS
14	1		*CAP HUB RH FRT	Serviceable	35.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (\$\$)	4,498.41	116.47
- List Item Discount on L Items 10.00/10.00% (\$\$)	363.94	11.65
Total Parts (\$\$)	4,134.47	104.82

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	1,400.00	200.00
2	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	0.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,500.00	440.00
4	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
5	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
6	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
Gross Labour Cost (S\$)			3,630.00	640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >