REF NTUC NS/ INC1900 9650 / J90362

THE COLUMN	
	ASSIGNMENT
From: Date:	Veh No: SHB5506U Yr Regn: 1 Nov 2017
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Tax / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: Topota Prins c.c 1798
at Workshop m/s	Colour Naroga A/C: Insured / Std / NI / NA
of	Sp.Reading 166482 T/Radio: Insured / Std / NI / NA
Insured: GBD 3&C	Eng/No:
Policy No. 5087118746-02 (01/01/2019) C/NO: JTDKB3FU703573278
Claims No. My 646 65-600	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / SIRID / STD A/Rim or
	Tyre Size: F: 198 65 R15
(Policy Condition)	R: -
Remark: The veh had commenced its N/S	S O/S BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or Falken
Bal. or Market Value:	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. & mm R/Bal. 6 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 6 mm L/Bal. £ mm
Est. Repairs:	D.O.A. D.O.I. 28/5/19
Lum Sum: % 3 Val.: Yes or No	
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle	E: IN/OUT
Date:Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction SH B 5506 U - NS //VC 13018	700/8100 200 200 200 200 200 200 200 200 200
GBD 382C - X	530 RIGIMSW 2 12017-04/10/2013 05/19/2122
09/2/19 @ 1.4my consisted with	Poh Sunn fran Ag \$967.83 2day \$80382C
(Red & mon 17, 80%)	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
RECEIVE	D 1 0 JUL 2019
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
ate/Time, File Pass to? : Preli. Report	Days Of Repair:
old things : Final Report	Resurvey No. of Trip: Survey Fee: 160
Date/Time, File Return to?	Transportation:
)	Add Fee: : Site Insp (\$)s+RSsi
	: Interview (\$) Photos
Report Format :	: Tech. Invs (\$) Others
Lump Sum / I.B.I: (\$ 769,133)	: Weekend (\$

TOTAL

TP Claims against NTUC Income: Follow-Through Survey

Date: 09/07/2019

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.
1	MT/1050092-002	CITYCAB PTE LTD	SHC 982E	SMD 9034T
2	MT/1046594-002	SMRT TAXIS PTE LTD	SHB 162K	SGK 9564P
3	MT/1046105-002	SMRT TAXIS PTE LTD	SHB 5506U	GBD 382C
4	MT/1052638-001	SMRT TAXIS PTE LTD	SHC 4614S	SLB 887E

eBaoTech									(GeneralC	laim
Hello, NAC_PAYA_UBI_80	0601						Change Lan	guage	• Change P	assword	Log Out
My Desktop	Poli	cy Query									24
Notice of Loss	Policy N	lo.				Date of	Accident	25/0	5/2019 10:34	1	
	Vehicle	No.(For Motor)	GBD382	С		Certifica	te Number				
					Se	arch					
	Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
	0	5087118746- 02		ADEMCO (FAR EAST) PTE LTD	197700631N	GFT	Comprehensive	GBD382C	100000000	01/01/2019	
					Con	tinue					

Shiau Chan (LKKAuto)

From:

Shiau Chan (LKKAuto)

Sent:

Tuesday, 9 July 2019 1:42 PM

To:

Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis)
SUR

Cc: Subject:

RE: SHB5506U

Dear Poh Suan,

WITHOUT PREJUDICE

Confirm final fig \$969.83 before GST and 2 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1,

#02-25 | S(408933)

----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis) < YeoPohsuan@smrt.com.sg>

Sent: Monday, 8 July 2019 8:15 AM

To: Hwee Jie (LKK Auto) <hweejie@lkkauto.com>

Cc: SUR <sur@lkkauto.com>; CS A Team <cs-a@lkkauto.com>

Subject: SHB5506U

Hi Hwee Jie,

Attached herewith the repair estimate of SHB 5506U having Case No: TAX/05/19/2122.

There is no change to the approved amount of \$969.83 @ 2 working days under part by part repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards

Poh Suan

----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis)

Sent: Sunday, 7 July 2019 11:15 AM

To: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis)

Subject: Scan Data from FX-D421D6

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type:	Company	
Owner ID: Vehicle Details	5369K	
Vehicle No.:	SHB5506U	
Vehicle to be Exported:	No	
Intended Deregistration Date:	28 May 2019	
Vehicle Make:	TOYOTA	
Vehicle Model:	PRIUS HYBRID 1.8 CVT	
Primary Colour:	Maroon	
Manufacturing Year:	2017	
Engine No.:	2ZRS099950	
Chassis No.:	JTDKB3FU703573278	
Maximum Power Output:	90.0 kW (120 bhp)	
Open Market Value:	\$29,007.00	
Original Registration Date:	01 Nov 2017	
First Registration Date:	01 Nov 2017	
Transfer Count:	0	
Actual ARF Paid: Intended PARF Rebate Details	\$5,000.00	
PARF Eligibility:	Yes	
PARF Eligibility Expiry Date:	31 Oct 2025	
PARF Rebate Amount: Intended COE Rebate Details	\$3,750.00	
COE Expiry Date:	31 Oct 2025	
COE Category:	A - Car up to 1600cc & 97kW (130bhp)	
COE Period(Years):	8	
PQP Paid:	\$33,596.00	
COE Rebate Amount:	\$26,980.00	
Total Rebate Amount: Message	\$30,730.00	
The second of th		

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 28 May 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Occupation

Gender

Date Of Driving Pass

Driving Experience

Mobile Number

Fax Number Contact Number EMail Address

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

aforesaid.	
THE RESIDENCE OF THE PARTY OF T	ACCIDENT STATEMENT
Date Of Report	27/05/2019 13:25
Date Of Accident	25/05/2019 20:30
Exact Location Of Accident	ALEXANDRA ROAD
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SHB5506U
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000
Vehicle Particulars	
Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-19093197MFSH
Cover Note Number	
Driver	
Name of Driver	CHEW CHOON KEE
NRIC No	\$76057691
Date Of Birth	25/02/1976
0	

OUTDOOR

25/04/1995

MALE

NOEMAIL

24 YEARS AND 1 MONTH

(LOCAL) +65-80000000

Address

1

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - RELIEF

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

Number of vehicles (including own vehicle)

involved in the accident

NO

Was any body injured in the Accident? Was any injured conveyed to hospital by

ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

2

Passenger 1

NAME:

: UNKNOWN

GENDER:

: MALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

I WAS TRAVELLING ALONG ALEXANDRA ROAD AT THE RIGHT MOST LANE WITH A PASSENGER ON BOARD AND HAD SLOWED DOWN TO A STOP DUE TO RED TRAFFIC LIGHT AHEAD. AFTER WHICH, I FELT AN IMPACT FROM BEHIND, THE VEHICLE GBD382C FROM BEHIND HAD COLLIDED ONTO THE REAR PORTION OF MY TAXI.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

GBD382C

Vehicle Make/Model/Colour Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

ONG CHOON HOW

NRIC/Passport Number

S7334354B

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

ale 37/5/19

Sketch Plan Pg. 2

SKETCH PLAN			COMMUN WEALTY
LENG KEE RD			AVE
7	1 1 1 2	2	
\			
		٧	
\ \		2	
		No	
AUDI		ALEXANDRA	A- CUP FOUR
CENTRE		W 34	A-SHB5506U B-680382C
		B	303820
ESCRIBE CIRCUMSTANCES	S OF THE ACCIDENT		
9			
N. C.			
ECLARATIONTE	5-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1		
We declare the foregoing part	iculars are true in every respect.		7
1 / / /	112.		ale 20/8/19
WS			
olicyholder's Signature ate & Time:	Driver's Signature (If driver is not the policyholder)		eporting Centre Personnel's Signature ame:
100 M 1111001	Date & Time:		ame: RIC/FIN No.:

Page 5 of 10



Case Details

Case Reference Number :

TAX/05/19/2122

Type of Repair : Accident Repair Vehicle Registration Number:

SHB5506U

Company Type: SMRT Taxis Pte Ltd

Estimation ID: EST-7055-ID

Assigned By: Taxi Claims Manager

Insurance Company Name: NTUC Income Insurance Co-

operative Ltd

Accident Date and Time: 25/05/2019 12:27 PM

Vehicle Age(In Months): 18

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

				SMRT Recor	nmend	ation						Survey	or Approval	
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.92	Replace	1	0	Repair *	
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 1	2	3.80	7.60	25.00	5.70	Replace	0	0	Not Give ▼	
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 2	2	3.80	7.60	25.00	5.70	Replace	0	0	Not Giv€ ▼	
One Time Key In	Main			PAD, RR BUMPER, RH & LH, 3	2	3.80	7.60	25.00	5.70	Replace	0	0	Not Give ▼	hn
One Time Key In	Main			RETAINER, RR BUMPER, RH	1	112.70	112.70	25.00	84.53	Replace	0	0	Not Giv€ ▼	
One Time Key In	Main			RETAINER, RR BUMPER, LH	1	111.50	111.50	25.00	83.63	Replace	0	0	Not Give ▼	
One Time Key In	Main			GUARD, RR BUMPER, LOWER	1	558.30	558.30	25.00	418.72	Replace	1	418.73	Replace *	SCR
One Time Key In	Main			COVER, GUARD RR BUMPER LOWER	1	14.80	14.80	25.00	11.10	Replace	1	11.10	Replace *	SCR

Total Spare Part Cost 2,121.77

Surveyor Total 549.82

Lump Sum Discount (%) 0.00

Lump Sum Dis (%)

Final Spare Part Cost 2,121.77

Final Sur Total 549.82

				SMRT Recom	menda	ition						Survey	or Approval	
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replac	e Remark
One Time Key In	Main			FILLER, RR BUMPER, RH	1	119.90	119.90	25.00	89.93	Replace	0	0	Not Give	hn
One Time Key In	Main			FILLER, RR BUMPER, LH	1	119.90	119.90	25.00	89.93	Replace	0	0	Not Giv€	nn
One Time Key In	Main			REAR BUMPER REINFORCEMENT	1	318.80	318.80	25.00	239.10	Replace	0	0	Not Give	n _k
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.0	Replace	nec.
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Not Give	
One Time Key In	Main			COVER, REAR FLOOR UNDER , RH	1	169.50	169.50	25.00	127.13	Replace	0	0	Not Give	· } n
One Time Key In	Main			COVER, REAR FLOOR UNDER CENTER	1	222.60	222.60	25.00	166.95	Replace	0	0	Not Give	
One Time Key In	Main			COVER, REAR FLOOR UNDER , LH	1	234.30	234.30	25.00	175.73	Replace	0	0	Not Give	. 1
						To	tal Spare	Part Cost	2,121.77		Su	rveyor Total	549.82	
						Lump	Sum Disc	ount (%)	0.00		Lump	Sum Dis (%)	0	
						Fi	nal Spare I	Part Cost	2,121.77		Fir	nal Sur Total	549.82	

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(S)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	845.00	200 /	
Total:			845.00	200.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY FILLER RR BUMPER LH	180.00	0	

Total:

738.00

200.00

5/28/2019

https://vacsweb.smrt.com.sg/Estimation.aspx

` S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
3	Main	TO RESPRAY FILLER RR BUMPER RH	180.00	0	
Total:			738.00	200.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	0	
3	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0	
4	Main	TO WASH AND VACUUM	60.00	0	
5	Main	TO REPLACE SUNDRY PARTS	100.00	0	
Total:			560.00	20.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)		
Total Spare Part Detail	2,121.77	549.82		
Total Labour Cost	845.00	200.00		
Total Spray Painting	738.00	200.00		
Other 560.00		20.00		
Overall Total	4,264.77	969.82		
Lump Sum Repair Option				
ump Sum Total	0.00	969.82		
Surveyor Approved Amount		969.82		
No of Repair Days*	5	2		
Remarks	•	p/p repair, photo after paint		
Surveyor Name		Hwee jie		

Signature

Estimator Assesment(\$)

Surveyor Assesment(\$)

Save Clear

Survey Date

28/05/2019

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- * Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- * No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:




SMRT Accident Vehicle Repair Estimates


BMRT Automative Services Pto Ltd
80 Woodlands Industrial Park E4, Singapore 757705
FAX Number: 63685502
Ecimate/ Telephone Number: 68662672
Accident Reporting Number: 68662672

Date Generated : 07/07/2019 User ID : PohSuan

	Section A - Accident Details
Registration Number	SHB5508U
Case Reference Number	TAX/05/19/2122
Registration Date	1/11/2017
Company Type	SMRT Taxis Pte Ltd
Make	тоуота
Model	PRIUS4
Name of Driver	CHEW CHOON KEE (JIANG JUNQI)
Type of Accident	Head to Rear
Accident Date and Time	25/5/2019 8:27 PM
Accident Reported Date and Time	27/5/2019 1:29 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	25/5/2019 10:30 PM
Replacement Vehicle issued?	No
Job Card Number	24101689
Special Instruction to ARC, if any	TOWED \$40
Prepared Date and Time	28/5/2019 2:06 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$200.00
Total Spray Cost	\$738,00	\$200,00
Total Spare Part Cost	\$2,121.77	\$549.83
Total Other Cost	\$560.00	\$20.00
TOTAL COST	\$4,264.77	\$969.83 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	2.0
Prepared / Adjusted By	Zhi Yang Phua	Hwee Jie (LKK) / NTUC
ARC / Surveyor Sign Off Date	28/05/2019 2:25 PM	28/05/2019 2:28 PM
Signature		ь —
Remarks	,	p/p repair, photo after paint





ophis



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd

60 Wesdlands Industrial Park E4, Singapore 757705

FAX Number : 53685582

Estmater Tolephane Number : 68662573

Accident Reporting Number : 68662572

Date Generated : 07/07/2019 User ID : PohSuan

	Section C - Gubte	tion and Accident Invoice Details	43.0
Quotation Number	QN-1906-0485	Invoice Number	
Quotation Date	28.06.2019	Invoice Date	
Invoice Amount		Prepared Date	

	Details of Repair Estimates	
Part 1 - Labour Works Job Scope		Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$845,00	\$200.00
Total Labour	\$845.00	\$200.00

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY FILLER RR BUMPER LH	\$180.00	\$0.00
TO RESPRAY FILLER RR BUMPER RH	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$738.00	\$200.00

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80,00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$0.00
TO WASH AND VACUUM	\$60,00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$560.00	\$20.00

Part	Portion	Stock	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price	Estimator Approved	Surveyor. Approved
TOTALDET	I SALES TRANSPORTER	52159479	COVER, RR BUMPER ASSY	1.00	\$423.90	100.00	\$0.00	Replace	Repair /
		52462470 30	PAD, RR BUMPER, RH & LH , 1	0,00	\$3.80	0.00	\$0.00	Replace	Not Given
		52462470 20	PAD, RR BUMPER, RH & LH , 2	0.00	\$3.80	0.00	\$0.00	Replace	Not Given
		52452470 10	PAD, RR BUMPER, RH & LH . 3	0.00	\$3.80	0.00	\$0.00	Replace	Not Given
		52575470 40	RETAINER, RR BUMPER, RH	0.00	\$112.70	0.00	\$0.00	Replace	Not Given X
		52576470 40	RETAINER, RR BUMPER,	0.00	\$111.50	0.00	\$0.00	Replace	Not Given X
		52453470 10	GUARD, RR BUMPER, LOWER	1.00	\$558.30	25.00	\$418.73	Replace	Replace /
		52169470	COVER, GUARD RR BUMPER LOWER	1.00	\$14.80	25.00	\$11.10	Replace	Replace /
		52565479 00	FILLER, RR BUMPER , RH	0.00	\$119.90	0.00	\$0.00	Replace	Not Given
		52566479 00	FILLER, RR BUMPER , LH	0.00	\$119,90	0.00	\$0,00	Replace	Not Given
		52023470 30	REAR BUMPER REINFORCEMENT	0.00	\$318.80	0.00	\$0.00	Replace	Not Given
			PIXEL STICKER	2.00	\$60.00	0,00	\$120.00	Replace	Replace
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given X
		58398470	COVER, REAR FLOOR UNDER , RH	0.00	\$169.50	0.00	\$0.00	Replace	Not Given



SMRT Accident Vehicle Repair Estimates

SMRT Autometive Services Pte Ltd
69 Waedlands Industrial Park E4, Singapore 757705
FAX Humber: 03685592
Estimatol Telephone Number: 58692823
Accident Reporting Number: 68662672

Date Generated : 97/07/2019 UserID : PohSuan

		COVER, REAR FLOOR UNDER CENTER	0.00	\$222.60	0.00	\$0.00	Replace	Not Given X
	58399470	COVER, REAR FLOOR UNDER . LH	0.00	\$234.30	0.00	\$0.00	Replace	Not Given
Total	30	OHDER, EI		\$2,657.60		\$549.83		

Added Spare Parts	/ Material Usa	ge After Surveyor Signed off	THE PARTY AND				430 300
Part Portion	Stock-	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	Surveyor Check
Total							

+ 200,00 + 200,00 + 200,00



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





NTUC	NTUC INCOME INSURANCE CO-OPERATIVE LTD			NS/INC19009650/Jqd3e2		
		D UNION HOUSESINGAPORE	Date:	16-07-2019 INC4		
1.		Policy Particulars	:- THIR	D PARTY CLAIM		
I	nsured Veh.	GBD 382C	Veh. li	nspected	SHB 5506U	
F	Policy No.	5087118746-02	Cover	age (\$)	0.00	
	Claim No.	MT/1046105-002	Exces	s (\$)	0.00	
1	Assign From		Assig	n Date	28/05/2019	
2.		Vehicle Partie	culars &	Condition		
ı	Make & Model	TOYOTA PRIUS	c.c		1798	
E	Engine No.	HIDDEN	Year o	of Reg.	2017	
(Chassis No.	JTDKB3FU703573278	Colou	r	MAROON	
	Odometer	166482	Steeri	ng	IN ORDER	
E	Brakes	IN ORDER	Modifi	cation	SPORTS RIM	
	General	GOOD				
3.		Conditi	ons of	Tyres		
		Size	Make		Balance	
F	R/H Front Tyre	195/65 R15	FALKE	N	6 mm	
ι	_/H Front Tyre	195/65 R15	FALKE	N	6 mm	
F	R/H Rear Tyre	195/65 R15	FALKE	N	6 mm	
ι	_/H Rear Tyre	195/65 R15	FALKE	N	6 mm	
4.	distance in the	Description	on of Da	amages		
ן	THE VEHICLE SU	STAINED DAMAGES AT THE RE	AR POR	TION.		
	DAMAGES SEE D	ETAILS.				
5.		Genera	Inform	ation		
1	Accident Date	25/05/2019	Insped	tion Date	28/05/2019	
5	Survey held at	SMRT AUTOMOTIVE SERVICE	S PTE L	TD		
		60 WOODLANDS INDUSTRIAL	PARK E	4 SINGAPORE 7577	05	
5a.		R	emarks	The state of the s	equinos de la late	
Ā	A)THE INSPECTION B)IN ACCORDANCE	ON WAS CONDUCTED ON A"WIT CE TO YOUR INSTRUCTIONS, W	HOUT P	REJUDICE" BASIS. NOT AUTHORISED	REPAIRS.	
5b.		Estimate	Days of	Repair		
E	ESTIMATED NOR	MAL PERIOD FOR REPAIR:		2 Working Days		



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 5506U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	GUARD, RR BUMPER, LOWER (DISC 25%)	SCRATCHED	558.30	418.73
1	COVER, GUARD RR BUMPER LOWER (DISC 25%)	SCRATCHED	14.80	11.10
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
2	PAD, RR BUMPER, RH & LH, 1 @\$3.80	NOT NECESSARY	7.60	=
2	PAD, RR BUMPER, RH & LH, 2 @\$3.80	NOT NECESSARY	7.60	
2	PAD, RR BUMPER, RH & LH, 3 @\$3.80	NOT NECESSARY	7.60	
1	RETAINER, RR BUMPER, RH	NOT NECESSARY	112.70	
1	RETAINER, RR BUMPER, LH	NOT NECESSARY	111.50	
1	FILLER, RR BUMPER, RH	NOT NECESSARY	119.90	-
1	FILLER, RR BUMPER, LH	NOT NECESSARY	119.90	
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	318.80	
1	SENSOR REVERSE	NOT NECESSARY	180.00	
1	COVER, REAR FLOOR UNDER, RH	NOT NECESSARY	169.50	-
1	COVER, REAR FLOOR UNDER CENTER	NOT NECESSARY	222.60	
1	COVER, REAR FLOOR UNDER, LH	NOT NECESSARY	234.30	
1	COVER, RR BUMPER ASSY	TO REPAIR SEE LABOUR	423.90	-
			2,729.00	549.83
	LABOUR			
	PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF COVER, RR BUMPER ASSY.		845.00	200.00
	SPRAY PAINT.		738.00	200.00
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	20.00
	TO APPLY RUST-PROOFING ON AFFECTED AREA.	NOT NECESSARY	200.00	
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.	NOT NECESSARY	120.00	-
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	
			2,143.00	420.00
	GRAND TOTAL		4,872.00	969.83

RECOMMENDED COST OF REPAIRS (CONFIRMED) 969.83

Report Ref No. NS/INC19009650/Jqd3e2





Report Ref No. NS/INC19009650/Jqd3e2

ONG HWEE JIE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:-This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.