

(08/11/13)

ASS. REC. BY: Hue Jde

REF

NTUC NS/INC 19009651 E 15/03/2019

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_


Insured: SJR 77866Policy No. 5044537992-08 (14/07/2018-13/07-2019)Claims No. MT/1046697-002

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SHB 5093T Yr Regn: 10 Oct 2017Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi Prime Mover /

Truck / Trailer or

Make: Toyota Prius c.c. 1798Colour maroon A/C: Insured / Std / NI / NASp. Reading 939348 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JTDKB3FU703572809Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65 R15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 28/5/19 D.O.I. 29/5/19Survey held at SundDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SHB 5093T - CC3 / AIG 13020781 / Pleb3w2 2017 - 04/11/2013 05/19/2129
	SJR 77866 - X
20/9/19	Finalize Conf. \$3539.54, 4 day
	C# 5.858.96 Red - 62% 7
	RECEIVED 28 SEP 2019
	20/9/2019

Date/Time, File Pass to?

23/09/19

1) Typist

Date/Time, File Return to?

2)

☐ : Preli. Report☒ : Final ReportDays Of Repair: 4Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)Survey Fee: 160

Transportation: \_\_\_\_\_

S + RS, \$ \_\_\_\_\_

Photos

Others

TOTAL

160

Report Format: \_\_\_\_\_

Lump Sum / I.B.I. (\$) 3,539.54 p/p

eBaoTech

GeneralClaim

Hello, NAC\_PAYA\_UBI\_800601

[Change Language](#) [Change Password](#) [Log Out](#)[My Desktop](#)  
[Notice of Loss](#)

## Policy Query

Policy No.	<input type="text"/>	Date of Accident	<input type="text" value="28/05/2019 10:34"/>
Vehicle No.(For Motor)	<input type="text" value="SJR7786G"/>	Certificate Number	<input type="text"/>
<input type="button" value="Search"/>			

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input type="radio"/>	5044577992-08		CHONG TENG KWANG	S11588681	GPC	drive CLASSIC	SJR7786G	SJR7786G	14/07/2018	13/07/2019

**TP Claims against NTUC Income: Follow-Through Survey**

Date : 23/09/2019

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	Estimate	Tentative repair cost
1	<b>MT/1046697-002</b>	SMRT TAXIS PTE LTD	SHB 5093T	SJR 7786G	28/05/2019	11:10	\$ 9,398.50	\$ 3,539.54
2	<b>MT/1061689-002</b>	SMRT BUSES LTD	SMB 223J	SMM 3323B	09/09/2019	09:50	\$ 2,895.00	\$ 800.00

Claim received from LKK Auto

[> Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	5369K
<b>Vehicle Details</b>	
Vehicle No.:	SHB5093T
Vehicle to be Exported:	No
Intended Deregistration Date:	31 May 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Maroon
Manufacturing Year:	2017
Engine No.:	2ZRS097558
Chassis No.:	JTDKB3FU703572809
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	10 Oct 2017
First Registration Date:	10 Oct 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Oct 2025
PARF Rebate Amount:	\$3,750.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	09 Oct 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$34,052.00
COE Rebate Amount:	\$27,060.00
<b>Total Rebate Amount:</b>	<b>\$30,810.00</b>
<b>Message</b>	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 31 May 2019

OK

**RE: SHB5093T**

Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis) <YeoPohsuan@smrt.com.sg>

Fri 20/9/2019 1:33 PM

To: Steve Chen (LKK Auto) <SteveChen@lkkauto.com>

Cc: SUR <sur@lkkauto.com>; CS A Team <cs-a@lkkauto.com>

Hi,

Amount confirmed as per your recommendation, thanks.

Regards  
Poh Suan

-----Original Message-----

From: Steve Chen (LKK Auto) [<mailto:SteveChen@lkkauto.com>]

Sent: Friday, 20 September 2019 10:57 AM

To: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)

Subject: SHB5093T

Dear Poh Suan,

We confirm the finalize \$3,539.54 (P/P, before GST). 4 repair days.

Thanks

Best Regards,  
Steve Chen | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: [SteveChen@lkkauto.com](mailto:SteveChen@lkkauto.com) | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park,  
Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis) [<mailto:YeoPohsuan@smrt.com.sg>]

Sent: Friday, September 20, 2019 9:32 AM

To: Steve Chen (LKK Auto)

Subject: SHB5093T

Hi Steve,

Attached herewith the repair estimate of SHB 5093T having Case No: TAX/05/19/2129.

There is no change to the approved amount of \$3,539.54 @ 4 working days under part by part repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	29/05/2019 09:33
Date Of Accident	28/05/2019 11:10
Exact Location Of Accident	QUEENS STREET TOWARDS MIDDLE ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB5093T
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-80000000
Alternative Phone No	OFFICE-80000000

### Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-19093197MFSH
Cover Note Number	

### Driver

Name of Driver	CHIN GEE LONG
NRIC No	S1330994I
Date Of Birth	29/07/1958
Occupation	OUTDOOR
Date Of Driving Pass	17/02/1992
Driving Experience	27 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address	683A
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

I WAS TRAVELLING ALONG QUEENS STREET TOWARDS MIDDLE ROAD. SUDDENLY I FELT AN IMPACT AT THE RIGHT PORTION OF MY TAXI. A VEHICLE SJR7786G CAME OUT FROM THE CAR PARK ON THE OPPOSITE DIRECTION AND COLLIDED ONTO THE RIGHT PORTION OF MY TAXI.


#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJR7786G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LEE KEE KHON
NRIC/Passport Number	S1266579B
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

A: SNB 50937  
B: SJR 77866



28/5/2019


[illegible]

### DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature \_\_\_\_\_  
Date & Time \_\_\_\_\_

are true in every respect.

 22/5/2018

\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



## Case Details

**Case Reference Number :**

TAX/05/19/2129

**Type of Repair :** Accident Repair

**Vehicle Registration Number :**

SHB5093T

**Company Type :** SMRT Taxis Pte Ltd

**Estimation ID :** EST-7070-ID

**Assigned By :** Taxi Claims Manager Team

**Insurance Company Name :** NTUC Income Insurance Co-operative Ltd

**Accident Date and Time :** 28/05/2019 03:10 AM

**Vehicle Age(In Months) :** 19

## Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

## Estimation Details

**Spare Part's Cost Detail**

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remark
One Time Key In	Main			PANEL SUB-ASSY, FRONT DOOR RH	1	1,249.60	1,249.60	25.00	937.20	Replace	1	937.2	Replace	✓ 00
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace	✓ OK
One Time Key In	Main			DOOR OUTER HANDLE FRONT , RH	1	378.90	378.90	25.00	284.17	Replace	1	284.18	Replace	✓ OK
One Time Key In	Main			DOOR FRAME INNER HANDLE FRONT , RH	1	187.70	187.70	25.00	140.77	Replace	0	0	Not Give	✗ N/A
One Time Key In	Main			DOOR LOCK STRIKER	1	38.00	38.00	25.00	28.50	Replace	0	0	Not Give	✗ N/A
One Time Key In	Main			HINGE ASSY, FRONT DOOR , UPPER RH	1	82.10	82.10	25.00	61.57	Replace	0	0	Not Give	✗ N/A
One Time Key In	Main			HINGE ASSY, FRONT DOOR , LOWER RH	1	92.10	92.10	25.00	69.07	Replace	0	0	Not Give	✗ N/A
One Time Key In	Main			DOOR FRONT WINDOW REGULATOR SUB-ASSY, RH	1	230.80	230.80	25.00	173.10	Replace	0	0	Not Give	✗ N/A

Total Spare Part Cost 4,601.24

Surveyor Total 1,865.08

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 4,601.24

Final Sur Total 1,865.08

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remark
One Time Key In	Main			DOOR FRONT MOTOR ASSY, POWER WINDOW REGULATOR, RH	1	768.60	768.60	10.00	691.74	Replace	0	0	Not Give	X N/A
One Time Key In	Main			LOCK ASSY, FRONT DOOR RH	1	581.90	581.90	10.00	523.71	Replace	1	523.71	Replace	X BT
One Time Key In	Main			MOULDING ASSY, FRONT DOOR BELT, RH	1	88.60	88.60	25.00	66.45	Replace	0	0	Not Give	X N/A
One Time Key In	Main			CHECK ASSY, FRONT DOOR	1	153.50	153.50	25.00	115.13	Replace	0	0	Not Give	X N/A
One Time Key In	Main			PANEL SUB-ASSY, REAR DOOR, RH	1	1,243.90	1,243.90	25.00	932.93	Replace	1	0	Repair	X R
One Time Key In	Main			PIXEL STICKER	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace	X AK
One Time Key In	Main			WEATHERSTRIP, REAR DOOR, NO.2, RH	1	33.20	33.20	25.00	24.90	Replace	0	0	Not Give	X N/A
One Time Key In	Main			MOULDING ASSY, BODY ROCKER PANEL, RH	1	576.00	576.00	25.00	432.00	Replace	0	0	Not Give	X N/A
Total Spare Part Cost									4,601.24	Surveyor Total 1,865.08				
Lump Sum Discount (%)									0.00	Lump Sum Dis (%) 0				
Final Spare Part Cost									4,601.24	Final Sur Total 1,865.08				

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR RH PORTION	845.00	300	
Total:			845.00	300.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY FRONT DOOR RH	378.00	200	

Total:

936.00

400.00

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
2	Main	TO RESPRAY ROCKER PANEL MOULDING	180.00	0	
3	Main	TO RESPRAY RH REAR DOOR	378.00	200	
Total:			936.00	400.00	+ 190 (Supp) = 590

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	30	
3	Main	TO TRANSFER DOOR MECHANISM	120.00	50	
4	Main	TO REMOVE AND REFIT WIRE HARDESS	200.00	0	
5	Main	TO WASH AND VACUUM	60.00	0	
Total:			560.00	100.00	

## Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	4,601.24	1,865.08
Total Labour Cost	845.00	300.00
Total Spray Painting	936.00	400.00
Other	560.00	100.00
Overall Total	<del>6,942.24</del> 9398.50	2,665.08
Lump Sum Repair Option		
Lump Sum Total	0.00	2,665.08
Surveyor Approved Amount		2,665.08
No of Repair Days*	5	3
Remarks	-	p/p repair, photo before paint
Surveyor Name		Hwee jie

Estimator Assesment(\$)

Surveyor Assesment(\$)

Signature

Survey Date

29/05/2019

Save

Clear



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:



## Section A - Accident Details

Registration Number	SHB5093T
Case Reference Number	TAX/05/19/2129
Registration Date	10/10/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	CHIN GEE LONG
Type of Accident	Side Swipe
Accident Date and Time	28/5/2019 11:10 AM
Accident Reported Date and Time	28/5/2019 12:41 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle Is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	24101708
Special Instruction to ARC, if any	TP
Prepared Date and Time	29/5/2019 10:29 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Signature

## Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$300.00
Total Spray Cost	\$1,136.00	\$500.00
Total Spare Part Cost	\$5,490.98	\$2,639.54
Total Other Cost	\$560.00	\$100.00
TOTAL COST	\$8,031.98	\$3,539.54 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	6.0	4.0
Prepared / Adjusted By	Tuck Foo Kok	Hwee Jie (LKK) / NTUC
ARC / Surveyor Sign Off Date	29/05/2019 11:21 AM	29/05/2019 3:35 PM
Signature		
Remarks	Supplementary = 1 day	p/p repair, photo before paint

## Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1909-0292	Invoice Number	
Quotation Date	18.09.2019	Invoice Date	
Invoice Amount		Prepared Date	

## Section D - Details of Repair Estimates

## Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	\$845.00	\$300.00
<b>Total Labour</b>	<b>\$845.00</b>	<b>\$300.00</b>

## Part 2 - Spray Painting &amp; Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY ROCKER PANEL MOULDING	\$200.00	\$100.00
TO RESPRAY FRONT DOOR RH	\$378.00	\$200.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$0.00
TO RESPRAY RH REAR DOOR	\$378.00	\$200.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$1,136.00</b>	<b>\$500.00</b>

## Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$30.00
TO TRANSFER DOOR MECHANISM	\$120.00	\$50.00
TO REMOVE AND REFIT WIRE HARDESS	\$200.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
<b>Total Other Costs</b>	<b>\$560.00</b>	<b>\$100.00</b>

## Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		6700147152	PANEL SUB-ASSY, FRONT DOOR RH	1.00	\$1,249.60	25.00	\$937.20	Replace	Replace
			STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace
		6921047041A1	DOOR OUTER HANDLE FRONT, RH	1.00	\$378.90	25.00	\$284.18	Replace	Replace
		6920147070	DOOR FRAME INNER HANDLE FRONT, RH	0.00	\$187.70	0.00	\$0.00	Replace	Not Given
		6941020110	DOOR LOCK STRIKER	0.00	\$38.00	0.00	\$0.00	Replace	Not Given
		6871012151	HINGE ASSY, FRONT DOOR, UPPER RH	0.00	\$82.10	0.00	\$0.00	Replace	Not Given
		6873012120	HINGE ASSY, FRONT DOOR, LOWER RH	0.00	\$92.10	0.00	\$0.00	Replace	Not Given
		6980121020	DOOR FRONT WINDOW REGULATOR SUB-ASSY,	0.00	\$230.80	0.00	\$0.00	Replace	Not Given
		8571047140	DOOR FRONT MOTOR ASSY, POWER WINDOW	0.00	\$768.60	0.00	\$0.00	Replace	Not Given
		6903047100	LOCK ASSY, FRONT DOOR RH	1.00	\$581.90	10.00	\$523.71	Replace	Replace
		7571047040	MOULDING ASSY, FRONT DOOR BELT, RH	0.00	\$88.60	0.00	\$0.00	Replace	Not Given
		6861047040	CHECK ASSY, FRONT DOOR	0.00	\$153.50	0.00	\$0.00	Replace	Not Given
		6700347210	PANEL SUB-ASSY, REAR DOOR, RH	1.00	\$1,243.90	100.00	\$0.00	Replace	Repair

			PIXEL STICKER	1.00	\$60.00	0.00	\$60.00	Replace	Replace	✓
		67895470 10	WEATHERSTRIP, REAR DOOR, NO.2, RH	0.00	\$33.20	0.00	\$0.00	Replace	Not Given	X
		75850479	MOULDING ASSY, BODY ROCKER PANEL, RH	0.00	\$576.00	0.00	\$0.00	Replace	Not Given	X
Total					\$5,824.90		\$1,865.09			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	
		69801210 20	DOOR FRONT WINDOW REGULATOR SUB-ASSY,	1.00	\$230.80	25.00	\$173.10	Replace	Replace	✓
		85710471 40	DOOR FRONT MOTOR ASSY, POWER WINDOW	1.00	\$768.80	25.00	\$576.45	Replace	Replace	✓
		67895470 10	WEATHERSTRIP, REAR DOOR, NO.2, RH	1.00	\$33.20	25.00	\$24.90	Replace	Replace	✓
Total					1,032.60		774.45			

A BT  
A DM  
A CUT

2639.54  
+ 300.00  
+ 600.00  
-----  
3539.54



# REQUEST FOR SUPPLYMENT PARTS

Contractor:			
Accident Case Number	TAX 05 19 2129	Date of Collection	1 / 1
Vehicle No	SHB 5093 T	Date of Request	30-05-2019
Vehicle Model	TOYOTA PRIUS	Number of Days to Extend (If any)	1 2

S/N	Part Number	Part Description	Quantity	Unit Price
		FRONT DOOR REGULATOR RH	1pc	BT 173.10
		FRONT DOOR REGULATOR MOTOR RH	1pc	DM 576.45
		WEATHERSTRIP REAR DOOR LHD, L RH	1pc	CUT 24.90
	Labour	TO SPRAY Rear door panel GARNISH RH		\$200 \$100

<<<Please submit photographs for damaged parts>>>

I, (Name) \_\_\_\_\_

(Position) \_\_\_\_\_

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

.....  
Signature of person making this declaration  
[to be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19009651/Esd3e2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE  
189556

Date: 10-10-2019



Code: INC4

**1. Policy Particulars :- THIRD PARTY CLAIM**

Insured Veh.	SJR 7786G	Veh. Inspected	SHB 5093T
Policy No.	5044577992-08	Coverage (\$)	0.00
Claim No.	MT/1046697-002	Excess (\$)	0.00
Assign From		Assign Date	29/05/2019

**2. Vehicle Particulars & Condition**

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU703572809	Colour	MAROON
Odometer	339348	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

**3. Conditions of Tyres**

	Size	Make	Balance
R/H Front Tyre	195/65 R15	WEST LAKE	6 mm
L/H Front Tyre	195/65 R15	WEST LAKE	6 mm
R/H Rear Tyre	195/65 R15	WEST LAKE	6 mm
L/H Rear Tyre	195/65 R15	WEST LAKE	6 mm

**4. Description of Damages**

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.  
DAMAGES SEE DETAILS.

**5. General Information**

Accident Date	28/05/2019	Inspection Date	29/05/2019
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

**5a. Remarks**

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

**5b. Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 5093T**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	PANEL SUB-ASSY, FRONT DOOR RH (DISC 25%)	DENTED	1,249.60	937.20
1	DOOR OUTER HANDLE FRONT, RH (DISC 25%)	BROKEN	378.90	284.18
1	DOOR FRONT WINDOW REGULATOR SUB-ASSY, (DISC 25%)	BENT	230.80	173.10
1	DOOR FRONT MOTOR ASSY, POWER WINDOW (DISC 25%)	DAMAGED	768.60	576.45
1	WEATHERSTRIP, REAR DOOR, NO.2, RH (DISC 25%)	CUT	33.20	24.90
1	LOCK ASSY, FRONT DOOR RH (DISC 10%)	BENT	581.90	523.71
1	STICKER DECAL SMRT (DOOR) (SN)	NECESSARY	60.00	60.00
1	PIXEL STICKER (SN)	NECESSARY	60.00	60.00
1	DOOR FRAME INNER HANDLE FRONT, RH	NOT NECESSARY	187.70	-
1	DOOR LOCK STRIKER	NOT NECESSARY	38.00	-
1	HINGE ASSY, FRONT DOOR, UPPER RH	NOT NECESSARY	82.10	-
1	HINGE ASSY, FRONT DOOR, LOWER RH	NOT NECESSARY	92.10	-
1	DOOR FRONT WINDOW REGULATOR SUB-ASSY, RH	NOT NECESSARY	230.80	-
1	DOOR FRONT MOTOR ASSY, POWER WINDOR REGULATOR, RH	NOT NECESSARY	768.60	-
1	MOULDING ASSY, FRONT DOOR BELT, RH	NOT NECESSARY	88.60	-
1	CHECK ASSY, FRONT DOOR	NOT NECESSARY	153.50	-
1	WEATHERSTRIP, REAR DOOR, NO.2, RH	NOT NECESSARY	33.20	-
1	MOULDING ASSY, BODY ROCKER PANEL, RH	NOT NECESSARY	576.00	-
1	PANEL SUB-ASSY, REAR DOOR, RH	TO REPAIR SEE LABOUR	1,243.90	-
			6,857.50	2,639.54
<b><u>LABOUR</u></b>				
	PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF PANEL SUB-ASSY, REAR DOOR, RH.		845.00	300.00
	SPRAY PAINT.		1,136.00	500.00
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	20.00
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		100.00	30.00
	TO TRANSFER DOOR MECHANISM.		120.00	50.00
	TO REMOVE AND REFIT WIRE HARDESS.	NOT NECESSARY	200.00	-

Report Ref No. NS/INC19009651/Esd3e2



## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			2,541.00	900.00
GRAND TOTAL			9,398.50	3,539.54

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			3,539.54
---	--	--	----------

Report Ref No. NS/INC19009651/Esd3e2

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.