

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5361P**AAD1905-252**

Not Authorised
11 Sep \$5200

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHC 5361P

VF1ABL15AUC279600

RENAULT

LATITUDE

27.5.19

EQ

14/10/2014

	PART
1	DOOR PANEL REAR LH
1	ROCKER PANEL INNER GARNISH LH
1	ROCKER PANEL INNER LH
1	ROCKER PANEL OUTER LH
1	ROCKER PANEL CENTER LH
1	BOOT REFLECTOR LAMP LH
1	FENDER PANEL REAR LH
1	FENDER PANEL INNER TRIM REAR LH
1	WHEELARCH REAR LH
1	BUMPER COVER REAR
1	BUMPER LOWER REAR
1	BUMPER BRACKET CTR REAR
1	BUMPER BRACKET SIDE LH REAR
1	BUMPER RETAINER LH REAR
1	BUMPER REFLECTOR LH
1	BUMPER BEAM REAR
1	BUMPER BEAM BRACKET LH REAR
1	TAILLAMP LH
1	TAILLAMP PANEL LH
1	FUEL FLAP

	LIST
\$	<i>N</i> 2,844.66 <i>X</i>
\$	<i>SL</i> 466.51 <i>X</i>
\$	<i>N</i> 1,024.79 <i>X</i>
\$	<i>N</i> 1,184.99 <i>X</i>
\$	<i>N</i> 990.25 <i>X</i>
\$	<i>SL</i> 493.35 <i>X</i>
\$	<i>SL</i> 3,299.13 <i>✓</i>
\$	<i>SL</i> 671.45 <i>X</i>
\$	<i>SL</i> 543.47 <i>X</i>
\$	<i>Bu</i> <i>SL</i> 1,108.46 <i>✓</i>
\$	<i>SL</i> 768.84 <i>X</i>
\$	<i>SL</i> 113.47 <i>X</i>
\$	<i>P.I</i> 135.97 <i>✓</i>
\$	<i>SL</i> 44.99 <i>X</i>
\$	<i>SL</i> 43.61 <i>X</i>
\$	<i>N</i> 777.52 <i>X</i>
\$	<i>N</i> 225.95 <i>X</i>
\$	<i>SL</i> 552.55 <i>X</i>
\$	<i>N</i> 986.70 <i>X</i>
\$	<i>SL</i> 343.57 <i>X</i>
TOTAL \$	16,620.23
10% \$	1,662.02
\$	14,958.21

Special Nett

1	REAR DOOR ADVERTISEMENT STICKER	\$	<i>N</i> 300.00 <i>150SLN</i>
1	REAR BUMPER ADVERTISEMENT STICKER	\$	<i>N</i> 300.00 <i>100SLN</i>
1	REAR LH FENDER ADVERTISEMENT STICKER	\$	<i>N</i> 300.00 <i>150SLN</i>
1	FENDER INNER TRIM CLIP LH	\$	<i>nn</i> 28.00 <i>X</i>

Trans-cab Auto Services Pte Ltd

AAD1905-252

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5361P

1	TAILLAMP CLIP LH	\$	nn	5.00	X
1SET	FENDER WHEELARCH REAR LH CLIP	\$	nn	35.00	X
2	REAR WINDSCREEN SEALANT	\$	nn	80.00	405n
1	WINDSCREEN MOULDING	\$	nn	100.00	—
1	REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	305n
1	REAR LEFT TYRE	\$	sn	300.00	X
1	REAR LEFT TYRE RIM	\$	sn	380.00	X
1SET	PARKING AID	\$	sn	700.00	X
1SET	REAR BUMPER CLIP	\$	nn	66.00	—
1SET	BUMPER BRACKET CTR CLIP	\$	nn	33.00	—
1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	nn	10.00	X
1SET	BUMPER RETAINER CLIP LH RR	\$	nn	20.00	X
1SET	BUMPER LOWER REAR RIVET	\$	nn	22.00	X
1SET	BUMPER LOWER REAR CLIP	\$	nn	66.00	X
TOTAL		\$		2,845.00	
TOTAL PARTS		\$		17,803.21	

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	700	4,500.00
Putty and spray painting of the affected portion.	\$	660	4,500.00
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	100	380.00
To check steering geometry and computer wheel alignment	\$	nn	220.00 X
To rust-proofing of the affected areas.	\$	30	170.00
To transfer of rear windscreen fittings and conduct water seepage test.	\$	120	170.00
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	nn	380.00 X

Trans-cab Auto Services Pte Ltd**AAD1905-252**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5361P

To transfer of tire, rim and on wheel balancing.	\$	nn 170.00 X
To transfer of Rear bumper fittings, attachment and perform water seepage test.	\$	nn 380.00 X
To Check Electrical Lighting Concerned.	\$	170.00 201
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	nn 380.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00 X
To reinstall rear bumper parking sensor.	\$	170.00 601
To apply paint protection system (PPS) maintain and enhancement	\$	nn 380.00 X
To remove and replace corporate sticker	\$	330.00 601
TOTAL	\$	12,680.00
Over All Total	\$	30,483.21

LUMP SUM (REPAIR DAY)**15 DAYS**

6 day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: