

22/03/2019

ASS. REC. BY:

REF: CS/CTI19009661/Kvd3⁰² Special Instruction:Surveyor: Ramdhani

ASSIGNMENT (Office)

From (Person): Chong Boon Senof CTIDate/Time: 31/5/19 @ 10.47am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJF 8298E

Insured:

SLQ 5172Y

at Workshop m/s

Cheng Hwe MotorTel: 64812001

of

No. 10 Amk Ind park 2A #01-04

Policy No:

Claim No:

SNM19D202441

Sum Insured:

Excess:

Make of Veh:

D.O.A.

29/05/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:19am @ 31/5/19

Person Contacted:

DuglyhVehicle IN/OUT

Date/Time

Action/Instruction

Estimate

✓

SJF 8298E-XSLQ 5172Y-CS/CTI18021967/Gsb n 2JUA: 2/12/2018

ASS. REC. BY:

REF:

C121

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

1 / File pass to

217 / 11/2019 @ 22501 Cabernet Estate (Red 946, 3013)

RECEIVED 03 JUL 2019

Veh No:

SJK-8298E

Yr Regn:

06, 08

Type:

M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mazda

c.c.

1999

Colour

M. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

146956

T/Radio:

Insured / Std / NI / NA

Eng/No.

C/No:

TM6G1410F-180105645

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/45ZR17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

29/5/19

D.O.A.

31/5/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?



: Prel. Report



: Final Report

1)

Date/Time, File Return to?

2) 31 - typist

Days Of Repair:

4

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

) S + RS. \$

) F + RS.

) Others

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Report Format:

merimen

Lump Sum / I.B.I: (\$

2250/2

220

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Friday, 31 May 2019 10:47 AM
To: chmamk@singnet.com.sg
Cc: assignments
Subject: RE: OUR REF: SNM19D202441-Repair Survey /ENQUIRY OF LIABILITY - SJQ8298E(DOA: 29/05/2019) YR OI: SLQ5172Y

WITHOUT PREJUDICE

Dear Sir,

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平狮城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Lim Shu Min

Sent: Friday, 31 May, 2019 9:45 AM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; chmamk@singnet.com.sg; Chee So Chow <sochow.chee@sg.cntaiping.com>

Subject: OUR REF: SNM19D202441-Repair Survey /ENQUIRY OF LIABILITY - SJQ8298E(DOA: 29/05/2019) YR OI: SLQ5172Y

Dear Boon Sen,

Please conduct PRS – SJQ8298E soonest possible.

File with Officer-In-Charge – Chong Boon Sen - 63896171

Thank you

Lim Shu Min

Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 63896156 | F: (65) 62247175

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI
Sent: Friday, 31 May, 2019 8:51 AM
To: Lim Shu Min <shumin.lim@sg.cntaiping.com>
Subject: FW: Repair Survey /ENQUIRY OF LIABILITY - SJQ8298E(DOA: 29/05/2019) YR OI: SLQ5172Y

From: Cheng Hoe Motor Pte Ltd (AMK) [<mailto:chmamk@singnet.com.sg>]
Sent: Thursday, 30 May 2019 5:31 PM
To: gicclaimsdept@sg.cntaiping.com; Claims Dept of CTI <claimsdept@sg.cntaiping.com>; chmotor@singnet.com.sg
Subject: Repair Survey /ENQUIRY OF LIABILITY - SJQ8298E(DOA: 29/05/2019) YR OI: SLQ5172Y

Dear Sir,

OUR CLIENT : SJQ8298E

DOA : 29/05/19@ 2220hr

YR INSURED : SLQ5172Y (CHEW CHOON KWANG)

(A) Kindly arrange your auto surveyor on the survey at our Ang Mo Kio workshop.

(B) Also, please advise on liability and are you agree on DIRECT SETTLEMENT?

p/s: owner left his vehicle at our Ang Mo Kio workshop on 30/5/19 @1430hr.

Thank you.

Regards

Dorlyn

Cheng Hoe Motor Pte Ltd
Tel :64812001

Fax : 64821296

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 9983Z

Vehicle Details

Vehicle No.: SJF8298E

Vehicle to be Exported: No

Intended Deregistration Date: 30 May 2019

Vehicle Make: MAZDA

Vehicle Model: MAZDA6 2.0L SDN R

Primary Colour: Silver

Manufacturing Year: 2008

Engine No.: LF20220218

Chassis No.: JM6GH10F180105645

Maximum Power Output: 108.0 kW (144 bhp)

Open Market Value: \$22,953.00

Original Registration Date: 12 Jun 2008

First Registration Date: 12 Jun 2008

Transfer Count: 1

Actual ARF Paid: \$22,953.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 11 Jun 2023

COE Category: B - Car (1601cc & above)

COE Period(Years): 5

PQP Paid: \$18,953.00


COE Rebate Amount: \$15,288.00

Total Rebate Amount: \$15,288.00**Message**

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 30 May 2019

OK

**CHENG HOE MOTOR PTE LTD**

Bik 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761
 Tel : 67556142 Fax : 67557719
 Email: chmotor@singnet.com.sg

TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)
CHEW CHOON KWANG

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	TP/CHINA (SLQ5172Y)
Policy No:		Date of Loss:	29/05/2019
Vehicle Reg. No.:	SJF8298E	Driveable?	
Party At Fault:	UNKNOWN	Driver (Insured):	CHEW CHOON KWANG
Driver (TP):	TER LIONG CHUAN		
Make/Model:	MAZDA 6, 2.0 SDN V (A)	Vehicle Reg. Date:	12/06/2008
Vehicle Colour:	SILVER	Chassis No:	JM6GH10F180105645
Engine No:	LF20220218		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	0		
Description of Accident/Loss	REFER TO GIA REPORT ATTACHED.		
Remarks:	VEHICLE CURRENTLY LYING ANG MO KIO WORKSHOP.		
Present Location:	CHENG HOE MOTOR PTE LTD (YISHUN)		

Not Authorise
11 Ppy 8?
Missing After Paint
4 days

COST OF CLAIMS		Amount
Parts	LKK Auto Consultants hence notify the Repairer of the following:	1,391.00
Miscellaneous Items	• To resurvey before/after spray painting	495.00
Labour	• To display damaged part(s) during resurvey	1,310.00
Paintwork Labour	• Parts prices are subject to confirmation	0.00
Towing	• Third party survey is on a "Without Prejudice" basis	0.00
	• No illegal modification(s) is allowed	
	• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	
	Gross Total (\$\$)	3,196.00
	+ GST 7.00% (\$\$)	223.72
	Nett Amount (\$\$)	3,419.72

This claim is handled by: **SHARON CHIONG BENG CHOON**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 31 May 2019)

Parts: 143 MAZDA 6 2.0 SDN V (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Cheng Hoe Motor Pte Ltd/SJF8298E/31/05/2019 11:05

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 PC REAR BUMPER	0.00	0.00	*500.00F
2	1		*1 PC REAR BUMPER REINFORCEMENT	0.00	0.00	*170.00F
3	1		*1 PC REAR BUMPER NUMBER PLATE LAMP	0.00	0.00	*180.00F
4	1		*5 PCS REAR BUMPER CLIPS @2/PC	0.00	0.00	*10.00F
5	1		*1 PC BOOTLID LOGO	0.00	0.00	*26.00F
6	1		*1 PC BOOTLID LOGO EMBLEM (MAZDA)	0.00	0.00	*18.00F
7	1		*1 PC BOOTLID LOGO EMBLEM (6)	0.00	0.00	*14.00F
8	1		*1 PC BOOTLID INNER RUBBER	0.00	0.00	*110.00F
9	1		*1 PC REAR END PANEL	0.00	0.00	*220.00F
10	1		*1 PC REAR END PANEL INNER TOP GARNISH	0.00	0.00	*135.00F
11	1		*4 PCS REAR END PANEL INNER TOP GARNISH CLIPS @2/PC	0.00	0.00	*8.00F

F=Franchise part.

Total Parts (S\$) **1,391.00**Cheng Hoe Motor Pte Ltd/SJF8298E/31/05/2019 11:05. Not valid without Reference section.
Generated using Merimen e-Claims IEAS**Estimates on Miscellaneous Items**

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	1 PC REVERSE CAMERA	250.00
2	1	1 SET REVERSE SENSOR	200.00
3	1	1 UNIT REAR NUMBER PLATE	45.00

Sub Total (S\$) **495.00****Estimates on Labour**

No	Particulars	Lab.Type	Amount
Labour Items			
1	REMOVE & REFIX REAR BUMPER & ATTACHEMENTS, TAILLAMPS, CUT, WELD & RENEW REAR END PANEL & REALIGN THE SAME	New	600.00
2	PUTTY & RESPRAY REAR BUMPER & REINFORCEMENT, REVERSE SENSORS, BOOTLID, REAR END PANEL & ALL AFFECTED AREAS	New	600.00
3	REMOVE & REFIX REVERSE CAMERA, RESET & REALIGN THE SAME	New	50.00
4	RUSTPROOFING	New	60.00

Gross Labour Cost (S\$) **1,310.00**Cheng Hoe Motor Pte Ltd/SJF8298E/31/05/2019 11:05. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119009661/KVD3N2
Date: 04/07/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30653018011	
Claimant Vehicle No :	SJF8298E	Insured Vehicle No :	SLQ5172Y	
Date of Loss:	29/05/2019	Nature of Claim:	TP	Claim No: SNM19D202441-CHONGBS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJF8298E	Engine No:	LF20220218
Make & Model:	MAZDA 6, 2.0 SDN V (A)	Chassis No:	JM6GH10F180105645
Reg. Date:	12/06/2008 (Man. Year: 2008)	Odometer:	146956 km
Colour:	Metallic Silver		
Engine Capacity:	1999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45ZR17	Rear Tyre Size:	225/45ZR17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	1,391.00	1,391.00	0.00	0.00
Miscellaneous Items	495.00	245.00	250.00	50.51
Labour	1,310.00	1,220.00	90.00	6.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	3,196.00	2,856.00	340.00	10.64
Approved Total (Overridden) (\$\$)		2,250.00		
(\$\$)	3,196.00	2,250.00	946.00	29.60
+ GST 7.00/7.00% (\$\$)	223.72	157.50	66.22	29.60
Nett Amount (\$\$)	3,419.72	2,407.50	1,012.22	29.60

INSPECTION

Date of Assignment:	03/07/2019	Present Location:	Cheng Hoe Motor Pte Ltd (Yishun)
Date Inspected:	31/05/2019	Inspected At:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 04 Jul 2019)
Parts: 143	MAZDA 6 2.0 SDN V (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJF8298E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 PC REAR BUMPER	Buckled	500.00 F	*500.00 F
2	1		*1 PC REAR BUMPER REINFORCEMENT	Bent	170.00 F	*170.00 F
3	1		*1 PC REAR BUMPER NUMBER PLATE LAMP	Cracked	180.00 F	*180.00 F
4	1		*5 PCS REAR BUMPER CLIPS @2/PC	Necessary	10.00 F	*10.00 F
5	1		*1 PC BOOTLID LOGO	Necessary	26.00 F	*26.00 F
6	1		*1 PC BOOTLID LOGO EMBLEM (MAZDA)	Necessary	18.00 F	*18.00 F
7	1		*1 PC BOOTLID LOGO EMBLEM (6)	Necessary	14.00 F	*14.00 F
8	1		*1 PC BOOTLID INNER RUBBER	Dented/Distorted	110.00 F	*110.00 F
9	1		*1 PC REAR END PANEL	Bent	220.00 F	*220.00 F
10	1		*1 PC REAR END PANEL INNER TOP GARNISH	Mtg Cracked	135.00 F	*135.00 F
11	1		*4 PCS REAR END PANEL INNER TOP GARNISH CLIPS @2/PC	Necessary	8.00 F	*8.00 F

F=Franchise part.

Total Parts (S\$) **1,391.00** **1,391.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	1 PC REVERSE CAMERA (Serviceable)	250.00	0.00
2	1	1 SET REVERSE SENSOR (Shorted)	200.00	200.00
3	1	1 UNIT REAR NUMBER PLATE (Dented)	45.00	45.00
Sub Total (S\$)			495.00	245.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX REAR BUMPER & ATTACHEMENTS, TAILLAMPS, CUT, WELD & RENEW REAR END PANEL & REALIGN THE SAME	New	600.00	540.00
2	PUTTY & RESPRAY REAR BUMPER & REINFORCEMENT, REVERSE SENSORS, BOOTLID, REAR END PANEL & ALL AFFECTED AREAS	New	600.00	600.00
3	REMOVE & REFIX REVERSE CAMERA, RESET & REALIGN THE SAME	New	50.00	50.00
4	RUSTPROOFING	New	60.00	30.00
Gross Labour Cost (S\$)			1,310.00	1,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >