













































PAR Automotive Consultancy

Thomson Rd Post Office PO Box 029 Singapore 915701 Tel : 645 31173, Fax : 645 36131

Regn No: S208074L

Report No: 0776-18-TCA

26 November 2018

ACCIDENT VEHICLE SURVEY REPORT

Lim Kar Tian
Blk 816 Tampines Ave 4 #08-253
Singapore 520816

VEHICLE INFORMATION:


Vehicle Reg No.	SBB10L	Odometer:	37218km
Make & Model:	Toyota Vellfire 2.5A	Colour:	White
Chassis number	AGH3000020142	Date of accident:	16/05/2018
Year of Regn.:	17/09/2015	Date inspected:	18/05/2018
Repairer at:	Twincar Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-17 Kaki Bukit Auto Hub Singapore 417921	Date inspected (After Repair):	28/05/2018

RE-INSPECTION




We had carried out re-inspection during works in progress and post repair inspection on the above vehicle. Attached in Annex B are the re-inspection photos, showing the work in progress and our re-inspection to the hidden part that were damaged.



REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.






















































































SBB 10L











