

INS. CASE OWNER:

CC3 / CTI 1900 9691 / Jha3

LKK:
IDAC:

Surveyor:

DAG

DOI:

ASSIGNMENT

31/5/19

Date / Time:

30/5/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SUP5542T

Claim No.:

SNM190202429/002/TKL

Name of Insured:

Lim Choo Leong

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A.:

31/5/19

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability: %

Final ? Yes / No

SHF362D



INSRS:

WSP:

Tel:

Liability:

RMKS:

Sme7.m.



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

SUP5542T. X

SHF362D -

- TO CHECK WITH OI IF ANY UPDATE FROM TRAFFIC POLICE.

19/6/19

called OI to inform TP claim. OI disputed, and will provide us with video evidence via email letter. Hand copy sent.

- PIR IN. ACTION OF OI

- FINANCED

23/06/19

- TP REPORT WHILE FORWARDING TP LOD

- REPORT DONE

- TP LOD IN BY EMAIL

21/11/19

- OI REQUEST WARRANT TO OI

- OI APPROVED WARRANT

11/02/2020

- SEND SET OFFER TO TP

PRELIMINARY ADVICE

Date/Time: 04/06/19

Sent By: 03

- TP ACCEPTED OFFER

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: P/P

S\$ 16,317.64

(9 days)

Reduction:

67 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time: 11/02/2020

Confirm with:

LEE GOK

Email ☐ Call ☐

Final Liability:

%

100

(Assessed / Assessed) BOLA S/N No.:

NIL

If NO or B 28, Ass. Lia:

Repair Cost:

S\$ 16,317.64

PIR ACTION OF OI

Loss of Rental (LOR):

S\$ 1,662.78

(14 days)

x \$118.77

Loss of Use (LOU):

S\$ -

(\$ x days)

Loss of Income (LOI):

S\$ -

(\$ x days)

LOR only ☒ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$ 7.00

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost

S\$ -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$400.00

Total:

S\$ 17,987.42

Global Sum S\$:

17,980.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

S\$ 17,980.00

Name 1:

CHRT TAXIS PTE LTD

Payee 2: (Strike if N.A.)

S\$ -

Name 2:

Payee 3: (Strike if N.A.)

S\$ -

Name 3:

(08/11/13)

REF

CTI

ASS. REC. BY:

Hue Ju

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 9 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHF 362D Yr Regn: 14 Dec 2017Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius c.c. 1798Colour: Maroon A/C: Insured / Std / NI / NA

Sp. Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKB3FU603576608Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65 R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 27/5/19D.O.I. 30/5/19

Survey held at

SumitDes. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

T/P \$16,317.64

CRP: \$33,315.05 (67%)

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

Add Fee:

☐

Site Insp (\$ _____)

☐

Interview (\$ _____)

☐

Tech. Invs (\$ _____)

☐



Weekend (\$ _____)

S + RS, SI

VIC

Section A - Accident Details

Registration Number	SHF382D
Case Reference Number	TAX/05/19/2126
Registration Date	14/12/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	POH SWEE KHENG
Type of Accident	Head On
Accident Date and Time	27/5/2019 8:00 PM
Accident Reported Date and Time	28/5/2019 9:29 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	27/5/2019 8:01 PM
Replacement Vehicle issued?	No
Job Card Number	24101701
Special Instruction to ARC, if any	TOWED TO TP COMPOUND \$90
Prepared Date and Time	30/5/2019 8:59 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



p/p repair

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,071.00	\$1,400.00
Total Spray Cost	\$3,168.00	\$800.00
Total Spare Part Cost	\$42,467.69	\$13,787.64
Total Other Cost	\$1,926.00	\$330.00
TOTAL COST	\$49,632.69	\$16,317.64 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	12.0	9.0
Prepared / Adjusted By	Tuck Foo Kok	Hwee Jie (LKK) / China Taiping
ARC / Surveyor Sign Off Date	30/05/2019 3:41 PM	30/05/2019 2:10 PM
Signature		
Remarks	SUP = 3 DAYS	p/p repair, photo before paint.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1906-0466	Invoice Number	
Quotation Date	27.06.2018	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT FENDER LH	\$200.00	\$200.00 ✓
TO REPAIR BOTH FRONT CHASSIS FRAME	\$350.00	\$200.00 ✓
TO REPAIR FRONT PORTION	\$1,521.00	\$1,000.00 ✓
Total Labour	\$2,071.00	\$1,400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00 ✓
TO REPSRAY FRONT HOOD	\$378.00	\$200.00 ✓
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$0.00
TO RESPRAY RADIATOR SUPPORT LOWER	\$180.00	\$0.00
TO RESPRAY FRT MEMBER, RH	\$180.00	\$0.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00 ✓
TO RESPRAY FRONT FENDER LH	\$378.00	\$0.00
TO RESPRAY APRON PANEL RH	\$180.00	\$0.00
TO RESPRAY FRONT DOOR RH	\$378.00	\$0.00
TO RESPRAY FRONT PILLAR RH	\$180.00	\$0.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00 ✓
Total Spray Painting & Panel Beating	\$3,168.00	\$800.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$128.00	\$90.00 ✓
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00 ✓
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	\$20.00 ✓
TO TOP UP A/C GAS	\$120.00	\$50.00 ✓
TO ALIGN CHASSIS	\$350.00	\$0.00
TO CHECK & RESET SYSTEM FUNCTION	\$350.00	\$0.00
TO REMOVE AND REFIT WIRE HARDESS	\$300.00	\$0.00
TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER	\$120.00	\$50.00 ✓
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$80.00	\$0.00
TO REMOVE / REFIT WINDSCREEN	\$120.00	\$100.00 ✓
Total Other Costs	\$1,926.00	\$330.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119479 82	COVER, FR BUMPER	1.00	\$495.50	25.00	\$371.63 ✓	Replace	Replace ✓
		52127479 07	COVER, FR BUMPER RH	1.00	\$28.10	25.00	\$21.08 ✓	Replace	Replace ✓

52161160	CLIPS PIECE, FRT & RR BUMPER	10.00	\$1.50	25.00	\$11.25	Replace	Replace	✓
53101470	GRILLE SUB-ASSY	1.00	\$335.60	25.00	\$251.70	Replace	Replace	✓
75310470	EMBLEM ASSY FRONT	1.00	\$87.10	25.00	\$65.33	Replace	Replace	✓
53112472	GRILLE, RADIATOR	1.00	\$165.00	25.00	\$123.75	Replace	Replace	✓
52114471	BRACKET, FR BUMPER	1.00	\$99.80	25.00	\$74.85	Replace	Replace	✓
90	NUMBER PLATE	1.00	\$35.00	0.00	\$35.00	Replace	Replace	✓
	NUMBER PLATE FRAME	1.00	\$25.00	0.00	\$25.00	Replace	Replace	✓
53395470	SEAL, HOOD TO FR END	1.00	\$24.40	25.00	\$18.30	Replace	Replace	✓
52116470	SUPPORT, FR BUMPER LH	1.00	\$82.30	25.00	\$61.73	Replace	Replace	✓
52115470	SUPPORT, FR BUMPER RH	1.00	\$76.90	25.00	\$57.68	Replace	Replace	✓
53801470	FENDER SUB-ASSY, FR, RH	1.00	\$933.10	100.00	\$0.00	Replace	Repair	✓
75374471	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$52.90	25.00	\$39.68	Replace	Replace	✓
53807470	SEAL SUB-ASSY, RH	1.00	\$50.20	25.00	\$37.65	Replace	Replace	✓
53875470	LINER, FR FENDER, RH	0.00	\$198.40	0.00	\$0.00	Replace	Not Given	X
53701471	APRON SUB-ASSY, FRONT FENDER, RH	0.00	\$944.20	0.00	\$0.00	Replace	Not Given	X
57101470	MEMBER SUB-ASSY, FR RH	0.00	\$2,012.70	0.00	\$0.00	Replace	Check	X
53851470	PAD, FR WHEEL RH	0.00	\$57.70	0.00	\$0.00	Replace	Not Given	X
51107470	FRONT REINFORCEMENT SIDE	1.00	\$128.20	25.00	\$96.15	Replace	Replace	✓
85319471	WIPER WASHER INLET	0.00	\$55.40	0.00	\$0.00	Replace	Check	X
85315471	WIPER WASHER JAR	0.00	\$183.60	0.00	\$0.00	Replace	Check	X
67001471	PANEL SUB-ASSY, FRONT DOOR RH	0.00	\$1,249.60	0.00	\$0.00	Replace	Not Given	X
52	STICKER DECAL SMRT (DOOR)	0.00	\$60.00	0.00	\$0.00	Replace	Not Given	X
89173464	SENSOR, AIR BAG, FRONT, RH & LH	0.00	\$310.50	0.00	\$0.00	Replace	Check	X
53802471	FENDER SUB-ASSY, FR, LH	0.00	\$933.10	0.00	\$0.00	Replace	Not Given	X
75374471	EMBLEM, SIDE PANEL (HYBRID)	0.00	\$52.90	0.00	\$0.00	Replace	Not Given	X
53341470	INSULATOR, HOOD	1.00	\$393.90	25.00	\$295.43	Replace	Replace	✓
90467090	INSULATOR, HOOD CLIP	6.00	\$2.30	25.00	\$10.35	Replace	Replace	✓
53420471	HINGE ASSY, HOOD, LH	1.00	\$57.00	25.00	\$42.75	Replace	Replace	✓
53410471	HINGE ASSY, HOOD, RH	1.00	\$57.00	25.00	\$42.75	Replace	Replace	✓
53510471	LOCK ASSY, HOOD	0.00	\$131.10	0.00	\$0.00	Replace	Check	X
53630470	CABLE ASSY, HOOD	0.00	\$53.20	0.00	\$0.00	Replace	Not Given	X
75535470	MOULDING RH	0.00	\$83.30	0.00	\$0.00	Replace	Not Given	X
55708472	WIPER GARNISH LOUVER SUB-ASSY	0.00	\$666.90	0.00	\$0.00	Replace	Not Given	X
55754470	WIPER GARNISH SHIELD, COWL WATER, LH	0.00	\$18.90	0.00	\$0.00	Replace	Not Given	X
55753470	WIPER GARNISH SHIELD, COWL WATER, RH	0.00	\$18.90	0.00	\$0.00	Replace	Not Given	X
81013470	PILLAR, FRONT BODY, RH	0.00	\$339.40	0.00	\$0.00	Replace	Not Given	X
60117470	COVER SUB-ASSY, FRONT PILLAR, UPR RH	0.00	\$96.90	0.00	\$0.00	Replace	Check	X
88790281	THERMISTOR ASSY	0.00	\$68.00	0.00	\$0.00	Replace	Check	X
53289470	COVER, RADIATOR	0.00	\$227.80	0.00	\$0.00	Replace	Check	X
53205479	SUPPORT S/A UPPER	0.00	\$364.90	0.00	\$0.00	Replace	Check	X
53028470	SUPPORT SUB-ASSY LOWER	0.00	\$397.40	0.00	\$0.00	Replace	Check	X
53203479	SUPPORT S/A LH	0.00	\$237.00	0.00	\$0.00	Replace	Check	X
53202479	SUPPORT S/A RH	0.00	\$237.00	0.00	\$0.00	Replace	Check	X
53217470	BRACE, HOOD LOCK SUPPORT	0.00	\$76.20	0.00	\$0.00	Replace	Check	X
53214470	SUPPORT, RADIATOR UPPER LH	0.00	\$76.70	0.00	\$0.00	Replace	Check	X

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
Fax Number : 63985592
Estimator Telephone Number : 65062023
Accident Reporting Number : 6862612

Date Generated : 08/07/2013

User ID : PehDuan

53213470	SUPPORT, RADIATOR	0.00	\$76.70	0.00	\$0.00	Replace	Check	X
50	UPPER RH							
81185476	UNIT, HEADLAMP, LH	0.00	\$2,558.90	0.00	\$0.00	Replace	Check	X
91								
81145476	UNIT, HEADLAMP, RH	1.00	\$2,558.90	10.00	\$2,303.01	Replace	Replace	X
91								
81016476	COMPUTER SUB-ASSY,	0.00	\$486.40	0.00	\$0.00	Replace	Check	X
90	HEADLAMP, RH NO.1							
86510470	HORN ASSY, HIGH	0.00	\$112.80	0.00	\$0.00	Replace	Check	X
50								
86520470	HORN ASSY, LOW	0.00	\$112.80	0.00	\$0.00	Replace	Check	X
30								
88460103	AIR CON CONDENSER	1.00	\$1,317.70	25.00	\$988.28	Replace	Replace	X
20	ASSY							
88710471	TUBE & ACCESSORY	0.00	\$574.40	0.00	\$0.00	Replace	Check	X
60								
88703470	HOSE SUB-ASSY,	0.00	\$337.10	0.00	\$0.00	Replace	Check	X
80	DISCHARGE							
88704471	HOSE SUB-ASSY,	0.00	\$541.90	0.00	\$0.00	Replace	Check	X
00	SUCTION							
88707470	PIPE SUB-ASSY,	0.00	\$389.60	0.00	\$0.00	Replace	Check	X
90	SUCTION							
88370470	AIR CON COMPRESSOR	0.00	\$2,887.80	0.00	\$0.00	Replace	Check	X
92	ASSY							
	COOLANT	0.00	\$12.30	0.00	\$0.00	Replace	Check	X
16592370	GUIDE, RADIATOR AIR	0.00	\$93.90	0.00	\$0.00	Replace	Check	X
20								
16594370	GUIDE, RADIATOR AIR,	0.00	\$44.70	0.00	\$0.00	Replace	Check	X
10	UPPER							
16595370	GUIDE, RADIATOR AIR,	0.00	\$58.80	0.00	\$0.00	Replace	Check	X
50	LH							
16593370	GUIDE, RADIATOR AIR,	0.00	\$54.60	0.00	\$0.00	Replace	Check	X
40	RH							
16562370	SEAL, RADIATOR TO RH	0.00	\$24.80	0.00	\$0.00	Replace	Check	X
10								
16400373	RADIATOR ASSY	0.00	\$1,841.10	0.00	\$0.00	Replace	Check	X
10								
90480400	GROMMET (FOR	0.00	\$12.70	0.00	\$0.00	Replace	Check	X
21	RADIATOR LOWER							
16523370	CUSHION, (FOR	0.00	\$9.80	0.00	\$0.00	Replace	Check	X
10	RADIATOR UPPER							
16361370	FAN RADIATOR, LH	0.00	\$181.80	0.00	\$0.00	Replace	Check	X
60								
16361370	FAN RADIATOR, RH	0.00	\$233.00	0.00	\$0.00	Replace	Check	X
70								
16711371	FAN SHROUD RADIATOR	0.00	\$219.30	0.00	\$0.00	Replace	Check	X
60								
16363370	MOTOR, COOLING FAN,	0.00	\$543.50	0.00	\$0.00	Replace	Check	X
60	LH							
16363361	MOTOR, COOLING FAN,	0.00	\$443.40	0.00	\$0.00	Replace	Check	X
60	RH							
16571372	HOSE, RADIATOR, NO.1	0.00	\$42.60	0.00	\$0.00	Replace	Check	X
10								
16572372	HOSE, RADIATOR, NO.2	0.00	\$40.20	0.00	\$0.00	Replace	Check	X
10								
164A237	TANK, RESERVE SEALED	0.00	\$127.00	0.00	\$0.00	Replace	Check	X
012	W/O CAP							
16261371	HOSE, WATER BYPASS,	0.00	\$37.40	0.00	\$0.00	Replace	Check	X
50	NO.1							
16264371	HOSE, WATER BYPASS,	0.00	\$37.40	0.00	\$0.00	Replace	Check	X
20	NO.2							
16267370	HOSE, WATER BYPASS,	0.00	\$20.10	0.00	\$0.00	Replace	Check	X
90	NO.3							
16261371	HOSE, WATER BYPASS,	0.00	\$13.20	0.00	\$0.00	Replace	Check	X
00	NO.4							
16296370	HOSE, WATER BYPASS,	0.00	\$37.80	0.00	\$0.00	Replace	Check	X
10	NO.8							
16268371	PIPE, WATER BYPASS,	0.00	\$11.00	0.00	\$0.00	Replace	Check	X
00	NO.1							
16268371	PIPE, WATER BYPASS,	0.00	\$11.00	0.00	\$0.00	Replace	Check	X
20	NO.2							
16276370	PIPE, WATER BYPASS,	0.00	\$56.40	0.00	\$0.00	Replace	Check	X
20	NO.3							
16577370	PIPE, RADIATOR	0.00	\$32.90	0.00	\$0.00	Replace	Check	X
90								
16573370	HOSE, RADIATOR, NO.3	0.00	\$29.60	0.00	\$0.00	Replace	Check	X
20								
16282370	HOSE, WATER BYPASS,	0.00	\$13.20	0.00	\$0.00	Replace	Check	X
90	NO.5							
16278370	PIPE, WATER BYPASS,	0.00	\$51.80	0.00	\$0.00	Replace	Check	X
20	NO.5							
16283370	HOSE, WATER BYPASS,	0.00	\$13.20	0.00	\$0.00	Replace	Check	X
21	NO.6							
G904047	INVERTER WATER PUMP	0.00	\$432.00	0.00	\$0.00	Replace	Check	X
040	ASSY							

G922E47 010	HOSE, HV WATER PUMP INLET	0.00	\$37.90	0.00	\$0.00	Replace	Check	X
G922F47 010	HOSE, HV WATER PUMP OUTLET	0.00	\$29.60	0.00	\$0.00	Replace	Check	X
G91H047 011	TANK ASSY, INVERTER RESERVE	0.00	\$371.30	0.00	\$0.00	Replace	Check	X
G922A47 010	HOSE, INVERTER COOLING INLET	0.00	\$43.10	0.00	\$0.00	Replace	Check	X
G922C47 010	HOSE, INVERTER COOLING OUTLET	0.00	\$29.60	0.00	\$0.00	Replace	Check	X
G922H47 010	HOSE, INVERTER RADIATOR INLET	0.00	\$40.70	0.00	\$0.00	Replace	Check	X
G125A47 010	COOLER, MOTOR COOLING	0.00	\$249.10	0.00	\$0.00	Replace	Check	X
8211147J 21	WIRE, ENGINE ROOM MAIN	0.00	\$6,138.00	0.00	\$0.00	Replace	Not Given	X
17751371 10	INLET, AIR CLEANER, NO 1	0.00	\$130.50	0.00	\$0.00	Replace	Check	X
17752371 21	INLET, AIR CLEANER, NO 2	0.00	\$93.90	0.00	\$0.00	Replace	Check	X
17753370 10	INLET, AIR CLEANER, NO 3	0.00	\$35.30	0.00	\$0.00	Replace	Check	X
96111107 50	CLAMP (FOR AIR CLEANER HOSE , NO.2)	0.00	\$9.00	0.00	\$0.00	Replace	Check	X
96111106 50	CLAMP (FOR AIR CLEANER INLET , NO.1)	0.00	\$7.10	0.00	\$0.00	Replace	Check	X
96111104 30	CLAMP (FOR RESONATOR INTAKE AIR	0.00	\$7.10	0.00	\$0.00	Replace	Check	X
17881373 30	HOSE, AIR CLEANER , NO.1	0.00	\$62.10	0.00	\$0.00	Replace	Check	X
17893371 30	RESONATOR, INTAKE AIR	0.00	\$14.90	0.00	\$0.00	Replace	Check	X
17771370 20	BRACKET, AIR CLEANER	0.00	\$26.90	0.00	\$0.00	Replace	Check	X
17700373 30	AIR CLEANER ASSY	0.00	\$956.20	0.00	\$0.00	Replace	Check	X
90904060 08	TUBE, UNION (FOR AIR CLEANER HOSE)	0.00	\$19.40	0.00	\$0.00	Replace	Check	X
22030370 60	BODY ASSY, THROTTLE	0.00	\$1,942.40	0.00	\$0.00	Replace	Check	X
17120371 10	MANIFOLD, INTAKE	0.00	\$867.70	0.00	\$0.00	Replace	Check	X
51410470 20	COVER ASSY, ENGINE UNDER CENTER SET	0.00	\$452.80	0.00	\$0.00	Replace	Check	X
52611471 40	ABSORBER, FR BUMPER	0.00	\$70.30	0.00	\$0.00	Replace	Check	X
52021471 10	REINFORCEMENT FRONT UPPER	1.00	\$691.10	25.00	\$518.33	Replace	Replace	DD
52618470 90	ABSORBER, FR BUMPER LOWER	1.00	\$117.00	25.00	\$87.75	Replace	Replace	DD
52132470 10	REINFORCEMENT FRONT LOWER	1.00	\$238.50	25.00	\$178.88	Replace	Replace	DD
52103470 10	EXTENSION SUBASSY, LH	0.00	\$116.30	0.00	\$0.00	Replace	Check	X
52102470 20	EXTENSION SUBASSY, RH	0.00	\$116.30	0.00	\$0.00	Replace	Check	X
81210470 20	LAMP ASSY, FOG, RH	1.00	\$910.20	10.00	\$819.18	Replace	Replace	BR
51420470 30	COVER ASSY, ENGINE	0.00	\$180.10	0.00	\$0.00	Replace	Check	X
53301471 10	HOOD SUB-ASSY	1.00	\$938.40	25.00	\$703.80	Replace	Replace	DD
Total			\$43,960.90		\$7,281.29			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		85315471 60	WIPER WASHER JAR	1.00	\$183.60	25.00	\$137.70	Replace	Replace
		53205479 00	SUPPORT S/A UPPER	1.00	\$364.90	25.00	\$273.68	Replace	Replace
		53202479 01	SUPPORT S/A RH	1.00	\$237.00	25.00	\$177.75	Replace	Replace
		53203479 01	SUPPORT S/A LH	1.00	\$237.00	25.00	\$177.75	Replace	Replace
		53217470 30	BRACE, HOOD LOCK SUPPORT	1.00	\$76.20	25.00	\$57.15	Replace	Replace
		53213470 50	SUPPORT, RADIATOR UPPER RH	1.00	\$76.70	25.00	\$57.53	Replace	Replace
		18400373 10	RADIATOR ASSY	1.00	\$1,841.10	25.00	\$1,380.83	Replace	Replace
		18711371 60	FAN SHROUD RADIATOR	1.00	\$219.30	25.00	\$164.48	Replace	Replace
		16363361 60	MOTOR, COOLING FAN , RH	1.00	\$443.40	25.00	\$332.55	Replace	Replace
		16363370 60	MOTOR, COOLING FAN , LH	1.00	\$543.50	25.00	\$407.63	Replace	Replace

	16361370 70	FAN RADIATOR, RH	1.00	\$233.00	25.00	\$174.75	Replace	Replace	
	16361370 80	FAN RADIATOR, LH	1.00	\$181.80	5.00	\$172.71	Replace	Replace	
	17751371 10	INLET, AIR CLEANER, NO 1	1.00	\$130.50	25.00	\$97.88	Replace	Replace	gra
	17752371 21	INLET, AIR CLEANER, NO 2	1.00	\$83.90	25.00	\$70.43	Replace	Replace	DI
	17753370 10	INLET, AIR CLEANER, NO 3	1.00	\$35.30	25.00	\$28.48	Replace	Replace	crs
	17700373 30	AIR CLEANER ASSY	1.00	\$956.20	25.00	\$717.15	Replace	Replace	crq
	53801470 80	FENDER SUB-ASSY, FR, RH	1.00	\$933.10	25.00	\$899.83	Replace	Replace	grc
	18593370 40	GUIDE, RADIATOR AIR, RH	1.00	\$54.60	25.00	\$40.95	Replace	Replace	DI
	561014E9 59	WINDSCREEN FRONT GLASS SUB-ASSY	1.00	\$1,828.40	25.00	\$1,219.80	Replace	Replace	crq
	75533470 70	WINDSCREEN FRONT MOULDING, TOP FRONT	1.00	\$44.00	25.00	\$33.00	Replace	Replace	
		SEALANT W/SCREEN	2.00	\$37.00	0.00	\$74.00	Replace	Replace	HEVNe
		COOLANT	1.00	\$12.32	0.00	\$12.32	Replace	Replace	
Total				8,560.82		6,506.35			

$$\begin{array}{r}
 13,787.64 \\
 + 1,400.00 \\
 + 1,130.00 \\
 \hline
 16,317.64
 \end{array}$$



Case Details

Case Reference Number :
TAX/05/19/2126
Type of Repair : Accident Repair
Vehicle Registration Number :
SHF362D

Company Type : SMRT Taxis Pte Ltd
Estimation ID : EST-7088-ID
Assigned By : Taxi Claims Manager
Team

Insurance Company Name : China Taiping Insurance (Singapore) Pte Ltd
Accident Date and Time : 27/05/2019 12:00 PM
Vehicle Age(In Months) : 17

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation										Surveyor Approval				Remarks
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			COVER, FR BUMPER	1	495.50	495.50	25.00	371.63	Replace	1	371.63	Replace	✓ DR
One Time Key In	Main			COVER, FR BUMPER RH	1	28.10	28.10	25.00	21.08	Replace	1	21.08	Replace	✓ MC
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	10	11.25	Replace	✓ MC
One Time Key In	Main			GRILLE SUB-ASSY	1	335.60	335.60	25.00	251.70	Replace	1	251.70	Replace	✓ DR
One Time Key In	Main			EMBLEM ASSY FRONT	1	87.10	87.10	25.00	65.32	Replace	1	65.32	Replace	✓ MC
One Time Key In	Main			GRILLE, RADIATOR	1	165.00	165.00	25.00	123.75	Replace	1	123.75	Replace	✓ DR
One Time Key In	Main			BRACKET, FR BUMPER	1	99.80	99.80	25.00	74.85	Replace	1	74.85	Replace	✓ DR
One Time Key In	Main			NUMBER PLATE	1	35.00	35.00	0.00	35.00	Replace	1	35.00	Replace	✓ DT
One Time Key In	Main			NUMBER PLATE FRAME	1	25.00	25.00	0.00	25.00	Replace	1	25.00	Replace	✓ DR

Total Spare Part Cost 35,997.72

Surveyor Total 7,281.25

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 35,997.72

Final Sur Total 7,281.25

SMRT Recommendation											Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace Remarks
One Time Key In	Main			SEAL, HOOD TO FR END	1	24.40	24.40	25.00	18.30	Replace	1	18.30	Replace * / nec
One Time Key In	Main			SUPPORT, FR BUMPER LH	1	82.30	82.30	25.00	61.72	Replace	1	61.72 ³	Replace * / BR
One Time Key In	Main			SUPPORT, FR BUMPER RH	1	76.90	76.90	25.00	57.68	Replace	1	57.68	Replace * / BR
One Time Key In	Main			FENDER SUB-ASSY, FR, RH	1	933.10	933.10	25.00	699.83	Replace	1	0	Repair * X R
One Time Key In	Main			EMBLEM, SIDE PANEL (HYBRID)	1	52.90	52.90	25.00	39.67	Replace	1	39.67 ⁹	Replace * / nec
One Time Key In	Main			SEAL SUB-ASSY, RH	1	50.20	50.20	25.00	37.65	Replace	1	37.65	Replace * / nec
One Time Key In	Main			LINER, FR FENDER, RH	1	198.40	198.40	25.00	148.80	Replace	0	0	Not Give * X NN
One Time Key In	Main			APRON SUB-ASSY, FRONT FENDER, RH	1	944.20	944.20	25.00	708.15	Replace	0	0	Not Give * X NN
One Time Key In	Main			MEMBER SUB-ASSY, FR RH	1	2,012.70	2,012.70	25.00	1,509.53	Replace	0	0	Check * X NN
One Time Key In	Main			PAD, FR WHEEL RH	1	57.70	57.70	25.00	43.28	Replace	0	0	Not Give * X NN
One Time Key In	Main			FRONT REINFORCEMENT SIDE RH	1	128.20	128.20	25.00	96.15	Replace	1	96.15	Replace * / DD
One Time Key In	Main			WIPER WASHER INLET	1	55.40	55.40	25.00	41.55	Replace	0	0	Check * X NN
One Time Key In	Main			WIPER WASHER JAR	1	183.60	183.60	25.00	137.70	Replace	0	0	Check * X NN
One Time Key In	Main			PANEL SUB-ASSY, FRONT DOOR RH	1	1,249.60	1,249.60	25.00	937.20	Replace	0	0	Not Give * X NN
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	0	0	Not Give * X NN

Total Spare Part Cost 35,997.72

Surveyor Total 7,281.25

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 35,997.72

Final Sur Total 7,281.25

SMRT Recommendation											Surveyor Approval			Remarks
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			SENSOR, AIR BAG, FRONT, RH & LH	1	310.50	310.50	10.00	279.45	Replace	0	0	Check	* X NAI
One Time Key In	Main			FENDER SUB-ASSY, FR, LH	1	933.10	933.10	25.00	699.83	Replace	0	0	Not Give	* X NAI
One Time Key In	Main			EMBLEM, SIDE PANEL (HYBRID)	1	52.90	52.90	25.00	39.67	Replace	0	0	Not Give	* X NAI
One Time Key In	Main			INSULATOR, HOOD	1	393.90	393.90	25.00	295.42	Replace	1	295.42	Replace	* / CRU
One Time Key In	Main			INSULATOR, HOOD CLIP	6	2.30	13.80	25.00	10.35	Replace	6	10.35	Replace	* / MC
One Time Key In	Main			HINGE ASSY, HOOD, LH	1	57.00	57.00	25.00	42.75	Replace	1	42.75	Replace	* / BT
One Time Key In	Main			HINGE ASSY, HOOD, RH	1	57.00	57.00	25.00	42.75	Replace	1	42.75	Replace	* / BT
One Time Key In	Main			LOCK ASSY, HOOD	1	131.10	131.10	25.00	98.32	Replace	0	0	Check	* X NAI
One Time Key In	Main			CABLE ASSY, HOOD	1	53.20	53.20	25.00	39.90	Replace	0	0	Not Give	* X NAI
One Time Key In	Main			MOULDING RH	1	83.30	83.30	25.00	62.47	Replace	0	0	Not Give	* X NAI
One Time Key In	Main			WIPER GARNISH LOUVER SUB-ASSY	1	866.90	866.90	25.00	500.17	Replace	0	0	Not Give	* X NAI
One Time Key In	Main			WIPER GARNISH SHIELD, COWL WATER, LH	1	18.90	18.90	25.00	14.17	Replace	0	0	Not Give	* X NAI
One Time Key In	Main			WIPER GARNISH SHIELD, COWL WATER, RH	1	18.90	18.90	25.00	14.17	Replace	0	0	Not Give	* X NAI
One Time Key In	Main			PILLAR, FRONT BODY, RH	1	339.40	339.40	25.00	254.55	Replace	0	0	Not Give	* X NAI
One Time Key In	Main			COVER SUB-ASSY, FRONT PILLAR, UPR RH	1	96.90	96.90	25.00	72.68	Replace	0	0	Check	* X NAI

Total Spare Part Cost 35,997.72

Surveyor Total 7,281.25

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 35,997.72

Final Sur Total 7,281.25

SMRT Recommendation											Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace Remarks
One Time Key In	Main			THERMISTOR ASSY	1	68.00	68.00	25.00	51.00	Replace	0	0	Check * X NAI
One Time Key In	Main			COVER, RADIATOR	1	227.80	227.80	25.00	170.85	Replace	0	0	Check * X NAI
One Time Key In	Main			SUPPORT S/A UPPER	1	364.90	364.90	25.00	273.67	Replace	0	0	Check * X NAI
One Time Key In	Main			SUPPORT SUB-ASSY LOWER	1	397.40	397.40	25.00	298.05	Replace	0	0	Check * X NAI
One Time Key In	Main			SUPPORT S/A LH	1	237.00	237.00	25.00	177.75	Replace	0	0	Check * X NAI
One Time Key In	Main			SUPPORT S/A RH	1	237.00	237.00	25.00	177.75	Replace	0	0	Check * X NAI
One Time Key In	Main			BRACE, HOOD LOCK SUPPORT	1	76.20	76.20	25.00	57.15	Replace	0	0	Check * X NAI
One Time Key In	Main			SUPPORT, RADIATOR UPPER LH	1	76.70	76.70	25.00	57.53	Replace	0	0	Check * X NN
One Time Key In	Main			SUPPORT, RADIATOR UPPER RH	1	76.70	76.70	25.00	57.53	Replace	0	0	Check * X NAI
One Time Key In	Main			UNIT, HEADLAMP , LH	1	2,558.90	2,558.90	10.00	2,303.01	Replace	0	0	Check * X NAI
One Time Key In	Main			UNIT, HEADLAMP , RH	1	2,558.90	2,558.90	10.00	2,303.01	Replace	1	2,303.01	Replace * / BR
One Time Key In	Main			COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	1	486.40	486.40	10.00	437.76	Replace	0	0	Check * X NN
One Time Key In	Main			HORN ASSY, HIGH	1	112.80	112.80	10.00	101.52	Replace	0	0	Check * X NN
One Time Key In	Main			HORN ASSY, LOW	1	112.80	112.80	10.00	101.52	Replace	0	0	Check * X NAI
One Time Key In	Main			AIR CON CONDENSER ASSY	1	1,317.70	1,317.70	25.00	988.28	Replace	1	988.28	Replace * / 00

Total Spare Part Cost 35,997.72

Surveyor Total 7,281.25

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 35,997.72

Final Sur Total 7,281.25

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			TUBE & ACCESSORY	1	574.40	574.40	25.00	430.80	Replace	0	0	Check	* X N/A
One Time Key In	Main			HOSE SUB-ASSY, DISCHARGE	1	337.10	337.10	25.00	252.83	Replace	0	0	Check	* X N/A
One Time Key In	Main			HOSE SUB-ASSY, SUCTION	1	541.90	541.90	25.00	406.42	Replace	0	0	Check	* X N/A
One Time Key In	Main			PIPE SUB-ASSY, SUCTION	1	389.60	389.60	25.00	292.20	Replace	0	0	Check	* X N/A
One Time Key In	Main			AIR CON COMPRESSOR ASSY	1	2,887.80	2,887.80	10.00	2,599.02	Replace	0	0	Check	* X N/A
One Time Key In	Main			COOLANT	1	12.30	12.30	0.00	12.30	Replace	0	0	Check	* X N/A
One Time Key In	Main			GUIDE, RADIATOR AIR	1	93.90	93.90	25.00	70.43	Replace	0	0	Check	* X N/A
One Time Key In	Main			GUIDE, RADIATOR AIR , UPPER	1	44.70	44.70	25.00	33.53	Replace	0	0	Check	* X N/A
One Time Key In	Main			GUIDE, RADIATOR AIR , LH	1	58.80	58.80	25.00	44.10	Replace	0	0	Check	* X N/A
One Time Key In	Main			GUIDE, RADIATOR AIR , RH	1	54.60	54.60	25.00	40.95	Replace	0	0	Check	* X N/A
One Time Key In	Main			SEAL, RADIATOR TO RH	1	24.80	24.80	25.00	18.60	Replace	0	0	Check	* X N/A
One Time Key In	Main			RADIATOR ASSY	1	1,841.10	1,841.10	25.00	1,380.82	Replace	0	0	Check	* X N/A
One Time Key In	Main			GROMMET (FOR RADIATOR LOWER SUPPORT)	2	12.70	25.40	25.00	19.05	Replace	0	0	Check	* X N/A
One Time Key In	Main			CUSHION, (FOR RADIATOR UPPER SUPPORT)	2	9.80	19.60	25.00	14.70	Replace	0	0	Check	* X N/A
One Time Key In	Main			FAN RADIATOR , LH	1	181.80	181.80	25.00	136.35	Replace	0	0	Check	* X N/A

Total Spare Part Cost 35,997.72

Surveyor Total 7,281.25

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 35,997.72

Final Sur Total 7,281.25

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			FAN RADIATOR , RH	1	233.00	233.00	25.00	174.75	Replace	0	0	Check	* X NAI
One Time Key In	Main			FAN SHROUD RADIATOR	1	219.30	219.30	25.00	164.48	Replace	0	0	Check	* X NAI
One Time Key In	Main			MOTOR, COOLING FAN , LH	1	543.50	543.50	10.00	489.15	Replace	0	0	Check	* X NAI
One Time Key In	Main			MOTOR, COOLING FAN , RH	1	443.40	443.40	10.00	399.06	Replace	0	0	Check	* X NAI
One Time Key In	Main			HOSE, RADIATOR , NO.1	1	42.60	42.60	25.00	31.95	Replace	0	0	Check	* X NAI
One Time Key In	Main			HOSE, RADIATOR , NO.2	1	40.20	40.20	25.00	30.15	Replace	0	0	Check	* X NAI
One Time Key In	Main			TANK, RESERVE SEALED W/O CAP	1	127.00	127.00	25.00	95.25	Replace	0	0	Check	* X NAI
One Time Key In	Main			HOSE, WATER BYPASS , NO.1	1	37.40	37.40	25.00	28.05	Replace	0	0	Check	* X NAI
One Time Key In	Main			HOSE, WATER BYPASS , NO.2	1	37.40	37.40	25.00	28.05	Replace	0	0	Check	* X NAI
One Time Key In	Main			HOSE, WATER BYPASS , NO.3	1	20.10	20.10	25.00	15.08	Replace	0	0	Check	* X NAI
One Time Key In	Main			HOSE, WATER BYPASS , NO.4	1	13.20	13.20	25.00	9.90	Replace	0	0	Check	* X NAI
One Time Key In	Main			HOSE, WATER BYPASS , NO.6	1	37.90	37.90	25.00	28.42	Replace	0	0	Check	* X NAI
One Time Key In	Main			PIPE, WATER BYPASS , NO.1	1	11.00	11.00	25.00	8.25	Replace	0	0	Check	* X NAI
One Time Key In	Main			PIPE, WATER BYPASS , NO.2	1	11.00	11.00	25.00	8.25	Replace	0	0	Check	* X NAI
One Time Key In	Main			PIPE, WATER BYPASS , NO.3	1	56.40	56.40	25.00	42.30	Replace	0	0	Check	* X NAI

Total Spare Part Cost 35,997.72

Lump Sum Discount (%) 0.00

Final Spare Part Cost 35,997.72

Surveyor Total 7,281.25

Lump Sum Dis (%) 0

Final Sur Total 7,281.25

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			PIPE, RADIATOR	1	32.90	32.90	25.00	24.67	Replace	0	0	Check	* X N/A
One Time Key In	Main			HOSE, RADIATOR , NO.3	1	29.60	29.60	25.00	22.20	Replace	0	0	Check	* X N/A
One Time Key In	Main			HOSE, WATER BYPASS, NO.5	1	13.20	13.20	25.00	9.90	Replace	0	0	Check	* X N/A
One Time Key In	Main			PIPE, WATER BYPASS, NO.5	1	51.80	51.80	25.00	38.85	Replace	0	0	Check	* X N/A
One Time Key In	Main			HOSE, WATER BYPASS, NO.6	1	13.20	13.20	25.00	9.90	Replace	0	0	Check	* X N/A
One Time Key In	Main			INVERTER WATER PUMP ASSY	1	432.00	432.00	10.00	388.80	Replace	0	0	Check	* X N/A
One Time Key In	Main			HOSE, HV WATER PUMP INLET	1	37.90	37.90	25.00	28.42	Replace	0	0	Check	* X N/A
One Time Key In	Main			HOSE, HV WATER PUMP OUTLET	1	29.60	29.60	25.00	22.20	Replace	0	0	Check	* X N/A
One Time Key In	Main			TANK ASSY, INVERTER RESERVE	1	371.30	371.30	25.00	278.48	Replace	0	0	Check	* X N/A
One Time Key In	Main			HOSE, INVERTER COOLING INLET	1	43.10	43.10	25.00	32.33	Replace	0	0	Check	* X N/A
One Time Key In	Main			HOSE, INVERTER COOLING OUTLET	1	29.60	29.60	25.00	22.20	Replace	0	0	Check	* X N/A
One Time Key In	Main			HOSE, INVERTER RADIATOR INLET	1	40.70	40.70	25.00	30.53	Replace	0	0	Check	* X N/A
One Time Key In	Main			COOLER, MOTOR COOLING	1	249.10	249.10	10.00	224.19	Replace	0	0	Check	* X N/A
One Time Key In	Main			WIRE, ENGINE ROOM MAIN	1	6,138.00	6,138.00	10.00	5,524.20	Replace	0	0	Not Give	* X N/A
One Time Key In	Main			INLET, AIR CLEANER, NO 1	1	130.50	130.50	25.00	97.88	Replace	0	0	Check	* X N/A

Total Spare Part Cost 35,997.72

Surveyor Total 7,281.25

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 35,997.72

Final Sur Total 7,281.25

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			INLET, AIR CLEANER, NO.2	1	93.90	93.90	25.00	70.43	Replace	0	0	Check	* X N/A
One Time Key In	Main			INLET, AIR CLEANER, NO.3	1	35.30	35.30	25.00	26.47	Replace	0	0	Check	* X N/A
One Time Key In	Main			CLAMP (FOR AIR CLEANER HOSE , NO.2)	1	9.00	9.00	25.00	6.75	Replace	0	0	Check	* X N/A
One Time Key In	Main			CLAMP (FOR AIR CLEANER INLET , NO.1)	2	7.10	14.20	25.00	10.65	Replace	0	0	Check	* X N/A
One Time Key In	Main			CLAMP (FOR RESONATOR INTAKE AIR)	1	7.10	7.10	25.00	5.32	Replace	0	0	Check	* X N/A
One Time Key In	Main			HOSE, AIR CLEANER , NO.1	1	62.10	62.10	25.00	46.58	Replace	0	0	Check	* X N/A
One Time Key In	Main			RESONATOR, INTAKE AIR	1	14.90	14.90	25.00	11.18	Replace	0	0	Check	* X N/A
One Time Key In	Main			BRACKET, AIR CLEANER	1	26.90	26.90	25.00	20.17	Replace	0	0	Check	* X N/A
One Time Key In	Main			AIR CLEANER ASSY	1	956.20	956.20	25.00	717.15	Replace	0	0	Check	* X N/A
One Time Key In	Main			TUBE, UNION (FOR AIR CLEANER HOSE)	1	19.40	19.40	25.00	14.55	Replace	0	0	Check	* X N/A
One Time Key In	Main			BODY ASSY, THROTTLE	1	1,942.40	1,942.40	10.00	1,748.16	Replace	0	0	Check	* X N/A
One Time Key In	Main			MANIFOLD, INTAKE	1	867.70	867.70	25.00	650.78	Replace	0	0	Check	* X N/A
One Time Key In	Main			COVER ASSY, ENGINE UNDER CENTER SET	1	452.80	452.80	25.00	339.60	Replace	0	0	Check	* X N/A
One Time Key In	Main			ABSORBER, FR BUMPER	1	70.30	70.30	25.00	52.72	Replace	0	0	Check	* X N/A
One Time Key In	Main			REINFORCEMENT FRONT UPPER	1	691.10	691.10	25.00	518.33	Replace	1	518.33	Replace	* / 00

Total Spare Part Cost 35,997.72

Surveyor Total 7,281.25

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 35,997.72

Final Sur Total 7,281.25

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			ABSORBER, FR BUMPER LOWER	1	117.00	117.00	25.00	87.75	Replace	1	87.75	Replace	✓ CRW
One Time Key In	Main			REINFORCEMENT FRONT LOWER	1	238.50	238.50	25.00	178.88	Replace	1	178.88	Replace	✓ DO
One Time Key In	Main			EXTENSION SUBASSY, LH	1	116.30	116.30	25.00	87.22	Replace	0	0	Check	✗ NAI
One Time Key In	Main			EXTENSION SUBASSY, RH	1	116.30	116.30	25.00	87.22	Replace	0	0	Check	✗ NAI
One Time Key In	Main			LAMP ASSY, FOG, RH	1	910.20	910.20	10.00	819.18	Replace	1	819.18	Replace	✓ DR
One Time Key In	Main			COVER ASSY, ENGINE	1	180.10	180.10	25.00	135.07	Replace	0	0	Check	✗ NAI
One Time Key In	Main			HOOD SUB-ASSY	1	938.40	938.40	25.00	703.80	Replace	1	703.80	Replace	✓ DO
Total Spare Part Cost									35,997.72	Surveyor Total 7,281.25				
Lump Sum Discount (%)									0.00	Lump Sum Dis (%) 0				
Final Spare Part Cost									35,997.72	Final Sur Total 7,281.25				

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT PORTION	1,521.00	1,000	
Total:			1,521.00	1,000.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200	
2	Main	TO REPSRAY FRONT HOOD	378.00	200	
3	Main	TO RESPRAY FRONT SUPPORT PANEL	180.00	0	
4	Main	TO RESPRAY RADIATOR SUPPORT LOWER	180.00	0	
5	Main	TO RESPRAY FRT MEMBER, RH	180.00	0	
Total:			2,796.00	600.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
6	Main	TO RESPRAY FRONT FENDER RH	378.00	200	
7	Main	TO RESPRAY FRONT FENDER LH	378.00	0	
8	Main	TO RESPRAY APRON PANEL RH	180.00	0	
9	Main	TO RESPRAY FRONT DOOR RH	378.00	0	
10	Main	TO RESPRAY FRONT PILLAR RH	180.00	0	
Total:			2,790.00	600.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TOWING CHARGE	126.00	0	90 /
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	20	
4	Main	TO TOP UP A/C GAS	120.00	50	
5	Main	TO ALIGN CHASSIS	350.00	0	
6	Main	TO CHECK & RESET SYSTEM FUNCTION	350.00	0	
7	Main	TO REMOVE AND REFIT WIRE HARDESS	300.00	0	
8	Main	TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER	120.00	50	
9	Main	TO REPLACE SUNDRY PARTS	100.00	0.00	
10	Main	TO WASH AND VACUUM	60.00	0	
Total:			1,806.00	140.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	35,997.72	7,281.25
Total Labour Cost	1,521.00	1,000.00
Total Spray Painting	2,790.00	600.00
Other	1,806.00	140.00

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Overall Total	42,114.72	9,021.25
Lump Sum Repair Option		
Lump Sum Total	0.00	9,021.25
Surveyor Approved Amount		9,021.25
No of Repair Days	12	6
Remarks		p/p repair, photo before paint.

Surveyor Name

Hasee Jie

Signature



Save

Clear

Survey Date

30/05/2019

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REQUEST FOR SUPPLYMENT PARTS

Contractor:		WEGA ENGINEERING PTE LTD	
Accident Case Number	7AX/05/19/2126	Date of Collection	2015/1/19
Vehicle No	SHP 362 D	Date of Request	1/15/19
Vehicle Model	2007A PRIUS 4	Number of Days to Extend (If any)	3 DAYS

S/N	Part Number	Part Description	Quantity	Unit Price
	1403,04,	Wiper Washer Jar		\$183.60 ✓
	1414,15,16,17	Support S/A Upper		\$364.90 ✓
	1457,56,55	Support S/A LH		\$237.00 ✓
	1454,55,56	Support S/A RH		\$237.00 ✓
	1423,24,44,50	Support S/A RH		\$237.00 ✓
	51	Support S/A RH		\$237.00 ✓
	1452,53	Brace Hood Lock Support		\$76.20 ✓
	1411,12,13	Support Radiator Upper RH		\$76.70 ✓
	1505,06	Radiator Assy		\$1841.10 ✓
	1483,84,85	Fan Shroud Radiator		\$219.30 ✓
	1486,87			

DEF \$137.70
 BVC \$273.68
 BT \$177.75
 BT \$177.75
 BT \$57.15
 BT \$57.53
 BVC \$1380.83
 CRA \$164.48

<<<Please submit photographs for damaged parts>>>

I, (Name)

CHIA

(Position)

Do solemnly and sincerely declare that: - Supplementary Parts are raised for replacement for the aforesaid vehicle.

Signature of person making this declaration

[To be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission

①

REQUEST FOR SUPPLYMENT PARTS

Contractor:		WEGA ENGINEERING PTE LTD	
Accident Case Number	TAX/05/19/2126	Date of Collection	30/5/19
Vehicle No	S4F 362 D	Date of Request	1/6/19
Vehicle Model	TOYOTA PRIUS 4	Number of Days to Extend (If any)	

S/N	Part Number	Part Description	Quantity	Unit Price
	1488,89	Motor Cooling Fan LH	(1am)	\$543.50 ✓
	1490,1	Motor Cooling Fan RH	(1am)	\$443.40 ✓
	1493,94	Fan Radiator LH		\$181.80 ✓
	1491,92	Fan Radiator RH		\$233.00 ✓
	1478,79,80	Inlet Air Cleaner NO 1		\$130.50 ✓
	1409,10,18,19	Inlet Air Cleaner NO 2		\$93.90 ✓
	1405,06,07	Inlet Air Cleaner NO 3		\$35.30 ✓
	1475,76,77	Air Cleaner Assy		\$956.20 ✓

\$407.63
 Jam \$332.55
 Jam \$332.55
 CRA \$172.71
 CRA \$174.75
 CRA \$97.88
 DEF \$70.43
 CRA \$26.48
 CRA \$717.15

<<<Please submit photographs for damaged parts>>>

I, (Name)

CHIA

(Position)

Do solemnly and sincerely declare that Supplementary Parts are raised for replacement for the aforesaid vehicle.

Signature of person making this declaration

[To be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission

(2)