



## Case Details

**Case Reference Number :**

TAX/05/19/2126

**Type of Repair :** Accident Repair

**Vehicle Registration Number :**

SHF362D

**Company Type :** SMRT Taxis Pte Ltd

**Estimation ID :** EST-7088-ID

**Assigned By :** Taxi Claims Manager  
Team

**Insurance Company Name :** China Taiping Insurance (Singapore) Pte Ltd

**Accident Date and Time :** 27/05/2019 12:00 PM

**Vehicle Age(In Months) :** 17

## Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

## Estimation Details

### Spare Part's Cost Detail

| BOM Type        | Costing Type | Portion | Material Number | SMRT Recommendation          |     |                         |                |        |                 |                 | Surveyor Approval |                          |                |         |
|-----------------|--------------|---------|-----------------|------------------------------|-----|-------------------------|----------------|--------|-----------------|-----------------|-------------------|--------------------------|----------------|---------|
|                 |              |         |                 | Part Name                    | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace | Remarks |
| One Time Key In | Main         |         |                 | COVER, FR BUMPER             | 1   | 495.50                  | 495.50         | 25.00  | 371.63          | Replace         | 1                 | 371.63                   | Replace ▾      |         |
| One Time Key In | Main         |         |                 | COVER, FR BUMPER RH          | 1   | 28.10                   | 28.10          | 25.00  | 21.08           | Replace         | 1                 | 21.08                    | Replace ▾      |         |
| One Time Key In | Main         |         |                 | CLIPS PIECE, FRT & RR BUMPER | 10  | 1.50                    | 15.00          | 25.00  | 11.25           | Replace         | 10                | 11.25                    | Replace ▾      |         |
| One Time Key In | Main         |         |                 | GRILLE SUB-ASSY              | 1   | 335.60                  | 335.60         | 25.00  | 251.70          | Replace         | 1                 | 251.70                   | Replace ▾      |         |
| One Time Key In | Main         |         |                 | EMBLEM ASSY FRONT            | 1   | 87.10                   | 87.10          | 25.00  | 65.32           | Replace         | 1                 | 65.32                    | Replace ▾      |         |
| One Time Key In | Main         |         |                 | GRILLE, RADIATOR             | 1   | 165.00                  | 165.00         | 25.00  | 123.75          | Replace         | 1                 | 123.75                   | Replace ▾      |         |
| One Time Key In | Main         |         |                 | BRACKET, FR BUMPER           | 1   | 99.80                   | 99.80          | 25.00  | 74.85           | Replace         | 1                 | 74.85                    | Replace ▾      |         |
| One Time Key In | Main         |         |                 | NUMBER PLATE                 | 1   | 35.00                   | 35.00          | 0.00   | 35.00           | Replace         | 1                 | 35.00                    | Replace ▾      |         |
| One Time Key In | Main         |         |                 | NUMBER PLATE FRAME           | 1   | 25.00                   | 25.00          | 0.00   | 25.00           | Replace         | 1                 | 25.00                    | Replace ▾      |         |

Total Spare Part Cost 35,997.72

Lump Sum Discount (%) 0.00

Final Spare Part Cost 35,997.72

Surveyor Total 7,281.25

Lump Sum Dis (%) 0

Final Sur Total 7,281.25

| SMRT Recommendation |              |         |                 |                                   |     |                         |                |        |                 |                 | Surveyor Approval |                          |                |         |
|---------------------|--------------|---------|-----------------|-----------------------------------|-----|-------------------------|----------------|--------|-----------------|-----------------|-------------------|--------------------------|----------------|---------|
| BOM Type            | Costing Type | Portion | Material Number | Part Name                         | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace | Remarks |
| One Time Key In     | Main         |         |                 | SEAL, HOOD TO FR END              | 1   | 24.40                   | 24.40          | 25.00  | 18.30           | Replace         | 1                 | 18.30                    | Replace ▾      |         |
| One Time Key In     | Main         |         |                 | SUPPORT, FR BUMPER LH             | 1   | 82.30                   | 82.30          | 25.00  | 61.72           | Replace         | 1                 | 61.72                    | Replace ▾      |         |
| One Time Key In     | Main         |         |                 | SUPPORT, FR BUMPER RH             | 1   | 76.90                   | 76.90          | 25.00  | 57.68           | Replace         | 1                 | 57.68                    | Replace ▾      |         |
| One Time Key In     | Main         |         |                 | FENDER SUB-ASSY, FR , RH          | 1   | 933.10                  | 933.10         | 25.00  | 699.83          | Replace         | 1                 | 0                        | Repair ▾       |         |
| One Time Key In     | Main         |         |                 | EMBLEM, SIDE PANEL ( HYBRID)      | 1   | 52.90                   | 52.90          | 25.00  | 39.67           | Replace         | 1                 | 39.67                    | Replace ▾      |         |
| One Time Key In     | Main         |         |                 | SEAL SUB-ASSY, RH                 | 1   | 50.20                   | 50.20          | 25.00  | 37.65           | Replace         | 1                 | 37.65                    | Replace ▾      |         |
| One Time Key In     | Main         |         |                 | LINER, FR FENDER, RH              | 1   | 198.40                  | 198.40         | 25.00  | 148.80          | Replace         | 0                 | 0                        | Not Give ▾     |         |
| One Time Key In     | Main         |         |                 | APRON SUB-ASSY, FRONT FENDER , RH | 1   | 944.20                  | 944.20         | 25.00  | 708.15          | Replace         | 0                 | 0                        | Not Give ▾     |         |
| One Time Key In     | Main         |         |                 | MEMBER SUB-ASSY, FR RH            | 1   | 2,012.70                | 2,012.70       | 25.00  | 1,509.53        | Replace         | 0                 | 0                        | Check ▾        |         |
| One Time Key In     | Main         |         |                 | PAD, FR WHEEL RH                  | 1   | 57.70                   | 57.70          | 25.00  | 43.28           | Replace         | 0                 | 0                        | Not Give ▾     |         |
| One Time Key In     | Main         |         |                 | FRONT REINFORCEMENT SIDE RH       | 1   | 128.20                  | 128.20         | 25.00  | 96.15           | Replace         | 1                 | 96.15                    | Replace ▾      |         |
| One Time Key In     | Main         |         |                 | WIPER WASHER INLET                | 1   | 55.40                   | 55.40          | 25.00  | 41.55           | Replace         | 0                 | 0                        | Check ▾        |         |
| One Time Key In     | Main         |         |                 | WIPER WASHER JAR                  | 1   | 183.60                  | 183.60         | 25.00  | 137.70          | Replace         | 0                 | 0                        | Check ▾        |         |
| One Time Key In     | Main         |         |                 | PANEL SUB-ASSY, FRONT DOOR RH     | 1   | 1,249.60                | 1,249.60       | 25.00  | 937.20          | Replace         | 0                 | 0                        | Not Give ▾     |         |
| One Time Key In     | Main         |         |                 | STICKER DECAL SMRT (DOOR)         | 1   | 60.00                   | 60.00          | 0.00   | 60.00           | Replace         | 0                 | 0                        | Not Give ▾     |         |

|                       |           |                  |          |
|-----------------------|-----------|------------------|----------|
| Total Spare Part Cost | 35,997.72 | Surveyor Total   | 7,281.25 |
| Lump Sum Discount (%) | 0.00      | Lump Sum Dis (%) | 0        |
| Final Spare Part Cost | 35,997.72 | Final Sur Total  | 7,281.25 |

| SMRT Recommendation |              |         |                 |                                       |     |                         |                |        |                 |                 | Surveyor Approval |                          |                |         |
|---------------------|--------------|---------|-----------------|---------------------------------------|-----|-------------------------|----------------|--------|-----------------|-----------------|-------------------|--------------------------|----------------|---------|
| BOM Type            | Costing Type | Portion | Material Number | Part Name                             | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace | Remarks |
| One Time Key In     | Main         |         |                 | SENSOR, AIR BAG, FRONT, RH & LH       | 1   | 310.50                  | 310.50         | 10.00  | 279.45          | Replace         | 0                 | 0                        | Check ▾        |         |
| One Time Key In     | Main         |         |                 | FENDER SUB-ASSY, FR , LH              | 1   | 933.10                  | 933.10         | 25.00  | 699.83          | Replace         | 0                 | 0                        | Not Give ▾     |         |
| One Time Key In     | Main         |         |                 | EMBLEM, SIDE PANEL ( HYBRID)          | 1   | 52.90                   | 52.90          | 25.00  | 39.67           | Replace         | 0                 | 0                        | Not Give ▾     |         |
| One Time Key In     | Main         |         |                 | INSULATOR, HOOD                       | 1   | 393.90                  | 393.90         | 25.00  | 295.42          | Replace         | 1                 | 295.42                   | Replace ▾      |         |
| One Time Key In     | Main         |         |                 | INSULATOR, HOOD CLIP                  | 6   | 2.30                    | 13.80          | 25.00  | 10.35           | Replace         | 6                 | 10.35                    | Replace ▾      |         |
| One Time Key In     | Main         |         |                 | HINGE ASSY, HOOD, LH                  | 1   | 57.00                   | 57.00          | 25.00  | 42.75           | Replace         | 1                 | 42.75                    | Replace ▾      |         |
| One Time Key In     | Main         |         |                 | HINGE ASSY, HOOD, RH                  | 1   | 57.00                   | 57.00          | 25.00  | 42.75           | Replace         | 1                 | 42.75                    | Replace ▾      |         |
| One Time Key In     | Main         |         |                 | LOCK ASSY, HOOD                       | 1   | 131.10                  | 131.10         | 25.00  | 98.32           | Replace         | 0                 | 0                        | Check ▾        |         |
| One Time Key In     | Main         |         |                 | CABLE ASSY, HOOD                      | 1   | 53.20                   | 53.20          | 25.00  | 39.90           | Replace         | 0                 | 0                        | Not Give ▾     |         |
| One Time Key In     | Main         |         |                 | MOULDING RH                           | 1   | 83.30                   | 83.30          | 25.00  | 62.47           | Replace         | 0                 | 0                        | Not Give ▾     |         |
| One Time Key In     | Main         |         |                 | WIPER GARNISH LOUVER SUB-ASSY         | 1   | 666.90                  | 666.90         | 25.00  | 500.17          | Replace         | 0                 | 0                        | Not Give ▾     |         |
| One Time Key In     | Main         |         |                 | WIPER GARNISH SHIELD, COWL WATER , LH | 1   | 18.90                   | 18.90          | 25.00  | 14.17           | Replace         | 0                 | 0                        | Not Give ▾     |         |
| One Time Key In     | Main         |         |                 | WIPER GARNISH SHIELD, COWL WATER , RH | 1   | 18.90                   | 18.90          | 25.00  | 14.17           | Replace         | 0                 | 0                        | Not Give ▾     |         |
| One Time Key In     | Main         |         |                 | PILLAR, FRONT BODY, RH                | 1   | 339.40                  | 339.40         | 25.00  | 254.55          | Replace         | 0                 | 0                        | Not Give ▾     |         |
| One Time Key In     | Main         |         |                 | COVER SUB-ASSY, FRONT PILLAR , UPR RH | 1   | 96.90                   | 96.90          | 25.00  | 72.68           | Replace         | 0                 | 0                        | Check ▾        |         |

|                       |           |                  |          |
|-----------------------|-----------|------------------|----------|
| Total Spare Part Cost | 35,997.72 | Surveyor Total   | 7,281.25 |
| Lump Sum Discount (%) | 0.00      | Lump Sum Dis (%) | 0        |
| Final Spare Part Cost | 35,997.72 | Final Sur Total  | 7,281.25 |

| SMRT Recommendation |              |         |                 |                                      |     |                         |                |        |                 |                 | Surveyor Approval              |                                       |                |         |
|---------------------|--------------|---------|-----------------|--------------------------------------|-----|-------------------------|----------------|--------|-----------------|-----------------|--------------------------------|---------------------------------------|----------------|---------|
| BOM Type            | Costing Type | Portion | Material Number | Part Name                            | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace | Surveyor Quantity              | Surveyor Final Price(\$)              | Repair/Replace | Remarks |
| One Time Key In     | Main         |         |                 | THERMISTOR ASSY                      | 1   | 68.00                   | 68.00          | 25.00  | 51.00           | Replace         | <input type="text" value="0"/> | <input type="text" value="0"/>        | Check ▾        |         |
| One Time Key In     | Main         |         |                 | COVER, RADIATOR                      | 1   | 227.80                  | 227.80         | 25.00  | 170.85          | Replace         | <input type="text" value="0"/> | <input type="text" value="0"/>        | Check ▾        |         |
| One Time Key In     | Main         |         |                 | SUPPORT S/A UPPER                    | 1   | 364.90                  | 364.90         | 25.00  | 273.67          | Replace         | <input type="text" value="0"/> | <input type="text" value="0"/>        | Check ▾        |         |
| One Time Key In     | Main         |         |                 | SUPPORT SUB-ASSY LOWER               | 1   | 397.40                  | 397.40         | 25.00  | 298.05          | Replace         | <input type="text" value="0"/> | <input type="text" value="0"/>        | Check ▾        |         |
| One Time Key In     | Main         |         |                 | SUPPORT S/A LH                       | 1   | 237.00                  | 237.00         | 25.00  | 177.75          | Replace         | <input type="text" value="0"/> | <input type="text" value="0"/>        | Check ▾        |         |
| One Time Key In     | Main         |         |                 | SUPPORT S/A RH                       | 1   | 237.00                  | 237.00         | 25.00  | 177.75          | Replace         | <input type="text" value="0"/> | <input type="text" value="0"/>        | Check ▾        |         |
| One Time Key In     | Main         |         |                 | BRACE, HOOD LOCK SUPPORT             | 1   | 76.20                   | 76.20          | 25.00  | 57.15           | Replace         | <input type="text" value="0"/> | <input type="text" value="0"/>        | Check ▾        |         |
| One Time Key In     | Main         |         |                 | SUPPORT, RADIATOR UPPER LH           | 1   | 76.70                   | 76.70          | 25.00  | 57.53           | Replace         | <input type="text" value="0"/> | <input type="text" value="0"/>        | Check ▾        |         |
| One Time Key In     | Main         |         |                 | SUPPORT, RADIATOR UPPER RH           | 1   | 76.70                   | 76.70          | 25.00  | 57.53           | Replace         | <input type="text" value="0"/> | <input type="text" value="0"/>        | Check ▾        |         |
| One Time Key In     | Main         |         |                 | UNIT, HEADLAMP , LH                  | 1   | 2,558.90                | 2,558.90       | 10.00  | 2,303.01        | Replace         | <input type="text" value="0"/> | <input type="text" value="0"/>        | Check ▾        |         |
| One Time Key In     | Main         |         |                 | UNIT, HEADLAMP , RH                  | 1   | 2,558.90                | 2,558.90       | 10.00  | 2,303.01        | Replace         | <input type="text" value="1"/> | <input type="text" value="2,303.01"/> | Replace ▾      |         |
| One Time Key In     | Main         |         |                 | COMPUTER SUB-ASSY, HEADLAMP, RH NO.1 | 1   | 486.40                  | 486.40         | 10.00  | 437.76          | Replace         | <input type="text" value="0"/> | <input type="text" value="0"/>        | Check ▾        |         |
| One Time Key In     | Main         |         |                 | HORN ASSY, HIGH                      | 1   | 112.80                  | 112.80         | 10.00  | 101.52          | Replace         | <input type="text" value="0"/> | <input type="text" value="0"/>        | Check ▾        |         |
| One Time Key In     | Main         |         |                 | HORN ASSY, LOW                       | 1   | 112.80                  | 112.80         | 10.00  | 101.52          | Replace         | <input type="text" value="0"/> | <input type="text" value="0"/>        | Check ▾        |         |
| One Time Key In     | Main         |         |                 | AIR CON CONDENSER ASSY               | 1   | 1,317.70                | 1,317.70       | 25.00  | 988.28          | Replace         | <input type="text" value="1"/> | <input type="text" value="988.28"/>   | Replace ▾      |         |

|                       |           |                  |                                |
|-----------------------|-----------|------------------|--------------------------------|
| Total Spare Part Cost | 35,997.72 | Surveyor Total   | 7,281.25                       |
| Lump Sum Discount (%) | 0.00      | Lump Sum Dis (%) | <input type="text" value="0"/> |
| Final Spare Part Cost | 35,997.72 | Final Sur Total  | 7,281.25                       |

| SMRT Recommendation |              |         |                 |                                       |     |                         |                |        |                 |                 | Surveyor Approval |                          |                |         |
|---------------------|--------------|---------|-----------------|---------------------------------------|-----|-------------------------|----------------|--------|-----------------|-----------------|-------------------|--------------------------|----------------|---------|
| BOM Type            | Costing Type | Portion | Material Number | Part Name                             | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace | Remarks |
| One Time Key In     | Main         |         |                 | TUBE & ACCESSORY                      | 1   | 574.40                  | 574.40         | 25.00  | 430.80          | Replace         | 0                 | 0                        | Check ▼        |         |
| One Time Key In     | Main         |         |                 | HOSE SUB-ASSY, DISCHARGE              | 1   | 337.10                  | 337.10         | 25.00  | 252.83          | Replace         | 0                 | 0                        | Check ▼        |         |
| One Time Key In     | Main         |         |                 | HOSE SUB-ASSY, SUCTION                | 1   | 541.90                  | 541.90         | 25.00  | 406.42          | Replace         | 0                 | 0                        | Check ▼        |         |
| One Time Key In     | Main         |         |                 | PIPE SUB-ASSY, SUCTION                | 1   | 389.60                  | 389.60         | 25.00  | 292.20          | Replace         | 0                 | 0                        | Check ▼        |         |
| One Time Key In     | Main         |         |                 | AIR CON COMPRESSOR ASSY               | 1   | 2,887.80                | 2,887.80       | 10.00  | 2,599.02        | Replace         | 0                 | 0                        | Check ▼        |         |
| One Time Key In     | Main         |         |                 | COOLANT                               | 1   | 12.30                   | 12.30          | 0.00   | 12.30           | Replace         | 0                 | 0                        | Check ▼        |         |
| One Time Key In     | Main         |         |                 | GUIDE, RADIATOR AIR                   | 1   | 93.90                   | 93.90          | 25.00  | 70.43           | Replace         | 0                 | 0                        | Check ▼        |         |
| One Time Key In     | Main         |         |                 | GUIDE, RADIATOR AIR , UPPER           | 1   | 44.70                   | 44.70          | 25.00  | 33.53           | Replace         | 0                 | 0                        | Check ▼        |         |
| One Time Key In     | Main         |         |                 | GUIDE, RADIATOR AIR , LH              | 1   | 58.80                   | 58.80          | 25.00  | 44.10           | Replace         | 0                 | 0                        | Check ▼        |         |
| One Time Key In     | Main         |         |                 | GUIDE, RADIATOR AIR , RH              | 1   | 54.60                   | 54.60          | 25.00  | 40.95           | Replace         | 0                 | 0                        | Check ▼        |         |
| One Time Key In     | Main         |         |                 | SEAL, RADIATOR TO RH                  | 1   | 24.80                   | 24.80          | 25.00  | 18.60           | Replace         | 0                 | 0                        | Check ▼        |         |
| One Time Key In     | Main         |         |                 | RADIATOR ASSY                         | 1   | 1,841.10                | 1,841.10       | 25.00  | 1,380.82        | Replace         | 0                 | 0                        | Check ▼        |         |
| One Time Key In     | Main         |         |                 | GROMMET (FOR RADIATOR LOWER SUPPORT)  | 2   | 12.70                   | 25.40          | 25.00  | 19.05           | Replace         | 0                 | 0                        | Check ▼        |         |
| One Time Key In     | Main         |         |                 | CUSHION, (FOR RADIATOR UPPER SUPPORT) | 2   | 9.80                    | 19.60          | 25.00  | 14.70           | Replace         | 0                 | 0                        | Check ▼        |         |
| One Time Key In     | Main         |         |                 | FAN RADIATOR , LH                     | 1   | 181.80                  | 181.80         | 25.00  | 136.35          | Replace         | 0                 | 0                        | Check ▼        |         |

|                       |           |                  |          |
|-----------------------|-----------|------------------|----------|
| Total Spare Part Cost | 35,997.72 | Surveyor Total   | 7,281.25 |
| Lump Sum Discount (%) | 0.00      | Lump Sum Dis (%) | 0        |
| Final Spare Part Cost | 35,997.72 | Final Sur Total  | 7,281.25 |

| SMRT Recommendation |              |         |                 |                              |     |                         |                |        |                 |                 | Surveyor Approval |                          |                |         |
|---------------------|--------------|---------|-----------------|------------------------------|-----|-------------------------|----------------|--------|-----------------|-----------------|-------------------|--------------------------|----------------|---------|
| BOM Type            | Costing Type | Portion | Material Number | Part Name                    | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace | Remarks |
| One Time Key In     | Main         |         |                 | FAN RADIATOR , RH            | 1   | 233.00                  | 233.00         | 25.00  | 174.75          | Replace         | 0                 | 0                        | Check ▼        |         |
| One Time Key In     | Main         |         |                 | FAN SHROUD RADIATOR          | 1   | 219.30                  | 219.30         | 25.00  | 164.48          | Replace         | 0                 | 0                        | Check ▼        |         |
| One Time Key In     | Main         |         |                 | MOTOR, COOLING FAN , LH      | 1   | 543.50                  | 543.50         | 10.00  | 489.15          | Replace         | 0                 | 0                        | Check ▼        |         |
| One Time Key In     | Main         |         |                 | MOTOR, COOLING FAN , RH      | 1   | 443.40                  | 443.40         | 10.00  | 399.06          | Replace         | 0                 | 0                        | Check ▼        |         |
| One Time Key In     | Main         |         |                 | HOSE, RADIATOR , NO.1        | 1   | 42.60                   | 42.60          | 25.00  | 31.95           | Replace         | 0                 | 0                        | Check ▼        |         |
| One Time Key In     | Main         |         |                 | HOSE, RADIATOR , NO.2        | 1   | 40.20                   | 40.20          | 25.00  | 30.15           | Replace         | 0                 | 0                        | Check ▼        |         |
| One Time Key In     | Main         |         |                 | TANK, RESERVE SEALED W/O CAP | 1   | 127.00                  | 127.00         | 25.00  | 95.25           | Replace         | 0                 | 0                        | Check ▼        |         |
| One Time Key In     | Main         |         |                 | HOSE, WATER BYPASS , NO.1    | 1   | 37.40                   | 37.40          | 25.00  | 28.05           | Replace         | 0                 | 0                        | Check ▼        |         |
| One Time Key In     | Main         |         |                 | HOSE, WATER BYPASS , NO.2    | 1   | 37.40                   | 37.40          | 25.00  | 28.05           | Replace         | 0                 | 0                        | Check ▼        |         |
| One Time Key In     | Main         |         |                 | HOSE, WATER BYPASS , NO.3    | 1   | 20.10                   | 20.10          | 25.00  | 15.08           | Replace         | 0                 | 0                        | Check ▼        |         |
| One Time Key In     | Main         |         |                 | HOSE, WATER BYPASS , NO.4    | 1   | 13.20                   | 13.20          | 25.00  | 9.90            | Replace         | 0                 | 0                        | Check ▼        |         |
| One Time Key In     | Main         |         |                 | HOSE, WATER BYPASS , NO.8    | 1   | 37.90                   | 37.90          | 25.00  | 28.42           | Replace         | 0                 | 0                        | Check ▼        |         |
| One Time Key In     | Main         |         |                 | PIPE, WATER BYPASS , NO.1    | 1   | 11.00                   | 11.00          | 25.00  | 8.25            | Replace         | 0                 | 0                        | Check ▼        |         |
| One Time Key In     | Main         |         |                 | PIPE, WATER BYPASS , NO.2    | 1   | 11.00                   | 11.00          | 25.00  | 8.25            | Replace         | 0                 | 0                        | Check ▼        |         |
| One Time Key In     | Main         |         |                 | PIPE, WATER BYPASS, NO.3     | 1   | 56.40                   | 56.40          | 25.00  | 42.30           | Replace         | 0                 | 0                        | Check ▼        |         |

|                       |           |                  |          |
|-----------------------|-----------|------------------|----------|
| Total Spare Part Cost | 35,997.72 | Surveyor Total   | 7,281.25 |
| Lump Sum Discount (%) | 0.00      | Lump Sum Dis (%) | 0        |
| Final Spare Part Cost | 35,997.72 | Final Sur Total  | 7,281.25 |

| SMRT Recommendation |              |         |                 |                               |     |                         |                |        |                 |                 | Surveyor Approval |                          |                |         |
|---------------------|--------------|---------|-----------------|-------------------------------|-----|-------------------------|----------------|--------|-----------------|-----------------|-------------------|--------------------------|----------------|---------|
| BOM Type            | Costing Type | Portion | Material Number | Part Name                     | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace | Remarks |
| One Time Key In     | Main         |         |                 | PIPE, RADIATOR                | 1   | 32.90                   | 32.90          | 25.00  | 24.67           | Replace         | 0                 | 0                        | Check ▾        |         |
| One Time Key In     | Main         |         |                 | HOSE, RADIATOR , NO.3         | 1   | 29.60                   | 29.60          | 25.00  | 22.20           | Replace         | 0                 | 0                        | Check ▾        |         |
| One Time Key In     | Main         |         |                 | HOSE, WATER BYPASS, NO.5      | 1   | 13.20                   | 13.20          | 25.00  | 9.90            | Replace         | 0                 | 0                        | Check ▾        |         |
| One Time Key In     | Main         |         |                 | PIPE, WATER BYPASS, NO.5      | 1   | 51.80                   | 51.80          | 25.00  | 38.85           | Replace         | 0                 | 0                        | Check ▾        |         |
| One Time Key In     | Main         |         |                 | HOSE, WATER BYPASS, NO.6      | 1   | 13.20                   | 13.20          | 25.00  | 9.90            | Replace         | 0                 | 0                        | Check ▾        |         |
| One Time Key In     | Main         |         |                 | INVERTER WATER PUMP ASSY      | 1   | 432.00                  | 432.00         | 10.00  | 388.80          | Replace         | 0                 | 0                        | Check ▾        |         |
| One Time Key In     | Main         |         |                 | HOSE, HV WATER PUMP INLET     | 1   | 37.90                   | 37.90          | 25.00  | 28.42           | Replace         | 0                 | 0                        | Check ▾        |         |
| One Time Key In     | Main         |         |                 | HOSE, HV WATER PUMP OUTLET    | 1   | 29.60                   | 29.60          | 25.00  | 22.20           | Replace         | 0                 | 0                        | Check ▾        |         |
| One Time Key In     | Main         |         |                 | TANK ASSY, INVERTER RESERVE   | 1   | 371.30                  | 371.30         | 25.00  | 278.48          | Replace         | 0                 | 0                        | Check ▾        |         |
| One Time Key In     | Main         |         |                 | HOSE, INVERTER COOLING INLET  | 1   | 43.10                   | 43.10          | 25.00  | 32.33           | Replace         | 0                 | 0                        | Check ▾        |         |
| One Time Key In     | Main         |         |                 | HOSE, INVERTER COOLING OUTLET | 1   | 29.60                   | 29.60          | 25.00  | 22.20           | Replace         | 0                 | 0                        | Check ▾        |         |
| One Time Key In     | Main         |         |                 | HOSE, INVERTER RADIATOR INLET | 1   | 40.70                   | 40.70          | 25.00  | 30.53           | Replace         | 0                 | 0                        | Check ▾        |         |
| One Time Key In     | Main         |         |                 | COOLER, MOTOR COOLING         | 1   | 249.10                  | 249.10         | 10.00  | 224.19          | Replace         | 0                 | 0                        | Check ▾        |         |
| One Time Key In     | Main         |         |                 | WIRE, ENGINE ROOM MAIN        | 1   | 6,138.00                | 6,138.00       | 10.00  | 5,524.20        | Replace         | 0                 | 0                        | Not Give ▾     |         |
| One Time Key In     | Main         |         |                 | INLET, AIR CLEANER, NO 1      | 1   | 130.50                  | 130.50         | 25.00  | 97.88           | Replace         | 0                 | 0                        | Check ▾        |         |

|                       |           |                  |          |
|-----------------------|-----------|------------------|----------|
| Total Spare Part Cost | 35,997.72 | Surveyor Total   | 7,281.25 |
| Lump Sum Discount (%) | 0.00      | Lump Sum Dis (%) | 0        |
| Final Spare Part Cost | 35,997.72 | Final Sur Total  | 7,281.25 |

| SMRT Recommendation |              |         |                 |                                        |     |                         |                |        |                 |                 | Surveyor Approval |                          |                |         |
|---------------------|--------------|---------|-----------------|----------------------------------------|-----|-------------------------|----------------|--------|-----------------|-----------------|-------------------|--------------------------|----------------|---------|
| BOM Type            | Costing Type | Portion | Material Number | Part Name                              | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace | Remarks |
| One Time Key In     | Main         |         |                 | INLET, AIR CLEANER, NO 2               | 1   | 93.90                   | 93.90          | 25.00  | 70.43           | Replace         | 0                 | 0                        | Check ▾        |         |
| One Time Key In     | Main         |         |                 | INLET, AIR CLEANER, NO 3               | 1   | 35.30                   | 35.30          | 25.00  | 26.47           | Replace         | 0                 | 0                        | Check ▾        |         |
| One Time Key In     | Main         |         |                 | CLAMP ( FOR AIR CLEANER HOSE , NO.2 )  | 1   | 9.00                    | 9.00           | 25.00  | 6.75            | Replace         | 0                 | 0                        | Check ▾        |         |
| One Time Key In     | Main         |         |                 | CLAMP ( FOR AIR CLEANER INLET , NO.1 ) | 2   | 7.10                    | 14.20          | 25.00  | 10.65           | Replace         | 0                 | 0                        | Check ▾        |         |
| One Time Key In     | Main         |         |                 | CLAMP ( FOR RESONATOR INTAKE AIR )     | 1   | 7.10                    | 7.10           | 25.00  | 5.32            | Replace         | 0                 | 0                        | Check ▾        |         |
| One Time Key In     | Main         |         |                 | HOSE, AIR CLEANER , NO.1               | 1   | 62.10                   | 62.10          | 25.00  | 46.58           | Replace         | 0                 | 0                        | Check ▾        |         |
| One Time Key In     | Main         |         |                 | RESONATOR, INTAKE AIR                  | 1   | 14.90                   | 14.90          | 25.00  | 11.18           | Replace         | 0                 | 0                        | Check ▾        |         |
| One Time Key In     | Main         |         |                 | BRACKET, AIR CLEANER                   | 1   | 26.90                   | 26.90          | 25.00  | 20.17           | Replace         | 0                 | 0                        | Check ▾        |         |
| One Time Key In     | Main         |         |                 | AIR CLEANER ASSY                       | 1   | 956.20                  | 956.20         | 25.00  | 717.15          | Replace         | 0                 | 0                        | Check ▾        |         |
| One Time Key In     | Main         |         |                 | TUBE, UNION ( FOR AIR CLEANER HOSE )   | 1   | 19.40                   | 19.40          | 25.00  | 14.55           | Replace         | 0                 | 0                        | Check ▾        |         |
| One Time Key In     | Main         |         |                 | BODY ASSY, THROTTLE                    | 1   | 1,942.40                | 1,942.40       | 10.00  | 1,748.16        | Replace         | 0                 | 0                        | Check ▾        |         |
| One Time Key In     | Main         |         |                 | MANIFOLD, INTAKE                       | 1   | 867.70                  | 867.70         | 25.00  | 650.78          | Replace         | 0                 | 0                        | Check ▾        |         |
| One Time Key In     | Main         |         |                 | COVER ASSY, ENGINE UNDER CENTER SET    | 1   | 452.80                  | 452.80         | 25.00  | 339.60          | Replace         | 0                 | 0                        | Check ▾        |         |
| One Time Key In     | Main         |         |                 | ABSORBER, FR BUMPER                    | 1   | 70.30                   | 70.30          | 25.00  | 52.72           | Replace         | 0                 | 0                        | Check ▾        |         |
| One Time Key In     | Main         |         |                 | REINFORCEMENT FRONT UPPER              | 1   | 691.10                  | 691.10         | 25.00  | 518.33          | Replace         | 1                 | 518.33                   | Replace ▾      |         |

|                       |           |                  |          |
|-----------------------|-----------|------------------|----------|
| Total Spare Part Cost | 35,997.72 | Surveyor Total   | 7,281.25 |
| Lump Sum Discount (%) | 0.00      | Lump Sum Dis (%) | 0        |
| Final Spare Part Cost | 35,997.72 | Final Sur Total  | 7,281.25 |

| SMRT Recommendation   |              |         |                 |                           |     |                         |                |        |                 | Surveyor Approval |                   |                          |                |         |
|-----------------------|--------------|---------|-----------------|---------------------------|-----|-------------------------|----------------|--------|-----------------|-------------------|-------------------|--------------------------|----------------|---------|
| BOM Type              | Costing Type | Portion | Material Number | Part Name                 | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace   | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace | Remarks |
| One Time Key In       | Main         |         |                 | ABSORBER, FR BUMPER LOWER | 1   | 117.00                  | 117.00         | 25.00  | 87.75           | Replace           | 1                 | 87.75                    | Replace ▾      |         |
| One Time Key In       | Main         |         |                 | REINFORCEMENT FRONT LOWER | 1   | 238.50                  | 238.50         | 25.00  | 178.88          | Replace           | 1                 | 178.88                   | Replace ▾      |         |
| One Time Key In       | Main         |         |                 | EXTENSION SUBASSY, LH     | 1   | 116.30                  | 116.30         | 25.00  | 87.22           | Replace           | 0                 | 0                        | Check ▾        |         |
| One Time Key In       | Main         |         |                 | EXTENSION SUBASSY, RH     | 1   | 116.30                  | 116.30         | 25.00  | 87.22           | Replace           | 0                 | 0                        | Check ▾        |         |
| One Time Key In       | Main         |         |                 | LAMP ASSY, FOG, RH        | 1   | 910.20                  | 910.20         | 10.00  | 819.18          | Replace           | 1                 | 819.18                   | Replace ▾      |         |
| One Time Key In       | Main         |         |                 | COVER ASSY, ENGINE        | 1   | 180.10                  | 180.10         | 25.00  | 135.07          | Replace           | 0                 | 0                        | Check ▾        |         |
| One Time Key In       | Main         |         |                 | HOOD SUB-ASSY             | 1   | 938.40                  | 938.40         | 25.00  | 703.80          | Replace           | 1                 | 703.80                   | Replace ▾      |         |
| Total Spare Part Cost |              |         |                 |                           |     |                         |                |        | 35,997.72       | Surveyor Total    |                   | 7,281.25                 |                |         |
| Lump Sum Discount (%) |              |         |                 |                           |     |                         |                |        | 0.00            | Lump Sum Dis (%)  |                   | 0                        |                |         |
| Final Spare Part Cost |              |         |                 |                           |     |                         |                |        | 35,997.72       | Final Sur Total   |                   | 7,281.25                 |                |         |

Labour's Cost Detail

| S.No.  | Costing Type | Job Scope               | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|--------|--------------|-------------------------|-------------------------|-------------------------|---------|
| 1      | Main         | TO REPAIR FRONT PORTION | 1,521.00                | 1,000                   |         |
| Total: |              |                         | 1,521.00                | 1,000.00                |         |

Spray Cost Detail

| S.No.  | Costing Type | Job Scope                         | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|--------|--------------|-----------------------------------|-------------------------|-------------------------|---------|
| 1      | Main         | TO REPSRAY FRONT BUMPER           | 378.00                  | 200                     |         |
| 2      | Main         | TO REPSRAY FRONT HOOD             | 378.00                  | 200                     |         |
| 3      | Main         | TO RESPRAY FRONT SUPPORT PANEL    | 180.00                  | 0                       |         |
| 4      | Main         | TO RESPRAY RADIATOR SUPPORT LOWER | 180.00                  | 0                       |         |
| 5      | Main         | TO RESPRAY FRT MEMBER,RH          | 180.00                  | 0                       |         |
| Total: |              |                                   | 2,790.00                | 600.00                  |         |

| S.No.         | Costing Type | Job Scope                  | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|---------------|--------------|----------------------------|-------------------------|-------------------------|---------|
| 6             | Main         | TO RESPRAY FRONT FENDER RH | 378.00                  | 200                     |         |
| 7             | Main         | TO RESPRAY FRONT FENDER LH | 378.00                  | 0                       |         |
| 8             | Main         | TO RESPRAY APRON PANEL RH  | 180.00                  | 0                       |         |
| 9             | Main         | TO RESPRAY FRONT DOOR RH   | 378.00                  | 0                       |         |
| 10            | Main         | TO RESPRAY FRONT PILLAR RH | 180.00                  | 0                       |         |
| <b>Total:</b> |              |                            | <b>2,790.00</b>         | <b>600.00</b>           |         |

**Other Cost Detail**

| S.No.         | Costing Type | Job Scope                                                                       | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|---------------|--------------|---------------------------------------------------------------------------------|-------------------------|-------------------------|---------|
| 1             | Main         | TOWING CHARGE                                                                   | 126.00                  | 0                       |         |
| 2             | Main         | TO CHECK WIRING AND SYSTEM FUNCTION                                             | 80.00                   | 20                      |         |
| 3             | Main         | TO APPLY RUST-PROOFING ON AFFECTED AREA                                         | 200.00                  | 20                      |         |
| 4             | Main         | TO TOP UP A/C GAS                                                               | 120.00                  | 50                      |         |
| 5             | Main         | TO ALIGN CHASSIS                                                                | 350.00                  | 0                       |         |
| 6             | Main         | TO CHECK & RESET SYSTEM FUNCTION                                                | 350.00                  | 0                       |         |
| 7             | Main         | TO REMOVE AND REFIT WIRE HARDESS                                                | 300.00                  | 0                       |         |
| 8             | Main         | TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER | 120.00                  | 50                      |         |
| 9             | Main         | TO REPLACE SUNDRY PARTS                                                         | 100.00                  | 0.00                    |         |
| 10            | Main         | TO WASH AND VACUUM                                                              | 60.00                   | 0                       |         |
| <b>Total:</b> |              |                                                                                 | <b>1,806.00</b>         | <b>140.00</b>           |         |

**Summary**

|                         | Estimator Assesment(\$) | Surveyor Assesment(\$) |
|-------------------------|-------------------------|------------------------|
| Total Spare Part Detail | 35,997.72               | 7,281.25               |
| Total Labour Cost       | 1,521.00                | 1,000.00               |
| Total Spray Painting    | 2,790.00                | 600.00                 |
| Other                   | 1,806.00                | 140.00                 |

|                          | Estimator Assesment(\$)                                                           | Surveyor Assesment(\$)                                                              |
|--------------------------|-----------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
| Overall Total            | 42,114.72                                                                         | 9,021.25                                                                            |
| Lump Sum Repair Option   |                                                                                   |                                                                                     |
| Lump Sum Total           | 0.00                                                                              | 9,021.25                                                                            |
| Surveyor Approved Amount |                                                                                   | 9,021.25                                                                            |
| No of Repair Days*       | 12                                                                                | 6                                                                                   |
| Remarks                  | -                                                                                 | p/p repair, photo before paint.                                                     |
| Surveyor Name            |                                                                                   | Hwee jie                                                                            |
| Signature                |  |  |
| Survey Date              | 30/05/2019                                                                        |                                                                                     |

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: