


VIC

Section A - Accident Details

Registration Number	SHF382D
Case Reference Number	TAX/05/19/2126
Registration Date	14/12/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	POH SWEE KHENG
Type of Accident	Head On
Accident Date and Time	27/5/2019 8:00 PM
Accident Reported Date and Time	28/5/2019 9:29 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	27/5/2019 8:01 PM
Replacement Vehicle issued?	No
Job Card Number	24101701
Special Instruction to ARC, if any	TOWED TO TP COMPOUND \$90
Prepared Date and Time	30/5/2019 6:59 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



b2/b3

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,071.00	\$1,400.00
Total Spray Cost	\$3,166.00	\$800.00
Total Spare Part Cost	\$42,467.69	\$13,787.84
Total Other Cost	\$1,828.00	\$330.00
TOTAL COST	\$49,532.69	\$16,317.84 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	12.0	9.0
Prepared / Adjusted By	Tuck Foo Kok	Hwee Jie (LKK) / China Talping
ARC / Surveyor Sign Off Date	30/05/2019 3:41 PM	30/05/2019 2:10 PM
Signature		
Remarks	SUP = 3 DAYS	p/p repair, photo before paint.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1908-0468	Invoice Number	
Quotation Date	27.06.2018	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT FENDER LH	\$200.00	\$200.00
TO REPAIR BOTH FRONT CHASSIS FRAME	\$350.00	\$200.00
TO REPAIR FRONT PORTION	\$1,521.00	\$1,000.00
Total Labour	\$2,071.00	\$1,400.00

Supp
Supp
/

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO REPSRAY FRONT HOOD	\$378.00	\$200.00
TO REPSRAY FRONT SUPPORT PANEL	\$180.00	\$0.00
TO REPSRAY RADIATOR SUPPORT LOWER	\$180.00	\$0.00
TO REPSRAY FRT MEMBER, RH	\$180.00	\$0.00
TO REPSRAY FRONT FENDER RH	\$378.00	\$200.00
TO REPSRAY FRONT FENDER LH	\$378.00	\$0.00
TO REPSRAY APRON PANEL RH	\$180.00	\$0.00
TO REPSRAY FRONT DOOR RH	\$378.00	\$0.00
TO REPSRAY FRONT PILLAR RH	\$180.00	\$0.00
TO REPSRAY FRONT FENDER LH	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$3,188.00	\$800.00

Supp

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$128.00	\$90.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	\$20.00
TO TOP UP A/C GAS	\$120.00	\$50.00
TO ALIGN CHASSIS	\$350.00	\$0.00
TO CHECK & RESET SYSTEM FUNCTION	\$350.00	\$0.00
TO REMOVE AND REFIT WIRE HARDESS	\$300.00	\$0.00
TO REMOVE & REFIT FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER	\$120.00	\$50.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO REMOVE / REFIT WINDSCREEN	\$120.00	\$100.00
Total Other Costs	\$1,926.00	\$330.00

Supp

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119479	COVER, FR BUMPER	1.00	\$495.50	25.00	\$371.63	Replace	Replace
		52127479	COVER, FR BUMPER RH	1.00	\$28.10	25.00	\$21.08	Replace	Replace



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
50 Woodlands Industrial Park S1, Singapore
Tel Number: 63803002
Estimate / Quotation Number: 6663213
Accident Reporting Number: 6663213

Date Generated: 06/01/2016

User ID: Pankaj

82161180	CLIPS PIECE, FRT & RR	10.00	\$1.50	25.00	\$11.25	Replace	Replace	✓
10	BUMPER							
53101470	GRILLE SUB-ASSY	1.00	\$335.80	25.00	\$251.70	Replace	Replace	✓
80								
75310470	EMBLEM ASSY FRONT	1.00	\$67.10	25.00	\$65.33	Replace	Replace	✓
80								
53112472	GRILLE, RADIATOR	1.00	\$165.00	25.00	\$123.75	Replace	Replace	✓
40								
52114471	BRACKET, FR BUMPER	1.00	\$99.80	25.00	\$74.85	Replace	Replace	✓
80								
	NUMBER PLATE	1.00	\$35.00	0.00	\$35.00	Replace	Replace	✓
	NUMBER PLATE FRAME	1.00	\$25.00	0.00	\$25.00	Replace	Replace	✓
53395470	SEAL, HOOD TO FR END	1.00	\$24.40	25.00	\$18.30	Replace	Replace	✓
40								
52116470	SUPPORT, FR BUMPER	1.00	\$82.30	25.00	\$61.73	Replace	Replace	✓
80	LH							
52115470	SUPPORT, FR BUMPER	1.00	\$76.90	25.00	\$57.68	Replace	Replace	✓
80	RH							
53801470	FENDER SUB-ASSY, FR	1.00	\$933.10	100.00	\$0.00	Replace	Repair	✓
80	RH							
75374471	EMBLEM, SIDE PANEL (	1.00	\$52.90	25.00	\$38.68	Replace	Replace	✓
40	HYBRID)							
53807470	SEAL SUB-ASSY, RH	1.00	\$50.20	25.00	\$37.65	Replace	Replace	✓
20								
53875470	LINER, FR FENDER, RH	0.00	\$198.40	0.00	\$0.00	Replace	Not Given	✓
70								
53701471	APRON SUB-ASSY,	0.00	\$844.20	0.00	\$0.00	Replace	Not Given	✓
11	FRONT FENDER, RH							
57101470	MEMBER SUB-ASSY, FR	0.00	\$2,012.70	0.00	\$0.00	Replace	Check	✓
70	RH							
53851470	PAD, FR WHEEL RH	0.00	\$57.70	0.00	\$0.00	Replace	Not Given	✓
61								
51107470	FRONT	1.00	\$128.20	25.00	\$96.15	Replace	Replace	✓
20	REINFORCEMENT SIDE							
85319471	WIPER WASHER INLET	0.00	\$55.40	0.00	\$0.00	Replace	Check	✓
70								
85315471	WIPER WASHER JAR	0.00	\$183.80	0.00	\$0.00	Replace	Check	✓
60								
67001471	PANEL SUB-ASSY,	0.00	\$1,248.60	0.00	\$0.00	Replace	Not Given	✓
52	FRONT DOOR, RH							
	STICKER DECAL SMRT	0.00	\$80.00	0.00	\$0.00	Replace	Not Given	✓
	(DOOR)							
89173494	SENSOR, AIR BAG,	0.00	\$310.50	0.00	\$0.00	Replace	Check	✓
95	FRONT, RH & LH							
53803471	FENDER SUB-ASSY, FR	0.00	\$933.10	0.00	\$0.00	Replace	Not Given	✓
00	LH							
75374471	EMBLEM, SIDE PANEL (	0.00	\$52.90	0.00	\$0.00	Replace	Not Given	✓
40	HYBRID)							
53341470	INSULATOR, HOOD	1.00	\$393.90	25.00	\$295.43	Replace	Replace	✓
40								
90467090	INSULATOR, HOOD CLIP	6.00	\$2.30	25.00	\$10.35	Replace	Replace	✓
50								
53420471	HINGE ASSY, HOOD, LH	1.00	\$57.00	25.00	\$42.75	Replace	Replace	✓
30								
53410471	HINGE ASSY, HOOD, RH	1.00	\$57.00	25.00	\$42.75	Replace	Replace	✓
30								
53510471	LOCK ASSY, HOOD	0.00	\$131.10	0.00	\$0.00	Replace	Check	✓
40								
53630470	CABLE ASSY, HOOD	0.00	\$53.20	0.00	\$0.00	Replace	Not Given	✓
90								
75535470	MOULDING RH	0.00	\$83.30	0.00	\$0.00	Replace	Not Given	✓
70								
55708472	WIPER GARNISH	0.00	\$666.90	0.00	\$0.00	Replace	Not Given	✓
30	LOUVER SUB-ASSY							
55754470	WIPER GARNISH SHIELD	0.00	\$18.90	0.00	\$0.00	Replace	Not Given	✓
70	COWL WATER, LH							
55753470	WIPER GARNISH SHIELD	0.00	\$18.90	0.00	\$0.00	Replace	Not Given	✓
90	COWL WATER, RH							
61013470	PILLAR, FRONT BODY,	0.00	\$339.40	0.00	\$0.00	Replace	Not Given	✓
10	RH							
60117470	COVER SUB-ASSY,	0.00	\$96.90	0.00	\$0.00	Replace	Check	✓
20	FRONT PILLAR, UPR RH							
86790281	THERMISTOR ASSY	0.00	\$68.00	0.00	\$0.00	Replace	Check	✓
00								
53289470	COVER, RADIATOR	0.00	\$227.80	0.00	\$0.00	Replace	Check	✓
72								
53205479	SUPPORT S/A UPPER	0.00	\$364.90	0.00	\$0.00	Replace	Check	✓
00								
53028470	SUPPORT SUB-ASSY	0.00	\$397.40	0.00	\$0.00	Replace	Check	✓
10	LOWER							
53203479	SUPPORT S/A LH	0.00	\$237.00	0.00	\$0.00	Replace	Check	✓
01								
53202479	SUPPORT S/A RH	0.00	\$237.00	0.00	\$0.00	Replace	Check	✓
01								
53217470	BRACE, HOOD LOCK	0.00	\$78.20	0.00	\$0.00	Replace	Check	✓
30	SUPPORT							
53214470	SUPPORT, RADIATOR	0.00	\$76.70	0.00	\$0.00	Replace	Check	✓
50	UPPER LH							

83213470	SUPPORT, RADIATOR	0.00	\$78.70	0.00	\$0.00	Replace	Check	X
50	UPPER RH							
81185478	UNIT, HEADLAMP, LH	0.00	\$2,558.90	0.00	\$0.00	Replace	Check	X
81								
81145478	UNIT, HEADLAMP, RH	1.00	\$2,558.90	10.00	\$2,303.01	Replace	Replace	X
81								
81016478	COMPUTER SUB-ASSY,	0.00	\$486.40	0.00	\$0.00	Replace	Check	X
90	HEADLAMP, RH NO.1							
88510470	HORN ASSY, HIGH	0.00	\$112.80	0.00	\$0.00	Replace	Check	X
50								
88520470	HORN ASSY, LOW	0.00	\$112.80	0.00	\$0.00	Replace	Check	X
30								
88460103	AIR CON CONDENSER	1.00	\$1,317.70	25.00	\$988.28	Replace	Replace	X
20	ASSY							
88710471	TUBE & ACCESSORY	0.00	\$574.40	0.00	\$0.00	Replace	Check	X
80								
88703470	HOSE SUB-ASSY,	0.00	\$337.10	0.00	\$0.00	Replace	Check	X
80	DISCHARGE							
88704471	HOSE SUB-ASSY,	0.00	\$541.80	0.00	\$0.00	Replace	Check	X
00	SUCTION							
88707470	PIPE SUB-ASSY,	0.00	\$389.60	0.00	\$0.00	Replace	Check	X
30	SUCTION							
88370470	AIR CON COMPRESSOR	0.00	\$2,887.80	0.00	\$0.00	Replace	Check	X
92	ASSY							
	COOLANT	0.00	\$12.30	0.00	\$0.00	Replace	Check	X
16592370	GUIDE, RADIATOR AIR	0.00	\$93.90	0.00	\$0.00	Replace	Check	X
20								
16594370	GUIDE, RADIATOR AIR	0.00	\$44.70	0.00	\$0.00	Replace	Check	X
10	UPPER							
16595370	GUIDE, RADIATOR AIR	0.00	\$58.80	0.00	\$0.00	Replace	Check	X
50	LH							
16593370	GUIDE, RADIATOR AIR	0.00	\$54.60	0.00	\$0.00	Replace	Check	X
40	RH							
16592370	SEAL, RADIATOR TO RH	0.00	\$24.80	0.00	\$0.00	Replace	Check	X
10								
16400373	RADIATOR ASSY	0.00	\$1,841.10	0.00	\$0.00	Replace	Check	X
10								
90480400	GROMMET (FOR	0.00	\$12.70	0.00	\$0.00	Replace	Check	X
21	RADIATOR LOWER							
18523370	CUSHION, (FOR	0.00	\$9.90	0.00	\$0.00	Replace	Check	X
10	RADIATOR UPPER							
16361370	FAN RADIATOR, LH	0.00	\$181.80	0.00	\$0.00	Replace	Check	X
60								
16361370	FAN RADIATOR, RH	0.00	\$233.00	0.00	\$0.00	Replace	Check	X
70								
16711371	FAN SHROUD RADIATOR	0.00	\$219.30	0.00	\$0.00	Replace	Check	X
60								
16363370	MOTOR, COOLING FAN	0.00	\$543.50	0.00	\$0.00	Replace	Check	X
60	LH							
16363361	MOTOR, COOLING FAN	0.00	\$443.40	0.00	\$0.00	Replace	Check	X
50	RH							
18571372	HOSE, RADIATOR, NO.1	0.00	\$42.60	0.00	\$0.00	Replace	Check	X
10								
18572372	HOSE, RADIATOR, NO.2	0.00	\$40.20	0.00	\$0.00	Replace	Check	X
10								
164A237	TANK, RESERVE SEALED	0.00	\$127.00	0.00	\$0.00	Replace	Check	X
012	W/O CAP							
16261371	HOSE, WATER BYPASS	0.00	\$37.40	0.00	\$0.00	Replace	Check	X
50	NO.1							
16264371	HOSE, WATER BYPASS	0.00	\$37.40	0.00	\$0.00	Replace	Check	X
20	NO.2							
16267370	HOSE, WATER BYPASS	0.00	\$20.10	0.00	\$0.00	Replace	Check	X
90	NO.3							
16261371	HOSE, WATER BYPASS	0.00	\$13.20	0.00	\$0.00	Replace	Check	X
00	NO.4							
16266370	HOSE, WATER BYPASS	0.00	\$37.90	0.00	\$0.00	Replace	Check	X
10	NO.8							
16268371	PIPE, WATER BYPASS	0.00	\$11.00	0.00	\$0.00	Replace	Check	X
00	NO.1							
16268371	PIPE, WATER BYPASS	0.00	\$11.00	0.00	\$0.00	Replace	Check	X
20	NO.2							
16278370	PIPE, WATER BYPASS	0.00	\$56.40	0.00	\$0.00	Replace	Check	X
20	NO.3							
16577370	PIPE, RADIATOR	0.00	\$32.90	0.00	\$0.00	Replace	Check	X
60								
16573370	HOSE, RADIATOR, NO.3	0.00	\$29.60	0.00	\$0.00	Replace	Check	X
20								
16262370	HOSE, WATER BYPASS	0.00	\$13.20	0.00	\$0.00	Replace	Check	X
90	NO.5							
16278370	PIPE, WATER BYPASS	0.00	\$51.80	0.00	\$0.00	Replace	Check	X
20	NO.5							
16263370	HOSE, WATER BYPASS	0.00	\$13.20	0.00	\$0.00	Replace	Check	X
21	NO.6							
G904047	INVERTER WATER PUMP	0.00	\$432.00	0.00	\$0.00	Replace	Check	X
040	ASSY							

	G922E47 010	HOSE, HV WATER PUMP INLET	0.00	\$37.90	0.00	\$0.00	Replace	Check	X
	G922F47 010	HOSE, HV WATER PUMP OUTLET	0.00	\$29.60	0.00	\$0.00	Replace	Check	X
	G91H047 011	TANK ASSY, INVERTER RESERVE	0.00	\$371.30	0.00	\$0.00	Replace	Check	X
	G922A47 010	HOSE, INVERTER COOLING INLET	0.00	\$43.10	0.00	\$0.00	Replace	Check	X
	G922C47 010	HOSE, INVERTER COOLING OUTLET	0.00	\$29.60	0.00	\$0.00	Replace	Check	X
	G922H47 010	HOSE, INVERTER RADIATOR INLET	0.00	\$40.70	0.00	\$0.00	Replace	Check	X
	G125A47 010	COOLER, MOTOR COOLING	0.00	\$248.10	0.00	\$0.00	Replace	Check	X
	8211147J 21	WIRE, ENGINE ROOM MAIN	0.00	\$6,138.00	0.00	\$0.00	Replace	Not Given	X
	17751371 10	INLET, AIR CLEANER, NO 1	0.00	\$130.50	0.00	\$0.00	Replace	Check	X
	17752371 21	INLET, AIR CLEANER, NO 2	0.00	\$93.90	0.00	\$0.00	Replace	Check	X
	17753370 10	INLET, AIR CLEANER, NO 3	0.00	\$35.30	0.00	\$0.00	Replace	Check	X
	96111107 30	CLAMP (FOR AIR CLEANER HOSE, NO.2)	0.00	\$9.00	0.00	\$0.00	Replace	Check	X
	96111108 30	CLAMP (FOR AIR CLEANER INLET, NO.1)	0.00	\$7.10	0.00	\$0.00	Replace	Check	X
	96111104 30	CLAMP (FOR RESONATOR INTAKE AIR	0.00	\$7.10	0.00	\$0.00	Replace	Check	X
	17881373 30	HOSE, AIR CLEANER, NO.1	0.00	\$62.10	0.00	\$0.00	Replace	Check	X
	17893371 30	RESONATOR, INTAKE AIR	0.00	\$14.90	0.00	\$0.00	Replace	Check	X
	17771370 20	BRACKET, AIR CLEANER	0.00	\$26.90	0.00	\$0.00	Replace	Check	X
	17700373 30	AIR CLEANER ASSY	0.00	\$956.20	0.00	\$0.00	Replace	Check	X
	90904060 06	TUBE, UNION (FOR AIR CLEANER HOSE)	0.00	\$19.40	0.00	\$0.00	Replace	Check	X
	22030370 60	BODY ASSY, THROTTLE	0.00	\$1,942.40	0.00	\$0.00	Replace	Check	X
	17120371 10	MANIFOLD, INTAKE	0.00	\$867.70	0.00	\$0.00	Replace	Check	X
	51410470 20	COVER ASSY, ENGINE UNDER CENTER SET	0.00	\$452.80	0.00	\$0.00	Replace	Check	X
	52611471 40	ABSORBER, FR BUMPER	0.00	\$70.30	0.00	\$0.00	Replace	Check	X
	52021471 10	REINFORCEMENT FRONT UPPER	1.00	\$691.10	25.00	\$518.33	Replace	Replace	✓
	52618470 90	ABSORBER, FR BUMPER LOWER	1.00	\$117.00	25.00	\$87.75	Replace	Replace	✓
	52132470 10	REINFORCEMENT FRONT LOWER	1.00	\$238.50	25.00	\$178.88	Replace	Replace	✓
	52103470 10	EXTENSION SUBASSY, LH	0.00	\$116.30	0.00	\$0.00	Replace	Check	X
	52102470 20	EXTENSION SUBASSY, RH	0.00	\$116.30	0.00	\$0.00	Replace	Check	X
	81210470 20	LAMP ASSY, FOG, RH	1.00	\$910.20	10.00	\$819.18	Replace	Replace	✓
	51420470 30	COVER ASSY, ENGINE	0.00	\$180.10	0.00	\$0.00	Replace	Check	X
	53301471 10	HOOD SUB-ASSY	1.00	\$938.40	25.00	\$703.90	Replace	Replace	✓
Total				\$43,960.90		\$7,281.28			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		85315471 60	WIPER WASHER JAR	1.00	\$183.60	25.00	\$137.70	Replace	Replace
		53205479 00	SUPPORT S/A UPPER	1.00	\$384.90	25.00	\$273.68	Replace	Replace
		53202479 01	SUPPORT S/A RH	1.00	\$237.00	25.00	\$177.75	Replace	Replace
		53203479 01	SUPPORT S/A LH	1.00	\$237.00	25.00	\$177.75	Replace	Replace
		53217470 39	BRACE, HOOD LOCK SUPPORT	1.00	\$76.30	25.00	\$57.15	Replace	Replace
		53213470 50	SUPPORT, RADIATOR UPPER RH	1.00	\$76.70	25.00	\$57.53	Replace	Replace
		16400373 10	RADIATOR ASSY	1.00	\$1,841.10	25.00	\$1,380.83	Replace	Replace
		18711371 60	FAN SHROUD RADIATOR	1.00	\$219.30	25.00	\$164.48	Replace	Replace
		18363351 60	MOTOR, COOLING FAN, RH	1.00	\$443.40	25.00	\$332.55	Replace	Replace
		18363370 60	MOTOR, COOLING FAN, LH	1.00	\$543.50	25.00	\$407.63	Replace	Replace

	16361370 79	FAN RADIATOR , RH	1.00	\$233.00	25.00	\$174.75	Replace	Replace	✓
	16361370 80	FAN RADIATOR , LH	1.00	\$181.80	5.00	\$172.71	Replace	Replace	✓
	17751371 10	INLET, AIR CLEANER, NO 1	1.00	\$138.50	25.00	\$97.88	Replace	Replace	✓
	17752371 21	INLET, AIR CLEANER, NO 2	1.00	\$93.90	25.00	\$70.43	Replace	Replace	✓
	17753370 10	INLET, AIR CLEANER, NO 3	1.00	\$35.30	25.00	\$29.48	Replace	Replace	✓
	17700373 20	AIR CLEANER ASSY	1.00	\$956.20	25.00	\$717.15	Replace	Replace	✓
	53601470 80	FENDER SUB-ASSY, FR , RH	1.00	\$933.10	25.00	\$898.83	Replace	Replace	✓
	16593370 40	GUIDE, RADIATOR AIR , RH	1.00	\$54.60	25.00	\$40.85	Replace	Replace	✓
	56101459 59	WINDSCREEN FRONT GLASS SUB-ASSY	1.00	\$1,629.40	25.00	\$1,219.80	Replace	Replace	✓
	75533470 79	WINDSCREEN FRONT MOULDING, TOP FRONT	1.00	\$44.00	25.00	\$33.00	Replace	Replace	✓
		SEALANT W/SCREEN	2.00	\$37.00	0.00	\$74.00	Replace	Replace	✓
		COOLANT	1.00	\$12.32	0.00	\$12.32	Replace	Replace	✓
Total				8,560.82		6,506.35			

$$\begin{array}{r}
 13,787.64 \\
 + 1,400.00 \\
 + 1,130.00 \\
 \hline
 16,317.64
 \end{array}$$



Case Details

Case Reference Number :

TAX00519/2126

Type of Repair : Accident Repair

Vehicle Registration Number :

SHF9520

Company Type : SMRT Taxi Pte Ltd

Estimation ID : EST-7088-ID

Assigned By : Taxi Claims Manager

Team :

Insurance Company Name : China Taiping Insurance (Singapore) Pte Ltd

Accident Date and Time : 27/05/2019 12:00 PM

Vehicle Age(In Months) : 17

Documents / Photographs

[View Documents / Photographs](#)

Total Documents : 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(S)	List Price(S)	Disc(%)	Final Price(S)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(S)	Repair/Replace	Remarks
One Time Key In	Main			COVER, FR BUMPER	1	495.50	495.50	25.00	371.63	Replace	1	371.63	Replace *	/ DR
One Time Key In	Main			COVER, FR BUMPER RH	1	25.10	25.10	25.00	21.08	Replace	1	21.08	Replace *	/ MS
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	10	11.25	Replace *	/ MC
One Time Key In	Main			GRILLE SUB-ASSY	1	335.80	335.80	25.00	251.70	Replace	1	251.70	Replace *	/ DR
One Time Key In	Main			EMBLEM ASSY FRONT	1	87.10	87.10	25.00	65.32	Replace	1	65.32	Replace *	/ MC
One Time Key In	Main			GRILLE, RADIATOR	1	185.00	185.00	25.00	138.75	Replace	1	138.75	Replace *	/ DR
One Time Key In	Main			BRACKET, FR BUMPER	1	99.80	99.80	25.00	74.85	Replace	1	74.85	Replace *	/ DR
One Time Key In	Main			NUMBER PLATE	1	35.00	35.00	0.00	35.00	Replace	1	35.00	Replace *	/ OT
One Time Key In	Main			NUMBER PLATE FRAME	1	25.00	25.00	0.00	25.00	Replace	1	25.00	Replace *	/ DR

Total Spare Part Cost 25,987.72

Surveyor Total 7,281.25

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 25,987.72

Final Sur Total 7,281.25

SMRT Recommendation											Surveyor Approval			
BOB Type	Coasting Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			SEAL, HOOD TO FR END	1	24.40	24.40	25.00	18.30	Replace	1	18.30	Replace	/ MC
One Time Key In	Main			SUPPORT, FR BUMPER LH	1	82.30	82.30	25.00	61.72	Replace	1	61.72	Replace	/ GR
One Time Key In	Main			SUPPORT, FR BUMPER RH	1	76.90	76.90	25.00	57.68	Replace	1	57.68	Replace	/ GR
One Time Key In	Main			FENDER SUB-ASSY, FR, RH	1	933.10	933.10	25.00	699.83	Replace	1	0	Repair	X R
One Time Key In	Main			EMBLEM, SIDE PANEL (HYBRID)	1	52.90	52.90	25.00	39.67	Replace	1	39.67	Replace	/ MC
One Time Key In	Main			SEAL SUB-ASSY, RH	1	50.20	50.20	25.00	37.65	Replace	1	37.65	Replace	/ MC
One Time Key In	Main			LINER, FR FENDER, RH	1	188.40	188.40	25.00	141.30	Replace	0	0	Not Give	X NN
One Time Key In	Main			APRON SUB-ASSY, FRONT FENDER, RH	1	944.20	944.20	25.00	708.15	Replace	0	0	Not Give	X NN
One Time Key In	Main			MEMBER SUB-ASSY, FR RH	1	2,012.70	2,012.70	25.00	1,509.53	Replace	0	0	Check	X NN
One Time Key In	Main			PAD, FR WHEEL RH	1	57.70	57.70	25.00	43.28	Replace	0	0	Not Give	X NN
One Time Key In	Main			FRONT REINFORCEMENT SIDE RH	1	128.20	128.20	25.00	96.15	Replace	1	96.15	Replace	/ DD
One Time Key In	Main			WIPER WASHER INLET	1	55.40	55.40	25.00	41.55	Replace	0	0	Check	X NN
One Time Key In	Main			WIPER WASHER JAR	1	183.60	183.60	25.00	137.70	Replace	0	0	Check	X NN
One Time Key In	Main			PANEL SUB-ASSY, FRONT DOOR RH	1	1,249.60	1,249.60	25.00	937.20	Replace	0	0	Not Give	X NN
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	0	0	Not Give	X NN

Total Spare Part Cost 35,997.72

Surveyor Total 7,281.25

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 35,997.72

Final Sur Total 7,281.25

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			SENSOR, AIR BAG, FRONT, RH & LH	1	210.50	210.50	10.00	279.45	Replace	0	0	Check	X N/A
One Time Key In	Main			FENDER SUB-ASSY, FR, LH	1	922.10	922.10	25.00	691.55	Replace	0	0	Not Give	X N/A
One Time Key In	Main			EMBLEM, SIDE PANEL (HYBRID)	1	52.90	52.90	25.00	39.67	Replace	0	0	Not Give	X N/A
One Time Key In	Main			INSULATOR, HOOD	1	293.90	293.90	25.00	220.42	Replace	1	293.90	Replace	/ CR
One Time Key In	Main			INSULATOR, HOOD CLIP	6	2.30	13.80	25.00	10.35	Replace	0	10.35	Replace	/ MC
One Time Key In	Main			HINGE ASSY, HOOD, LH	1	57.00	57.00	25.00	42.75	Replace	1	42.75	Replace	/ OT
One Time Key In	Main			HINGE ASSY, HOOD, RH	1	57.00	57.00	25.00	42.75	Replace	1	42.75	Replace	/ BT
One Time Key In	Main			LOCK ASSY, HOOD	1	121.10	121.10	25.00	90.82	Replace	0	0	Check	X N/A
One Time Key In	Main			CABLE ASSY, HOOD	1	53.20	53.20	25.00	39.90	Replace	0	0	Not Give	X N/A
One Time Key In	Main			MOULDING RH	1	83.30	83.30	25.00	62.47	Replace	0	0	Not Give	X N/A
One Time Key In	Main			WIPER GARNISH LOUVER SUB-ASSY	1	566.90	566.90	25.00	500.17	Replace	0	0	Not Give	X N/A
One Time Key In	Main			WIPER GARNISH SHIELD, COWL WATER, LH	1	18.90	18.90	25.00	14.17	Replace	0	0	Not Give	X N/A
One Time Key In	Main			WIPER GARNISH SHIELD, COWL WATER, RH	1	18.90	18.90	25.00	14.17	Replace	0	0	Not Give	X N/A
One Time Key In	Main			PILLAR, FRONT BODY, RH	1	239.40	239.40	25.00	254.55	Replace	0	0	Not Give	X N/A
One Time Key In	Main			COVER SUB-ASSY, FRONT PILLAR, UPR RH	1	96.90	96.90	25.00	72.68	Replace	0	0	Check	X N/A
						Total Spare Part Cost		36,997.72		Surveyor Total		7,281.25		
						Lump Sum Discount (%)		0.00		Lump Sum Dis (%)		0		
						Final Spare Part Cost		36,997.72		Final Sur Total		7,281.25		

SMRT Recommendation											Surveyor Approval			
BOM Type	Coating Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			THERMISTOR ASSY	1	68.00	68.00	25.00	51.00	Replace	0	0	Check	* X NAI
One Time Key In	Main			COVER, RADIATOR	1	227.90	227.90	25.00	170.85	Replace	0	0	Check	* X NAI
One Time Key In	Main			SUPPORT S/A UPPER	1	264.90	264.90	25.00	273.67	Replace	0	0	Check	* X NAI
One Time Key In	Main			SUPPORT SUB-ASSY LOWER	1	297.40	297.40	25.00	298.05	Replace	0	0	Check	* X NAI
One Time Key In	Main			SUPPORT S/A LH	1	227.00	227.00	25.00	177.75	Replace	0	0	Check	* X NAI
One Time Key In	Main			SUPPORT S/A RH	1	227.00	227.00	25.00	177.75	Replace	0	0	Check	* Y NAI
One Time Key In	Main			BRACE, HOOD LOCK SUPPORT	1	76.20	76.20	25.00	57.15	Replace	0	0	Check	* X NAI
One Time Key In	Main			SUPPORT, RADIATOR UPPER LH	1	76.70	76.70	25.00	57.53	Replace	0	0	Check	* X NAI
One Time Key In	Main			SUPPORT, RADIATOR UPPER RH	1	76.70	76.70	25.00	57.53	Replace	0	0	Check	* Y NAI
One Time Key In	Main			UNIT, HEADLAMP , LH	1	2,303.90	2,303.90	10.00	2,303.01	Replace	0	0	Check	* X NAI
One Time Key In	Main			UNIT, HEADLAMP , RH	1	2,303.90	2,303.90	10.00	2,303.01	Replace	1	2,303.01	Replace	* / BR
One Time Key In	Main			COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	1	486.40	486.40	10.00	437.76	Replace	0	0	Check	* X NAI
One Time Key In	Main			HORN ASSY, HIGH	1	112.80	112.80	10.00	101.52	Replace	0	0	Check	* X NAI
One Time Key In	Main			HORN ASSY, LOW	1	112.80	112.80	10.00	101.52	Replace	0	0	Check	* X NAI
One Time Key In	Main			AIR CON CONDENSER ASSY	1	1,317.70	1,317.70	25.00	988.28	Replace	1	988.28	Replace	* / 00

Total Spare Part Cost 35,987.72

Surveyor Total 7,281.25

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 35,987.72

Final Sur Total 7,281.25

SMRT Recommendation											Surveyor Approval			
SOM Type	Coating Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			TUBE & ACCESSORY	1	\$74.40	\$74.40	25.00	430.80	Replace	0	0	Check +	X NM
One Time Key In	Main			HOSE SUB-ASSY, DISCHARGE	1	\$37.10	\$37.10	25.00	252.83	Replace	0	0	Check +	X NM
One Time Key In	Main			HOSE SUB-ASSY, SUCTION	1	\$41.90	\$41.90	25.00	406.42	Replace	0	0	Check +	X NM
One Time Key In	Main			PIPE SUB-ASSY, SUCTION	1	\$89.80	\$89.80	25.00	290.20	Replace	0	0	Check +	X NM
One Time Key In	Main			AIR CON COMPRESSOR ASSY	1	2,887.80	2,887.80	10.00	2,599.02	Replace	0	0	Check +	X NM
One Time Key In	Main			COOLANT	1	12.30	12.30	0.00	12.30	Replace	0	0	Check +	X NM
One Time Key In	Main			GUIDE, RADIATOR AIR	1	\$3.80	\$3.80	25.00	70.43	Replace	0	0	Check +	X NM
One Time Key In	Main			GUIDE, RADIATOR AIR, UPPER	1	44.70	44.70	25.00	33.53	Replace	0	0	Check +	X NM
One Time Key In	Main			GUIDE, RADIATOR AIR, LH	1	\$8.80	\$8.80	25.00	44.10	Replace	0	0	Check +	X NM
One Time Key In	Main			GUIDE, RADIATOR AIR, RH	1	\$4.80	\$4.80	25.00	40.96	Replace	0	0	Check +	X NM
One Time Key In	Main			SEAL, RADIATOR TO RH	1	\$4.80	\$4.80	25.00	16.80	Replace	0	0	Check +	X NM
One Time Key In	Main			RADIATOR ASSY	1	1,841.10	1,841.10	25.00	1,380.82	Replace	0	0	Check +	X NM
One Time Key In	Main			GROMMET (FOR RADIATOR LOWER SUPPORT)	2	12.70	25.40	25.00	19.06	Replace	0	0	Check +	X NM
One Time Key In	Main			CUSHION (FOR RADIATOR UPPER SUPPORT)	2	9.80	19.60	25.00	14.70	Replace	0	0	Check +	X NM
One Time Key In	Main			FAN RADIATOR, LH	1	181.80	181.80	25.00	136.20	Replace	0	0	Check +	X NM
Total Spare Part Cost						35,987.72		Surveyor Total		7,281.25				
Lump Sum Discount (%)						0.00		Lump Sum Dis (%)		0				
Final Spare Part Cost						35,987.72		Final Sur Total		7,281.25				

SMRT Recommendation											Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace Remarks
One Time Key In	Main			FAN RADIATOR , RH	1	233.00	233.00	25.00	174.75	Replace	0	0	Check * X NAI
One Time Key In	Main			FAN SHROUD RADIATOR	1	219.30	219.30	25.00	164.48	Replace	0	0	Check * X NAI
One Time Key In	Main			MOTOR, COOLING FAN , LH	1	543.30	543.30	10.00	488.97	Replace	0	0	Check * X NAI
One Time Key In	Main			MOTOR, COOLING FAN , RH	1	443.40	443.40	10.00	399.06	Replace	0	0	Check * X NAI
One Time Key In	Main			HOSE, RADIATOR , NO.1	1	42.80	42.80	25.00	32.10	Replace	0	0	Check * X NAI
One Time Key In	Main			HOSE, RADIATOR , NO.2	1	40.20	40.20	25.00	30.15	Replace	0	0	Check * X NAI
One Time Key In	Main			TANK, RESERVE SEALED W/O CAP	1	127.00	127.00	25.00	95.25	Replace	0	0	Check * X NAI
One Time Key In	Main			HOSE, WATER BYPASS , NO.1	1	37.40	37.40	25.00	28.05	Replace	0	0	Check * X NAI
One Time Key In	Main			HOSE, WATER BYPASS , NO.2	1	37.40	37.40	25.00	28.05	Replace	0	0	Check * X NAI
One Time Key In	Main			HOSE, WATER BYPASS , NO.3	1	20.10	20.10	25.00	15.08	Replace	0	0	Check * X NAI
One Time Key In	Main			HOSE, WATER BYPASS , NO.4	1	13.20	13.20	25.00	9.90	Replace	0	0	Check * X NAI
One Time Key In	Main			HOSE, WATER BYPASS , NO.5	1	37.90	37.90	25.00	28.42	Replace	0	0	Check * X NAI
One Time Key In	Main			PIPE, WATER BYPASS , NO.1	1	11.00	11.00	25.00	8.25	Replace	0	0	Check * X NAI
One Time Key In	Main			PIPE, WATER BYPASS , NO.2	1	11.00	11.00	25.00	8.25	Replace	0	0	Check * X NAI
One Time Key In	Main			PIPE, WATER BYPASS , NO.3	1	58.40	58.40	25.00	43.80	Replace	0	0	Check * X NAI

Total Spare Part Cost 35,997.72

Lump Sum Discount (%) 0.00

Final Spare Part Cost 35,997.72

Surveyor Total 7,281.25

Lump Sum Dis (%) 0

Final Sur Total 7,281.25

SMRT Recommendation											Surveyor Approval				
BOM Type	Coasting Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks	
One Time Key In	Main			PIPE, RADIATOR	1	22.90	22.90	25.00	24.67	Replace	0	0	Check	* X NAI	
One Time Key In	Main			HOSE, RADIATOR , NO.3	1	29.60	29.60	25.00	22.20	Replace	0	0	Check	* X NAI	
One Time Key In	Main			HOSE, WATER BYPASS, NO.5	1	13.20	13.20	25.00	9.90	Replace	0	0	Check	* X NAI	
One Time Key In	Main			PIPE, WATER BYPASS, NO.5	1	31.80	31.80	25.00	23.85	Replace	0	0	Check	* X NAI	
One Time Key In	Main			HOSE, WATER BYPASS, NO.5	1	13.20	13.20	25.00	9.90	Replace	0	0	Check	* X NAI	
One Time Key In	Main			INVERTER WATER PUMP ASSY	1	422.00	422.00	10.00	388.80	Replace	0	0	Check	* X NAI	
One Time Key In	Main			HOSE, HV WATER PUMP INLET	1	37.90	37.90	25.00	28.42	Replace	0	0	Check	* X NAI	
One Time Key In	Main			HOSE, HV WATER PUMP OUTLET	1	29.60	29.60	25.00	22.20	Replace	0	0	Check	* X NAI	
One Time Key In	Main			TANK ASSY, INVERTER RESERVE	1	271.30	271.30	25.00	203.48	Replace	0	0	Check	* X NAI	
One Time Key In	Main			HOSE, INVERTER COOLING INLET	1	43.10	43.10	25.00	32.33	Replace	0	0	Check	* X NAI	
One Time Key In	Main			HOSE, INVERTER COOLING OUTLET	1	29.60	29.60	25.00	22.20	Replace	0	0	Check	* X NAI	
One Time Key In	Main			HOSE, INVERTER RADIATOR INLET	1	40.70	40.70	25.00	30.53	Replace	0	0	Check	* X NAI	
One Time Key In	Main			COOLER, MOTOR COOLING	1	248.10	248.10	10.00	223.29	Replace	0	0	Check	* X NAI	
One Time Key In	Main			WIRE, ENGINE ROOM MAIN	1	5,138.00	5,138.00	10.00	5,024.20	Replace	0	0	Not Give	* X NAI	
One Time Key In	Main			INLET, AIR CLEANER, NO 1	1	130.50	130.50	25.00	97.88	Replace	0	0	Check	* X NAI	
Total Spare Part Cost											35,997.72	Surveyor Total		7,281.25	
Lump Sum Discount (%)											0.00	Lump Sum Dis (%)		0	
Final Spare Part Cost											35,997.72	Final Sur Total		7,281.25	

SMRT Recommendation											Surveyor Approval			
BOM Type	Custling Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			INLET, AIR CLEANER, NO 2	1	83.90	83.90	25.00	70.43	Replace	0	0	Check	* X N/A
One Time Key In	Main			INLET, AIR CLEANER, NO 2	1	35.30	35.30	25.00	35.47	Replace	0	0	Check	* X N/A
One Time Key In	Main			CLAMP (FOR AIR CLEANER HOSE, NO.2)	1	9.00	9.00	25.00	6.75	Replace	0	0	Check	* X N/A
One Time Key In	Main			CLAMP (FOR AIR CLEANER INLET, NO.1)	2	7.10	14.20	25.00	10.65	Replace	0	0	Check	* X N/A
One Time Key In	Main			CLAMP (FOR RESONATOR INTAKE AIR)	1	7.10	7.10	25.00	5.33	Replace	0	0	Check	* X N/A
One Time Key In	Main			HOSE, AIR CLEANER, NO.1	1	62.10	62.10	25.00	46.58	Replace	0	0	Check	* X N/A
One Time Key In	Main			RESONATOR, INTAKE AIR	1	14.90	14.90	25.00	11.18	Replace	0	0	Check	* X N/A
One Time Key In	Main			BRACKET, AIR CLEANER	1	20.90	20.90	25.00	20.17	Replace	0	0	Check	* X N/A
One Time Key In	Main			AIR CLEANER ASSY	1	998.20	998.20	25.00	717.15	Replace	0	0	Check	* X N/A
One Time Key In	Main			TUBE, UNION (FOR AIR CLEANER HOSE)	1	19.40	19.40	25.00	14.55	Replace	0	0	Check	* X N/A
One Time Key In	Main			BODY ASSY, THROTTLE	1	1,942.45	1,942.45	10.00	1,748.15	Replace	0	0	Check	* X N/A
One Time Key In	Main			MANIFOLD, INTAKE	1	987.70	987.70	25.00	650.78	Replace	0	0	Check	* X N/A
One Time Key In	Main			COVER ASSY, ENGINE UNDER CENTER SET	1	492.90	492.90	25.00	328.90	Replace	0	0	Check	* X N/A
One Time Key In	Main			ABSORBER, FR BUMPER	1	70.30	70.30	25.00	52.72	Replace	0	0	Check	* X N/A
One Time Key In	Main			REINFORCEMENT FRONT UPPER	1	681.10	681.10	25.00	510.33	Replace	1	510.33	Replace	* / 00

Total Spare Part Cost 35,987.72

Surveyor Total 7,381.25

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 35,987.72

Final Sur Total 7,381.25

SMRT Recommendation											Surveyor Approval			
BoM Type	Coating Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			ABSORBER, FH BUMPER LOWER	1	117.00	117.00	25.00	87.75	Replace	1	87.75	Replace *	/ CRV
One Time Key In	Main			REINFORCEMENT FRONT LOWER	1	238.80	238.80	25.00	179.88	Replace	1	179.88	Replace *	/ DO
One Time Key In	Main			EXTENSION SUBASSY, LH	1	116.30	116.30	25.00	87.23	Replace	0	0	Check *	X NAI
One Time Key In	Main			EXTENSION SUBASSY, RH	1	116.30	116.30	25.00	87.23	Replace	0	0	Check *	X NAI
One Time Key In	Main			LAMP ASSY, FOG, RH	1	819.20	819.20	10.00	819.18	Replace	1	819.18	Replace *	/ DR
One Time Key In	Main			COVER ASSY, ENGINE	1	180.10	180.10	25.00	135.07	Replace	0	0	Check *	X NAI
One Time Key In	Main			HOOD SUB-ASSY	1	938.40	938.40	25.00	703.80	Replace	1	703.80	Replace *	/ DO
Total Spare Part Cost									35,997.72		Surveyor Total		7,281.25	
Lump Sum Discount (%)									0.00		Lump Sum Dis (%)		0	
Final Spare Part Cost									35,997.72		Final Sur Total		7,281.25	

Labour's Cost Detail

S.No.	Coating Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT PORTION	1,521.00	1,000	
Total:			1,521.00	1,000.00	

Spray Cost Detail

S.No.	Coating Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200	
2	Main	TO REPSRAY FRONT HOOD	378.00	200	
3	Main	TO REPSRAY FRONT SUPPORT PANEL	180.00	0	
4	Main	TO REPSRAY RADIATOR SUPPORT LOWER	180.00	0	
5	Main	TO REPSRAY FRT MEMBER,RH	180.00	0	
Total:			2,796.00	400.00	

S.No.	Coating Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
6	Main	TO RESPRAY FRONT FENDER RH	278.00	200	
7	Main	TO RESPRAY FRONT FENDER LH	278.00	0	
8	Main	TO RESPRAY APRON PANEL, RH	180.00	0	
9	Main	TO RESPRAY FRONT DOOR RH	278.00	0	
10	Main	TO RESPRAY FRONT PILLAR RH	180.00	0	
Total:			2,790.00	800.00	

Other Cost Detail

S.No.	Coating Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TOWING CHARGE	120.00	0 90 /	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	90.00	20	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	20	
4	Main	TO TOP UP A/C GAS	120.00	50	
5	Main	TO ALIGN CHASSIS	300.00	0	
6	Main	TO CHECK & RESET SYSTEM FUNCTION	300.00	0	
7	Main	TO REMOVE AND REFIT WIRE HARNESS	300.00	0	
8	Main	TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSEY & INNER COOLER & AIR CON CONDENSER	120.00	50	
9	Main	TO REPLACE SUNDRY PARTS	100.00	0.00	
10	Main	TO WASH AND VACUUM	60.00	0	
Total:			1,806.00	140.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	35,997.72	7,281.25
Time Labour Cost	1,521.00	1,800.00
Total Spray Painting	2,790.00	800.00
Other	1,806.00	140.00

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Overall Total	42,114.72	8,021.25
Lump Sum Repair Option		
Lump Sum Total	8.00	8,021.25
Surveyor Approved Amount		8,021.25
No of Repair Days	12	8
Remarks		3/3 repair, photo before paint
Surveyor Name		Hasee Jia
Signature		
		Save Clear
Survey Date	30/05/2019	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REQUEST FOR SUPPLEMENT PARTS

Contractor:		WEGA ENGINEERING PTE LTD	
Accident Case Number	7AX/05/19/2126	Date of Collection	2015/19
Vehicle No	SHP 362 D	Date of Request	1/5/19
Vehicle Model	2007A PRIUS 4	Number of Days to Extend (If any)	3 DAYS

S/N	Part Number	Part Description	Quantity	Unit Price
	1403,04	Wiper Washer Jar		\$183.60 ✓
	1414,15,16,17 N57,58,59	Support S/A Upper		\$364.90 ✓
	1454,55,56	Support S/A LH		\$237.00 ✓
	1423,24,44,50 51	Support S/A RH		\$237.00 ✓
	1452,53	Bruce Hood Lock Support		\$76.20 ✓
	1411,12,13 1505,06	Support Radiator Upper RH		\$76.70 ✓
	1463,54,85	Radiator Assy		\$1841.10 ✓
	1466,87	Fan Shroud Radiator		\$219.30 ✓

DEF \$137.70
BVC \$273.68
BT \$177.75
BT \$177.75
BT \$57.15
BT \$57.53
BVC \$180.81
CRA \$164.48

Please submit photographs for damaged parts

I, (Name)

CHIA

(Position)

Do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

Signature of person making this declaration

(To be signed in front of an authorised witness)

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission

①

REQUEST FOR SUPPLEMENT PARTS

WEGA ENGINEERING PTE LTD			
Contractor:			
Accident Case Number	TAT/05/19/2126	Date of Collection	30/5/19
Vehicle No	S4F 362 D	Date of Request	1/6/19
Vehicle Model	TOYOTA PRIUS 4	Number of Days to Extend (If any)	

S/N	Part Number	Part Description	Quantity	Unit Price
	1456, 84	Motor Cooling Fan LH	(1mm)	\$543.50 ✓
	1450, 1	Motor Cooling Fan RH	(1mm)	\$443.40 ✓
	1493, 44	Fan Radiator LH		\$181.80 ✓
	1491, 52	Fan Radiator RH		\$233.00 ✓
	1475, 79, 80	Inlet Air Cleaner NO 1		\$130.50 ✓
	1409, 10, 18, 19	Inlet Air Cleaner NO 2		\$93.40 ✓
	1405, 06, 07	Inlet Air Cleaner NO 3		\$35.30 ✓
	1475, 76, 77	Air Cleaner Assy		\$956.20 ✓

\$497.63
 Jan ~~\$332.50~~
 Jan \$332.50
 CRA \$171.71
 CRA \$174.72
 CRA \$197.88
 DEF \$70.43
 CRA \$26.4
 CRA \$717.11

Please submit photographs for damaged parts

I, (Name) CHIA
 (Position) _____

Do solemnly and sincerely declare that Supplementary Parts are raised for replacement for the aforesaid vehicle.

 Signature of person making this declaration
 [To be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff	
Acknowledge By	ARC Executive / Supervisor / SA
Approval By	Surveyor / In-house Staff
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC
Photo Submitted	YES / NO
	Date of submission

(2)

REQUEST FOR SUPPLYMENT PARTS

WEGA ENGINEERING PTE LTD			
Contractor:			
Accident Case Number	TAX/05/19/2126	Date of Collection	30/5/19
Vehicle No	SHP 3620	Date of Request	1/6/19
Vehicle Model	TOYOTA PRINS 4	Number of Days to Extend (If any)	

S/N	Part Number	Part Description	Quantity	Unit Price
	1397,98,99	Fender & L Assy Fr RH		\$933.10 ✓
	1460,61	Guide Radiator Air RH		\$54.60 ✓
	1466,67,68,69,70,71,72,73	Front Windscreen Assy		\$1626.40 ✓
		Front Windscreen Moulding		\$48.50 ✓
		Windscreen Sealant	2 BTL	\$46.00 ✓
		Coolant		\$12.00 ✓
		To Remove & Refit Windscreen		\$160.00
	1465,96,97	To Repair Frt Chassis Member		\$350.00

BVC \$699.83
DEF \$4095
CRA \$1219.1
rec \$37
rec \$74
rec \$12.3
\$100
\$2.00

Please submit photographs for damaged parts

I, (Name) CHIA

(Position)

Do solemnly and sincerely declare that: Supplementary Parts are raised for replacement for the aforesaid vehicle.

.....


Signature of person making this declaration
(To be signed in front of an authorised witness)

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission

③

REQUEST FOR SUPPLYMENT PARTS

Contractor:		WEGA ENGINEERING PTE LTD	
Accident Case Number	78X/05/19/2126	Date of Collection	30.5.19
Vehicle No	S4F 362 D	Date of Request	1.6.19
Vehicle Model	TOYOTA PRIUS 4	Number of Days to Extend (If any)	

S/N	Part Number	Part Description	Quantity	Unit Price
	1503, 04	To Repair Pnt LH Fender		\$200.00 \$200
		To Respray Pnt LH Fender		\$375.00 \$200


Please submit photographs for damaged parts

I, (Name)

CAIA

(Position)

Do solemnly and sincerely declare that: Supplementary Parts are raised for replacement for the aforesaid vehicle.

.....


Signature of person making this declaration
 [To be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission

(4)