



新友合汽车私人有限公司
SIN YEW HUP AUTO PTE LTD
 393M, Woodlands Road, Yew Tee Industrial Estate, Singapore 677981
 Tel: 6760 0819 Fax: 6769 0221 Email: syhapl@singnet.com.sg
 Specialise in Insurance Claims and General Motor Repair Work

31 MAY 2019

THIRD PARTY CLAIM

Third Party Vehicle No : SMJ2415S
 Date of Accident : 28/05/2019

C B CHUA CONSTRUCTION

C/o 393M Woodlands Road
 Yew Tee Industrial Estate
 Singapore 677981

COST OF REPAIR TO NISSAN CABSTAR : GY5195Z

A) Chassis No : JN1SF4F23Z0854246

B) Date of Registration : 04/05/2005

S/No.	Pc/s	Item(s) :-
01.	1	TAIL GATE
02.	1	TAIL GATE NISSAN STICKER
03.	1	TAIL LAMP COMPLETE LH
04.	1	RAER DECK STOPPER LH
05.	1	REAR DECK NISSAN STICKER
06.	1	REAR NUMBER PLATE BRACKET

\$
 1,399.70 *Rx*
 141.80 *ne*
 148.70 *con*
 8.90 *bt*
 25.70 *ne*
 65.30 *bt*

1,790.10

Less 10% discount :-

179.01

1,611.09

Special Nett(s) :-

07.	1	TAIL GATE 70KM/H STICKER
08.	1	TAIL GATE 13 PAX STICKER
09.	1	REAR NUMBER PLATE
10.	1	REVERSE SENSOR

15.00 *ne*
 15.00 *ne*
 20.00 *bt*
 280.00 *200 mq* ✓

1,941.09

Labour Charges :

- a) To dismantle all damaged parts, panel beat / straighten rear deck, all dents , check , adjust, replace and re-align the above parts
- b) To putty and spray paint tail gate, rear deck and all affected portions
- c) To anti rusty rear affected portions
- d) To replace reverse sensor and check wiring

400.00 ✓

400.00 ✓

80.00 *30*

100.00 *30*

2,921.09

GST (7%) :-

204.48

Total :-

3,125.57

=====

Tanfm 97495749
 'wp' 31/5/19 @ 340pm.

Lumpsum
 Resum after repair

4 days

tanfm@khaan.com.