



Co./GST Regn. No. 200921075G

新友合汽车私人有限公司 SIN YEW HUP AUTO PTE LTD

393M, Woodlands Road, Yew Tee Industrial Estate, Singapore 677981
Tel: 6760 0819 Fax: 6769 0221 Email: syhapt@singnet.com.sg
Specialise in Insurance Claims and General Motor Repair Work

31 MAY 2019

THIRD PARTY CLAIM

Third Party Vehicle No : SMJ2415S

Date of Accident : 28/05/2019

C B CHUA CONSTRUCTION

C/o 393M Woodlands Road

Yew Tee Industrial Estate

Singapore 677981

COST OF REPAIR TO NISSAN CABSTAR : GY5195Z

A) Chassis No : JN1SF4F23Z0854246

B) Date of Registration : 04/05/2005

S/No.	Pc/s	Item(s) :-	\$
01.	1	TAIL GATE	1,399.70
02.	1	TAIL GATE NISSAN STICKER	141.80
03.	1	TAIL LAMP COMPLETE LH	148.70
04.	1	RAER DECK STOPPER LH	8.90
05	1	REAR DECK NISSAN STICKER	25.70
06	1	REAR NUMBER PLATE BRACKET	65.30

			1,790.10
Less 10% discount :-			179.01

			1,611.09

<u>Special Nett(s) :-</u>			
07.	1	TAIL GATE 70KM/H STICKER	15.00
08.	1	TAIL GATE 13 PAX STICKER	15.00
09.	1	REAR NUMBER PLATE	20.00
10.	1	REVERSE SENSOR	280.00

			1,941.09
<u>Labour Charges :</u>			
a)	To dismantle all damaged parts, panel beat / straighten rear deck, all dents , check , adjust, replace and re-align the above parts		400.00
b)	To putty and spray paint tail gate, rear deck and all affected portions		400.00
c)	To anti rusty rear affected portions		80.00
d)	To replace reverse sensor and check wiring		100.00

			2,921.09
GST (7%) :-			204.48

Total :-			3,125.57
