

ETKA - Order Form

Order Form:

SLT3810L

14:14

30.05.2019

Item Description	Remark	Model	Qty	SGD	D
81A 821 105 VIN: WAUZZZGA4HA060138 Wing Location : 1C08-E Stock : +3.00	left		1	1047,00	/ 00
81A 821 106 VIN: WAUZZZGA4HA060138 Wing Location : 1D07-E Stock : +2.00	right		1	1047,00	/ 00
81A 098 625 VIN: WAUZZZGA4HA060138 attachment parts for one fender Location : A01-B-5 Stock : +1.00			2	71,40	?
81A 821 471 VIN: WAUZZZGA4HA060138 Bracket Location : AA03-C-3 Stock : +4.00	left		1	13,80	/ 00
81A 821 472 VIN: WAUZZZGA4HA060138 Bracket Location : BB02-D-5 Stock : 0	right		1	13,80	/ 00
81A 821 467 VIN: WAUZZZGA4HA060138 Bracket Location : CC01-C-4 Stock : +1.00	left		1	42,60	/ 00
81A 821 468 VIN: WAUZZZGA4HA060138 Bracket Location : BB02-D-3 Stock : 0	right		1	42,60	/ 00
81A 821 469 VIN: WAUZZZGA4HA060138 Bracket Location : AA10-E-3 Stock : +1.00	left		1	13,80	/ 00
81A 821 470 VIN: WAUZZZGA4HA060138 Bracket Location : BB04-B-3 Stock : 0	right		1	13,80	/ 00
N 016 185 7 VIN: WAUZZZGA4HA060138 Pop rivet Location : K06-B-1 Stock : +477.00	3.2X6.0		12	36,00	- 00



Audi

ETKA - Order Form

Order Form:

SLT3810L

14:14

30.05.2019

Item Description	Remark	Model	Qty	SGD	D
81A 821 135 VIN: WAUZZZGA4HA060138 Brace Location : AA09-C-4 Stock : +4.00	left		1	28,80	9
81A 821 136 VIN: WAUZZZGA4HA060138 Brace Location : AA05-E-2 Stock : +1.00	right		1	28,80	/ 00
81A 821 112 VIN: WAUZZZGA4HA060138 Closing element Location : EE04-B Stock : +2.00	right		1	29,70	/ APC
81A 864 236 VIN: WAUZZZGA4HA060138 Insulation for wing Stock : 0	right		1	68,80	/ CR4
81A 864 237 VIN: WAUZZZGA4HA060138 Seal Wheel housing liner Location : PF02-E-1 Stock : 0	upper		2	65,20	/ APC
81A 821 171 B VIN: WAUZZZGA4HA060138 Wheel housing liner Location : 1D06-C Stock : +4.00	left	PR-FMO	1	182,50	/ CR4
81A 821 172 B VIN: WAUZZZGA4HA060138 Wheel housing liner Stock : 0	right	PR-FMO	1	182,50	/ CR4
81A 098 629 VIN: WAUZZZGA4HA060138 1 set attachment parts for wheel housing liner Location : A04-F-3 Stock : +4.00			2	103,00	/ APC
81A 823 029 VIN: WAUZZZGA4HA060138 Bonnet Location : 2B06-C Stock : +6.00			1	2549,00	/ 00
81A 098 615 VIN: WAUZZZGA4HA060138 1 set attachment parts for bonnet Location : A01-B-6 Stock : +1.00			1	149,00	X



Audi

ETKA - Order Form

Order Form:

SLT3810L

14:14

30.05.2019

Item Description	Remark	Model	Qty	SGD	D
81A 823 301 D VIN: WAUZZZGA4HA060138 Lid hinge D - 20.03.2017>> Stock : 0	left		1	55,30	✓ 00
81A 823 302 D VIN: WAUZZZGA4HA060138 Lid hinge D - 20.03.2017>> Stock : 0	right		1	55,30	✓ 00
81A 823 359 A VIN: WAUZZZGA4HA060138 Gas filled strut D - 12.12.2016>> Location : CC01-A Stock : +2.00			1	92,40	X
5Q0 823 402 VIN: WAUZZZGA4HA060138 Bracket for gas filled strut Stock : 0	right		1	31,00	X
81A 823 185 A VIN: WAUZZZGA4HA060138 Striker Location : BB04-B-3 Stock : +1.00			1	99,40	✓ 00
81A 823 186 A VIN: WAUZZZGA4HA060138 Striker Stock : 0			1	99,40	✓ 00
81A 863 825 VIN: WAUZZZGA4HA060138 sound abs. for engine bonnet Stock : 0			1	201,00	X
81A 823 124 VIN: WAUZZZGA4HA060138 Impact protection Location : L04-A Stock : +2.00	center -nrc		1	26,50	✓ nrc
81A 823 125 VIN: WAUZZZGA4HA060138 Impact protection Location : BB12-B-6 Stock : +1.00	left -nrc		1	27,50	✓ nrc
81A 823 126 VIN: WAUZZZGA4HA060138 Impact protection Location : BB12-B-5 Stock : +1.00	right -nrc		1	26,50	✓ nrc



Audi

ETKA - Order Form


Order Form:

SLT3810L

14:14

30.05.2019

Item Description	Remark	Model	Qty	SGD	D
8EO 863 727 A VIN: WAUZZZGA4HA060138 Retaining clip Location : BB04-B-4 Stock : +15.00			2	2,00	
81A 821 170 VIN: WAUZZZGA4HA060138 Cover Location : EE08-E-1 Stock : +1.00	<i>Fender inner</i> right		1	36,80	/ CR4
81A 821 654 VIN: WAUZZZGA4HA060138 Cover	" " right		1	13,80	/ CR4
81C 819 403 9B9 VIN: WAUZZZGA4HA060138 Cover for plenum chamber Satin black Stock : 0	front RHD		1	143,50	X
81A 806 239 VIN: WAUZZZGA4HA060138 water box Front panel D >> - 18.02.2019			1	124,00	X
81A 823 509 A VIN: WAUZZZGA4HA060138 Lid lock with micro-switch Location : BB01-C-2 Stock : +1.00			21	367,00	/ DP
81A 823 531 VIN: WAUZZZGA4HA060138 Bowden cable Stock : 0	center		1	52,10	?
81C 823 535 VIN: WAUZZZGA4HA060138 Lid lock cable Stock : 0	rhd		1	66,70	?
4H0 823 543 VIN: WAUZZZGA4HA060138 Cover Location : BB05-D-5 Stock : +27.00			1	8,90	X
81A 823 529 A VIN: WAUZZZGA4HA060138 Release element Stock : 0			1	52,10	X
81A 823 656 VIN: WAUZZZGA4HA060138 Bowden cable Stock : 0	right		1	52,10	X



ETKA - Order Form

Order Form:

SLT3810L

14:14

30.05.2019

Item Description	Remark	Model	Qty	SGD	D
8W0 823 661 D VIN: WAUZZZGA4HA060138 release lever Location : BB01-B-2 Stock : +2.00			1	12,00	X
5Q0 951 221 J VIN: WAUZZZGA4HA060138 Fanfare Location : HH10-D Stock : +1.00	low tone left		1	261,50	X
3B0 951 223 E VIN: WAUZZZGA4HA060138 Signal horn Stock : 0	high tone right		1	179,50	X
81A 951 229 VIN: WAUZZZGA4HA060138 spring shackle Location : GG09-C-4 Stock : +1.00	left		1	28,40	X
81A 951 230 VIN: WAUZZZGA4HA060138 spring shackle Stock : 0	right		1	28,40	X
81A 853 717 4W3 VIN: WAUZZZGA4HA060138 wheel cover anthracite Location : L06-L Stock : +4.00	left front		1	293,50	/ MK
81A 853 718 4W3 VIN: WAUZZZGA4HA060138 wheel cover anthracite Location : 1F05-C-5 Stock : +4.00	right front		1	293,50	/ BR
81A 805 607 B VIN: WAUZZZGA4HA060138 Mounting for main beam headl. Location : AA05-A Stock : +1.00			1	107,00	/ BR
81A 805 608 C VIN: WAUZZZGA4HA060138 Mounting for main beam headl. Location : AA09-A Stock : 0			1	107,00	X /
81A 941 773 A VIN: WAUZZZGA4HA060138 LED headlight Location : 1C01-C Stock : +4.00	left	PR-AV0	1	4491,00	X /



Audi

ETKA - Order Form

Order Form:

SLT3810L

14:14

30.05.2019

Item Description	Remark	Model	Qty	SGD	D
81A 941 774 A VIN: WAUZZZGA4HA060138 LED headlight Location : 1C02-E Stock : +4.00	right	PR-AV0	1	4491,00	/
7FP 941 572 AC VIN: WAUZZZGA4HA060138 Power module for main light electronics Location : JJ04-D Stock : +5.00			1	692,50	/ SH
8S0 907 397 D VIN: WAUZZZGA4HA060138 Control unit for light control system Location : JJ04-D Stock : +3.00			1	507,50	/ SH
81A 998 474 VIN: WAUZZZGA4HA060138 LED with heat sink	right		1	665,50	/ TW
81A 941 718 VIN: WAUZZZGA4HA060138 Hose	right		1	25,90	?
81A 955 101 VIN: WAUZZZGA4HA060138 Lift cylinder for headlight washer system Location : JJ10-E-2 Stock : +2.00	left		1	127,50	X
81A 955 102 VIN: WAUZZZGA4HA060138 Lift cylinder for headlight washer system Location : JJ10-E-5 Stock : +2.00	right		1	127,50	X PR
7P6 955 964 A VIN: WAUZZZGA4HA060138 Hose on rollers for 5 m modify in workshop Location : GG08-E-3 Stock : +2.00			1	170,00	?
8D0 955 873 VIN: WAUZZZGA4HA060138 Distributor Location : GG11-E-3 Stock : +4.00			1	26,80	/ MC
6R0 955 665 VIN: WAUZZZGA4HA060138 Elbow fitting Location : GG11-C-4 Stock : +4.00	90 degree angle		3	81,00	/ MC



Audi

ETKA - Order Form

Order Form:

SLT3810L

14:14

30.05.2019

Item Description	Remark	Model	Qty	SGD	D
5Q0 955 453 BE VIN: WAUZZZGA4HA060138 Wash water reservoir Location : J10-A Stock : +2.00			1	156,00	?
81A 805 594 A VIN: WAUZZZGA4HA060138 <i>fl pol</i> Lock carrier with mounting for coolant radiator Location : 1G03-B Stock : +1.00		PR-TJ4+8Z6, 8Z9	1	907,00	<i>GR</i>
5Q0 816 411 AS VIN: WAUZZZGA4HA060138 A/C condenser with fluid reservoir Location : 1F03-D Stock : +2.00	KEIHIN		1	502,50	?
4D0 260 749 B VIN: WAUZZZGA4HA060138 seal ring Included in position: Location : C01-D-1 Stock : +20.00	7,6X2,5 6,7		1	3,00	?
3D0 260 749 C VIN: WAUZZZGA4HA060138 seal ring Included in position: Location : C01-D-3 Stock : +27.00	9,5X2,5 5		1	4,00	?
5Q0 820 741 B VIN: WAUZZZGA4HA060138 Refrigerant line (A/C condenser > cut-off point) Location : C14-A-2 Stock : +1.00			1	600,50	?
4D0 260 749 B VIN: WAUZZZGA4HA060138 seal ring Included in position: Location : C01-D-1 Stock : +20.00	7,6X2,5 6,7		2	6,00	
5Q0 816 721 AD VIN: WAUZZZGA4HA060138 Refrigerant line (A/C compressor > A/C condenser) Location : E13-A-3 Stock : +2.00			1	461,00	?



Audi

ETKA - Order Form

Order Form:

SLT3810L

14:14

30.05.2019

Item Description	Remark	Model	Qty	SGD	D
3D0 260 749 C VIN: WAUZZZGA4HA060138 seal ring Included in position: Location : C01-D-3 Stock : +27.00	9,5X2,5 5		1	4,00	
4E0 260 749 A VIN: WAUZZZGA4HA060138 seal ring Included in position: Location : C01-D-2 Stock : +2.00	11X2,5 5		1	3,60	
5Q0 121 251 GD VIN: WAUZZZGA4HA060138 Cooler for coolant Location : 1F05-D Stock : +1.00	650X414X24		1	878,00	?
5Q0 121 251 HS VIN: WAUZZZGA4HA060138 Additional cooler for coolant Location : 1F07-E Stock : +2.00			1	837,00	?
G A13 040 M2 VIN: WAUZZZGA4HA060138 Ready-mix coolant Frost protection up to -25 °C D >> - 08.07.2019 Location : 1J03-B Stock : +1059.00	1.5 Ltr.		4	84,00	/ HAC
5Q0 121 203 DE VIN: WAUZZZGA4HA060138 Radiator fan with fan ring Stock : 0	400W 440MM MAGNA		1	1483,00	X
81A 121 283 K VIN: WAUZZZGA4HA060138 Air guide D - 13.02.2017>> Location : J03-A Stock : 0	left	PR-2JB,2JF, 2JG,2JW+8Z6, 8Z9	1	26,70	X
81A 121 284 K VIN: WAUZZZGA4HA060138 Air guide D - 13.02.2017>> Location : J05-C Stock : 0	right	PR-2JB,2JF, 2JG,2JW+8Z6, 8Z9	1	26,70	?
81A 121 230 VIN: WAUZZZGA4HA060138 Seal Stock : 0	right outer	PR-KH6,9AK	1	5,60	



ETKA - Order Form

Order Form:

SLT3810L

14:14

30.05.2019

Item Description	Remark	Model	Qty	SGD	D
81A 121 285 VIN: WAUZZZGA4HA060138 Air guide Location : J05-C Stock : +1.00	upper centre		1	19,00	?
5Q0 129 254 B VIN: WAUZZZGA4HA060138 Air guide contains: 5Q0 129 654 E Location : J01-F Stock : +2.00			1	52,30	?
5Q0 129 618 J VIN: WAUZZZGA4HA060138 Air guide Location : B07-F-1 Stock : +2.00			1	61,50	?
5Q0 129 637 B VIN: WAUZZZGA4HA060138 Water drainage hose Location : B06-B-3 Stock : +2.00			1	30,60	?
04C 129 656 L VIN: WAUZZZGA4HA060138 Intake manifold D - 20.02.2017>> Location : B03-A Stock : +1.00			1	128,50	X
04C 129 601 G VIN: WAUZZZGA4HA060138 Air filter D >> - 19.06.2017 Stock : 0			1	251,50	X
81A 805 030 A VIN: WAUZZZGA4HA060138 Closing element	right		1	26,50	?
81A 810 126 A VIN: WAUZZZGA4HA060138 Side member	right		1	367,50	?
81A 809 840 VIN: WAUZZZGA4HA060138 Sectional part - pillar A/B with frame member	right - A - Pillar	RHS	1	1703,00	?
6L0 809 864 A VIN: WAUZZZGA4HA060138 rivetted cap nut Roof carrier Stock : 0	M6		2	5,00	
81A 831 052 C VIN: WAUZZZGA4HA060138 Door Location : 1F06-C Stock : +1.00	- Front Right		1	2285,00	✓ 00



Audi

ETKA - Order Form

Order Form:

SLT3810L

14:14

30.05.2019

Item Description	Remark	Model	Qty	SGD	D
81A 831 721 C VIN: WAUZZZGA4HA060138 door seal, inner Location : J12-G Stock : 0			1	146,00	OK
81A 098 619 VIN: WAUZZZGA4HA060138 1 set of attachment parts for door Stock : 0			1	84,80	X
81A 837 249 VIN: WAUZZZGA4HA060138 Door catch Location : BB06-B-3 Stock : +1.00	left a. right		1	109,00	?
WHT 003 237 VIN: WAUZZZGA4HA060138 Hexagon socket flat head bolt Location : K04-B-2 Stock : +40.00	M6X12		2	2,00	/
WHT 003 497 VIN: WAUZZZGA4HA060138 Hexagon socket oval head bolt (combi) Location : K04-B-1 Stock : +23.00	M8X23		1	2,10	
8X4 833 408 A VIN: WAUZZZGA4HA060138 Door hinge half- Upper part Location : DD10-C-6 Stock : 0	right upper		1	40,10	/ 00
8V5 833 404 C VIN: WAUZZZGA4HA060138 Door hinge half- Lower part Location : DD10-B-3 Stock : 0	right lower		2	80,80	/ 00
8X4 833 406 A VIN: WAUZZZGA4HA060138 Door hinge half- Upper part Location : AA08-B-2 Stock : 0	right lower		1	38,50	/ 00
81A 837 462 VIN: WAUZZZGA4HA060138 Window regulator without motor Location : 1D03-D-9 Stock : +2.00	right		1	240,50	/ 00



Audi

ETKA - Order Form

Order Form:

SLT3810L

14:14

30.05.2019

Item Description	Remark	Model	Qty	SGD	D
5Q0 959 801 B VIN: WAUZZZGA4HA060138 Window regulator motor Stock : 0	right		1	223,50	?
5Q0 959 593 E Z00 VIN: WAUZZZGA4HA060138 Door control unit Location : HH04-C Stock : 0	driver side		1	456,00	?
81C 857 410 B 9B9 VIN: WAUZZZGA4HA060138 Exterior mirror mounting with electric adjusting unit Satin black Stock : 0	rhd	PR-6XC,6XD	1	470,50	/ M7
81A 857 528 GRU VIN: WAUZZZGA4HA060138 Mirror cap primed Stock : 0	right	PR-6FA+7Y0, 7Y4,79A,79C	1	136,00	/ M7
81A 857 536 E VIN: WAUZZZGA4HA060138 mirror glass (aspherical- wide angle) with plate Stock : 0	right	PR-6TS+6XC, 6XD,6XE	1	282,00	X
81A 837 638 B 5FQ VIN: WAUZZZGA4HA060138 corner trim black-glossy Location : DD12-D-3 Stock : +1.00	right		1	41,00	X
81A 837 440 B VIN: WAUZZZGA4HA060138 Window guide			1	376,50	?
81A 837 478 VIN: WAUZZZGA4HA060138 Window aperture seal Stock : 0	right outer		1	119,00	/ M7
81A 853 960 4W3 VIN: WAUZZZGA4HA060138 cover for door anthracite Location : L05-E Stock : 0	right front		1	234,50	/ M7
81A 833 052 C VIN: WAUZZZGA4HA060138 Door Location : 1F06-C Stock : 0	- Right Rear		1	2285,00	/ AD



Audi

ETKA - Order Form


Order Form:

SLT3810L

14:14

30.05.2019

Item Description	Remark	Model	Qty	SGD	D
81A 839 912 A VIN: WAUZZZGA4HA060138 Outer door seal (self-adhesive) see workshop manual Location : DD02-A Stock : +2.00	right		1	118,50	/ M
D 355 205 A2 VIN: WAUZZZGA4HA060138 bonding agent Location : H07-E-2 Stock : +13.00	30ML		1	44,90	/ M
D 009 401 04 VIN: WAUZZZGA4HA060138 cleaning solution	250ML		1	64,60	/ M
D 009 500 25 VIN: WAUZZZGA4HA060138 applicator			1	6,80	/ M
81A 098 620 VIN: WAUZZZGA4HA060138 1 set of attachment parts for door Stock : 0			1	84,80	X
81A 839 249 VIN: WAUZZZGA4HA060138 Door catch Location : DD10-C-4 Stock : +2.00	left a. right		1	109,00	?
WHT 003 237 VIN: WAUZZZGA4HA060138 Hexagon socket flat head bolt Location : K04-B-2 Stock : +40.00	M6X12		2	2,00	/
WHT 003 497 VIN: WAUZZZGA4HA060138 Hexagon socket oval head bolt (combi) Location : K04-B-1 Stock : +23.00	M8X23		1	2,10	/
81A 853 970 4W3 VIN: WAUZZZGA4HA060138 cover for door anthracite Location : EE08-C-1 Stock : 0	right rear		1	206,00	/ M
81A 845 099 E NVB VIN: WAUZZZGA4HA060138 Windscreen (laminated) with colour strip not pretreated Location : 2A02-D-3 Stock : +2.00			1	913,00	?



ETKA - Order Form

Order Form: SLT3810L

14:14

30.05.2019

Item Description	Remark	Model	Qty	SGD	D
8U0 955 609 VIN: WAUZZZGA4HA060138 Gel foil for rain sensor (self-adhesive) Location : GG01-F-4 Stock : +64.00			1	128,00	?
D 009 200 02 VIN: WAUZZZGA4HA060138 primer	10ml		2	37,20	?
				----- 43488,70 3044,21 + 7.0% VAT 46532,91 -----	SGD



ETKA - Order Form

Order Form:

SLT3810L-AIRBAG

14:14

30.05.2019

SLT3810L-AIRBAG

Editor:

Item Description	Remark	Model	Qty	SGD	D
81A 857 705 A V04 VIN: WAUZZZGA4HA060138 three-point automatic seat belt with belt tensioner Black Stock : 0	- Seatbelt - LHS		1	952,00	/
533 867 910 A VIN: WAUZZZGA4HA060138 Felt strips (self-adhesive) 'order qty. 25' Location : BB10-B-5 Stock : +11.00	20X1X880MM left		1	21,20	/ MC
81A 857 706 A V04 VIN: WAUZZZGA4HA060138 three-point automatic seat belt with belt tensioner Black Stock : 0	- Seatbelt RHS		1	952,00	/
533 867 910 A VIN: WAUZZZGA4HA060138 Felt strips (self-adhesive) 'order qty. 25' Location : BB10-B-5 Stock : +11.00	20X1X880MM left		1	21,20	/ MC
4M0 857 819 VIN: WAUZZZGA4HA060138 Seat belt height adjuster for height adjustment Location : BB01-C-6 Stock : 0	left a. right		2	322,00	?
5Q0 959 655 AQ VIN: WAUZZZGA4HA060138 Control unit for airbag			1	1578,00	/ MC
5Q0 959 651 B VIN: WAUZZZGA4HA060138 Crash sensor for airbag Location : GG08-C-6 Stock : +5.00			2	763,00	/ MC
				----- 4609,40 + 7.0% VAT 322,66	



ETKA - Order Form

Order Form:

SLT3810L-AIRBAG

14:14

30.05.2019

Item Description	Remark	Model	Qty	SGD	D
				4932,06 *****	SGD



ETKA - Order Form

Order Form: SLT3810L-MECHANICAL


14:13

30.05.2019

SLT3810L-MECHANICAL

Editor:

Item Description	Remark	Model	Qty	SGD	D
81A 601 025 VIN: WAUZZZGA4HA060138 Aluminium rim Colour code: Stock : +2.00	6,5JX16H2 ET43 5/112 8Z8	PR-F32	2	1096,00	✓ 007
311 601 361 VIN: WAUZZZGA4HA060138 Rubber valve Location : G11-C-6 Stock : +75.00			4	12,40	✓ 118
3Q0 199 315 D VIN: WAUZZZGA4HA060138 Assembly carrier Stock : 0			1	718,00	?
N 912 010 01 VIN: WAUZZZGA4HA060138 hexagon head bolt (combi) Location : K08-F-4 Stock : +19.00	M14X1,5X50		1	15,20	?
N 910 661 01 VIN: WAUZZZGA4HA060138 hexagon head bolt (combi)	M10X35		1	7,60	?
N 911 671 01 VIN: WAUZZZGA4HA060138 bolt,hex.hd.with shoul.(combi)	M10X75		1	7,70	?
N 107 854 01 VIN: WAUZZZGA4HA060138 Hexagon flange screw (combi)	M12X1,5X95		4	42,40	?
N 912 312 01 VIN: WAUZZZGA4HA060138 Hexagon flange screw (combi)	M10X30		4	16,80	?
N 107 854 01 VIN: WAUZZZGA4HA060138 Hexagon flange screw (combi)	M12X1,5X95		2	21,20	?



ETKA - Order Form

Order Form:

SLT3810L-MECHANICAL

14:13

30.05.2019

Item Description	Remark	Model	Qty	SGD	D
N 912 177 01 VIN: WAUZZZGA4HA060138 bolt, hex. hd. with shoul. (combi)	M12X1,5X85		2	21,40	?
N 912 177 01 VIN: WAUZZZGA4HA060138 bolt, hex. hd. with shoul. (combi)	M12X1,5X85		2	21,40	?
N 015 081 6 VIN: WAUZZZGA4HA060138 Hexagon collar nut	M12X1,5		2	5,60	?
WHT 000 785 VIN: WAUZZZGA4HA060138 Hexagon collar nut	M12X1,5		2	14,80	?
N 103 320 02 VIN: WAUZZZGA4HA060138 Hexagon collar nut	M10		6	13,20	?
N 106 902 01 VIN: WAUZZZGA4HA060138 round hd. screw	M8X70		4	10,00	?
N 015 081 6 VIN: WAUZZZGA4HA060138 Hexagon collar nut	M12X1,5		2	5,60	?
N 105 524 02 VIN: WAUZZZGA4HA060138 Hex collared bolt	M12X1,5X70		2	21,40	?
81A 407 151 C VIN: WAUZZZGA4HA060138 track control arm, complete D - 07.11.2016>> - 10.06.2019 Stock : 0	left		1	331,50	?
N 912 177 01 VIN: WAUZZZGA4HA060138 bolt, hex. hd. with shoul. (combi) Location : K09-E-2 Stock : +5.00	M12X1,5X85		1	10,70	?
N 912 177 01 VIN: WAUZZZGA4HA060138 bolt, hex. hd. with shoul. (combi) Location : K09-E-2 Stock : +5.00	M12X1,5X85		1	10,70	?
N 015 081 6 VIN: WAUZZZGA4HA060138 Hexagon collar nut	M12X1,5		1	2,80	?
N 103 320 02 VIN: WAUZZZGA4HA060138 Hexagon collar nut	M10		3	6,60	?



ETKA - Order Form

Order Form: SLT3810L-MECHANICAL

14:13

30.05.2019

Item Description	Remark	Model	Qty	SGD	D
81A 407 152 C VIN: WAUZZZGA4HA060138 track control arm, complete marked with: D - 07.11.2016>> - 10.06.2019	right 5Q0 407 154 H		1	331,50	?
N 912 177 01 VIN: WAUZZZGA4HA060138 bolt, hex. hd. with shoul. (combi) Location : K09-E-2 Stock : +5.00	M12X1,5X85		1	10,70	?
N 912 177 01 VIN: WAUZZZGA4HA060138 bolt, hex. hd. with shoul. (combi) Location : K09-E-2 Stock : +5.00	M12X1,5X85		1	10,70	?
N 015 081 6 VIN: WAUZZZGA4HA060138 Hexagon collar nut	M12X1,5		1	2,80	?
N 103 320 02 VIN: WAUZZZGA4HA060138 Hexagon collar nut	M10		3	6,60	?
5Q0 411 303 R VIN: WAUZZZGA4HA060138 stabilizer, complete			1	371,50	?
N 106 902 01 VIN: WAUZZZGA4HA060138 round hd. screw Location : K06-E-4 Stock : 0	M8X70		4	10,00	?
N 015 081 6 VIN: WAUZZZGA4HA060138 Hexagon collar nut	M12X1,5		2	5,60	?
5Q0 407 253 A VIN: WAUZZZGA4HA060138 Wheel bearing housing Stock : 0	left 85MM		1	620,00	?
WHT 000 237 VIN: WAUZZZGA4HA060138 Ball screw Location : K04-F-3 Stock : +10.00	M12X1,5X45		3	31,20	?
WHT 005 437 VIN: WAUZZZGA4HA060138 dodecagonal head bolt D >> - 04.09.2017	M16X1,5X70		1	13,80	?
WHT 000 785 VIN: WAUZZZGA4HA060138 Hexagon collar nut	M12X1,5		1	7,40	?



ETKA - Order Form

Order Form:

SLT3810L-MECHANICAL

14:13

30.05.2019

Item Description	Remark	Model	Qty	SGD	D
N 909 548 02 VIN: WAUZZZGA4HA060138 Oval hexagon socket head bolt	M12X1,5X80		1	8,20	?
N 101 064 02 VIN: WAUZZZGA4HA060138 Hexagon collar nut self-locking	M12X1,5		1	2,80	?
WHT 005 538 VIN: WAUZZZGA4HA060138 Hexagon collar nut	M12X1,5		1	5,40	-
5Q0 407 254 A VIN: WAUZZZGA4HA060138 Wheel bearing housing	right 85MM		1	620,00	
WHT 000 237 VIN: WAUZZZGA4HA060138 Ball screw Location : K04-F-3 Stock : +10.00	M12X1,5X45		3	31,20	?
WHT 005 437 VIN: WAUZZZGA4HA060138 dodecagonal head bolt D >> - 04.09.2017	M16X1,5X70		1	13,80	?
WHT 000 785 VIN: WAUZZZGA4HA060138 Hexagon collar nut	M12X1,5		1	7,40	
N 909 548 02 VIN: WAUZZZGA4HA060138 Oval hexagon socket head bolt	M12X1,5X80		1	8,20	?
N 101 064 02 VIN: WAUZZZGA4HA060138 Hexagon collar nut self-locking	M12X1,5		1	2,80	
WHT 005 538 VIN: WAUZZZGA4HA060138 Hexagon collar nut	M12X1,5		1	5,40	?
8S0 498 625 A VIN: WAUZZZGA4HA060138 Wheel bearing with assembly parts Location : E05-G Stock : +2.00			2	884,00	?
3C0 407 365 B VIN: WAUZZZGA4HA060138 Guide joint Location : D12-F Stock : +1.00	left	PR-12A, 12B, 12K, 12U, 1LC, 1LJ	1	131,50	)



ETKA - Order Form

Order Form:

SLT3810L-MECHANICAL

14:13

30.05.2019

Item Description	Remark	Model	Qty	SGD	D
WHT 000 785 VIN: WAUZZZGA4HA060138 Hexagon collar nut Location : K06-E-3 Stock : +4.00	M12X1,5		1	7,40	?
N 103 320 02 VIN: WAUZZZGA4HA060138 Hexagon collar nut	M10		3	6,60	?
3C0 407 366 B VIN: WAUZZZGA4HA060138 Guide joint Location : D12-F Stock : +1.00	right	PR-1ZA, 1ZB, 1ZK, 1ZU, 1LC, 1LJ	1	131,50	?
WHT 000 785 VIN: WAUZZZGA4HA060138 Hexagon collar nut Location : K06-E-3 Stock : +4.00	M12X1,5		1	7,40	?
N 103 320 02 VIN: WAUZZZGA4HA060138 Hexagon collar nut	M10		3	6,60	
5Q0 411 315 B VIN: WAUZZZGA4HA060138 Coupling rod Location : D12-F Stock : +12.00			2	174,80	?
N 015 081 6 VIN: WAUZZZGA4HA060138 Hexagon collar nut Location : K08-C-3 Stock : +37.00	M12X1,5		4	11,20	?
5Q0 407 271 DC VIN: WAUZZZGA4HA060138 drive shaft with constant velocity joints Stock : 0	left tripodic		1	2208,00	?
WHT 005 437 VIN: WAUZZZGA4HA060138 dodecagonal head bolt D >> - 04.09.2017 Location : K04-B-2 Stock : +4.00	M16X1,5X70		1	13,80	?
N 909 910 02 VIN: WAUZZZGA4HA060138 Socket head bolt with inner multipoint head	M10X23		6	16,80	?



ETKA - Order Form

Order Form:	SLT3810L-MECHANICAL	14:13	30.05.2019
-------------	---------------------	-------	------------

Item Description	Remark	Model	Qty	SGD	D
5Q0 407 272 EA VIN: WAUZZZGA4HA060138 drive shaft with constant velocity joints Stock : 0	right tripodic		1	2208,00	7
WHT 005 437 VIN: WAUZZZGA4HA060138 dodecagonal head bolt D >> - 04.09.2017 Location : K04-B-2 Stock : +4.00	M16X1,5X70		1	13,80	7
N 909 910 02 VIN: WAUZZZGA4HA060138 Socket head bolt with inner multipoint head	M10X23		6	16,80	7
5Q0 413 031 HJ VIN: WAUZZZGA4HA060138 Gas shock absorber Stock : 0	54,6MM		2	559,00	7
N 910 216 01 VIN: WAUZZZGA4HA060138 Hexagon collar nut Location : K08-B-3 Stock : +12.00	M14X1,5		2	12,00	7
N 909 548 02 VIN: WAUZZZGA4HA060138 Oval hexagon socket head bolt	M12X1,5X80		2	16,40	7
N 101 064 02 VIN: WAUZZZGA4HA060138 Hexagon collar nut self-locking	M12X1,5		2	5,60	7
5Q0 412 331 E VIN: WAUZZZGA4HA060138 suspension strut storage D - 23.01.2017>> Location : D08-E Stock : +3.00			2	228,00	7
N 910 216 01 VIN: WAUZZZGA4HA060138 Hexagon collar nut Location : K08-B-3 Stock : +12.00	M14X1,5		2	12,00	7
N 909 548 02 VIN: WAUZZZGA4HA060138 Oval hexagon socket head bolt	M12X1,5X80		2	16,40	7
N 101 064 02 VIN: WAUZZZGA4HA060138 Hexagon collar nut self-locking	M12X1,5		2	5,60	7



Audi

ETKA - Order Form

Order Form:

SLT3810L-MECHANICAL

14:13

30.05.2019

Item Description	Remark	Model	Qty	SGD	D
5Q0 412 249 E VIN: WAUZZZGA4HA060138 Deep groove ball thrust bearing Location : D06-E-2 Stock : +3.00			2	85,00	0
N 910 216 01 VIN: WAUZZZGA4HA060138 Hexagon collar nut Location : K08-B-3 Stock : +12.00	M14X1,5		2	12,00	7
N 909 548 02 VIN: WAUZZZGA4HA060138 Oval hexagon socket head bolt	M12X1,5X80		2	16,40	7
N 101 064 02 VIN: WAUZZZGA4HA060138 Hexagon collar nut self-locking	M12X1,5		2	5,60	7
1K0 412 303 AA VIN: WAUZZZGA4HA060138 rubber stop for shock absorber Stock : 0	90MM		2	60,40	7
N 910 216 01 VIN: WAUZZZGA4HA060138 Hexagon collar nut Location : K08-B-3 Stock : +12.00	M14X1,5		2	12,00	7
N 909 548 02 VIN: WAUZZZGA4HA060138 Oval hexagon socket head bolt	M12X1,5X80		2	16,40	7
N 101 064 02 VIN: WAUZZZGA4HA060138 Hexagon collar nut self-locking	M12X1,5		2	5,60	7
sundries - 800 Front Ab plate - 40 X A1 sealant - 180 cl/wax - 140 stone chip - 180 Front w/s sealant - 200 LHS Front tyre - Refer to Kelvin about tyre brand/size - X1					
+ Tie rod end RHS - 118 + Tie rod end LHS - 118 + 7.0% VAT				11446,60 801,26 12247,86	SGD

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0694/2019/DY/TF
Date : 30-May-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Steve,
We took 43 days + 7 Sunday & 2 PH
Carrine - 31/10/2019

28 days

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Ng Chun Kiang
Address : Blk 331A Anchorvale Street
#14-553
Singapore 541331
Telephone : HP +65 90614099
Type of Claim : Own Damage Claims
Policy No. : 1700069141-01
Vehicle No : **SLT 3810 L**
Model Code : Audi Q2 1.0 TFSI S tronic
Model / Year : Oct-17
Engine No : CHZ 390331
Chassis No : WAUZZZGA4HA060138
Mileage : 34250
Date In : 28-May-19
Liability : -
Excess Cost : -
Estimated By : Allan Wu
Accident Date : 28-May-19
Place of Accident : West Coast Highway>Clementi-

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLT 3810 L

S/N	Nature of Jobs	Estimated Charges			
1	To tow and recover vehicle from scene of accident.	S/N	AIG		
2	To carry out first measurement test on car o-liner.	S/N	\$	800.00	\$ 800.00
3	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N	\$	360.00	\$ 360.00
4	To remove and renew aircon condenser, additional radiator, radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N	\$	1,400.00	\$ 1,400.00
5	To remove and reinstall centre console and dashboard assy for A-pillar renewal. To renew both front seatbelts and airbag control unit.	S/N	\$	3,200.00	\$ 3,200.00
SUB-TOTAL LABOUR CHARGES		:	\$	5,760.00	\$ 5,760.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLT 3810 L

S/N	Nature of Jobs		Estimated Charges	
		c/f		\$ 5,760.00
6	To remove and reinstall rhs front seat assy, ABCD pillar trims, sill trims, carpets, electronic components and fuse trays.	S/N	\$ 1,800.00	\$ 1,800.00
7	To remove and reinstall engine assy with gearbox assy to facilitate car o-liner repairs.	S/N	\$ 2,800.00	\$ 2,800.00
8	To remove and reinstall front suspension assy with subframe to facilitate car o-liner repairs. Inspect for damages and renew if necessary.	S/N	\$ 2,400.00	\$ 2,400.00
9	To renew front windscreen for A-pillar renewal.	S/N	\$ 480.00	
10	To place vehicle on car o-liner.	S/N	\$ 1,800.00	\$ 1,800.00
SUB-TOTAL LABOUR CHARGES		:	<u>\$ 9,280.00</u>	<u>\$ 14,560.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLT 3810 L

S/N	Nature of Jobs		Estimated Charges		
		<i>c/f</i>		\$	14,560.00
11	To dislodge and reinstall rhs A-pillar, rhs front doors and rhs rear door harness, multi-lock system and power window devices.	S/N	\$ 1,060.00	\$	1,060.00
12	To dismantle and renew front bumper, both headlights, both front fenders, rhs front door, rhs wing mirror assy and rhs rear door. Cut out and reweld rhs fender support and closing element and rhs A-pillar. Align both front chassis frames to specification of origin. Renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.		\$ 17,200.00	\$	9,000.00
13	To respray front bumper, bonnet, rhs A-pillar, rhs front fender top support, rhs front door, both front fenders, engine compartment, rhs wing mirror cover, door entrance, rhs rear door and hinges. To carry out joint sealant work and stone chip treatment.		\$ 9,400.00	\$	5,500.00
14	To renew rhs front rim, lhs front tyre and lhs front rim. To carry out wheel alignment.	S/N	\$ 320.00	\$	320.00
15	To carry out diagnostic check.	S/N	\$ 384.00	\$	384.00
TOTAL LABOUR CHARGES			\$ 43,404.00	\$	30,824.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLT 3810 L

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 1,706.00	\$ 1,364.00
2	FRONT BUMPER FIXING PARTS	\$ 314.00	
3	FRONT BUMPER GRILLE - CENTRE	\$ 179.00	
4	FRONT BUMPER AIR GRILLE - LH / RH	\$ 308.00	\$ 245.60
5	FRONT BUMPER AIR GRILLE EN CAP - LH / RH	\$ 62.00	\$ 48.80
6	FRONT BUMPER SPOILER	\$ 273.00	\$ 218.00
7	FRONT BUMPER CLOSING ELEMENT - CENTRE	\$ 142.00	
8	FRONT WHEEL SPOILER - LH / RH	\$ 62.00	\$ 49.12
9	FRONT BUMPER ADAPTER - LH / RH	\$ 70.00	\$ 55.92
10	RADIATOR GRILLE	\$ 1,301.00	
11	RADIATOR GRILLE STRICKER PLATE (TOP)	\$ 114.00	
12	FRONT BUMPER CARRIER	\$ 625.00	
13	FRONT BUMPER GUIDE SECTION - LH / RH	\$ 64.00	\$ 25.60
14	FRONT BUMPER TOP COVER - LH / RH	\$ 91.00	
15	FOAM FILLER PIECE	\$ 71.00	
16	FRONT BUMPER DISTANCE PIECE	\$ 12.00	
17	CAUTION STICKER	\$ 13.00	
18	A/C STICKER	\$ 7.00	
19	FRONT FENDER - LH / RH	\$ 2,094.00	\$ 1,675.20
20	FRONT FENDER ATTACHMENT PARTS	2 \$ 72.00	\$ 72.00
SUB-TOTAL SPARE PARTS		\$ 7,580.00	\$ 3,754.24

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.