

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183


6/6/19

Telefax

Name

: Steve (LKK)

Surveyed Date

: 31/5/19, 12.30pm

Authorised Date

: Not Authorise (Revert)

Excess Cost

: Excess - ?

Liability

: 18 days

Remarks

:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No. PA/00/0694/2019/DY/TF
Date 21-Jun-19
Service Advisor Glory Tan
Pages 1 OF 1
Regn No SLT 3810 L
Model No Audi Q2 1.0 TFSI S tronic

Quantity Description

Unit Price Amount

Parts

1	Engine mounting ✓
2	Gearbox mounting ✓
3	Hexagon flange screw
4	Front subframe support LHS ✓
5	Front subframe support RHS ✓
6	Shock absorber deep groove ball thrust bearing ✓
7	Shock absorber suspension strut storage ✓
8	Steering gear ✓
9	Track rod ✓
10	Repair set for steering box ✓

\$	216.00	BT ✓
\$	241.00	de ✓
\$	43.00	ner ✓
\$	22.00	bt ✓
\$	22.00	bt ✓
\$	43.00	bt ✓
\$	114.00	de ✓
\$	4,540.00	bt ✓
\$	172.00	bt ✓
\$	43.00	ner ✓

172.40
192.80
33.92
16.96
16.96
34
91.20
363.2
136.96
34.00

\$ 5,456.00

TOTAL

\$ 5,456.00

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No. PA/OD/0694/2019/DY/TF
Date 24-Aug-19
Service Advisor Glory Tan
Pages 1 OF 1
Regn No SLT 3810 L
Model No Audi Q2 1.0 TFSI S tronic

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Front fender top support upper part RHS	\$ 27.00	bt / 21.20
2	Chassis tag	\$ 423.00	acc / 338
3	Coolant pipe with inner heat exchanger	\$ 461.00	bt / 368.20
4	Pressure sensor refrigerant line	\$ 180.00	lost / 140.00
5	Noise insulation	\$ 239.00	cur / 191.20


\$ 1,330.00

TOTAL \$ 1,330.00

For Premium Automobiles Pte Ltd



Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLT 3810 L

		Damage Parts & Prices	
S/N	Parts Description	S/NETT	REMARKS
✓ 1	FRONT BUMPER	\$ 1,706.00	✓ OK
2	FRONT BUMPER FIXING PARTS	\$ 314.00	✓ OK
3	FRONT BUMPER GRILLE - CENTRE	\$ 179.00	?
✓ 4	FRONT BUMPER AIR GRILLE - LH / RH	\$ 308.00	✓ OK
✓ 5	FRONT BUMPER AIR GRILLE EN CAP - LH / RH	\$ 62.00	✓ OK
✓ 6	FRONT BUMPER SPOILER	\$ 273.00	✓ OK
7	FRONT BUMPER CLOSING ELEMENT - CENTRE	\$ 142.00	?
✓ 8	FRONT WHEEL SPOILER - LH / RH	\$ 62.00	✓ OK
✓ 9	FRONT BUMPER ADAPTER - LH / RH	\$ 70.00	✓
10	RADIATOR GRILLE	\$ 1,301.00	?
11	RADIATOR GRILLE STRICKER PLATE (TOP)	\$ 114.00	?
12	FRONT BUMPER CARRIER	\$ 625.00	?
sk-qr 13	FRONT BUMPER GUIDE SECTION - LH / RH	\$ 64.00	✓ OK
6/6 14	FRONT BUMPER TOP COVER - LH / RH	\$ 91.00	X
15	FOAM FILLER PIECE	\$ 71.00	?
16	FRONT BUMPER DISTANCE PIECE	\$ 12.00	?
17	CAUTION STICKER	\$ 13.00	X
18	A/C STICKER	\$ 7.00	X
✓ 19	FRONT FENDER - LH / RH	\$ 2,094.00	✓ OK
20	FRONT FENDER ATTACHMENT PARTS	2 \$ 72.00	✓ OK
SUB-TOTAL SPARE PARTS		\$ 7,580.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLT 3810 L

		Damage Parts & Prices	
S/N	Parts Description	S/NETT	REMARKS
121	FRONT FENDER TOP REAR BRACKET - LH / RH	\$ 28.00	✓ / 00
SK-air 6/b - 122	FRONT FENDER TOP FRONT BRACKET - LH / RH ✓	\$ 86.00	✓ / 00
SK-air 6/b - 123	FRONT FENDER TOP CENTER BRACKET - LH / RH ✓	\$ 28.00	✓ / 00
SK-air 6/b - 124	FRONT FENDER RIVET	\$ 36.00	✓ / 00
SK-air 6/b - 125	FRONT FENDER BRACE - LH / RH	\$ 58.00	✓ / 00
SK-air 6/b - 126	FRONT FENDER CLOSING ELEMENT - RH	\$ 30.00	✓ / 00
GER-V 7/b - 127	FRONT FENDER INSULATION - RH	\$ 69.00	✓ / 00
GER-V 7/b - 128	FRONT WHEEL HOUSING LINER SEAL - UPPER	2 \$ 66.00	✓ / 00
GER-V 7/b - 129	FRONT WHEEL HOUSING LINER - LH / RH ✓	\$ 366.00	✓ / 00
SK-air 6/b - 130	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	2 \$ 103.00	✓ / 00
SK-air 6/b - 131	BONNET	\$ 2,549.00	✓ / 00
132	BONNET ATTACHMENT PARTS	\$ 149.00	X
SK-air 6/b - 133	BONNET HINGE - LH / RH	\$ 112.00	✓ / 00
134	BONNET ABSORBER	\$ 93.00	X
135	BONNET ABSORBER BRACKET - RH	\$ 31.00	X
SK-air 6/b - 136	BONNET STRIKER	2 \$ 200.00	✓ / 00
137	BONNET SOUND ABSORBER	\$ 201.00	X
138	BONNET IMPACT PROTECTION	3 \$ 82.00	✓ / 00
139	FRONT FENDER TOP REAR COVER - RH (Fender cover)	\$ 37.00	✓ / 00
SK-air 6/b - 140	FRONT FENDER TOP REAR SMALL COVER - RH	\$ 14.00	✓ / 00
SUB-TOTAL SPARE PARTS		\$ 4,338.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLT 3810 L

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
41	PLENUM CHAMBER COVER	S	144.00 X
42	PLENUM CHAMBER PANEL	S	124.00 X
43	BONNET LOCK	21 S	367.00 / RR
44	BOWDEN CABLE	S	53.00 ?
45	BONNET LOCK CABLE	S	67.00 ?
46	BONNET LOCK CABLE COVER	S	9.00 X
47	BONNET RELEASE ELEMENT	S	53.00 X
48	BONNET BOWDEN CABLE	S	53.00 X
49	BONNET RELEASE LEVER	S	12.00 X
50	HORN - LOW TONE	S	262.00 X
51	HORN - HIGH TONE	S	180.00 X
52	HORN BRACKET	2 S	58.00 X
53	FRONT WHEEL ARCH TRIM - LH / RH	S	588.00 / RR
54	HEADLIGHT MOUNTING - LH / RH	S	214.00 / RR
55	HEADLIGHT - LH / RH	S	8,982.00 / RR
56	HEADLIGHT POWER MODULE	S	693.00 / RR
57	HEADLIGHT CONTROL MODULE	S	508.00 / RR
58	HEADLIGHT HEAT SINK	S	666.00 / RR
59	HEADLIGHT VENTILATION HOSE	S	26.00 ?
60	HEADLIGHT LIFT CYLINDER - LH / RH	S	256.00 / RR
SUB-TOTAL SPARE PARTS		S	13,315.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLT 3810 L

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
61	HEADLIGHT LIFT CYLINDER HOSE	\$ 170.00	?
✓ 62	HEADLIGHT LIFT CYLINDER HOSE JOINT	\$ 27.00	✓ OK
✓ 63	HEADLIGHT LIFT CYLINDER ELBOW FITTING	3 \$ 81.00	✓ OK
64	WATER RESERVOIR	\$ 156.00	?
✓ 65	LOCK CARRIER (for P1)	\$ 907.00	✓ OK
66	A/C CONDENSER	\$ 503.00	?
✓ 67	A/C REFRIGERANT LINE .h1/	\$ 601.00	?
✓ 68	A/C REFRIGERANT LINE - TO COMPRESSOR	\$ 461.00	?
69	RADIATOR	\$ 878.00	?
70	ADDITIONAL RADIATOR	\$ 837.00	?
✓ 71	COOLANT	\$ 84.00	✓ OK
72	RADIATOR FAN WITH RING	\$ 1,483.00	X
73	RADIATOR AIR GUIDE - LH / (RH)	\$ 54.00	X
74	RADIATOR SEAL - RH OUTER	\$ 6.00	?
75	RADIATOR AIR GUIDE - UPPER CENTRE	\$ 19.00	?
76	AIR DUCT AIR GUIDE - FRONT	\$ 53.00	?
77	AIR DUCT HOSE	\$ 62.00	?
78	AIR DUCT WATER DRAINAGE HOSE	\$ 31.00	?
79	INTAKE MANIFOLD SUCTION PIPE	\$ 129.00	X
80	AIR FILTER	\$ 252.00	X
SUB-TOTAL SPARE PARTS		\$ 6,794.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLT 3810 L

		Damage Parts & Prices	
S/N	Parts Description	S/NETT	REMARKS
81	FRONT FENDER REAR CLOSING ELEMENT - RH	\$ 27.00	OK
82	SIDE MEMBER - RH	\$ 368.00	?
83	A-PILLAR - RH	\$ 1,703.00	?
84	FRONT DOOR - RH	\$ 2,285.00	✓ PP
GER-V 7/b - 85	FRONT DOOR SEAL INNER - RH	\$ 146.00	✓ PP
86	FRONT DOOR ATTACHMENT PARTS	\$ 85.00	?
87	FRONT DOOR CATCH - LH	\$ 109.00	?
SK-air 6/b - 88	FRONT DOOR HINGE - UPPER RH	\$ 41.00	✓ PP
SK-air 6/b - 89	FRONT DOOR HINGE - LOWER RH	2 \$ 81.00	✓ PP
SK-air 6/b 90	FRONT DOOR HINGE UPPER PART - UPPER INNER RH	\$ 39.00	✓ PP
91	FRONT DOOR REGULATOR - RH	\$ 241.00	✓ PP
92	FRONT DOOR REGULATOR MOTOR- RH	\$ 224.00	?
93	FRONT DOOR CONTROL UNIT	\$ 456.00	?
SK-air 6/b - 94	WIND MIRROR MOUNTING - RH	\$ 471.00	✓ PP
SK-air 6/b - 95	WIND MIRROR CAP - RH	\$ 136.00	✓ PP
SK-air 6/b 96	WIND MIRROER GLASS - RH	\$ 282.00	?
97	FRONT DOOR CORNER TRIM - RH	\$ 41.00	?
98	FRONT DOOR WINDOW GUIDE - RH	\$ 377.00	?
SK-air 6/b - 99	FRONT DOOR WINDOW APERTURE SEAL - RH	\$ 119.00	✓ PP
SK-air 6/b 100	FRONT DOOR LOWER COVER	\$ 235.00	✓ PP
SUB-TOTAL SPARE PARTS		\$ 7,466.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved. Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLT 3810 L

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
GR-V 101	REAR DOOR - RH	\$ 2,285.00	✓ DD
7/6 102	REAR DOOR OUTER SEAL - RH	\$ 119.00	✓ DD
SK-air 103	BONDING AGENT	\$ 45.00	✓ DD
6/6 104	CLEANING SOLUTION	\$ 65.00	✓ DD
105	APPLICATOR	\$ 7.00	✓ DD
106	REAR DOOR ATTACHMENT PARTS	\$ 85.00	✓
107	REAR DOOR CATCH - RH	\$ 109.00	✓
SK-air 108	REAR DOOR LOWER COVER (Amul-g)	\$ 206.00	✓ DD
6/6 109	FRONT WINDSCREEN	\$ 913.00	✓
110	GEL FOIL	\$ 128.00	✓
111	PRIMER	2 \$ 38.00	✓
GR-air 112	FRONT SEATBELT - LH	\$ 952.00	✓ DD
7/6 113	FELT STRIPS	2 \$ 44.00	✓ DD
SK-air 114	FRONT SEAT BELT - RH	\$ 952.00	✓ DD
7/6 115	FRONT TOP SEAT BELT ADJUSTER	2 \$ 322.00	✓
SK-air 116	AIRBAG CONTROL UNIT	\$ 1,578.00	✓ DD
6/6 117	AIRBAG CRASH SENSOR	2 \$ 763.00	✓ DD
GR-V 118	FRONT RIM - LH / RH	2 \$ 1,096.00	✓ DD
7/6 119	RUBBER VALVE	\$ 13.00	✓ DD
120	FRONT SUB FRAME	\$ 718.00	✓
7/6	SUB-TOTAL SPARE PARTS	\$ 10,438.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLT 3810 L

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
121	FRONT SUB-FRAME BOLTS	\$ 209.00	
21/b 122	FRONT LOWER ARM - LH - bt ✓	\$ 332.00	
123	FRONT LOWER ARM BOLTS - LH	\$ 32.00	
21/b 124	FRONT LOWER ARM - RH - bt ✓	\$ 332.00	
125	FRONT LOWER ARM BOLTS - RH	\$ 32.00	
21/b 126	FRONT STABILIZER - bt ✓	\$ 372.00	
127	FRONT STABILIZER BOLTS	\$ 16.00	
21/b 128	FRONT WHEEL BEARING HOUSING - LH - bt ✓	\$ 620.00	
129	FRONT WHEEL BEARING HOUSING BOLTS - LH	\$ 72.00	
21/b 130	FRONT WHEEL BEARING HOUSING - RH - bt ✓	\$ 620.00	
131	FRONT WHEEL BEARING HOUSING BOLTS - RH	\$ 72.00	
21/b 132	FRONT WHEEL BEARING - LH / RH - bt ✓	\$ 884.00	
21/b 133	FRONT LOWER ARM BALL JOINT - LH - bt ✓	\$ 132.00	
134	FRONT LOWER ARM BALL JOINT BOLTS - LH	\$ 15.00	
21/b 135	FRONT LOWER ARM BALL JOINT - RH - bt ✓	\$ 132.00	
136	FRONT LOWER ARM BALL JOINT BOLTS - RH	\$ 15.00	
21/b 137	FRONT STABILIZER LINK - LH / RH - bt ✓	\$ 175.00	
138	FRONT DRIVE SHAFT - LH	\$ 2,208.00	
139	FRONT DRIVE SHAFT BOLTS - LH	\$ 31.00	
21/b 140	FRONT DRIVE SHAFT - RH - bt ✓	\$ 2,208.00	
SUB-TOTAL SPARE PARTS		\$ 8,509.00	

All charges are not inclusive of GST.

Legend Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLT 3810 L

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
141	FRONT DRIVE SHAFT BOLTS- RH	\$	31.00
2/b-142	FRONT ABSORBER - bt ✓	2 \$	559.00
143	FRONT ABSORBER BOLTS	\$	35.00
144	FRONT ABSORBER MOUNTING	2 \$	228.00
145	FRONT ABSORBER MOUNTING BOLTS	\$	35.00
146	FRONT ABSORBER BEARING	2 \$	85.00
147	FRONT ABSORBER STOPPER	2 \$	61.00
2/b-148	FRONT TIE ROD END - LH / RH - bt ✓	\$	236.00
149	ACRYLIC SEALANT	S/N \$	180.00
150	CAVITY WAX	S/N \$	140.00
151	STONE CHIP TREATMENT	S/N \$	180.00
152	FRONT WINDSCREEN SEALANT	S/N \$	200.00
153	FRONT TYRE - LH / RH x 2 70%	S/N	TBC / TN/CR
154	FRONT NO. PLATE	S/N \$	40.00 X
155	SUNDRIES	\$	800.00
TOTAL SPARE PARTS		:	\$ 61,250.00
TOTAL LABOUR CHARGES		:	\$ 43,404.00
GRAND TOTAL		:	\$ 104,654.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

PA/OD/0694/2019/DY/TF

Date

21-Jun-19

Service Advisor

Glory Tan

Pages

1 OF 1

Regn No

SLT 3810 L

Model No

Audi Q2 1.0 TFSI S tronic

Quantity Description

Unit Price

Amount

Parts

1	Engine mounting ✓
2	Gearbox mounting
3	Hexagon flange screw
4	Front subframe support LHS
5	Front subframe support RHS
6	Shock absorber deep groove ball thrust bearing
7	Shock absorber suspension strut storage
8	Steering gear
9	Track rod
10	Repair set for steering box

\$	216.00
\$	241.00
\$	43.00
\$	22.00
\$	22.00
\$	43.00
\$	114.00
\$	4,540.00
\$	172.00
\$	43.00

25/6
need another round Reby

\$ 5,456.00

TOTAL

\$ 5,456.00

For Premium Automobiles Pte Ltd



Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLT 3810 L

		Damage Parts & Prices	
S/N	Parts Description	S/NETT	REMARKS
81	FRONT FENDER REAR CLOSING ELEMENT - RH	\$ 27.00	OK ?
82	SIDE MEMBER - RH	\$ 368.00	?
83	A- PILLAR - RH	\$ 1,703.00	?
84	FRONT DOOR - RH	\$ 2,285.00	✓ DD
GER-V 7/6 85	FRONT DOOR SEAL INNER - RH	\$ 146.00	✓ INC
86	FRONT DOOR ATTACHMENT PARTS	\$ 85.00	X
87	FRONT DOOR CATCH - LH	\$ 109.00	?
SK-air 6/6 88	FRONT DOOR HINGE - UPPER RH	\$ 41.00	✓ DD
SK-air 6/6 89	FRONT DOOR HINGE - LOWER RH	2 \$ 81.00	✓ DD
90	FRONT DOOR HINGE UPPER PART - UPPER INNER RH	\$ 39.00	✓ DD
91	FRONT DOOR REGULATOR - RH	\$ 241.00	✓ DD
92	FRONT DOOR REGULATOR MOTOR- RH	\$ 224.00	?
93	FRONT DOOR CONTROL UNIT	\$ 456.00	?
SK-air 6/6 94	WIND MIRROR MOUNTING - RH	\$ 471.00	✓ CVT
SK-air 6/6 95	WIND MIRROR CAP - RH	\$ 136.00	✓ CVT
96	WIND MIRROER GLASS - RH	\$ 282.00	X
97	FRONT DOOR CORNER TRIM - RH	\$ 41.00	X
98	FRONT DOOR WINDOW GUIDE - RH	\$ 377.00	?
SK-air 6/6 99	FRONT DOOR WINDOW APERTURE SEAL - RH	\$ 119.00	✓ INC
100	FRONT DOOR LOWER COVER	\$ 235.00	✓ CVT
SK-air 6/6	SUB-TOTAL SPARE PARTS	\$ 7,466.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles Pte Ltd

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLT 3810 L

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0694/2019/NH

From
Telephone +65 -
Telefax +65 -
Mobile +65 -
Our Dept
Email

23-Mar-2020

Date
Total Pages

Dear Sir,

RE: INSURANCE CLAIM FOR SLT 3810 L – Audi Q2 1.0 TFSI S-TRONIC

With reference to the above-mentioned vehicle, no. **SLT 3810 L**, claimant, **Mr. Ng Chun Khiang**, please find the related document per attached.

1. A copy of the Original invoice no. 85014994 – S\$ 63,344.00.
2. A copy of the Discharge Voucher duly signed by client.

Premium Automobiles Pte Ltd,
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encl
AIG Insurance – SLT 3810 L

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 11:36

Company Reg.No.199902271W
GST Reg.No.199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120

Invoice: 85014994
Date: 20/03/2020
Order: SLT3810L
Term: 30

Account: A0006 (T 0)
AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

Regn No: SLT3810L (V 34402)

Regn Date: 26/10/2017

Mileage: 37044

WIP No: 54940

Model: Q2 1.0 TFSI S tronic GABANG

Chassis: WAUZZZGA4HA060138

Engine: CHZ 390331

DEPT: U

You have been assisted by:- UB-Kelvin Khoo (138)

		Details	Qty	Unit Price	Amount
S	SUBLET	To carry out contractual LIMIT repair basis as agreed	60,000.00	1.00	60,000.00
Q	EXC	Insurance Excess/Liability	-800.00	1.00	-800.00

Parts 0.00
Labour 0.00
Sublet 60,000.00
Menus 0.00
Lubricant 0.00

Sub- Total 59,200.00

7% GST 4,144.00

Grand Total 63,344.00



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLT 3810 L

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/069†/2019/KK
14 September 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE: CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi Q2 1.0 TFSI S TRONIC
Vehicle Chassis No. : WAUZZZGA4HA060138
Vehicle Regn No. : **SLT 3810 L**
Vehicle Mileage : 34250 KM
Vehicle Owner : Mr. Ng Chun Khiang
Certificate No : 1700069141-01
Own Damage Excess : \$856.00 (Inclusive GST)
Accident Date : 28/5/2019
Place : West Coast Highway > Clementi Rd Junction
Repair Cost : S\$ 63,344.00
WIP No. : 54940
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time :
Date : 16/9

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Jun 2019		03 Jun 2019 15:05 Edit Adj Rpt	S\$60,000.00 Edit Estimates	S\$60,000.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	NG CHUN KHIANG, ID: S8606873G, Tel: +6590614099, Email: JUNQIANGCK@HOTMAIL.COM		
Vehicle Reg. No.:	SLT3810L	Date of Loss:	28/05/2019 00:00 - :59 [19 Months and 2 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 3750110720SG	Policy/Cover Note No.:	1700069141 (Comprehensive)
		Excess:	S\$800.00
Repairer:	Premium Automobiles Pte Ltd (Benoi) 24 Benoi Sector, 629857 Pioneer - Tel: 67689911 / 63882323		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Chan, Yoke Shi] yokeshi.chan@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 13/06/2019]		
Driver/Custodian:	NG CHUN KHIANG (33 / Male) , NRIC: S8606873G, Tel: +6590614099 Email: JUNQIANGCK@HOTMAIL.COM		

ASSOCIATED MAIL RECEIVED

- [View All](#) [Compose Case Mail](#)
- AIG_SG (18/02/2020): Alert - Adj Mandate Approved (S\$60000.00) - SLT3810L - Claim Handler: Gan, Hunch...
 - AIG_SG (06/06/2019): Alert - Adj Mandate Approved (S\$60000.00) - SLT3810L - Claim Handler: Gan, Hunch...
 - AIG_SG (04/06/2019): SLT3810L / OD / 28/05/2019 / Coverage & Excess update

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLT3810L (3750110720SG)

OD

May 28 2019 12:00AM

[NG CHUN KHIANG]

Premium Automobiles Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View [View in Browser](#) ▼

Assessment Reports

1 per page ☒

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/06/19 11:01	Adjuster Immediate Advice	 Load HTM	☒

Photos/Images

3 per page ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/06/19 10:22	General View	 Load JPG ☒	☒
2	04/06/19 10:22	General View	 Load JPG ☒	☒
3	04/06/19 10:22	General View	 Load JPG ☒	☒
4	04/06/19 10:22	General View	 Load JPG ☒	☒
5	04/06/19 10:22	General View	 Load JPG ☒	☒
6	04/06/19 10:22	General View	 Load JPG ☒	☒
7	04/06/19 10:22	General View	 Load JPG ☒	☒
8	04/06/19 10:22	General View	 Load JPG ☒	☒
9	04/06/19 10:22	General View	 Load JPG ☒	☒
10	04/06/19 10:22	General View	 Load JPG ☒	☒
11	04/06/19 10:22	General View	 Load JPG ☒	☒
12	04/06/19 10:22	General View	 Load JPG ☒	☒
13	04/06/19 10:22	General View	 Load JPG ☒	☒
14	04/06/19 10:22	General View	 Load JPG ☒	☒
15	04/06/19 10:22	General View	 Load JPG ☒	☒
16	04/06/19 10:23	General View	 Load JPG ☒	☒
17	04/06/19 10:23	General View	 Load JPG ☒	☒
18	04/06/19 10:23	General View	 Load JPG ☒	☒
19	04/06/19 10:23	General View	 Load JPG ☒	☒
20	04/06/19 10:23	General View	 Load JPG ☒	☒
21	04/06/19 10:23	General View	 Load JPG ☒	☒
22	04/06/19 10:23	General View	 Load JPG ☒	☒
23	04/06/19 10:23	General View	 Load JPG ☒	☒
24	04/06/19 10:23	General View	 Load JPG ☒	☒
25	04/06/19 10:23	General View	 Load JPG ☒	☒
26	04/06/19 10:23	General View	 Load JPG ☒	☒
27	04/06/19 10:23	General View	 Load JPG ☒	☒
28	04/06/19 10:23	General View	 Load JPG ☒	☒
29	04/06/19 10:23	General View	 Load JPG ☒	☒
30	04/06/19 10:23	General View	 Load JPG ☒	☒
31	06/09/19 09:00	General View	 Load JPG ☒	☒
32	06/09/19 09:00	Chassis Number	 Load JPG ☒	☒
33	06/09/19 09:00	General View	 Load JPG ☒	☒

Assessment Reports			1 per page ▼	✓
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
34	06/09/19 09:00	General View	 Load JPG	✓
35	06/09/19 09:00	General View	 Load JPG	✓
36	06/09/19 09:00	General View	 Load JPG	✓
37	06/09/19 09:00	General View	 Load JPG	✓
38	06/09/19 09:00	General View	 Load JPG	✓
39	06/09/19 09:00	General View	 Load JPG	✓
40	06/09/19 09:00	General View	 Load JPG	✓
41	06/09/19 09:00	General View	 Load JPG	✓
42	06/09/19 09:00	General View	 Load JPG	✓
43	06/09/19 09:00	General View	 Load JPG	✓
44	06/09/19 09:00	General View	 Load JPG	✓
45	06/09/19 09:00	General View	 Load JPG	✓
46	06/09/19 09:00	General View	 Load JPG	✓
47	06/09/19 09:00	General View	 Load JPG	✓
48	06/09/19 09:00	General View	 Load JPG	✓
49	06/09/19 09:00	General View	 Load JPG	✓
50	06/09/19 09:00	General View	 Load JPG	✓
51	06/09/19 09:00	General View	 Load JPG	✓
52	06/09/19 09:00	General View	 Load JPG	✓
53	06/09/19 09:00	General View	 Load JPG	✓
54	06/09/19 09:00	General View	 Load JPG	✓
55	06/09/19 09:00	General View	 Load JPG	✓
56	06/09/19 09:00	General View	 Load JPG	✓
57	06/09/19 09:00	General View	 Load JPG	✓
58	06/09/19 09:00	General View	 Load JPG	✓
59	06/09/19 09:00	General View	 Load JPG	✓
60	06/09/19 09:00	General View	 Load JPG	✓
61	06/09/19 09:00	General View	 Load JPG	✓
62	06/09/19 09:00	General View	 Load JPG	✓
63	06/09/19 09:00	General View	 Load JPG	✓
64	06/09/19 09:00	General View	 Load JPG	✓
65	06/09/19 09:00	General View	 Load JPG	✓
66	06/09/19 09:00	General View	 Load JPG	✓
67	06/09/19 09:00	General View	 Load JPG	✓
68	06/09/19 09:00	General View	 Load JPG	✓
69	06/09/19 09:00	General View	 Load JPG	✓
70	06/09/19 09:00	General View	 Load JPG	✓
71	06/09/19 09:00	General View	 Load JPG	✓
72	06/09/19 09:00	General View	 Load JPG	✓
73	06/09/19 09:00	General View	 Load JPG	✓
74	06/09/19 09:00	General View	 Load JPG	✓
75	06/09/19 09:00	General View	 Load JPG	✓
76	06/09/19 09:00	General View	 Load JPG	✓
77	06/09/19 09:00	General View	 Load JPG	✓
78	06/09/19 09:00	General View	 Load JPG	✓
79	06/09/19 09:00	General View	 Load JPG	✓
80	06/09/19 09:00	General View	 Load JPG	✓
81	06/09/19 09:00	General View	Load JPG	✓

Assessment Reports			1 per page ▼	✓
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
82	06/09/19 09:00	General View	 Load JPG	✓
83	06/09/19 09:00	General View	 Load JPG	✓
84	06/09/19 09:00	General View	 Load JPG	✓
85	06/09/19 09:00	General View	 Load JPG	✓
86	06/09/19 09:00	General View	 Load JPG	✓
87	06/09/19 09:00	General View	 Load JPG	✓
88	06/09/19 09:00	General View	 Load JPG	✓
89	06/09/19 09:00	General View	 Load JPG	✓
90	06/09/19 09:00	General View	 Load JPG	✓
91	06/09/19 09:00	General View	 Load JPG	✓
92	06/09/19 09:00	General View	 Load JPG	✓
93	06/09/19 09:00	General View	 Load JPG	✓
94	06/09/19 09:00	General View	 Load JPG	✓
95	06/09/19 09:00	General View	 Load JPG	✓
96	06/09/19 09:00	General View	 Load JPG	✓
97	06/09/19 09:01	Photographs of Damaged Items	 Load JPG	✓
98	06/09/19 09:01	Photographs of Damaged Items	 Load JPG	✓
99	06/09/19 09:01	Photographs of Damaged Items	 Load JPG	✓
100	06/09/19 09:01	Photographs of Damaged Items	 Load JPG	✓
101	06/09/19 09:01	Photographs of Damaged Items	 Load JPG	✓
102	06/09/19 09:01	Photographs of Damaged Items	 Load JPG	✓
103	06/09/19 09:01	Photographs of Damaged Items	 Load JPG	✓
104	06/09/19 09:01	Photographs of Damaged Items	 Load JPG	✓
105	06/09/19 09:01	Photographs of Damaged Items	 Load JPG	✓
106	06/09/19 09:01	Photographs of Damaged Items	 Load JPG	✓
107	06/09/19 09:01	Photographs of Damaged Items	 Load JPG	✓
108	06/09/19 09:01	Photographs of Damaged Items	 Load JPG	✓
109	06/09/19 09:01	Photographs of Damaged Items	 Load JPG	✓
110	06/09/19 09:01	Photographs of Damaged Items	 Load JPG	✓
111	06/09/19 09:01	Photographs of Damaged Items	 Load JPG	✓
112	06/09/19 09:01	Photographs of Damaged Items	 Load JPG	✓
113	06/09/19 09:01	Photographs of Damaged Items	 Load JPG	✓
114	06/09/19 09:01	Photographs of Damaged Items	 Load JPG	✓
115	06/09/19 09:01	Photographs of Damaged Items	 Load JPG	✓
116	06/09/19 09:01	Photographs of Damaged Items	 Load JPG	✓
117	06/09/19 09:01	Photographs of Damaged Items	 Load JPG	✓
118	06/09/19 09:01	Photographs of Damaged Items	 Load JPG	✓
119	06/09/19 09:01	Photographs of Damaged Items	 Load JPG	✓
120	06/09/19 09:01	Photographs of Damaged Items	 Load JPG	✓
121	06/09/19 09:01	Reinspection Photo	 Load JPG	✓
122	06/09/19 09:01	Reinspection Photo	 Load JPG	✓
123	06/09/19 09:01	Reinspection Photo	 Load JPG	✓
124	06/09/19 09:01	Reinspection Photo	 Load JPG	✓
125	06/09/19 09:01	Reinspection Photo	 Load JPG	✓
126	06/09/19 09:01	Reinspection Photo	 Load JPG	✓
127	06/09/19 09:01	Reinspection Photo	 Load JPG	✓
128	06/09/19 09:01	Reinspection Photo	 Load JPG	✓
129	06/09/19 09:01	Reinspection Photo	 Load JPG	✓

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
Documentation				
			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/06/19 10:19	Certificate of Insurance	 Load PDF	☐
2	04/06/19 10:19	Driver's Driving License	 Load PDF	☐
3	04/06/19 10:19	ESTIMATE	 Load PDF	☐
4	04/06/19 10:19	Singapore Accident Statement	 Load PDF	☐
5	04/06/19 10:19	NEW CAR PRICE	 Load PDF	☐
6	04/06/19 10:19	SG CAR	 Load PDF	☐
7	06/02/20 09:24	LTA Document	 Load PDF	☐
8	06/02/20 09:55	ESTIMATE	 Load PDF	☐
9	06/02/20 09:55	SUPPLEMENTARY	 Load PDF	☐
10	31/03/20 09:58	DISCHARGE VOUCHER	 Load PDF	☐
11	31/03/20 09:58	WORKSHOP INVOICE	 Load PDF	☐

Linked Accident Report Documents

Assessment Reports			View	View in Browser
			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	28/06/19 12:35	Addendum Sheet	 Load JPG	☒
2	04/09/19 01:11	Accident Statement	 Load HTM	☐
3	04/09/19 01:22	Accident Statement	 Load HTM	☐
Photos/Images				
			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	28/05/19 19:09	Accident Photo	 Load JPG	☒
2	28/05/19 19:09	Accident Photo	 Load JPG	☒
3	28/05/19 19:09	Accident Photo	 Load JPG	☒
4	28/05/19 19:09	Accident Photo	 Load JPG	☒
5	28/05/19 19:09	Accident Photo	 Load JPG	☒
6	28/05/19 19:09	Accident Photo	 Load JPG	☒
7	28/05/19 19:09	Accident Photo	 Load JPG	☒
8	28/05/19 19:09	Accident Photo	 Load JPG	☒
9	28/05/19 19:09	Accident Photo	 Load JPG	☒
10	28/05/19 19:09	Accident Photo	 Load JPG	☒
11	28/05/19 19:09	Accident Photo	 Load JPG	☒
Documentation				
			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	28/06/19 12:35	Sketch Plan	 Load JPG	☒
2	28/06/19 12:35	Sketch Plan #2	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19009719/ETD3S2
Date: 31/03/2020

REFERENCE

Insured/Claimant:	NG CHUN KHIANG	Policy No:	1700069141	
Date of Loss:	28/05/2019	Nature of Claim:	OD	Claim No: 3750110720SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT3810L		
Make & Model:	AUDI Q2, 999cc 1.0 TFSI S TRONIC (A)	Engine No:	CHZ390331
Reg. Date:	26/10/2017 (Man. Year: 2017)	Chassis No:	WAUZZZGA4HA060138
Colour:	Yellow	Odometer:	34250 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$104,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	67,493.04	42,443.84	25,049.20	37.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	43,404.00	30,824.00	12,580.00	28.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	110,897.04	73,267.84	37,629.20	33.93
Approved Total (Overridden) (S\$)		60,000.00		
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	110,097.04	59,200.00	50,897.04	46.23
+ GST 7.00/7.00% (S\$)	7,706.79	4,144.00	3,562.79	46.23
Nett Amount (S\$)	117,803.83	63,344.00	54,459.83	46.23

INSPECTION

Date of Assignment:	03/06/2019	
Date Inspected:	31/05/2019	Inspected At: Premium Automobiles Pte Ltd (Benoi) 24 Benoi Sector Singapore 629857
Estimated Period of Repair:	43.0 days	

Adjuster: CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_printprt&caseid=827712&extid=305827&CFID=69444613&C... 1/7

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	1,706.00 FS	*1,364.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	314.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE - CENTRE	Not Necessary	179.00 FS	*- FS
4	2		*FRONT BUMPER AIR GRILLE - LH / RH	N/s Cut / O/s Missing	308.00 FS	*245.60 FS
5	2		*FRONT BUMPER AIR GRILLE EN CAP - LH / RH	N/s Cut / O/s Missing	62.00 FS	*48.80 FS
6	1		*FRONT BUMPER SPOILER	Cut	273.00 FS	*218.00 FS
7	1		*FRONT BUMPER CLOSING ELEMENT - CENTRE	Not Necessary	142.00 FS	*- FS
8	2		*FRONT WHEEL SPOILER - LH/RH	N/s Cut / O/s Missing	62.00 FS	*49.12 FS
9	1		*FRONT BUMPER ADAPTER - LH / RH	Broken	70.00 FS	*55.92 FS
10	1		*RADIATOR GRILLE	Not Necessary	1,301.00 FS	*- FS
11	1		*RADIATOR GRILLE STRICKER PLATE (TOP)	Not Necessary	114.00 FS	*- FS
12	1		*FRONT BUMPER CARRIER	Not Necessary	625.00 FS	*- FS
13	1		*FRONT BUMPER GUIDE SECTION - LH / RH	O/s Broken	64.00 FS	*25.60 FS
14	1		*FRONT BUMPER TOP COVER - LH / RH	Not Necessary	91.00 FS	*- FS
15	1		*FOAM FILLER PIECE	Not Necessary	71.00 FS	*- FS
16	1		*FRONT BUMPER DISTANCE PIECE	Not Necessary	12.00 FS	*- FS
17	1		*CAUTION STICKER	Not Necessary	13.00 FS	*- FS
18	1		*A/C STICKER	Not Necessary	7.00 FS	*- FS
19	1		*FRONT FENDER - LH / RH	Dented	2,094.00 FS	*1,675.20 FS
20	2		*FRONT FENDER ATTACHMENT PARTS	Dented	72.00 FS	*72.00 FS
21	2		*FRONT FENDER TOP REAR BRACKET - LH / RH	Dented	28.00 FS	*22.08 FS
22	2		*FRONT FENDER TOP FRONT BRACKET - LH / RH	Dented	86.00 FS	*68.16 FS
23	2		*FRONT FENDER TOP CENTER BRACKET - LH / RH	Dented	28.00 FS	*22.08 FS
24	1		*FRONT FENDER RIVET	Necessary	36.00 FS	*28.80 FS
25	2		*FRONT FENDER BRACE - LH / RH	Dented	58.00 FS	*46.08 FS
26	1		*FRONT FENDER CLOSING ELEMENT - RH	Necessary	30.00 FS	*23.76 FS
27	1		*FRONT FENDER INSULATION - RH	Crushed	69.00 FS	*55.04 FS
28	2		*FRONT WHEEL HOUSING LINER SEAL - UPPER	Necessary	66.00 FS	*52.16 FS
29	2		*FRONT WHEEL HOUSING LINER - LH / RH	Necessary / Crushed	366.00 FS	*292.00 FS
30	2		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Necessary	103.00 FS	*82.40 FS
31	1		*BONNET	Dented	2,549.00 FS	*2,039.20 FS
32	1		*BONNET ATTACHMENT PARTS	Not Necessary	149.00 FS	*- FS
33	2		*BONNET HINGE - LH / RH	Dented	112.00 FS	*88.48 FS
34	1		*BONNET ABSORBER	Not Necessary	93.00 FS	*- FS
35	1		*BONNET ABSORBER BRACKET - RH	Not Necessary	31.00 FS	*- FS
36	2		*BONNET STRIKER	Dented	200.00 FS	*159.04 FS
37	1		*BONNET SOUND ABSORBER	Not Necessary	201.00 FS	*- FS
38	1		*BONNET IMPACT PORTECTION	Necessary	82.00 FS	*64.40 FS
39	1		*FRONT FENDER TOP REAR COVER - RH (FENDER INNER)	Crushed	37.00 FS	*29.44 FS
40	1		*FRONT FENDER TOP REAR SMALL COVER - RH (FENDER INNER)	Crushed	14.00 FS	*11.04 FS
41	1		*PLENUM CHAMBER COVER	Not Necessary	144.00 FS	*- FS
42	1		*PLENUM CHAMBER PANEL	Not Necessary	124.00 FS	*- FS
43	1		*BONNET LOCK	Dented	367.00 FS	*293.60 FS
44	1		*BOWDEN CABLE	Not Necessary	53.00 FS	*- FS
45	1		*BONNET LOCK CABLE	Not Necessary	67.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	1		*BONNET LOCK CABLE COVER	Not Necessary	9.00 FS	*- FS
47	1		*BONNET RELEASE ELEMENT	Not Necessary	53.00 FS	*- FS
48	1		*BONNET BOWDEN CABLE	Not Necessary	53.00 FS	*- FS
49	1		*BONNET RELEASE LEVER	Not Necessary	12.00 FS	*- FS
50	1		*HORN - LOW TONE	Not Necessary	262.00 FS	*- FS
51	1		*HORN - HIGH TONE	Not Necessary	180.00 FS	*- FS
52	2		*HORN BRACKET	Not Necessary	58.00 FS	*- FS
53	2		*FRONT WHEEL ARCH TRIM - LH / RH	Necessary / Broken	588.00 FS	*469.60 FS
54	2		*HEADLIGHT MOUNTING - LH / RH	Broken	214.00 FS	*171.20 FS
55	2		*HEADLIGHT - LH / RH	Cut / Broken	8,982.00 FS	*7,184.00 FS
56	1		*HEADLIGHT POWER MODULE	Shorted	693.00 FS	*554.00 FS
57	1		*HEADLIGHT CONTROL MODULE	Shorted	508.00 FS	*406.00 FS
58	1		*HEADLIGHT HEAT SINK	Torn	666.00 FS	*532.40 FS
59	1		*HEADLIGHT VENTILATION HOSE	Broken	26.00 FS	*20.72 FS
60	1		*HEADLIGHT LIFT CYLINDER - LH / RH	O/s Broken	256.00 FS	*102.00 FS
61	1		*HEADLIGHT LIFT CYLINDER HOSE	Not Necessary	170.00 FS	*- FS
62	1		*HEADLIGHT LIFT CYLINDER HOSE JOINT	Necessary	27.00 FS	*21.44 FS
63	3		*HEADLIGHT LIFT CYLINDER ELBOW FITTING	Necessary	81.00 FS	*64.80 FS
64	1		*WATER RESERVOIR	Not Necessary	156.00 FS	*- FS
65	1		*LOCK CARRIER (RH)	Broken	907.00 FS	*725.60 FS
66	1		*A/C CONDENSER	Not Necessary	503.00 FS	*- FS
67	1		*A/C REFRIGERANT LINE	Bent	601.00 FS	*480.40 FS
68	1		*A/C REFRIGERANT LINE - TO COMPRESSOR	Bent	461.00 FS	*368.80 FS
69	1		*RADIATOR	Not Necessary	878.00 FS	*- FS
70	1		*ADDITIONAL RADIATOR	Not Necessary	837.00 FS	*- FS
71	1		*COOLANT	Necessary	84.00 FS	*67.20 FS
72	1		*RADIATOR FAN WITH RING	Not Necessary	1,483.00 FS	*- FS
73	1		*RADIATOR AIR GUIDE - LH / RH	Not Necessary	54.00 FS	*- FS
74	1		*RADIATOR SEAL - RH OUTER	Not Necessary	6.00 FS	*- FS
75	1		*RADIATOR AIR GUIDE - UPPER CENTRE	Not Necessary	19.00 FS	*- FS
76	1		*AIR DUCT AIR GUIDE - FRONT	Not Necessary	53.00 FS	*- FS
77	1		*AIR DUCT HOSE	Not Necessary	62.00 FS	*- FS
78	1		*AIR DUCT WATER DRAINAGE HOSE	Not Necessary	31.00 FS	*- FS
79	1		*INTAKE MANIFOLD SUCTION PIPE	Not Necessary	129.00 FS	*- FS
80	1		*AIR FILTER	Not Necessary	252.00 FS	*- FS
81	1		*FRONT FENDER REAR CLOSING ELEMENT - RH	Not Necessary	27.00 FS	*- FS
82	1		*SIDE MEMBER - RH	Dented	368.00 FS	*294.00 FS
83	1		*A-PILLAR - RH	Dented	1,703.00 FS	*1,362.40 FS
84	1		*FRONT DOOR - RH	Dented	2,285.00 FS	*1,828.00 FS
85	1		*FRONT DOOR SEAL INNER - RH	Necessary	146.00 FS	*116.80 FS
86	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	85.00 FS	*- FS
87	1		*FRONT DOOR CATCH - LH	Not Necessary	109.00 FS	*- FS
88	1		*FRONT DOOR HINGE - UPPER RH	Dented	41.00 FS	*32.08 FS
89	2		*FRONT DOOR HINGE - LOWER RH	Dented	81.00 FS	*64.64 FS
90	1		*FRONT DOOR HINGE UPPER PART - UPPER INNER RH	Dented	39.00 FS	*30.80 FS
91	1		*FRONT DOOR REGULATOR - RH	Dented	241.00 FS	*192.40 FS
92	1		*FRONT DOOR REGULATOR MOTOR - RH	Not Necessary	224.00 FS	*- FS
93	1		*FRONT DOOR CONTROL UNIT	Not Necessary	456.00 FS	*- FS
94	1		*WIND MIRROR MOUNTING - RH	Cut	471.00 FS	*376.40 FS
95	1		*WIND MIRROR CAP - RH	Cut	136.00 FS	*108.00 FS
96	1		*WIND MIRROR GLASS - RH	Not Necessary	282.00 FS	*- FS
97	1		*FRONT DOOR CORNER TRIM - RH	Not Necessary	41.00 FS	*- FS
98	1		*FRONT DOOR WINDOW GUIDE - RH	Not Necessary	377.00 FS	*- FS
99	1		*FRONT DOOR WINDOW APERTURE SEAL - RH	Necessary	119.00 FS	*95.20 FS
100	1		*FRONT DOOR LOWER COVER	Cut	235.00 FS	*187.60 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
101	1		*REAR DOOR - RH	Dented	2,285.00 FS	*1,828.00 FS
102	1		*REAR DOOR OUTER SEAL - RH	Necessary	119.00 FS	*94.80 FS
103	1		*BONDING AGENT	Necessary	45.00 FS	*35.92 FS
104	1		*CLEANING SOLUTION	Necessary	65.00 FS	*51.68 FS
105	1		*APPLICATOR	Not Necessary	7.00 FS	*- FS
106	1		*REAR DOOR ATTACHMENT PARTS	Not Necessary	85.00 FS	*- FS
107	1		*REAR DOOR CATCH - RH	Not Necessary	109.00 FS	*- FS
108	1		*REAR DOOR LOWER COVER (MOULDING)	Cut	206.00 FS	*164.80 FS
109	1		*FRONT WINDSCREEN	Not Necessary	913.00 FS	*- FS
110	1		*GEL FOIL	Not Necessary	128.00 FS	*- FS
111	2		*PRIMER	Not Necessary	38.00 FS	*- FS
112	1		*FRONT SEATBELT - LH	Jammed	952.00 FS	*761.60 FS
113	2		*FELT STRIPS	Necessary	44.00 FS	*33.92 FS
114	1		*FRONT SEAT BELT - RH	Jammed	952.00 FS	*761.60 FS
115	2		*FRONT TOP SEAT BELT ADJUSTER	Necessary	322.00 FS	*257.60 FS
116	1		*AIRBAG CONTROL UNIT	Necessary	1,578.00 FS	*1,262.40 FS
117	2		*AIRBAG CRASH SENSOR	Necessary	763.00 FS	*610.40 FS
118	2		*FRONT RIM - LH/RH	Cut	1,096.00 FS	*876.80 FS
119	1		*RUBBER VALVE	Necessary	13.00 FS	*9.92 FS
120	1		*FRONT SUB FRAME	Bent	718.00 FS	*574.40 FS
121	1		*FRONT SUB FRAME BOLTS	Not Necessary	209.00 FS	*- FS
122	1		*FRONT LOWER ARM - LH	Bent	332.00 FS	*265.20 FS
123	1		*FRONT LOWER ARM BOLTS - LH	Not Necessary	32.00 FS	*- FS
124	1		*FRONT LOWER ARM - RH	Bent	332.00 FS	*265.20 FS
125	1		*FRONT LOWER ARM BOLTS - RH	Not Necessary	32.00 FS	*- FS
126	1		*FRONT STABILIZER	Bent	372.00 FS	*297.20 FS
127	1		*FRONT STABILIZER BOLTS	Not Necessary	16.00 FS	*- FS
128	1		*FRONT WHEEL BEARING HOUSING - LH	Bent	620.00 FS	*496.00 FS
129	1		*FRONT WHEEL BEARING HOUSING BOLTS - LH	Not Necessary	72.00 FS	*- FS
130	1		*FRONT WHEEL BEARING HOUSING - RH	Bent	620.00 FS	*496.00 FS
131	1		*FRONT WHEEL BEARING HOUSING BOLTS - RH	Not Necessary	72.00 FS	*- FS
132	1		*FRONT WHEEL BEARING- LH/RH	Necessary	884.00 FS	*707.20 FS
133	1		*FRONT LOWER ARM BALL JOINT - LH	Necessary	132.00 FS	*105.20 FS
134	1		*FRONT LOWER ARM BALL JOINT BOLTS - LH	Not Necessary	15.00 FS	*- FS
135	1		*FRONT LOWER ARM BALL JOINT - RH	Necessary	132.00 FS	*105.20 FS
136	1		*FRONT LOWER ARM BALL JOINT BOLTS - RH	Not Necessary	15.00 FS	*- FS
137	1		*FRONT STABILIZER LINK - LH/RH	Bent	175.00 FS	*139.84 FS
138	1		*FRONT DRIVE SHAFT - LH	Not Necessary	2,208.00 FS	*- FS
139	1		*FRONT DRIVE SHAFT BOLTS - LH	Not Necessary	31.00 FS	*- FS
140	1		*FRONT DRIVE SHAFT - RH	Bent	2,208.00 FS	*1,766.40 FS
141	1		*FRONT DRIVE SHAFT BOLTS - RH	Not Necessary	31.00 FS	*- FS
142	2		*FRONT ABSORBER	Bent	559.00 FS	*223.60 FS
143	1		*FRONT ABSORBER BOLTS	Not Necessary	35.00 FS	*- FS
144	2		*FRONT ABSORBER MOUNTING	Not Necessary	228.00 FS	*- FS
145	1		*FRONT ABSORBER MOUNTING BOLTS	Not Necessary	35.00 FS	*- FS
146	2		*FRONT ABSORBER BEARING	Not Necessary	85.00 FS	*- FS
147	2		*FRONT ABSORBER STOPPER	Not Necessary	61.00 FS	*- FS
148	1		*FRONT TIE ROD END - LH/RH	Bent	236.00 FS	*188.80 FS
149	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
150	1		*CRAVITY WAX	Necessary	140.00 FS	*140.00 FS
151	1		*STONE CHIP TREATMENT	Necessary	180.00 FS	*180.00 FS
152	1		*FRONT WINDSCREEN SEALANT	Not Necessary	200.00 FS	*- FS
153	1		*FRONT NO. PLATE	Not Necessary	40.00 FS	*- FS
154	1		*SUNDRIES	Necessary	800.00 FS	*509.84 FS
155	1		*FRONT TYRE - LH (NPA)	Not Necessary	0.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
156	1		*ENGINE MOUNTING	Bent	172.40 FS	*172.40 FS
157	1		*GEARBOX MOUNTING	Deformed	192.80 FS	*192.80 FS
158	1		*HEXAGON FLANGE SCREW	Necessary	33.92 FS	*33.92 FS
159	1		*FRONT SUBFRAME SUPPORT LHS	Bent	16.96 FS	*16.96 FS
160	1		*FRONT SUBFRAME SUPPORT RHS	Bent	16.96 FS	*16.96 FS
161	1		*SHOCK ABSORBER DEEP GROOVE BALL THRUST BEARING	Bent	34.00 FS	*34.00 FS
162	1		*SHOCK ABSORBER SUSPENSION STRUT STORAGE	Distorted	91.20 FS	*91.20 FS
163	1		*STEERING GEAR	Bent	3,632.00 FS	*3,632.00 FS
164	1		*TRACK ROD	Bent	136.96 FS	*136.96 FS
165	1		*FRONT FENDER TOP SUPPORT UPPER PART RHS	Bent	21.20 FS	*21.20 FS
166	1		*CHASSIS TAG	Necessary	423.00 FS	*338.00 FS
167	1		*COOLANT PIPE WITH INNER HEAT EXCHANGER	Bent	461.00 FS	*368.80 FS
168	1		*PRESSURE SENSOR REFRIGERANT LINE	Bent	140.00 FS	*140.00 FS
169	1		*NOISE INSULATION	Cracked	191.20 FS	*191.20 FS
170	1		*REPAIR SET FOR STEERING BOX	Necessary	34.00 FS	*34.00 FS
171	1		*FRONT TYRE - LH	Cut	560.00 FS	*560.00 FS
172	1		*FRONT FENDER TOP MIDDLE BRACKET RHS	Dented	16.32 FS	*16.32 FS
173	1		*HEADLIGHT COMPENSATING PIECE	Broken	69.12 FS	*69.12 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 67,493.04 42,443.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TOW AND RECOVER VEHICLE FROM SCENE OF ACCIDENT. (NPA) (AIG)	New	0.00	0.00
2	TO CARRY OUT FIRST MEASUREMENT TEST ON CAR O-LINER.	New	800.00	800.00
3	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	New	360.00	360.00
4	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR, RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	New	1,400.00	1,400.00
5	TO REMOVE AND REINSTALL CENTRE CONSOLE AND DASHBOARD ASSY FOR A-PILLAR RENEWAL. TO RENEW BOTH FRONT SEATBELT AND AIRBAG CONTROL UNIT.	New	3,200.00	3,200.00
6	TO REMOVE AND REINSTALL RHS FRONT SEAT ASSY, ABCD PILLAR TRIMS, SILL TRIMS, CARPET, ELECTRONIC COMPONENTS AND FUSE TRAYS.	New	1,800.00	1,800.00
7	TO REMOVE AND REINSTALL ENGINE ASSY WITH GEARBOX ASSY TO FACILITATE CAR O-LINER REPAIRS.	New	2,800.00	2,800.00
8	TO REMOVE AND REINSTALL FRONT SUSPENSION ASSY WITH SUBFRAME TO FACILITATE CAR O-LINER REPAIRS. INSPECT FOR DAMAGES AND RENEW IF NECESSARY.	New	2,400.00	2,400.00
9	TO RENEW FRONT WINDSCREEN FOR A-PILLAR RENEWAL.	New	480.00	0.00
10	TO REPLACE VEHICLE ON CAR O-LINER.	New	1,800.00	1,800.00
11	TO DISLodge AND REINSTALL RHS A-PILLAR, RHS FRONT DOORS AND RHS REAR DOOR HARNESS, MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES.	New	1,060.00	1,060.00
12	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH HEADLIGHTS, BOTH FRONT FENDERS, RHS FRONT DOOR, RHS WING MIRROR ASSY AND RHS REAR DOOR. CUT OUT AND REWELD RHS FENDER SUPPORT AND CLOSING ELEMENT AND RHS A-PILLAR. ALIGN BOTH FRONT CHASSIS FRAMES TO SPECIFICATION OF ORIGIN. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	17,200.00	9,000.00
13	TO RESPRAY FRONT BUMPER, BONNET, RHS A-PILLAR, RHS FRONT FENDER TOP SUPPORT, RHS FRONT DOOR, BOTH FRONT FENDERS, ENGINE COMPARTMENT, RHS WING MIRROR COVER, DOOR ENTRANCE, RHS REAR DOOR AND HINGES. TO CARRY OUT JOINT SEALANT WORK AND STONE CHIP TREATMENT.	New	9,400.00	5,500.00
14	TO RENEW RHS FRONT RIMS, LHS FRONT TYRE AND LHS FRONT RIM. TO CARRY OUT WHEEL ALIGNMENT.	New	320.00	320.00
15	TO CARRY OUT DIAGNOSTIC CHECK.	New	384.00	384.00
Gross Labour Cost (S\$)			43,404.00	30,824.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >