

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 31 May 2019

To : LKK

By Fax: 6256-4315

Attn :

Tel:

VEHICLE NO : FBC 2692A

Yamaha Spark LC 135


ACCIDENT DATE: 21 May 2019

<u>Description</u>	<u>Qty</u>	<u>Quotation \$</u>
1 Head Lamp <i>Crack</i>	1	250.00 ✓
2 Handle Bar <i>2 mm</i>	1	135.00 <i>2X</i>
3 Head Lamp Cover <i>Scratched</i>	1	195.00 ✓
4 Front Mudguard <i>Ray</i>	1	265.00 <i>X</i>
5 Brake Lever <i>cut</i>	1	69.00 ✓
6 Handle Bar Grip <i>cut RH</i>	1 set	130.00 ✓
7 Exhaust Guard - Chrome <i>cut</i>	1	220.00 ✓
8 Exhaust Guard <i>cut</i>	1	190.00 ✓
9 Front RH Signal <i>Crack</i>	1	115.00 ✓
10 Rear Mudguard <i>2mm</i>	1	235.00 <i>X</i>
11 Footrest <i>2mm</i>	1	95.00 ✓
12 Footrest Rubber <i>defunct</i>	1	65.00 ✓
13 Kickstart <i>Jam</i>	1	135.00 ✓
14 Kickstart Shaft <i>Nic</i>	1	165.00 ✓

Sub-Total 2,264.00

Less 10% 226.40

Sub-Total 2,037.60



VEHICLE NO : FBC 2692A

Yamaha Spark LC 135

Nett Items

1	Rear box <i>MM</i>	280.00 X
2	Rear number plate <i>BT</i>	15.00 ✓
3	Towing fee 40.00 <i>MM</i>	40.00 X
4	Remove & replace necessary parts, align & etc	200.00 <i>150/-</i>
5	Check fork alignment	60.00 <i>30/-</i>
6	Supply body decal sticker	80.00 <i>MM</i>
7	To check engine (stalled after bike down)	350.00 <i>MM</i>

195.00

Sub-Total 1,025.00
Nett Total 3,062.60

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

1661.10

2/S 1300/-

Kindly revert upon completion. Thank you

[Signature]
SG 98 MOTOR PTE LTD

31/05/2019 @ 1300hr

MM Andrew

2/3mm

4 days.

[Signature]
J K K Auto

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Check on consistency of damage.

Damage area pending verification with witness and taxi driver.