

22/03/2002

ASS. REC. BY:

REF: CS/CTI19009724/J9d3m2

Special Instruction:

Surveior: Hme Jse

ASSIGNMENT (Office)

From (Person): Ong Chin Kiat

of CTZ

Date/Time: 3.6.19 10.24 AM

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SH 276L

Insured: SJP 4721B

at Workshop m/s World Auto

Tel: 63621776

of MD 1 Kranji Loop

Policy No: DMD (SN 30410218000

Claim No: SNM19D20179702

Sum Insured:

Excess:

Make of Veh:

D.O.A. 22.4.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 3.6.2019 11.08 AM

Person Contacted: Gan Ping

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SH 276L - X
	SJP 4721 B - X

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	31 May 2019		03 Jun 2019 10:24 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	KOH WIE LIANG, ID: S1821779A		
Main Claimant:	LCRF PTE LTD, Co. Reg. No.: 201624597K		
Vehicle Reg. No.:	SLH276L	Date of Loss:	22/04/2019 17:00 - :59 [30 Months and 2 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D201797C02	Policy/Cover Note No.:	DMPCSN30410218000
Vehicle Reg. No. (Insured):	SJF4721B	Policy No. (Claimant):	19-MK000194-R00
		Excess:	S\$0.00
Repairer:	World Auto Pte Ltd - Kranji (HQ) No 1 Kranji Loop, 739535 Kranji - Tel: 63621776		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]		
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 13/06/2019]		
Driver/Custodian (Insured):	KOH WIE LIANG (52 / Male), NRIC: S1821779A Email:		
Adj Asg. Remarks:	please assign Mr Chua WeiJie for SJE. vehicle at World Auto Pte Ltd No 1 Kranji Loop Singapore 739535. Kindly contact Gan Ping at 6362 1776 to arrange. thank you.		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	4597K
Vehicle Details	
Vehicle No.:	SLH276L
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Jun 2019
Vehicle Make:	HONDA
Vehicle Model:	SHUTTLE 1.5 HYBRID AT ABS D/AIRBAG 2WD
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	LEB4261218
Chassis No.:	GP71041699
Maximum Power Output:	101.0 kW (135 bhp)
Open Market Value:	\$20,966.00
Original Registration Date:	20 Oct 2016
First Registration Date:	20 Oct 2016
Transfer Count:	1
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Oct 2026
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	19 Oct 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,010.00
COE Rebate Amount:	\$41,991.00
Total Rebate Amount:	\$45,741.00

The information contained herein is correct as at 07 Jun 2019

OK

WORLD AUTO PTE LTD

Page 1 / 2

47 Jalan Pemimpin #01-02/03
Halcyon 2, S'pore 577200
Tel No. : 6451 3933 Fax No. : 6455 7576
E-Mail : worldaut@singnet.com.sg
Website : www.worldauto.com.sg
Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Estimate : ES190100

Parts — \$2568.20
20% = \$2054.56
S/N = \$310
Labour = \$1200

Date : 31/05/2019
Vehicle Num. : SLH 276L (LCR)
Make/Model : HONDA SHUTTLE HYBRID
Chassis/Eng# :
Accident Date : 22/04/2019
Claim No. :
Reference :
Policy No. :

\$3564.56

S/N Quantity Particular

Unit Price Amount S\$

LIST ITEMS :			
1.	1	REAR TAILGATE	BUL ✓
2.	1	REAR TAILGATE SHUTTLE EMBLEM	NEC ✓
3.	1	REAR TAILGATE HYBRID EMBLEM	NEC ✓
4.	1	REAR BUMPER	DEF ✓
5.	1	REAR BUMPER TOW COVER	NEC ✓
6.	1	REAR BUMPER REFLECTOR LENS GARNISH RH	NEC ✓
7.	1	REAR BUMPER REFLECTOR LENS LH	NEC ✓
8.	1	REAR BUMPER SIDE INNER FOAM RH	NEC ✓
9.	1	REAR END PANEL	NEC ✓
10.	1	REAR END PANEL TOP GARNISH	NEC ✓
11.	1	TAIL LAMP LOWER PANEL RH	NEC ✓
12.	1SET	REAR WINDSCREEN GLASS MOULDING	NEC ✓
List Total S\$:			1,100.00
20.00% Discount S\$:			56 84.60
			56 88.60
			1,100.00
			35.00
			128.00
			118.00
			160.00
			560.80
			168.00
			195.00

List Total S\$:

20.00% Discount S\$:

3,893.50

778.70

3,114.80

SPECIAL NETT ITEMS :			
1SET	1	REAR TAILGATE INNER TRIM BOARD CLIPS	NEC ✓
1SET	1	REAR BUMPER CLIP	NEC ✓
1SET	1	REAR END PANEL TOP GARNISH CLIPS	NEC ✓
1	1	WINDSCREEN SEALANT	NEC ✓
1SET	1	REVERSE SENSOR	shorted ✓
Special Nett Total S\$:			20 30.00
			30.00
			20.00
			60 80.00
			200 280.00
			440.00

LABOUR :

TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES

50 180.00

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Estimate : ES190100

Attention : Motor Claim Department

Date : 31/05/2019

Vehicle Num. : SLH 276L (LCR)

Make/Model : HONDA SHUTTLE HYBRID

Chassis/Eng# :

Accident Date : 22/04/2019

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		WIRINGS CHECK AND RECTIFY WHERE NECESSARY	30	180.00
		REMOVE & REFIT REAR WINDSCREEN GLASS	12	180.00
		REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN REAR CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS	1,600.00	500
		DEACTIVATE HV HYBRID SYSTEM IN ORDER TO FACILITATE REPAIRS AND REACTIVATE BACK SAME (HV HYBRID SYSTEM SAFETY PROCEDURES)	450.00	X
		PERFORM VEHICLE DIAGNOSTICS INCLUDING CLEARING FAULT CODES AND REINITIALISE HV HYBRID SYSTEM (HV HYBRID SYSTEM SAFETY PROCEDURES)	450.00	X
		PUTTY AND SPRAY PAINT ALL AFFECTED AREAS	1,200.00	500
		Labour Total S\$:		4,240.00

E. & O.E.

Total S\$: 7,794.80

=====

for WORLD AUTO PTE LTD

\$3515.60/-

Hux Jie - Lkk

3/6/19

P/P 4 days

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD**Estimate : ES190100**

Date : 31/05/2019

Vehicle Num. : SLH 276L (LCR)

Make/Model : HONDA SHUTTLE HYBRID

Chassis/Eng# :

Accident Date : 22/04/2019

Claim No. :

Reference :

Policy No. :

Attention : Motor Claim Department

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :

1.	1	REAR TAILGATE <i>BUL ✓</i>		1,100.00 ✓
2.	1	REAR TAILGATE SHUTTLE EMBLEM <i>rec ✓</i>		84.60
3.	1	REAR TAILGATE HYBRID EMBLEM <i>rec ✓</i>		88.60
4.	1	REAR BUMPER <i>DEF ✓</i>		1,100.00 ✓
5.	1	REAR BUMPER TOW COVER <i>nnx</i>		35.00
6.	1	REAR BUMPER REFLECTOR LENS GARNISH RH <i>nnx</i>		128.00
7.	1	REAR BUMPER REFLECTOR LENS RH <i>nnx</i>		118.00 X
8.	1	REAR BUMPER SIDE INNER FOAM RH <i>? nnx</i>		160.00 X
9.	1	REAR END PANEL <i>? nnx</i>		560.80 X
10.	1	REAR END PANEL TOP GARNISH <i>nnx</i>		155.50 X
11.	1	TAIL LAMP LOWER PANEL RH <i>nnx</i>		168.00
12.	1SET	REAR WINDSCREEN GLASS MOULDING <i>rec ✓</i>		195.00 ✓

List TotalS\$:

3,893.50

20.00% Discount S\$:

778.70

3,114.80

SPECIAL NETT ITEMS :

1.	1SET	REAR TAILGATE INNER TRIM BOARD CLIPS <i>rec ✓</i>		20 30.00
2.	1SET	REAR BUMPER CLIP <i>rec ✓</i>		30.00
3.	1SET	REAR END PANEL TOP GARNISH CLIPS <i>? nnx</i>		20.00 X
4.	1	WINDSCREEN SEALANT <i>rec ✓</i>		60 80.00
5.	1SET	REVERSE SENSOR <i>started ✓</i>		200 280.00

Special Nett Total S\$:

440.00

LABOUR :

TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES

50 180.00

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD**Estimate : ES190100**

Date : 31/05/2019

Vehicle Num. : SLH 276L (LCR)

Make/Model : HONDA SHUTTLE HYBRID

Chassis/Eng# :

Accident Date : 22/04/2019

Claim No. :

Reference :

Policy No. :

Attention : Motor Claim Department

S/N	Quantity	Particular	Unit Price	Amount S\$
		WIRINGS CHECK AND RECTIFY WHERE NECESSARY	30	180.00
		REMOVE & REFIT REAR WINDSCREEN GLASS	12	180.00
		REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN REAR CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS	1,600.00	500
		DEACTIVATE HV HYBRID SYSTEM IN ORDER TO FACILITATE REPAIRS AND REACTIVATE BACK SAME (HV HYBRID SYSTEM SAFETY PROCEDURES)	450.00	X
		PERFORM VEHICLE DIAGNOSTICS INCLUDING CLEARING FAULT CODES AND REINITIALISE HV HYBRID SYSTEM (HV HYBRID SYSTEM SAFETY PROCEDURES)	450.00	X
		PUTTY AND SPRAY PAINT ALL AFFECTED AREAS	1,200.00	500
		Labour Total S\$:		4,240.00

for **WORLD AUTO PTE LTD****E. & O.E.**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total S\$: 7,794.80

Huse Jie - LKK

3/6/19

P/P 4days

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT19009724/JQD3N2

Date: 09/07/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30410218000	
Claimant Vehicle No :	SLH276L	Insured Vehicle No :	SJF4721B	
Date of Loss:	22/04/2019	Nature of Claim:	TP	Claim No: SNM19D201797C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLH276L	Engine No:	LEB4261218
Make & Model:	HONDA SHUTTLE HYBRID, 1.5 (A)	Chassis No:	GP71041699
Reg. Date:	20/10/2016 (Man. Year: 2016)	Odometer:	201234 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,554.80	2,315.60	1,239.20	34.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,240.00	1,200.00	3,040.00	71.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	7,794.80	3,515.60	4,279.20	54.90
+ GST 7.00/7.00% (\$\$)	545.64	246.09	299.55	54.90
Nett Amount (\$\$)	8,340.44	3,761.69	4,578.75	54.90

INSPECTION

Date of Assignment:	03/06/2019	
Date Inspected:	03/06/2019	Inspected At: World Auto Pte Ltd - Kranji (HQ) No 1 Kranji Loop Singapore 739535
Estimated Period of Repair:	4.0 days	

Adjuster: ONG HWEE JIE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 09 Jul 2019)	
Parts:	N/A	HONDA SHUTTLE HYBRID 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLH276L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR TAILGATE	Buckled	1,100.00 FL	*1,100.00 FL
2	1	*REAR TAILGATE SHUTTLE EMBLEM	Necessary	84.60 FL	*56.00 FL
3	1	*REAR TAILGATE HYBRID EMBLEM	Necessary	88.60 FL	*56.00 FL
4	1	*REAR BUMPER	Deformed	1,100.00 FL	*1,100.00 FL
5	1	*REAR BUMPER TOW COVER	Not Necessary	35.00 FL	*- FL
6	1	*REAR BUMPER REFLECTOR LENS GARNISH RH	Not Necessary	128.00 FL	*- FL
7	1	*REAR BUMPER REFLECTOR LENS RH	Not Necessary	118.00 FL	*- FL
8	1	*REAR BUMPER SIDE INNER FOAM RH	Not Necessary	160.00 FL	*- FL
9	1	*REAR END PANEL	Not Necessary	560.80 FL	*- FL
10	1	*REAR END PANEL TOP GARNISH	Not Necessary	155.50 FL	*- FL
11	1	*TAIL LAMP LOWER PANEL RH	Not Necessary	168.00 FL	*- FL
12	1	*SET REAR WINDSCREEN GLASS MOULDING	Necessary	195.00 FL	*195.00 FL
13	1	*SET REAR TAILGATE INNER TRIM BOARD CLIPS	Necessary	30.00 FS	*20.00 FS
14	1	*SET REAR BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
15	1	*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	20.00 FS	*- FS
16	1	*WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS
17	1	*SET REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	4,333.50	2,817.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	778.70	501.40
Total Parts (\$\$)	3,554.80	2,315.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES	New	180.00	50.00
2	WIRING CHECK AND RECTIFY WHERE NECESSARY	New	180.00	30.00
3	REMOVE & REFIT REAR WINDSCREEN GLASS	New	180.00	120.00
4	REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT,CUT/WELD,STRAIGHTEN REAR CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS	New	1,600.00	500.00
5	DEACTIVATE HV HYBRID SYSTEM IN ORDER TO FACILITATE REPAIRS AND REACTIVATE BACK SAME (HV HYBRID SYSTEM SAFETY PROCEDURES)	New	450.00	0.00
6	PERFORM VEHICLE DIAGNOSTICS INCLUDING CLEARING FAULT CODES AND REINITIALISE HV HYBRID SYSTEM (HV HYBRID SYSTEM SAFETY PROCEDURES)	New	450.00	0.00
7	PUTTY AND SPRAY PAINT ALL AFFECTED AREAS	New	1,200.00	500.00
Gross Labour Cost (\$\$)			4,240.00	1,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >