

ASS. REC. BY:

REF:

C/CT/190097371E+d302

Special Instruction:

Survey: DriveASSIGNMENT (Office)From (Person): Chong Boon Sen

of

CTI

Date/Time:

03/6/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLF 2151K

Insured:

GU 3672Y

at Workshop m/s

Lah Motor

Tel:

of

285 Alexandra Rd.

Policy No:

DMCVGN16769119022

Claim No:

SNM190202459

Sum Insured:

Excess:

Make of Vehicle

(Client's Record)

D.O.A.

30/5/19

CA / REV / REP. / REV 24 HRS

cup

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN (OUT)

Date/Time	Action/Instruction
	<u>SLF 2151K</u>
	<u>GU 3672Y</u>

ASSIGNMENT

From: _____ Date: 10/6/2019

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLF 2151Kat Workshop m/s Kah motorof 255 Alexandra Road

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS mg

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLF 2151KYr Regn: 18/8/16Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Odyssey

c.c.

2356Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 105478

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JH MRC 1819 GC 296106

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/55R17R: 1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front

Rear

R/Bal. 7

mm

R/Bal. 7

mm

L/Bal. 7

mm

L/Bal. 7

mm

D.O.A. 30/5/19D.O.I. 10/6/19Survey held at Kah motorDes. of Damages: Frt / Rear / O/S (N/S) / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV-105K24/6/19 Finalize condition with Sin Hai, \$16,212.08, 9 repair days. OKed: 4408; 21%

RECEIVED 25 JUN 2019

Date/Time, File Pass to?

25/6 Typist

Date/Time, File Return to?

2)

Report Format: TPLump Sum / I.B.I: (\$ 16,212.08)Days Of Repair: 9Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

3 + RS, \$

Photos

Others

TOTAL

220220

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Monday, 3 June 2019 10:38 AM
To: Ng Sin Hai
Cc: assignments
Subject: RE: 3rd party direct settlement SLF2151K& your insured
GU3672Y/DOA:30/05/2019/Est \$ / OUR REF: SNM19D202459

WITHOUT PREJUDICE

Dear Sir,

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

(001)

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Ng Sin Hai [mailto:shng@kahmotor.onmicrosoft.com]

Sent: Monday, 3 June, 2019 10:27 AM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: RE: 3rd party direct settlement SLF2151K& your insured GU3672Y/DOA:30/05/2019/Est \$ / OUR REF: SNM19D202459

Dear Boon Sen,

Please arrange LKK for the survey.

Thank you and have a nice day,☺

Warmest Regards,

Ng Sin Hai

Kah Motor Co. Sdn. Bhd

(A member of Oriental Holdings Berhad)

Body Repair & Paint Centre

255 Alexandra Road

Singapore 159937

DID: 6471 5419

HP: 9072 1769

E-mail: shng@honda.com.sg



BLUE SKIES FOR
OUR CHILDREN



Visit our
Facebook page

Please consider the environment before printing this email

CONFIDENTIAL NOTE: The Information contained in the e-mail is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you for your collaboration.

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Sent: Monday, 3 June, 2019 10:12 AM

To: Ng Sin Hai <shng@kahmotor.onmicrosoft.com>

Subject: RE: 3rd party direct settlement SLF2151K& your insured GU3672Y/DOA:30/05/2019/Est \$ / OUR REF: SNM19D202459

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
LOW SAR HUEI
HONG FOOK CHOY
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Claims Dept of CTI

Sent: Monday, 3 June, 2019 10:09 AM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; shng@kahmotor.onmicrosoft.com

Cc: Angie Foo <angie.foo@sg.cntaiping.com>

Subject: FW: 3rd party direct settlement SLF2151K& your insured GU3672Y/DOA:30/05/2019/Est \$

Dear Boon Sen,

Please conduct PRS – TP: SLF2151K (SNM19D202459) soonest possible.
File with OIC – Boon Sen - 63896171

From: Ng Sin Hai [<mailto:shng@kahmotor.onmicrosoft.com>]

Sent: Friday, 31 May 2019 9:38 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: RE: 3rd party direct settlement SLF2151K& your insured GU3672Y/DOA:30/05/2019/Est \$

Dear All,

Please refer to the attached pdf, we are assisting our insured vehicle SLF2151K to file a 3rd party claim against your insured vehicle GU3672Y and to request for direct settlement.

Kindly assist and expedite to check the claim liability soonest.

Thank you and have a nice day, ☺

Warmest Regards,

Ng Sin Hai

Kah Motor Co. Sdn. Bhd

(A member of Oriental Holdings Berhad)

Body Repair & Paint Centre

255 Alexandra Road

Singapore 159937

DID: 6471 5419

HP: 9072 1769

E-mail: shng@honda.com.sg



Visit our
Facebook page



Please consider the environment before printing this email

CONFIDENTIAL NOTE: The Information contained in the e-mail is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you for your collaboration.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	31/05/2019 21:13
Date Of Accident	30/05/2019 18:00
Exact Location Of Accident	WEST COAST ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLF2151K
Insured/Policyholder	
Name Of Registered Owner	THAM KEANG CHUNG
NRIC No	S6809724Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96733086
Alternative Phone No	OFFICE-96733086

Vehicle Particulars

Manufacturer	HONDA
Model	ODYSSEY-2.4 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	THAM KEANG CHUNG
NRIC No	S6809724Z
Date Of Birth	13/03/1968
Occupation	INDOOR
Date Of Driving Pass	27/01/1987
Driving Experience	32 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96733086
Fax Number	
Contact Number	OFFICE-96733086
Email Address	NOEMAIL

Address	S
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GU3627Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	GOODS VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

Vehicle Number: _____

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA) I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time: _____


Driver's Signature
(If driver is not the policyholder)
Date & Time: _____


Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____

Vehicle Number: _____

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was traveling along West Coast Road. I was moving straight on my lane and vehicle B dashed out from his lane and hit onto my vehicle A.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature:
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 9724Z

Vehicle Details

Vehicle No.: SLF2151K
Vehicle to be Exported: No
Intended Deregistration Date: 10 Jun 2019
Vehicle Make: HONDA
Vehicle Model: ODYSSEY 2.4 EX-S CVT
Primary Colour: Purple
Manufacturing Year: 2016
Engine No.: K24W72012750
Chassis No.: JHMRC1880GC206106
Maximum Power Output: 129.0 kW (172 bhp)
Open Market Value: \$28,860.00
Original Registration Date: 18 Aug 2016
First Registration Date: 18 Aug 2016
Transfer Count: 0
Actual ARF Paid: \$32,404.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 17 Aug 2026
PARF Rebate Amount: \$24,303.00

Intended COE Rebate Details

COE Expiry Date: 17 Aug 2026
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$57,508.00
COE Rebate Amount: \$41,322.00
Total Rebate Amount: \$65,625.00

The information contained herein is correct as at 10 Jun 2019

OK

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

Registration No : SLF2151K

Chassis No : JHMRC1880GC206106

Model : ODYSSEY 2.4 EX-S 16YM

Owner's Name : THAM KEANG CHUNG

Ins Policy No. :

Date of Accident : 30/5/2019

Document No. : SQT19002521

Date : 10. Jun 2019

Customer No. : WZC008

Svc Advisor : NG SIN HAI

Engine No : K24W72012750

Date | Time : 10. Jun 2019 9:36:34 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:						
	OWNER INSURER:						
	ACC DATE:						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:						
	TP VEH:						
91505-TM8-003	CLIP,BUMPER <i>1 pc</i>	8	2.30	5	17.48	1.22	18.70
76201-T6A-J01ZA	CAPR.SKULL <i>(mir. (ov)) MIE</i>	1	66.00	5	62.70	4.39	67.09
76258-T6A-J03	MIRROR SET,L <i>/ CUT</i>	1	561.50	5	533.42	37.34	570.76
75332-T6A-J01ZA	GARNISH ASSYL.FR.DOOR LOWER <i>x R</i>	1	318.10	5	302.19	21.15	323.34
72456-T6A-003	GARNISH RR.FR.CENTER CORNER <i>x R</i>	1	5.50	5	5.22	0.37	5.59
67364-T6A-305ZA	TAPE SETL.FR.DOOR SASH INNER <i>/ 1 pc</i>	1	38.40	5	36.48	2.55	39.03
67364-T6A-305ZA	TAPE SETL.FR.DOOR SASH INNER <i>x R</i>	1	38.40	5	36.48	2.55	39.03
75332-T6A-J01ZG	GARNISH ASSYL.FR.DOOR LOWER <i>x R / CUT</i>	1	318.10	5	302.19	21.15	323.34
72950-T6A-003	MOLDING ASSYL.RR.DOOR <i>? x NN</i>	1	69.50	5	66.02	4.62	70.64
74450-T6A-J01ZA	GARNISH ASSYL.WHEEL ARCH <i>x R / CUT</i>	1	36.00	5	34.20	2.39	36.59
67550-T6A-000ZZ	PANEL COMPL.SLIDE DOOR <i>/ DD</i>	1	1000.50	5	950.47	66.53	1017.00
67861-T6A-305ZA	TAPE SETL.RR.DOOR SASH INNER <i>/ 1 pc</i>	1	57.10	5	54.24	3.80	58.04
72955-T6A-003	MOLDING ASSYL.QTR WINDSHIELD <i>? x NN</i>	1	109.70	5	104.21	7.29	111.50
60260-T6A-300ZZ	FENDER COMPL.FR. <i>x R</i>	1	548.60	5	521.17	36.48	557.65
04715-T6A-000ZZ	FACERR.BUMPER <i>x R</i>	1	537.50	5	510.62	35.74	546.36
71593-T6A-003	SPACERR.RR.BUMPER SIDE <i>x NN</i>	1	19.10	5	18.14	1.27	19.41
71598-T6A-003	SPACERL.RR.BUMPER SIDE <i>x NN</i>	1	19.10	5	18.14	1.27	19.41
71502-T6A-003ZA	FACER.RR.BUMPER GARNISH <i>x NN</i>	1	76.80	5	72.96	5.11	78.07
04646-T6A-J00ZZ	PANEL SETL.RR.OUTSIDE <i>/ DD</i>	1	1023.70	5 <i>944.20</i>	972.51	68.08	1040.59

Printed on 10/6/2019 1:02:31 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



KAH MOTOR CO. SDN. BHD.
 (A Member of the Oriental Holdings Berhad)
 Service and Body Repair
 Tel: +65 6841 3838 Website: www.honda.com.sg
 For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE
 3 ANSON ROAD #16-00
 SPRINGLEAF TOWER
 SINGAPORE 079909
 Registration No : SLF2151K
 Chassis No : JHMRC1880GC206106
 Model : ODYSSEY 2.4 EX-S 16YM
 Owner's Name : THAM KEANG CHUNG
 Ins Policy No. :
 Date of Accident : 30/5/2019

Document No. : SQT19002521 Page 2
 Date : 10. Jun 2019
 Customer No. : WZC008
 Svc Advisor : NG SIN HAI
 Engine No : K24W72012750
 Date | Time : 10. Jun 2019 9:36:34 AM
 Surveyor Name :
 Survey Date :
 Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
73525-SYY-000	RUBBERRR QTR W/SHIELD <i>2 X NAI</i>	2	9.70	5	18.43	1.29	19.72
73810-T6A-003	SEALR.QUARTER GLASS <i>1 X NAI</i>	1	35.10	5	33.34	2.33	35.67
91501-SMA-003	CLIP AQTR. <i>1 X NAI</i>	1	3.00	5	2.85	0.20	3.05
91501-SYA-000	CLIPQUARTER WINDSHIELD A <i>1 X NAI</i>	1	3.80	5	3.61	0.25	3.86
91513-S70-003	CLIPL <i>1 X NAI</i>	1	3.80	5	3.61	0.25	3.86
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>1 X NAI</i>	1	60.00		60.00	4.20	64.20
42700-T6A-Q81 <i>(9)</i>	DISKALUMINIUM WHEEL 17X7J <i>✓ (Rear LH) CVT</i>	1	915.00	5	869.25	60.85	930.10
Sum Item					5609.93	392.67	6,002.60

BOSUN	SUNDRIES	1	100.00		<i>30</i> 100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT.	1	80.00		80.00	5.60	85.60
BOBC	BODY UNDERSIDE COATING (N)	1	450.00		450.00	31.50	481.50
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	180.00		180.00	12.60	192.60
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00		180.00	12.60	192.60
BA02R	REMOVE & INSTALL REVERSE SENSORS-4 PCS (N)	1	180.00		180.00	12.60	192.60
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	450.00		450.00	31.50	481.50
BG52D	REMOVE & INSTALL RR. R QTR GLASS.(N)	1	380.00		<i>?</i> 380.00	26.60	406.60
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	560.00		<i>480</i> 560.00	39.20	599.20
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	560.00		560.00	39.20	599.20
BKDR12R	REMOVE & TRANSFER ITEMS TO NEW FR R DR. ADJUST	1	560.00		560.00	39.20	599.20
BKDR22R	REMOVE & TRANSFER ITEMS TO NEW RR R DR. ADJUST	1	560.00		560.00	39.20	599.20
BKFE22R	CUT & RENEW RR R FENDER. STRAIGHTEN INNER PANEL <i>7 X 560</i>	1	5000.00		<i>5920</i> 5000.00	350.00	5350.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P) <i>6 X 450</i>	1	3000.00		<i>2700</i> 3000.00	210.00	3210.00
BKBU01R	REMOVE AND RENEW LHR RIM	1	50.00		50.00	3.50	53.50
BC01R	PERFORM SETTING ON MULTI VIEW CAMERAS & SMART	1	560.00		560.00	39.20	599.20
Sum Labor					12850.00	899.50	13,749.50

Printed on 10/6/2019 1:02:31 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)
Service and Body Repair
Tel: +65 6841 3838 Website: www.honda.com.sg
For 24-hours Roadside Assistance. Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
Registration No : SLF2151K
Chassis No : JHMRC1880GC206106
Model : ODYSSEY 2.4 EX-S 16YM
Owner's Name : THAM KEANG CHUNG
Ins Policy No. :
Date of Accident : 30/5/2019

Document No. : SQT19002521 Page 3
Date : 10. Jun 2019
Customer No. : WZC008
Svc Advisor : NG SIN HAI
Engine No : K24W72012750
Date | Time : 10. Jun 2019 9:36:34 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00		180.00	12.60	192.60
Sum Ext. Service					180.00	12.60	192.60

Survey By : Steve (LKK)
Date & Time : 10/6/19, 1.30pm
Excess : _____
Status : _____
Signature : _____

Total Amount 18,639.93 1,304.77 19,944.70
Total (Inclusive of GST) 19,944.70

20620 09

9 to days P/P
Ry Btk spray

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Printed on 10/6/2019 1:02:31 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd. it will be refunded.



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZC008 / CHINA TAIPING
Chassis No: JHMRC1880GC206106
License No: SLF2151K
Mileage: 95059
Engine No: K24W72012750

Document No: SVO19036438
Printed By: SKHO
Order Date: 10. June 2019
Order Time: 2:53:41 PM
Service Advisor: NG SIN HAI

BKDR12R	0669 REMOVE & TRANSFER ITEMS TO NEW FR R DR. ADJUST & ALIGN INCLUDING FITTINGS ON ATTACHMENT ITEMS.(N)	1	560.00	560.00 /	39.20	599.20
BKDR22R	0669 REMOVE & TRANSFER ITEMS TO NEW RR R DR. ADJUST & ALIGN INCLUDING FITTINGS ON ATTACHMENT ITEMS.(N)	1	560.00	560.00 /	39.20	599.20
BKFE22R	0669 CUT & RENEW RR R FENDER, STRAIGHTEN INNER PANEL INCLUDING FITTING ON ATTACHMENT ITEMS.	1	3,920.00	3,920.00 /	274.40	4,194.40
BP06R	1610 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	2,700.00	2,700.00 /	189.00	2,889.00
BKBU01R	REMOVE AND RENEW LHR RIM	1	50.00	50.00 /	3.50	53.50
BC01R	PERFORM SETTING ON MULTI VIEW CAMERAS & SMART PARKING ASSIST SYSTEM	1	560.00	560.00 /	39.20	599.20
		SUM LABOUR:		10,310.00	721.70	11,031.70
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00	180.00 /	12.60	192.60
		SUM EXT SERVICE:		180.00	12.60	192.60
		TOTAL SGD		16,212.08	1,134.83	17,346.91
		Total Payable (SGD)				17,346.91

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICE

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZC008 / CHINA TAIPING
 Chassis No: JHMR01880GC206106
 License No: SLF2151K
 Mileage: 95059
 Engine No: K24W72012750

Document No: SVO19036438
 Printed By: SKHO
 Order Date: 10. June 2019
 Order Time: 2:53:41 PM
 Service Advisor: NG SIN HAI

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount Incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:THAM KEANG CHUNG OWNER INSURER:LIBERTY ACC DATE:30/05/2019 SURVEYED BY:STEVE DATE:10/06/2019 REF NO: TP INSURER:CHINA TAIPING TP VEH:GU3627Y SUPPLEMENTARY						
91505-TM8-003	CLIP,BUMPER	8	2.30	5	17.48	1.22	18.70
76258-T6A-J03	MIRROR SET,L	1	561.50	5	533.42	37.34	570.76
67364-T6A-305ZA	TAPE SETL.FR.DOOR SASH INNER	1	38.40	5	36.48	2.55	39.03
75332-T6A-J01ZG	GARNISH ASSYL.FR.DOOR LOWER	1	318.10	5	302.19	21.15	323.34
74450-T6A-J01ZH	GARN ASSY L,W/ARC	1	36.00	5	34.20	2.39	36.59
67550-T6A-000ZZ	PANEL COMPL.SLIDE DOOR	1	1,000.50	5	950.47	66.53	1,017.00
67861-T6A-305ZA	TAPE SETL.RR.DOOR SASH INNER	1	57.10	5	54.24	3.80	58.04
04646-T6A-J01ZZ	PANEL SET L,RR OUTSIDE	1	993.90	5	944.20	66.09	1,010.29
42700-T6A-Q81	DISKALUMINIUM WHEEL 17X7J	1	915.00	5	869.25	60.85	930.10
75333-T6A-J01ZA	GARNISH ASSYL.SLIDE DOOR LWR	1	313.70	5	298.01	20.86	318.87
72836-SHJ-A00	TAPE.SLIDE.DR.REFLECTOR	1	5.00	5	4.75	0.33	5.08
72965-T6A-003	MOLDINGL.SLIDE DOOR RETAINER	1	96.60	5	91.77	6.42	98.19
67050-T6A-000ZZ	PANEL COMPL.FR.DOOR	1	895.20	5	850.44	59.53	909.97
67365-T6A-J01	TAPE,L.FR.DOOR SASH UPPER	1	37.30	5	35.43	2.48	37.91
76251-T6A-J01ZL	SKULLCAP,L,ST	1	66.00	5	62.70	4.39	67.09
72181-T6A-J71	HANDLE COMPL.FR.	1	315.90	5	300.10	21.01	321.11
72183-SZW-J01	COVER COMPL.FR.	1	40.30	5	38.28	2.68	40.96
72450-T6A-003	MOLDING ASSYL.FR.DOOR	1	73.90	5	70.20	4.91	75.11
72496-T6A-003	GARNISHL.FR.CENTER CORNER	1	5.50	5	5.22	0.37	5.59
73163-T6A-013	MOLDINGL.DRIP SIDE	1	235.00	5	223.25	15.63	238.88
	SUM PARTS:				5,722.08	400.53	6,122.61
BOSUN	0701 SUNDRIES	1	30.00		30.00	2.10	32.10
BOJSE	1610 BODY JOINT SEALANT.	1	80.00		80.00	5.60	85.60
BOBC	1610 BODY UNDERSIDE COATING (N)	1	450.00		450.00	31.50	481.50
BML02I	1610 INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	180.00		180.00	12.60	192.60
BA02R	0669 REMOVE & INSTALL REVERSE SENSORS-4 PCS (N)	1	180.00		180.00	12.60	192.60
BC012R	0669 RESET VEHICLE SMART ENTRY	1	480.00		480.00	33.60	513.60
BMI03D	1757 REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES (N)	1	560.00		560.00	39.20	599.20

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651, Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937, Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICE

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: ****9724Z / THAM KEANG

Chassis No: JHMRC1880GC206106

License No: SLF2151K

Mileage: 95059

Engine No: K24W72012750

Document No: SVO19036438

Printed By: SKHO

Order Date: 10. June 2019

Order Time: 2:53:41 PM

Service Advisor: NG SIN HAI

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount Incl GST
	SUPPLEMENTARY						
75333-T6A-J01ZA	GARNISH ASSYL.SLIDE DOOR LWR / CUT	1	313.70	5	298.01	20.86	318.87
72838-SHJ-A00	TAPESLIDE.DR.REFLECTOR. / NPC	1	5.00	5	4.75	0.33	5.08
72965-T6A-003	MOLDINGL.SLIDE DOOR RETAINER / RT	1	98.80	5	91.77	6.42	98.19
67050-T6A-000ZZ	PANEL COMPL.FR.DOOR / DD	1	895.20	5	850.44	59.53	909.97
67385-T6A-J01	TAPE,L.FR.DOOR SASH UPPER / NPC	1	37.30	5	35.43	2.48	37.91
76251-T6A-J01ZL	SKULLCAP,L ST / Rpt	1	68.00	5	62.70	4.39	67.09
72181-T6A-J71	HANDLE COMPL.FR. /	1	315.90	5	300.10	21.01	321.11
72183-SZW-J01	COVER COMPL.FR. / CUT	1	40.30	5	38.28	2.68	40.96
72450-T6A-003	MOLDING ASSYL.FR.DOOR / CUT	1	73.90	5	70.20	4.91	75.11
72496-T6A-003	GARNISHL.FR.CENTER CORNER / NPC	1	5.50	5	5.22	0.37	5.59
73163-T6A-013	MOLDINGL.DRIP SIDE / GR	1	235.00	5	223.25	15.63	238.88
SUM PARTS:					1,980.15	138.61	2,118.76
TOTAL SGD					1,980.15	138.61	2,118.76

Total Payable (SGD)

2,118.76

GST Amount is calculated from individual line(s)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Jun 2019		13 Jun 2019 10:44 Edit Adj Rpt	S\$16,212.08 Edit Estimates	S\$16,212.08 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured: -, Co. Reg. No.: -									
Main Claimant: THAM KEANG CHUNG , ID: S68097242									
Vehicle Reg. No.: SLF2151K		Date of Loss: 30/05/2019 18:00 - :59 [33 Months and 12 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM19D202459C02		Policy/Cover Note No.: DMCVSN16769119022							
Vehicle Reg. No. (Insured): GU3672Y		Policy No. (Claimant):							
		Excess: S\$0.00							
Repairer: Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]									
Claimant's Insurer: Liberty Insurance Pte Ltd (HQ) - Tel: (65) 6221 8611									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 24/06/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLF2151K (SNM19D202459C02)
[GU3672Y]
TP
THAM KEANG CHUNG
May 30 2019 6:00PM
[-]
Kah Motor Co Sdn Bhd

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Video								1 per page		☐	☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)						Thumbnail	Print		
1	31/05/19 21:17	Video - Accident [Linked Accident Report Documents]							Load MOV		☐
Assessment Reports								1 per page		☐	☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)						Thumbnail	Print		
1	31/05/19 21:32	Accident Statement							Load HTM		☐
Photos/Images								3 per page		☐	☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)						Thumbnail	Print		
1	31/05/19 21:28	Accident Photo [Linked Accident Report Documents]							Load JPG		☒
2	31/05/19 21:28	Accident Photo [Linked Accident Report Documents]							Load JPG		☒
3	31/05/19 21:28	Accident Photo [Linked Accident Report Documents]							Load JPG		☒
4	31/05/19 21:28	Accident Photo [Linked Accident Report Documents]							Load JPG		☒
5	31/05/19 21:28	Accident Photo [Linked Accident Report Documents]							Load JPG		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	22/06/19 16:45	General View							Load JPG		☒
2	22/06/19 16:45	General View							Load JPG		☒
3	22/06/19 16:45	General View							Load JPG		☒
4	22/06/19 16:45	General View							Load JPG		☒
5	22/06/19 16:45	Odometer Reading							Load JPG		☒
6	22/06/19 16:45	Odometer Reading							Load JPG		☒
7	22/06/19 16:45	General View							Load JPG		☒
8	22/06/19 16:45	General View							Load JPG		☒
9	22/06/19 16:45	General View							Load JPG		☒
10	22/06/19 16:45	General View							Load JPG		☒
11	22/06/19 16:45	General View							Load JPG		☒
12	22/06/19 16:45	General View							Load JPG		☒
13	22/06/19 16:45	General View							Load JPG		☒
14	22/06/19 16:45	General View							Load JPG		☒
15	22/06/19 16:45	General View							Load JPG		☒
16	22/06/19 16:45	General View							Load JPG		☒
17	22/06/19 16:45	General View							Load JPG		☒
18	22/06/19 16:45	General View							Load JPG		☒
19	22/06/19 16:45	General View							Load JPG		☒
20	22/06/19 16:45	General View							Load JPG		☒
21	22/06/19 16:45	General View							Load JPG		☒
22	22/06/19 16:45	General View							Load JPG		☒

Video			1 per page	☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
23	22/06/19 16:45	General View	 Load JPG	☒
24	22/06/19 16:45	General View	 Load JPG	☒
25	22/06/19 16:45	General View	 Load JPG	☒
26	22/06/19 16:45	General View	 Load JPG	☒
27	22/06/19 16:45	General View	 Load JPG	☒
28	22/06/19 16:45	General View	 Load JPG	☒
29	22/06/19 16:45	General View	 Load JPG	☒
30	22/06/19 16:45	General View	 Load JPG	☒
31	22/06/19 16:45	General View	 Load JPG	☒
32	22/06/19 16:45	General View	 Load JPG	☒
33	22/06/19 16:45	General View	 Load JPG	☒
34	22/06/19 16:45	General View	 Load JPG	☒
35	22/06/19 16:45	General View	 Load JPG	☒
36	22/06/19 16:45	General View	 Load JPG	☒
37	22/06/19 16:45	General View	 Load JPG	☒
38	22/06/19 16:45	General View	 Load JPG	☒
39	22/06/19 16:45	General View	 Load JPG	☒
40	22/06/19 16:45	General View	 Load JPG	☒
41	22/06/19 16:45	General View	 Load JPG	☒
42	22/06/19 16:45	General View	 Load JPG	☒
43	22/06/19 16:45	General View	 Load JPG	☒
44	22/06/19 16:45	General View	 Load JPG	☒
45	22/06/19 16:45	General View	 Load JPG	☒
46	22/06/19 16:45	Reinspection Photo	 Load JPG	☒
47	22/06/19 16:45	Reinspection Photo	 Load JPG	☒
48	22/06/19 16:45	Reinspection Photo	 Load JPG	☒
49	22/06/19 16:45	Reinspection Photo	 Load JPG	☒
50	22/06/19 16:45	Reinspection Photo	 Load JPG	☒
51	22/06/19 16:45	Reinspection Photo	 Load JPG	☒
52	22/06/19 16:45	Reinspection Photo	 Load JPG	☒
53	22/06/19 16:45	Reinspection Photo	 Load JPG	☒
54	22/06/19 16:45	Reinspection Photo	 Load JPG	☒
55	22/06/19 16:45	Reinspection Photo	 Load JPG	☒
56	22/06/19 16:45	Reinspection Photo	 Load JPG	☒
57	22/06/19 16:45	Reinspection Photo	 Load JPG	☒
58	22/06/19 16:45	Reinspection Photo	 Load JPG	☒
59	22/06/19 16:45	Reinspection Photo	 Load JPG	☒
60	22/06/19 16:45	Reinspection Photo	 Load JPG	☒
61	22/06/19 16:45	Reinspection Photo	 Load JPG	☒
62	22/06/19 16:45	Reinspection Photo	 Load JPG	☒
63	22/06/19 16:45	Reinspection Photo	 Load JPG	☒
64	22/06/19 16:45	Reinspection Photo	 Load JPG	☒
65	22/06/19 16:45	Reinspection Photo	 Load JPG	☒
66	22/06/19 16:45	Reinspection Photo	 Load JPG	☒
67	22/06/19 16:45	Reinspection Photo	 Load JPG	☒
68	22/06/19 16:45	Reinspection Photo	 Load JPG	☒
69	22/06/19 16:45	Reinspection Photo	 Load JPG	☒
70	22/06/19 16:45	Reinspection Photo	 Load JPG	☒
71	22/06/19 16:45	Reinspection Photo	 Load JPG	☒
72	22/06/19 16:45	Reinspection Photo	 Load JPG	☒

Video			1 per page	☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
73	22/06/19 16:45	Reinspection Photo	 Load JPG	☒
74	22/06/19 16:45	Reinspection Photo	 Load JPG	☒
75	22/06/19 16:45	Reinspection Photo	 Load JPG	☒
76	22/06/19 16:45	Reinspection Photo	 Load JPG	☒
77	22/06/19 16:45	Reinspection Photo	 Load JPG	☒
78	22/06/19 16:45	Reinspection Photo	 Load JPG	☒
79	22/06/19 16:45	Reinspection Photo	 Load JPG	☒
80	22/06/19 16:45	Reinspection Photo	 Load JPG	☒
81	22/06/19 16:45	Reinspection Photo	 Load JPG	☒
82	22/06/19 16:45	Reinspection Photo	 Load JPG	☒
83	22/06/19 16:45	Reinspection Photo	 Load JPG	☒
84	22/06/19 16:45	Reinspection Photo	 Load JPG	☒
85	22/06/19 16:45	Reinspection Photo	 Load JPG	☒
86	22/06/19 16:45	Reinspection Photo	 Load JPG	☒
87	22/06/19 16:45	Reinspection Photo	 Load JPG	☒
88	22/06/19 16:45	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	13/06/19 10:48	pri contact	 Load PDF	
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	31/05/19 21:32	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/07/19 17:47	Supplementary	 Load PDF	

Linked Accident Report Documents

Video			1 per page	☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	31/05/19 21:17	Video - Accident	 Load MOV	
Assessment Reports			1 per page	☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	31/05/19 21:32	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	31/05/19 21:28	Accident Photo	 Load JPG	☒
2	31/05/19 21:28	Accident Photo	 Load JPG	☒
3	31/05/19 21:28	Accident Photo	 Load JPG	☒
4	31/05/19 21:28	Accident Photo	 Load JPG	☒
5	31/05/19 21:28	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	31/05/19 21:32	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT19009737/ETD3E2

Date: 04/07/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN16769119022
Claimant Vehicle No :	SLF2151K	Insured Vehicle No :	GU3872Y
Date of Loss:	30/05/2019	Nature of Claim:	TP
		Claim No:	SNM19D202459C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLF2151K	Engine No:	K24W72012750
Make & Model:	HONDA ODYSSEY, 2.4 (A)	Chassis No:	JHMRC1880GC206106
Reg. Date:	18/08/2016 (Man. Year: 2016)	Odometer:	105478 km
Colour:	Blue		
Engine Capacity:	2356 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Falken 7 mm	Rear Left Side:	Falken 7 mm
Front Right Side:	Falken 7 mm	Rear Right Side:	Falken 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,690.08	5,752.08	1,938.00	25.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,930.00	10,460.00	2,470.00	19.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	20,620.08	16,212.08	4,408.00	21.38
+ GST 7.00/7.00% (\$\$)	1,443.41	1,134.85	308.56	21.38
Nett Amount (\$\$)	22,063.49	17,346.93	4,716.56	21.38

INSPECTION

Date of Assignment:	13/06/2019	Inspected At:	Kah Motor Co Sdn Bhd (Ubi)
Date Inspected:	10/06/2019		15 Ubi Road 4
			Singapore 408610
Estimated Period of Repair:	9.0 days		

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 04 Jul 2019)	
Parts: M1-MPV	HONDA ODYSSEY 2.4 (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SLF2151K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*CLIP, BUMPER (8PCS)	Necessary	17.48 FS	*17.48 FS
2	1		*CAPR.SKULL	Missing	62.70 FS	*62.70 FS
3	1		*MIRROR SET,L	Cut	533.42 FS	*533.42 FS
4	1		*GARNISH ASSYL.FR.DOOR LOWER	Repair	302.19 FS	*- FS
5	1		*GARNISHR.FR.CENTER CORNER	Repair	5.22 FS	*- FS
6	1		*TAPE SETL.FR.DOOR SASH INNER	Necessary	36.48 FS	*36.48 FS
7	1		*TAPE SETL.FR.DOOR SASH INNER	Not Necessary	36.48 FS	*- FS
8	1		*GARNISH ASSYL.FR.DOOR LOWER	Cut	302.19 FS	*302.19 FS
9	1		*MOLDING ASSYL.RR.DOOR	Not Necessary	66.02 FS	*- FS
10	1		*GARNISH ASSYL.WHEEL ARCH	Cut	34.20 FS	*34.20 FS
11	1		*PANEL COMPL.SLIDE DOOR	Dented	950.47 FS	*950.47 FS
12	1		*TAPE SETLRR.DOOR SASH INNER	Necessary	54.24 FS	*54.24 FS
13	1		*MOLDING ASSYL.QTR WINDSHIELD	Not Necessary	104.21 FS	*- FS
14	1		*FENDER COMPL.FR.	Repair	521.17 FS	*- FS
15	1		*FACERR.BUMPER	Repair	510.62 FS	*- FS
16	1		*SPACERRR.RR.BUMPER SIDE	Not Necessary	18.14 FS	*- FS
17	1		*SPACERL.RR.BUMPER SIDE	Not Necessary	18.14 FS	*- FS
18	1		*FACER.RR.BUMPER GARNISH	Not Necessary	72.96 FS	*- FS
19	1		*PANEL SETL.RR.OUTSIDE	Dented	972.51 FS	*944.20 FS
20	2		*RUBBERRR QTR W/SHIELD	Not Necessary	18.43 FS	*- FS
21	1		*SEALR.QUARTER GLASS	Not Necessary	33.34 FS	*- FS
22	1		*CLIP AQTR	Not Necessary	2.85 FS	*- FS
23	1		*CLIPQUARTER WINDSHIELD A	Not Necessary	3.61 FS	*- FS
24	1		*CLIPL	Not Necessary	3.61 FS	*- FS
25	1		*WINDSCREEN SEALANT	Not Necessary	60.00 FS	*- FS
26	1		*DISKALUMINIUM WHEEL 17X7J	Cut	869.25 FS	*869.25 FS
27	1		*SUNDRIES	Necessary	100.00 FS	*30.00 FS
28	1		*GARNISH ASSYL.SLIDE DOOR LWR	Cut	298.01 FS	*298.01 FS
29	1		*TAPESLIDE.DR.REFLECTOR.	Necessary	4.75 FS	*4.75 FS
30	1		*MOLDINGL.SLIDE DOOR RETAINER	Bent	91.77 FS	*91.77 FS
31	1		*PANEL COMPL.FR.DOOR	Dented	850.44 FS	*850.44 FS
32	1		*TAPE,L.FR.DOOR SASH UPPER	Necessary	35.43 FS	*35.43 FS
33	1		*HANDLE COMPL.FR.	Cut	300.10 FS	*300.10 FS
34	1		*COVER COMPL.FR.	Cut	38.28 FS	*38.28 FS
35	1		*MOLDING ASSYL.FR.DOOR	Cut	70.20 FS	*70.20 FS
36	1		*GARNISHL.FR.CENTER CORNER	Necessary	5.22 FS	*5.22 FS
37	1		*MOLDINGL.DRIP SIDE	Broken	223.25 FS	*223.25 FS
38	1		*SKULLCAP,L.ST	Repeated	62.70 FS	*- FS

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Total Parts (S\$)	7,690.08	5,752.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	BODY JOINT SEALANT	New	80.00	80.00
2	BODY UNDERSIDE COATING	New	450.00	450.00
3	INSPECT FR LIGHTING MECHANISMS & FOCUS	New	180.00	0.00
4	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	New	180.00	180.00
5	REMOVE & INSTALL REVERSE SENSORS-4 PCS	New	180.00	180.00
6	APPLY BODY UNDERSIDE COATING	New	450.00	0.00
7	REMOVE & INSTALL RR.R QTR GLASS	New	380.00	0.00
8	RESET VEHICLE SMART ENTRY SYSTEM	New	560.00	480.00
9	REMOVE & INSTALL REAR COMPARTMENT LININGS	New	560.00	560.00
10	REMOVE & TRANSFER ITEMS TO NEW FR R DR. ADJUST	New	560.00	560.00
11	REMOVE & TRANSFER ITEMS TO NEW RR R DR. ADJUST	New	560.00	560.00
12	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (6P)	New	3,000.00	2,700.00
13	REMOVE & RENEW LHR RIM	New	50.00	50.00
14	PERFORM SETTING ON MULTI VIEW CAMERAS & SMART	New	560.00	560.00
15	WHEEL ALIGNMENT X4	New	180.00	180.00
16	CUT & RENEW RR R FENDER. STRAIGHTEN INNER PANEL	New	5,000.00	3,920.00
Gross Labour Cost (\$\$)			12,930.00	10,460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >