

ASS. REC. BY:

REF:

CS/OBE19009739/KH302

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person):

Joyce Foo

of

OBE

Date/Time:

03/6/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMC 2611D

Insured:

SKH 3111X

at Workshop m/s

YEE AUTO

Tel:

64575768

of

160 S/M Drive # 0277 S/M AUTO City

Policy No:

Claim No:

UC 012644

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

30/5/19

CA / REV / REP. / REV 24 HRS

WP

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN / OUT

Date/Time	Action/Instruction	Estimate ()
	SMC 2611D	
	SKH 3111X	CS/OBE19009727/KH302 D.O.A: 30/5/19
26/7	11 Pm @ 760a email & confirm (red: 13284.00; 63%)	

Nivitha (LKK Auto)

From: Shu Pei (LKKAuto) <shupe@lkkauto.com>
Sent: Monday, 3 June 2019 9:55 AM
To: assignments
Subject: FW: PRE-REPAIR INSPECTION OF VEHICLE SMC 2611D ACCIDENT ON 30.05.2019 @ 1620HOUR INVOLVING SMC 2611D AND SKH 3111X AT TAN TOCK SENG HOSPITAL A&E CARPARK
Attachments: QBE-PRI -SMC 2611D VS SKH 3111X.pdf; GBH1249C.pdf

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupe@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Joyce Foo <joyce.foo@qbe.com>
Sent: Monday, 3 June 2019 9:43 AM
To: Admin A <admin-a@lkkauto.com>
Cc: kkrishna@singnet.com.sg
Subject: FW: PRE-REPAIR INSPECTION OF VEHICLE SMC 2611D ACCIDENT ON 30.05.2019 @1620HOUR INVOLVING SMC 2611D AND SKH 3111X AT TAN TOCK SENG HOSPITAL A&E CARPARK

Our Ref. VC012644

Hi

Please assist to arrange for TP survey.

Thanks & Best Regards

Joyce Foo

Senior Assistant

Claims Dept/Asia

1 Raffles Quay, #29-10 South Tower, Singapore 048583

+65 64771184 | +65 62246633

Website LinkedIn Twitter



From: kkrishna@singnet.com.sg <kkrishna@singnet.com.sg>
Sent: Friday, 31 May 2019 1:29 PM

To: claims-singapore <claims-singapore@qbe.com>; Joyce Foo <joyce.foo@qbe.com>

Subject: PRE-REPAIR INSPECTION OF VEHICLE SMC 2611D ACCIDENT ON 30.05.2019 @1620HOUR INVOLVING SMC 2611D AND SKH 3111X AT TAN TOCK SENG HOSPITAL A&E CARPARK

Dear Sirs

Please see attached letter herein and revert urgently for the PRI to be arranged as soon as possible.

Regards

Farida on behalf of K. Krishna & Partners

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

K. KRISHNA & PARTNERS

Advocates & Solicitors
Commissioner for Oaths/Notary Public
(UEN No. 53131210X)

GST Registration No. M90371530C
101 Cecil Street #24-03/04 Tong Eng Building, Singapore 069533
Tel : 6323 3038 Fax : 6323 2120 (not for service of Court documents)
E-mail : kkrishna@singnet.com.sg

K. Krishnamoorthi
LLB (Hons) (London)
Barrister-at-Law (Gray's Inn)
B.Sc (Hons) (Est. Man) (S'pore)

S. Manohar
LLB (Hons) (S'pore)

Vengadesh s/o Kumaravelu
LLB (Hons)

Our Ref : SM.PRI-YEE AUTO SMC 2611D

31 May 2019

QBE Insurance (Singapore) Pte Ltd
1 Raffles Quay
#29-01
South Tower
Singapore 048583

Attention: Motor Claims Department

Dear Sirs

PRE-REPAIR INSPECTION OF VEHICLE SMC 2611D
ACCIDENT ON 30.05.2019 @1620HOUR INVOLVING SMC 2611D AND SKH 3111X AT
TAN TOCK SENG HOSPITAL A&E CARPARK

We act for Ms Boey Siong Fatt , the owner of motor vehicle no. **SMC 2611D** which was involved in the above captioned accident

We are instructed that the accident was caused by the negligence of the driver of motor vehicle no. **SKH 3111X**. Our search shows that you are the insurers of motor vehicle no. **SKH 3111X**.

We are requested to inform you that our client's vehicle is available for pre-repair inspection at the following address :-

M/S YEE AUTO PTE LTD
160 Sin Min Drive #02-17
Sin Ming Auto City
Singapore 575722
Tel; 64575768 Fax : 62528459

IMMEDIATE ATTENTION

FAX & EMAIL : joyce.heng@qbe.com
claim-singapore@qbe.com

PRE-REPAIR INSPECTION

-2-

K. KRISHNA & PARTNERS
Advocates & Solicitors

31 May 2019
QBE Insurance (Singapore) Pte Ltd

Please note that our client wishes to appoint their own surveyor to carry out for the PRI.

Please contact our client's workshop, **Mr Chan Kai Yee of M/s Yee Auto Pte Ltd** at his mobile no. **96874031** within **forty-eight (48) hours** from receipt of this fax to arrange for the inspection.

Yours faithfully



cc. workshop - (by email)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	31/05/2019 09:42
Date Of Accident	30/05/2019 16:20
Exact Location Of Accident	TAN TOCK SENG HOSPITAL A&E CARPARK
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SMC2611D
Insured/Policyholder	
Name Of Registered Owner	BOEY SIONG FATT
NRIC No	S0040620A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92287655
Alternative Phone No	OFFICE-92287655
Vehicle Particulars	
Manufacturer	MERCEDES-BENZ
Model	-
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	LONPAC INSURANCE BHD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	Z18VP05019684
Cover Note Number	
Driver	
Name of Driver	BOEY LIH HAN
NRIC No	S7705583E
Date Of Birth	25/02/1977
Occupation	INDOOR
Date Of Driving Pass	27/11/2012
Driving Experience	6 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92287655
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	-
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	DRIZZLING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

refer attached report.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKH3111X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

(A) SMC 2611 D

(B) SKH 3111 X



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 30/5/2019 at 4:20 pm. I Vehicle (A) SMC 2611 D at Tan Tock Seng Hospital A x E Carpark. I was going straight to exit. The Vehicle (B) SKH 3111 X with haze light was parking stationary. Suddenly, the Vehicle (B) SKH 3111 X dash out from my right hand side and hit my vehicle's right portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Boon
 Policyholder's Signature
 Date & Time:

[Signature] 31/5/19
 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

[Signature]
 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopte ltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S : QBE Insurance (Singapore) Pte Ltd
 1 Raffles Quay
 #29-01 South Tower
 Singapore 048583

Estimate No: ES1900014

Date: 03 Jun 2019

Policy No:

Veh Reg No: SMC2611D

Make/Model: MERCEDES BEN E200
 SEDAN (R17)

Chassis No: WDD2120342A789009

Engine No: 27492030055625

Reg. Date: 05/09/2013

ATTN: Motor Claim Department

Your Ref No: -

Claim Type: Third Party

Accident Date: 30/05/2019

TP Veh Reg No: SKH3111X

Not Authorized
6 days
6 days
6 days
6 days

Estimate Repair Cost to Vehicle No :SMC2611D

Description	U/Price	Quantity	List Price	Amount
			SS	SS
Net Price				
1 REAR REVERSE SENSORS - RH	368.00	1 PC	368.00	X
2 REAR TYRE - RH	380.00	1 PC	380.00	X
3 REAR WHEEL RIM - RH	850.00	1 PC	850.00	✓
			1,598.00	1,598.00
Spare Parts				
4 FRONT DOOR - RH	2,260.00	1 PC	2,260.00	✓
5 FRONT DOOR GLASS MOTOR RIVET	100.00	1 SET	100.00	✓
6 FRONT DOOR LOCK - RH	678.10	1 PC	678.10	X
7 FRONT DOOR LOWER MOUNLDING - RH	348.50	1 PC	348.50	✓
8 FRONT DOOR OUTER MOULDING - RH	328.00	1 PC	328.00	✓
9 FRONT DOOR WEATHERSTRIP - RH	298.20	1 PC	298.20	50% ✓
10 REAR BUMPER	1,570.00	1 PC	1,570.00	X
11 REAR BUMPER CLIPS	80.00	1 SET	80.00	✓
12 REAR BUMPER SIDE MOULDING - RH	190.00	1 PC	190.00	✓
13 REAR BUMPER SIDE RETAINER - LH	98.50	1 PC	98.50	X
14 REAR BUMPER SIDE RETAINER - RH	98.50	1 PC	98.50	X
15 REAR DOOR - RH	2,260.00	1 PC	2,260.00	✓
16 REAR DOOR GLASS MOTOR RIVET	100.00	1 SET	100.00	✓
17 REAR DOOR LOCK - RH	678.10	1 PC	678.10	X
18 REAR DOOR LOWER MOULDING - RH	284.20	1 PC	284.20	✓
19 REAR DOOR OUTER MOULDING - RH	328.00	1 PC	328.00	✓
20 REAR DOOR WEATHERSTRIP - RH	298.20	1 PC	298.20	50% ✓
21 REAR DRIVESHAFT - RH	1,588.00	1 PC	1,588.00	X
22 REAR IDLE ARM - RH	185.00	1 PC	185.00	X
23 REAR KNUCKLE ARM - RH	585.00	1 PC	585.00	✓
24 REAR KNUCKLE ARM BEARING - RH	325.00	1 PC	325.00	✓
25 REAR LOWER ARM - RH	459.00	1 PC	459.00	✓
26 REAR ROCKER PANEL COVER - RH	668.50	1 PC	668.50	X
27 REAR SHOCK ABSORBER - RH	678.00	1 PC	678.00	✓
28 REAR STAY BAR - RH	268.00	1 PC	268.00	X
29 REAR TRAILING ARM - RH	192.00	1 PC	192.00	✓
			14,946.80	14,946.80
Labour				
30 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	1,500.00	1 JOB	1,500.00	✓

10%

Wheel Alignment repair



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopteltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S : QBE Insurance (Singapore) Pte Ltd
1 Raffles Quay
#29-01 South Tower
Singapore 048583

Estimate No: **ES1900014**
Date: 03 Jun 2019
Policy No:
Veh Reg No: **SMC2611D**
Make/Model: MERCEDES BEN E200
SEDAN (R17)
Chassis No: WDD2120342A789009
Engine No: 27492030055625
Reg. Date: 05/09/2013

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 30/05/2019
TP Veh Reg No: SKH3111X

Estimate Repair Cost to Vehicle No :SMC2611D

Description	U/Price	Quantity	List Price	Amount
31 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	1,500.00	1 JOB	1,500.00	1000
32 TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL.	150.00	1 JOB	150.00	60
33 TO REMOVE/TRANSFER RH FRONT DOOR AND REAR DOOR MECHANISMS.	400.00	1 JOB	400.00	160
34 TO CHECK DIAGNOSTICS.	250.00	1 PC	250.00	X
35 TO CHECK WIRING FUNCTIONS.	120.00	1 JOB	120.00	30
36 WHEEL ALIGNMENT	120.00	1 T	120.00	60
37 TO REMOVE/REPLACE UNDERCARRIAGE LABOUR.	300.00	1 PC	300.00	760
			4,340.00	4,340.00

Total S\$ 20,884.80
Add GST @ 7% 1,461.94
Total Amount Payable S\$ 22,346.74

TOTAL: SINGAPORE DOLLAR TWENTY TWO THOUSAND THREE HUNDRED FORTY SIX AND CENTS SEVENTY FOUR ONLY

For Yee Auto Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SIN MING AUTOCITY



Work Order: R006301
 Name 2: YEE AUTO PTE LTD
 License: SMC 2611 D
 Technician: AH MAK
 Date: 3.6.19 13:15

Mercedes-Benz : 212 (E Class 2009-16) : Rear Wheel Drive : Sedan (W) Steel Spring Suspension Europe version/USA :
 Standard Suspension (Code 485)
 4-Wheel Total Alignment

Front : Left

Actual	Before	Specified Range
-0°44'		-0°45' -0°02'
0°00'		
0°02'		0°00' 0°10'
0°44'		
0°00'		
		-2°24' -1°24'

Camber
 Caster
 Toe
 SAI
 Included Angle
 Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°35'		-0°45' -0°02'
0°00'		
0°10'		0°00' 0°10'
0°35'		
0°00'		
		-2°24' -1°24'

Front

Cross Camber
 Cross Caster
 Cross SAI
 Total Toe
 Cross Turn Diff.

Actual	Before	Specified Range
-0°08'		-0°24' 0°24'
0°00'		-0°30' 0°30'
0°08'		
0°12'		0°00' 0°20'

Rear : Left

Actual	Before	Specified Range
-0°36'		-1°33' -0°33'
0°16'		0°04' 0°18'

Camber
 Toe

Rear : Right

Actual	Before	Specified Range
-3°11'		-1°33' -0°33'
1°39'		0°04' 0°18'

Rear

Cross Camber
 Total Toe
 Thrust Angle

Actual	Before	Specified Range
2°35'		-0°30' 0°30'
1°55'		0°14' 0°29'
-0°41'		-0°15' 0°15'



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
QBE INSURANCE (SINGAPORE) PTE LTD		Ref : CS/QBE19009739/Ktd3e2	
1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583		Date : 13-08-2019	
		Code : QBE	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKH 3111X	Veh. Inspected	SMC 2611D
Policy No.		Coverage (\$)	0.00
Claim No.	VC012644	Excess (\$)	0.00
Assign From	JOYCE FOO	Assign Date	03/06/2019
2. Vehicle Particulars & Condition			
Make & Model	MERCEDES BENZ E200 (A)	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	WDD2120342A789009	Colour	METALLIC GREY
Odometer	96315	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	245/45 R17	CONTINENTAL	7 mm
L/H Front Tyre	245/45 R17	CONTINENTAL	7 mm
R/H Rear Tyre	245/45 R17	CONTINENTAL	7 mm
L/H Rear Tyre	245/45 R17	CONTINENTAL	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND UNDERCARRIAGE PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	30/05/2019	Inspection Date	03/06/2019
Survey held at	160 SIN MING DRIVE #02-17 SIN MING AUTO CITY		
Repairer	YEE AUTO SERVICE		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMC 2611D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT DOOR - RH	BENT	2,260.00	2,080.00
1	SET FRONT DOOR GLASS MOTOR RIVET	NOT NECESSARY	100.00	-
1	FRONT DOOR LOCK - RH	TO REPAIR SEE LABOUR	678.10	-
1	FRONT DOOR LOWER MOULDING - RH	NECESSARY	348.50	124.00
1	FRONT DOOR OUTER MOULDING - RH	NECESSARY	328.00	129.00
1	REAR BUMPER	TO REPAIR SEE LABOUR	1,570.00	-
1	SET REAR BUMPER CLIPS	NECESSARY	80.00	80.00
1	REAR BUMPER SIDE MOULDING - RH	NECESSARY	190.00	132.65
1	REAR BUMPER SIDE RETAINER - LH	SERVICEABLE	98.50	-
1	REAR BUMPER SIDE RETAINER - RH	SERVICEABLE	98.50	-
1	REAR DOOR - RH	BENT	2,260.00	2,080.00
1	SET REAR DOOR GLASS MOTOR RIVET	NOT NECESSARY	100.00	-
1	REAR DOOR LOCK - RH	TO REPAIR SEE LABOUR	678.10	-
1	REAR DOOR LOWER MOULDING - RH	NECESSARY	284.20	124.00
1	REAR DOOR OUTER MOULDING - RH	NECESSARY	328.00	129.00
1	REAR DRIVESHAFT - RH	TO REPAIR SEE LABOUR	1,588.00	-
1	REAR IDLE ARM - RH	SERVICEABLE	185.00	-
1	REAR KNUCKLE ARM - RH	BENT	585.00	585.00
1	REAR KNUCKLE ARM BEARING - RH	NECESSARY	325.00	325.00
1	REAR LOWER ARM - RH	DISTORTED	459.00	395.00
1	REAR ROCKER PANEL COVER - RH	SERVICEABLE	668.50	-
1	REAR SHOCK ABSORBER - RH	BENT	678.00	605.00
1	REAR STAY BAR - RH	SERVICEABLE	268.00	-
1	REAR TRAILING ARM - RH	DISTORTED	192.00	192.00
	LESS 10% DISCOUNT		-	-698.07
			14,350.40	6,282.58
SPECIAL NETT ITEMS				
1	REAR REVERSE SENSORS - RH (SN)	SERVICEABLE	368.00	-

Report Ref No. CS/QBE19009739/Ktd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR TYRE - RH (SN)	SERVICEABLE	380.00	-
1	REAR WHEEL RIM - RH (SN)	DENTED / CUT	850.00	850.00
1	FRONT DOOR WEATHERSTRIP - RH (SN) (@\$252.00) (50%)	NECESSARY	298.20	126.00
1	REAR DOOR WEATHERSTRIP - RH (SN) (@\$252.00) (50%)	NECESSARY	298.20	126.00
			2,194.40	1,102.00
	LABOUR			
	TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY. INCLUSIVE OF THE REPAIR OF FRONT DOOR LOCK - RH, REAR BUMPER, REAR DOOR LOCK - RH AND REAR DRIVESHAFT - RH.		1,500.00	700.00
	TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.		1,500.00	1,000.00
	TO APPLY RUST-PROOFING ON REPAIRED, REPLACED PANEL.		150.00	60.00
	TO REMOVE / TRANSFER RH FRONT DOOR AND REAR DOOR MECHANISMS.		400.00	160.00
	TO CHECK DIAGNOSTICS.	NOT NECESSARY	250.00	-
	TO CHECK WIRING FUNCTIONS.		120.00	30.00
	WHEEL ALIGNMENT.		120.00	60.00
	TO REMOVE / REPLACE UNDERCARRIAGE LABOUR.		300.00	160.00
			4,340.00	2,170.00
GRAND TOTAL			20,884.80	9,554.58
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				7,600.00

Report Ref No. CS/QBE19009739/Ktd3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.