

INS. CASE OWNER:

CC b/ ALG 1900 9742, Uka's

IDAC:

Surveyor:

M. P. P. P.

DOI:

ASSIGNMENT

3/6/19

Date / Time:

3/6/19

Registered in Merimen:

3/6/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLR 6713A

Claim No.:

Name of Insured:

TAN PECK KONG

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II : S

D.O.A.:

31/5/2019

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L YES / NO)

OI GIA REPORT: YES / NO; TP GIA REPORT: YES / NO

Insured Liability:

%

Final? Yes / No

STP 5266



INSRS:

WSP:

Tel:

Liability:

RMKS:

K. M. C. H. N. S.

461



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STP 5266 } N/A 11/11/2019/14 : 31/5/19
SLR 6713A

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

4/12/19
K. M. C. H. N. S.

File pass to type mandate.

14/2/2020
K. M. C. H. N. S.

File pass to MK to close

8 Rental - TP claimant / driver's
signature different.

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

415

S\$ 11,800

(12 days) Reduction:

58 %

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with Shing

Email

Call

Final Liability:

100

(Agreed / Assessed) BOLA S/N No.:

28

If NO or B 28, Ass. Lia: 100

Repair Cost:

(4/651)

S\$ 12,626

(4 VEH C.C.; 01 LAST VEH)

Loss of Rental (LOR):

S\$ 800

(8 days) x \$100

Loss of Use (LOU):

S\$ -

(\$ - x - days)

Loss of Income (LOI):

S\$ -

(\$ - x - days)

LOR only ☒ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$ 2.00

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/Independent)

Legal Cost

S\$ -

Total:

S\$ 13,428

Global Sum S\$:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

\$320

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$ 13,428

Name 1:

KIM CHWEE AUTO PTE LTD

Payee 2: (Strike if N.A.)

S\$ -

Name 2:

Payee 3: (Strike if N.A.)

S\$ -

Name 3:

(08/11/13) wef
ASS. REC. BY: *Marcus*

REF:

Alu

ICCN

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen

Consistent? : Yes or No

Est. Repairs:

12

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

47A 12/20

Vehicle: IN / OUT

Date / Time

Action / Instruction

here at 14

302 31-1-2024 4 yrs fab. net (1880)

19/6/19 4/5 # 11,800 confirmed with Alu.

*- Repair limit
- To veh 10 yrs*

CRed \$15,969.20 (58%)

Veh No: *SYP 5226E* Yr Regn: *3.09*

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda / Avento c.c 1591

Colour

Grey

A/C: Insured / Std / NI / NA

Sp. Reading

*Noting any
certified.*

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KMHDU41BR94716674

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65-R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falber

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

3.15/19

D.O.I.

3/6/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & A.

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) \$ + RS. \$

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

Kim Chwee Auto Ptd Ltd

1 Kaki Bukit Avenue 6, #01-46/48/50, Autobay, Singapore 417883

H/P: 9487 7074 Tel: 6741 7244, 6746 5405 Fax: 6745 8520, 6746 5786

Email: general@fastechauto.com.sg

Not Authorized
N/A
3/6/19
4/5 @ 11800/
1200

QTY	PARTICULAR	AMOUNT S\$
1PCS	BOOTLID	DP/Buf \$907.60 ✓
1PCS	BOOTLID REAR LOGO	ru \$25.80 ✓
1PCS	BOOTLID 'AVANTE' EMBLEM	ru \$30.80 ✓
1PCS	BOOTLID 'S' EMBLEM	ru \$28.20 ✓
1PCS	BOOTLID INNER LOCK	11 \$183.60 X
1PCS	BOOTLID WEATHERSTRIPS	1m \$165.30 ✓
2PCS	BOOTLID HINGES @ \$110.10	11 \$220.20 X
2PCS	BOOTLID REFLECTORS @ \$189.60	11 \$379.20 X
1PCS	BOOTLID INNER TRIM	11 \$185.30 X
1SET	BOOTLID INNER TRIM CLIPS	11 \$50.00 X
1PCS	REAR BUMPER	D/S \$486.90 ✓
1PCS	REAR BUMPER REINFORCEMENT	11 \$354.00 ✓
2PCS	REAR BUMPER REINFORCEMENT STAYS @ \$135	0/Buf \$270.00 1PC 135
5PCS	REAR BUMPER REINFORCEMENT BRACKETS @ \$21	11 \$105.00 X
2PCS	REAR BUMPER SIDE RETAINERS @ \$45.50	11 \$91.00 X
1SET	REAR BUMPER CLIPS	ru \$50.00 ✓
1PCS	REAR BUMPER SPONGE	To 11 \$145.30 ✓
2PCS	TAILLAMPS @ \$266.50	one \$533.00 ✓
2PCS	TAILLAMPS HOUSING PANEL @ \$185.10	ru \$370.20 X
1PCS	REAR END PANEL	Body ID \$637.90 ✓
1PCS	REAR END PANEL TOP GARNISH	7m \$188.60 ✓
1PCS	REAR FLOOR PANEL	ru \$928.10 X
1PCS	REAR FLOOR PANEL TOP BOARD	8m \$280.60 X
1PCS	REAR EXHAUST	ru \$693.80 X
2PCS	REAR EXHAUST MOUNTINGS @ \$45.00	11 \$90.00 X
1PCS	BONNET	Buf \$1,102.00 ✓
1PCS	BONNET LOCK	7m \$83.60 ✓
2PCS	BONNET HINGES @ \$89.50	Buf \$179.00 ✓
1PCS	BONNET INNER RUBBER	ru \$42.00 ✓
1PCS	BONNET INSULATOR	To 11 \$266.30 ✓
1SET	BONNET INSULATOR CLIPS	ru \$50.00 ✓
2PCS	HEADLAMPS @ \$581.60	3m \$1,163.20 ✓
1PCS	FRONT GRILLE	3m \$385.00 ✓
1PCS	FRONT GRILLE LOGO 'RS'	ru \$22.80 ✓
1PCS	FRONT BUMPER	D/S \$480.60 ✓
2PCS	FRONT BUMPER BRACKETS @ \$45.00	11 \$90.22 X
1PCS	FRONT BUMPER SPONGE	To 11 \$145.80 ✓
1PCS	FRONT BUMPER LOWER GRILLE	To 11 \$105.20 ✓

202

1PCS	FRONT BUMPER REINFORCEMENT	D.J.	\$431.50	✓
2PCS	FRONT BUMPER SIDE RETAINERS @\$36.50	11	\$73.00	X
2PCS	FRONT FENDERS @\$405.30	Sent/Sec	\$810.60	✓
2PCS	FRONT FENDER 'VVTI' EMBLEM @\$42.00	me	\$84.00	✓
1PCS	FRONT SUPPORT PANEL	Bno	\$958.00	✓
1PCS	HORN UNIT	Bel	\$90.00	✓
2PCS	FRONT SUPPORT PANEL SIDE COVERS @\$45.50	To.n	\$91.00	✓
1PCS	AIRCON CONDENSER	D.J.	\$950.00	✓
1PCS	AIRCON SUCTION HOSE	Bel	\$295.00	✓
1PCS	AIRCON DISCHARGE HOSE	Bel	\$305.00	✓
1PCS	RADIATOR	D.J.	\$885.00	✓
1PCS	RADIATOR FAN ASSY	Bno	\$685.00	✓
1PCS	Battery tray	Cra	\$162.50	✓
1SET	FRONTPANEL INNER SHIELD CLIPS O/S	11	\$50.00	X
1PC	Alternator assy	Cne	\$620.40	✓
1PCS	AIR DUCT	Cne	\$115.30	✓
	Air cleaner box		\$18,149.20	
	truffle body			
	inlet manifold			
	S.NETT washer tank			
1SET	REAR BUMPER REVERSE SENSOR			
1PCS	REAR BUMPER LOWER SKIRTING			
1PCS	REAR END PANEL SEALANT			
1PCS	REAR FLOOR PANEL INSULATOR			
1PCS	FRONT LICENSE PLATE			
1BOL	RADIATOR COOLANT			
1PCS	FRONT BUMPER LOWER SKIRTING			
1SET	FRONT HEADLAMP GARNISH			
1PCS	BATTERY			

TO CHECK WIRING	\$80.00	30
TO DISMANTLE & REPLACING REVERSE SENOR	\$80.00	50
TO DISMANTLE & REFIX SEAT CUSHION UPHOLSTERY	\$150.00	80
TO DISMANTLE & REFIX REAR EXHAUST	\$100.00	X
TO DISMANTLE & REFIX PETROL TANK	\$100.00	X
TO DISMANTLE & REPLACING BOOTLID MECHANISM	\$100.00	60
TO REFILL AIRCON GAS	\$150.00	100
TO MOUNT VEHICLE ON CAR O-LINER	\$380.00	X
LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS	\$2,800.00	1600
TO PUTTY & SPRAY PAINTING	\$2,800.00	1800

TOTAL:

\$27,769.20

- To repair damaged parts
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No modification(s) is allowed
- All damaged parts must be resurveyed and is subject to approval from Insurance Company

Acknowledged by Repairer
Signature:

29820.128

15974.90

202

12779.92

4120

16899.87 302

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3655I
Vehicle Details	
Vehicle No.:	SJP5226E
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Jun 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	HD AVANTE 1.6 A
Primary Colour:	Grey
Manufacturing Year:	2009
Engine No.:	G4FC9U622680
Chassis No.:	KMH DU41BR9U718674
Maximum Power Output:	89.7 kW (120 bhp)
Open Market Value:	\$11,974.00
Original Registration Date:	27 Mar 2009
First Registration Date:	27 Mar 2009
Transfer Count:	2
Actual ARF Paid:	\$735.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Jan 2024
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$13,024.00
COE Rebate Amount:	\$12,120.00
Total Rebate Amount:	\$12,120.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 03 Jun 2019

OK

SGCARMART.COM

Login Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Porsche Carrera C2 Cab at \$178,800



Beautiful condition
StarAd

KA-HUP
VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND
HOTLINE: 6741 9997
VIEW OUR CARS

Browse by Category

Back (1 2 3 4 5 6 7 8 9 10) Next »

Sort by Date Posted

20 results/page

184 vehicles

avante

Advanced Search

Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	avante		Any	Any	2009	Any	Any	Any	Available
	Hyundai	Avante 1.6A (New 5-yr COE)	\$25,800	\$5,150 /yr	03-Jul-2009	1,591 cc	165,000 km	Sedan	Available
A Very Well Maintained Unit With An Almost Flawless Interior. Wear And Tear Parts Have Been Replaced. Be Confident To Own This Reliable And Fuel Efficient Workhorse With Spacious Interior To Carry You...									
Posted: 03-Jun-2019 Tags: 2009 Hyundai Avante, 2009 hyundai avante, Hyundai Avante, hyundai avante, Hyundai, Avante, avante, Used Hyundai									
	Hyundai	Avante 1.6A (COE till 05/2024)	\$24,800	\$5,010 /yr	13-May-2009	1,591 cc	107,000 km	Sedan	Available
One Teacher Owner Only. Car Tested With Quiet Drive. No Under Carriage Noise And Smooth Gear Change. New Paint Work Done With Very Clean Interior. Warranty Provided. Workshop Inspection Wellcome. All Trade ...									
SmartCars Boutique Pte Ltd									
Posted: 03-Jun-2019 Tags: 2009 Hyundai Avante, 2009 hyundai avante, Hyundai Avante, hyundai avante, Hyundai, Avante, avante, Used Hyundai									
	Hyundai	Avante 1.6A (COE till 05/2024)	\$25,800	\$5,220 /yr	13-May-2009	1,591 cc	-	Sedan	Available
Full Loan Available At \$600 Plus, We Can Help To Convert To Z10 Usage If Needed. In House Loan Or Bank Loan Available! Balloon Scheme Available! Fast, Easy And Flexible Loan Approval! We Are sgCarMart ...									
88 Motor Trading									
Posted: 03-Jun-2019 Tags: 2009 Hyundai Avante, 2009 hyundai avante, Hyundai Avante, hyundai avante, Hyundai, Avante, avante, Used Hyundai									
	Hyundai	Avante 1.6A (COE till 05/2024)	\$25,800	\$5,160 /yr	30-Sep-2009	1,591 cc	-	Sedan	Available
Full Loan Available At \$600 Plus, We Can Help To Convert To Z10 Usage If Needed. In House Loan Or Bank Loan Available! Balloon Scheme Available! Fast, Easy And Flexible Loan Approval! We Are sgCarMart ...									
88 Motor Trading									
Posted: 03-Jun-2019 Tags: 2009 Hyundai Avante, 2009 hyundai avante, Hyundai Avante, hyundai avante, Hyundai, Avante, avante, Used Hyundai									
	Hyundai	Avante 1.6A S (New 5-yr COE)	\$25,788	\$5,150 /yr	26-Jun-2009	1,591 cc	107,800 km	Sedan	Available
Original Paintwork And Beautiful Original Leather Seat. Transmission System And Engine Still In Excellent State. No Further Repair Needed. Flexible Loan Scheme And Trade In Are Welcome. Please Contact...									
Posted: 03-Jun-2019 Tags: 2009 Hyundai Avante, 2009 hyundai avante, Hyundai Avante, hyundai avante, Hyundai, Avante, avante, Used Hyundai									
	Hyundai	Avante 1.6M (New 5-yr COE)	\$22,800	\$4,560 /yr	12-Oct-2009	1,591 cc	-	Sedan	Available
Full Loan Available At \$500 Plus, \$8800 Buy Without Renew COE In House Loan Or Bank Loan Available! Balloon Scheme Available! Fast, Easy And Flexible Loan Approval! We Are sgCarMart Premium Dealer! Bu...									
88 Motor Trading									
Posted: 03-Jun-2019 Tags: 2009 Hyundai Avante, 2009 hyundai avante, Hyundai Avante, hyundai avante, Hyundai, Avante, avante, Used Hyundai									
	Hyundai	Avante 1.6A S Sunroof (COE till 04/2024)	\$25,800	\$5,260 /yr	29-Apr-2009	1,591 cc	-	Sedan	Available

Compare

sgCARMART.COM

Login Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources



Incorporate your Singapore
company with an ISO 9001
Certified Firm

LEARN MORE



avante

Price Range

Depreciation

2009

Vehicle Type

Submit

Advanced
Search

Home » Used Cars » Carway » Hyundai Avante 1.6A S (COE till 02/2024)

Hyundai Avante 1.6A S (COE till 02/2024)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map



Price \$27,800

Depreciation \$5,860 /yr

Reg Date 16-Mar-2009
(4yrs 8mths 26days COE left)

Mileage 130,000 km (12.7k /yr)

Manufactured 2009

Road Tax \$738 /yr

Transmission Auto

Dereg Value \$12,208 as of today (change)

OMV \$11,943

COE \$12,864

ARF \$11,943

Engine Cap 1,591 cc

Power 89.7 kW (120 bhp)

Curb Weight 1,264 kg

No. of Owners 3

Type of Vehicle Mid-Sized Sedan

Features

1.6L 4 Cylinders 16 Valves DOHC VVT Engine, 120 BHP, 4-Speed Auto Transmission, Digital Aircon Controls, Electric Power Steering, ABS, Airbags. View specs of the Hyundai Avante (2007-2011)

Accessories

Newly Done Up Full Bodykit, Leather Seats, Upgraded Sport Rims, Pioneer Audio Player, Reverse Sensor, Alarm Remote, Spacious Rear Boot Space.

Description

One Year In House Warranty, High Loan Available, Price Above Stated Is Actual Selling Price, Company Renew COE Cars Based On Car Condition, Accident Free, STA Or VICOM Evaluation Are Welcome, Wear And Tear Replaced, New Paintwork Done, Purchase With Official Warranty Certificate For A Peace Of Mind, Bank And In House Loan Available! Free 2 x Fully Synthetic Servicing, Free Grooming, Call Us Now.

Category

COE Car

Status

Available

Resources



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Car Valuation - Free

Find out the market value of your existing car for free. Get started



Location Map

Shortlist

Report Error

Compare

More Actions

Add note

Seller Information

Company

Carway

» dealer's pricelist
» 67 vehs sold | 51 vehs available

★ PREMIUM DEALER 2019 ★

Address

61 Ubi Avenue 2 #05-09
Search cars nearby this location

Location

Automobile Megamart

Website

www.carway.com.sg

Office No

68440777

Contact Person(s)

Addy Ho 88330777
Tanisha 88665777

Posted on: 01-Jun-2019 | Last Updated on: 03-Jun-2019

Upfront Payment

» more Financial info

Transfer Fee

\$25

Claim Audit

AUDIT TRAIL

No.	On	Audit	Remarks	By
1	03 Jun 2019 13:23	Clim Dtl Modified	Claimant's Name: -> -.	[A] HOW MEI KWAN
2	03 Jun 2019 13:23	Clim Veh Model Changed	(202734) HYUNDAI AVANTE 1.6 HD (A).	[A] HOW MEI KWAN
3	03 Jun 2019 13:23	Clim Created	Reg No: SJP5226E. Acct Date: 2019/05/31. Claim Type: TP. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Workshop: Kim Chwee Auto Pte Ltd (HQ)	[A] HOW MEI KWAN
4	03 Jun 2019 13:23	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] HOW MEI KWAN
5	03 Jun 2019 13:23	Adj Next Rpt Changed	Next Rpt: Final Rpt. Due Date: 2019/06/13	[A] HOW MEI KWAN
6	03 Jun 2019 13:23	Adj Mandate Set	Approved: 8000.00. Reinsp: Adj decides.	[A] HOW MEI KWAN
7	03 Jun 2019 13:23	Clim Ins Co Changed	[200005] AIG Asia Pacific Insurance Pte. Ltd. (SG) -> [203630] AIG Asia Pacific Insurance Pte. Ltd. (Express)	[I] Merimen Administrator
8	03 Jun 2019 13:27	Label Added	(19): Fastlane.	[A] HOW MEI KWAN
9	03 Jun 2019 13:27	Adj Adjuster Assigned	[None] -> MARCUS CHUA	[A] HOW MEI KWAN
10	04 Jun 2019 12:03	Clim Dtl Modified	Claimant's Name: NA -> AMIR BASHIRUDIN BIN SAMSUDIN. Claimant's ID: NA -> S894 3655I.	[A] HOW MEI KWAN
11	26 Dec 2019 10:02	Adj Rpt Initiated		[A] NUR SHAQILAH BTE ABDOL WAHAB
12	26 Dec 2019 10:02	Clim Dtl Modified	Claim Conclusion: -> 3.	[A] NUR SHAQILAH BTE ABDOL WAHAB
13	26 Dec 2019 10:02	Clim Dtl Modified	JPJ Reg. Date: -> 2009/03/27.	[A] NUR SHAQILAH BTE ABDOL WAHAB
14	26 Dec 2019 10:02	Clim Details Notified		[A] NUR SHAQILAH BTE ABDOL WAHAB
15	02 Jan 2020 18:59	Adj Mandate Request	Cur. Req: 13428.00: 4 vehicle chain collision, Insured vehicle last. BOLA 28	[A] Khanchna Pothuraj

Date From



Date To



Audit Type None



Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2386968	26 Dec 2019 10:02:19	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SJP5226E	SLR6713A	11.77

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Tuesday, 21 January 2020 10:21 AM
To: Jason
Cc: Admin A; Ong Shiyong
Subject: RE: YOUR REF: SLR6713A MY REF: SJP5226E DOA:31/05/2019 *** LKK REF: CC6/AIG19009742/Uka3

Tracking:	Recipient	Delivery
	Jason	
	Admin A	
	Ong Shiyong	
	olivialau@lkkauto.com	Delivered: 21/1/2020 10:21 AM
	Meikwan@lkkauto.com	Delivered: 21/1/2020 10:21 AM

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

We confirm settlement as follows:

1. Cost of Repair (w/GST)	\$ 12,626.00
2. Loss of Rental (8 days x \$100)	\$ 800.00
3. LTA Search Fee	\$ 2.00
Total	\$ 13,428.00

We will proceed to do the necessary.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Wishing you a Happy and Prosperous Lunar New Year



Best Regards,
Khanchna | Case Handler
LKK Auto Consultants Pte Ltd

Print Received Message

This mail is associated with :

***SJP5226E (6936765385SG)**

[SLR6713A]

TP

AMIR BASHIRUDIN BIN SAMSUDIN

May 31 2019 12:00AM

[TAN PECK KONG]

Kim Chwee Auto Pte Ltd

From **AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS)**, sent on **20/01/2020 10:30 AM**.
To **LKK_HQ**
Subject **Alert - Adj Mandate Approved (S\$13428.00) - SJP5226E - Claim Handler: MdNoor, Norsiah**

Approved:13428.00.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Jun 2019 Edit Reg		03 Jun 2019 00:00 Edit Adj Rpt	\$11,800.00 Edit Estimates	\$11,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	TAN PECK KONG, ID: S1234121J		
Main Claimant:	AMIR BASHIRUDIN BIN SAMSUDIN, ID: S8943655I		
Vehicle Reg. No.:	SJP5226E	Date of Loss:	31/05/2019 00:00 - :59 [122 Months and 4 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 6936765385SG	Policy/Cover Note No.:	1700043771 (Comprehensive)
Vehicle Reg. No. (Insured):	SLR6713A	Policy No. (Claimant):	5106324266
		Excess:	
Repairer:	Kim Chwee Auto Pte Ltd (HQ) 1 Kaki Bukit Avenue 6 #01-48, AutoBay@Kaki Bukit, 417883 Eunos - Tel: 67465405/67417244		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 13/06/2019]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG_EXPRESS (20/01/2020): Alert - Adj Mandate Approved (\$13428.00) - SJP5226E - Claim Handler: MdNoor, No...
- AIG_SG (04/06/2019): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJP5226E (6936765385SG)**
[SLR6713A]

TP

AMIR BASHIRUDIN BIN SAMSUDIN
May 31 2019 12:00AM
[TAN PECK KONG]
Kim Chwee Auto Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page			☒		
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print		
1	(Draft)		Third Party Express Settlement – Payment Breakdown												1			Edit		
															3 per page			☒		
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print		
1	03/06/19 16:22		General View												1			Load JPG		
2	03/06/19 16:22		General View												1			Load JPG		
3	03/06/19 16:22		General View												1			Load JPG		
4	03/06/19 16:22		General View												1			Load JPG		
5	03/06/19 16:22		General View												1			Load JPG		
6	03/06/19 16:22		General View												1			Load JPG		
7	03/06/19 16:22		General View												1			Load JPG		
8	03/06/19 16:22		General View												1			Load JPG		
9	03/06/19 16:22		General View												1			Load JPG		
10	03/06/19 16:22		General View												1			Load JPG		
11	03/06/19 16:22		General View												1			Load JPG		
12	03/06/19 16:22		General View												1			Load JPG		
13	03/06/19 16:22		General View												1			Load JPG		
14	03/06/19 16:22		General View												1			Load JPG		
15	03/06/19 16:22		General View												1			Load JPG		
16	03/06/19 16:22		General View												1			Load JPG		
17	03/06/19 16:22		General View												1			Load JPG		
18	03/06/19 16:22		General View												1			Load JPG		
19	03/06/19 16:22		General View												1			Load JPG		
20	03/06/19 16:22		General View												1			Load JPG		
21	03/06/19 16:22		General View												1			Load JPG		
22	03/06/19 16:22		General View												1			Load JPG		
23	03/06/19 16:22		General View												1			Load JPG		
24	03/06/19 16:22		General View												1			Load JPG		
25	03/06/19 16:22		General View												1			Load JPG		
26	03/06/19 16:22		General View												1			Load JPG		
27	03/06/19 16:22		General View												1			Load JPG		
28	03/06/19 16:22		General View												1			Load JPG		
29	03/06/19 16:22		General View												1			Load JPG		
30	03/06/19 16:22		General View												1			Load JPG		
31	03/06/19 16:22		General View												1			Load JPG		
32	03/06/19 16:22		General View												1			Load JPG		

Letters/Correspondences			1 per page	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
33	03/06/19 16:22	General View	 Load JPG	
34	03/06/19 16:22	General View	 Load JPG	
35	03/06/19 16:22	General View	 Load JPG	
36	03/06/19 16:22	General View	 Load JPG	
37	03/06/19 16:22	General View	 Load JPG	
38	03/06/19 16:22	General View	 Load JPG	
39	03/06/19 16:22	General View	 Load JPG	
40	03/06/19 16:22	General View	 Load JPG	
41	03/06/19 16:22	General View	 Load JPG	
42	03/06/19 16:22	General View	 Load JPG	
43	03/06/19 16:22	General View	 Load JPG	
44	03/06/19 16:22	General View	 Load JPG	
45	03/06/19 16:22	General View	 Load JPG	
46	03/06/19 16:22	General View	 Load JPG	
47	03/06/19 16:22	General View	 Load JPG	
48	03/06/19 16:22	General View	 Load JPG	
49	03/06/19 16:22	General View	 Load JPG	
50	03/06/19 16:22	General View	 Load JPG	
51	03/06/19 16:22	General View	 Load JPG	
52	03/06/19 16:22	General View	 Load JPG	
53	03/06/19 16:22	General View	 Load JPG	
54	03/06/19 16:22	General View	 Load JPG	
55	03/06/19 16:22	General View	 Load JPG	
56	03/06/19 16:22	General View	 Load JPG	
57	03/06/19 16:22	General View	 Load JPG	
58	03/06/19 16:22	General View	 Load JPG	
59	03/06/19 16:22	General View	 Load JPG	
60	03/06/19 16:22	General View	 Load JPG	
61	03/06/19 16:22	General View	 Load JPG	
62	03/06/19 16:22	General View	 Load JPG	
63	03/06/19 16:22	General View	 Load JPG	
64	03/06/19 16:22	General View	 Load JPG	
65	03/06/19 16:22	General View	 Load JPG	
66	03/06/19 16:22	General View	 Load JPG	
67	03/06/19 16:22	General View	 Load JPG	
68	03/06/19 16:22	General View	 Load JPG	
69	03/06/19 16:22	General View	 Load JPG	
70	03/06/19 16:22	General View	 Load JPG	
71	03/06/19 16:22	General View	 Load JPG	
72	03/06/19 16:22	General View	 Load JPG	
73	03/06/19 16:22	General View	 Load JPG	
74	03/06/19 16:22	General View	 Load JPG	
75	03/06/19 16:22	General View	 Load JPG	
76	03/06/19 16:22	General View	 Load JPG	
77	03/06/19 16:22	General View	 Load JPG	
78	03/06/19 16:22	General View	 Load JPG	
79	03/06/19 16:22	General View	 Load JPG	
80	03/06/19 16:22	General View	 Load JPG	

Letters/Correspondences			1 per page	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
81	03/06/19 16:22	General View	 Load JPG	☒
82	03/06/19 16:22	General View	 Load JPG	☒
83	03/06/19 16:22	General View	 Load JPG	☒
84	03/06/19 16:22	General View	 Load JPG	☒
85	03/06/19 16:22	General View	 Load JPG	☒
86	03/06/19 16:22	General View	 Load JPG	☒
87	03/06/19 16:22	General View	 Load JPG	☒
88	03/06/19 16:22	General View	 Load JPG	☒
89	03/06/19 16:22	General View	 Load JPG	☒
90	03/06/19 16:22	General View	 Load JPG	☒
91	03/06/19 16:22	Reinspection Photo	 Load JPG	☒
92	03/06/19 16:22	Reinspection Photo	 Load JPG	☒
93	03/06/19 16:22	Reinspection Photo	 Load JPG	☒
94	03/06/19 16:22	Reinspection Photo	 Load JPG	☒
95	03/06/19 16:22	Reinspection Photo	 Load JPG	☒
96	03/06/19 16:22	Reinspection Photo	 Load JPG	☒
97	03/06/19 16:22	Reinspection Photo	 Load JPG	☒
98	03/06/19 16:22	Reinspection Photo	 Load JPG	☒
99	03/06/19 16:22	Reinspection Photo	 Load JPG	☒
100	03/06/19 16:22	Reinspection Photo	 Load JPG	☒
101	03/06/19 16:22	Reinspection Photo	 Load JPG	☒
102	03/06/19 16:22	Reinspection Photo	 Load JPG	☒
103	03/06/19 16:22	Reinspection Photo	 Load JPG	☒
104	03/06/19 16:22	Reinspection Photo	 Load JPG	☒
105	03/06/19 16:22	Reinspection Photo	 Load JPG	☒
106	03/06/19 16:22	Reinspection Photo	 Load JPG	☒
107	03/06/19 16:22	Reinspection Photo	 Load JPG	☒
108	03/06/19 16:22	Reinspection Photo	 Load JPG	☒
109	03/06/19 16:22	Reinspection Photo	 Load JPG	☒
110	03/06/19 16:22	Reinspection Photo	 Load JPG	☒
111	03/06/19 16:22	Reinspection Photo	 Load JPG	☒
112	03/06/19 16:23	Reinspection Photo	 Load JPG	☒
113	03/06/19 16:23	Reinspection Photo	 Load JPG	☒
114	03/06/19 16:23	Reinspection Photo	 Load JPG	☒
115	03/06/19 16:23	Reinspection Photo	 Load JPG	☒
116	03/06/19 16:23	Reinspection Photo	 Load JPG	☒
117	03/06/19 16:23	Reinspection Photo	 Load JPG	☒
118	03/06/19 16:23	Reinspection Photo	 Load JPG	☒
119	03/06/19 16:23	Reinspection Photo	 Load JPG	☒
120	03/06/19 16:23	Reinspection Photo	 Load JPG	☒
121	03/06/19 16:23	Reinspection Photo	 Load JPG	☒
122	03/06/19 16:23	Reinspection Photo	 Load JPG	☒
123	03/06/19 16:23	Reinspection Photo	 Load JPG	☒
124	03/06/19 16:23	Reinspection Photo	 Load JPG	☒
125	03/06/19 16:23	Reinspection Photo	 Load JPG	☒
126	03/06/19 16:23	Reinspection Photo	 Load JPG	☒
127	03/06/19 16:23	Reinspection Photo	 Load JPG	☒
128	03/06/19 16:23	Reinspection Photo	Load JPG	☒

Letters/Correspondences			1 per page	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
129	03/06/19 16:23	Reinspection Photo	 Load JPG	
130	03/06/19 16:23	Reinspection Photo	 Load JPG	
131	03/06/19 16:23	Reinspection Photo	 Load JPG	
132	03/06/19 16:23	Reinspection Photo	 Load JPG	
133	03/06/19 16:23	Reinspection Photo	 Load JPG	
134	03/06/19 16:23	Reinspection Photo	 Load JPG	
135	03/06/19 16:23	Reinspection Photo	 Load JPG	
136	03/06/19 16:23	Reinspection Photo	 Load JPG	
137	03/06/19 16:23	Reinspection Photo	 Load JPG	
138	03/06/19 16:23	Reinspection Photo	 Load JPG	
139	03/06/19 16:23	Reinspection Photo	 Load JPG	
140	03/06/19 16:23	Reinspection Photo	 Load JPG	
141	03/06/19 16:23	Reinspection Photo	 Load JPG	
142	03/06/19 16:23	Reinspection Photo	 Load JPG	
143	03/06/19 16:23	Reinspection Photo	 Load JPG	
144	03/06/19 16:23	Reinspection Photo	 Load JPG	
145	03/06/19 16:23	Reinspection Photo	 Load JPG	
146	03/06/19 16:23	Reinspection Photo	 Load JPG	
147	03/06/19 16:23	Reinspection Photo	 Load JPG	
148	03/06/19 16:23	Reinspection Photo	 Load JPG	
149	03/06/19 16:23	Reinspection Photo	 Load JPG	
150	03/06/19 16:23	Reinspection Photo	 Load JPG	
151	03/06/19 16:23	Reinspection Photo	 Load JPG	
152	03/06/19 16:23	Reinspection Photo	 Load JPG	
153	03/06/19 16:23	Reinspection Photo	 Load JPG	
154	03/06/19 16:23	Reinspection Photo	 Load JPG	
155	03/06/19 16:23	Reinspection Photo	 Load JPG	
156	03/06/19 16:23	Reinspection Photo	 Load JPG	
157	03/06/19 16:23	Reinspection Photo	 Load JPG	
158	03/06/19 16:23	Reinspection Photo	 Load JPG	
159	03/06/19 16:23	Reinspection Photo	 Load JPG	
160	03/06/19 16:23	Reinspection Photo	 Load JPG	
161	03/06/19 16:23	Reinspection Photo	 Load JPG	
162	03/06/19 16:23	Reinspection Photo	 Load JPG	
163	03/06/19 16:23	Reinspection Photo	 Load JPG	
164	03/06/19 16:23	Reinspection Photo	 Load JPG	
165	03/06/19 16:23	Reinspection Photo	 Load JPG	
166	03/06/19 16:23	Reinspection Photo	 Load JPG	
167	03/06/19 16:23	Reinspection Photo	 Load JPG	
168	03/06/19 16:23	Reinspection Photo	 Load JPG	
169	03/06/19 16:23	Reinspection Photo	 Load JPG	
170	03/06/19 16:23	Reinspection Photo	 Load JPG	
171	03/06/19 16:23	Reinspection Photo	 Load JPG	
172	03/06/19 16:23	Reinspection Photo	 Load JPG	
173	03/06/19 16:23	Reinspection Photo	 Load JPG	
174	03/06/19 16:23	Reinspection Photo	 Load JPG	
175	03/06/19 16:23	Reinspection Photo	 Load JPG	
176	03/06/19 16:23	Reinspection Photo	Load JPG	

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
177	03/06/19 16:23	Reinspection Photo	 Load JPG	☒
178	03/06/19 16:23	Reinspection Photo	 Load JPG	☒
179	03/06/19 16:23	Reinspection Photo	 Load JPG	☒
180	03/06/19 16:23	Reinspection Photo	 Load JPG	☒
181	03/06/19 16:23	Reinspection Photo	 Load JPG	☒
182	03/06/19 16:23	Reinspection Photo	 Load JPG	☒
183	03/06/19 16:23	Reinspection Photo	 Load JPG	☒
184	03/06/19 16:23	Reinspection Photo	 Load JPG	☒
185	03/06/19 16:23	Reinspection Photo	 Load JPG	☒
186	03/06/19 16:23	Reinspection Photo	 Load JPG	☒
187	03/06/19 16:23	Reinspection Photo	 Load JPG	☒
188	03/06/19 16:23	Reinspection Photo	 Load JPG	☒
189	03/06/19 16:23	Reinspection Photo	 Load JPG	☒
190	03/06/19 16:23	Reinspection Photo	 Load JPG	☒
191	03/06/19 16:23	Reinspection Photo	 Load JPG	☒
192	03/06/19 16:23	Reinspection Photo	 Load JPG	☒
193	03/06/19 16:23	Reinspection Photo	 Load JPG	☒
194	03/06/19 16:23	Reinspection Photo	 Load JPG	☒
195	03/06/19 16:23	Reinspection Photo	 Load JPG	☒
196	03/06/19 16:23	Reinspection Photo	 Load JPG	☒
197	03/06/19 16:23	Reinspection Photo	 Load JPG	☒
198	03/06/19 16:23	Reinspection Photo	 Load JPG	☒
199	03/06/19 16:23	Reinspection Photo	 Load JPG	☒
200	03/06/19 16:23	Reinspection Photo	 Load JPG	☒
201	03/06/19 16:23	Reinspection Photo	 Load JPG	☒
202	03/06/19 16:23	Reinspection Photo	 Load JPG	☒
203	03/06/19 16:23	Reinspection Photo	 Load JPG	☒
204	03/06/19 16:23	Reinspection Photo	 Load JPG	☒
205	03/06/19 16:23	Reinspection Photo	 Load JPG	☒
206	03/06/19 16:23	Reinspection Photo	 Load JPG	☒
207	03/06/19 16:23	Reinspection Photo	 Load JPG	☒
208	03/06/19 16:23	Reinspection Photo	 Load JPG	☒
209	03/06/19 16:23	Reinspection Photo	 Load JPG	☒
210	03/06/19 16:23	Reinspection Photo	 Load JPG	☒
211	03/06/19 16:23	Reinspection Photo	 Load JPG	☒
212	03/06/19 16:23	Reinspection Photo	 Load JPG	☒
213	03/06/19 16:23	Reinspection Photo	 Load JPG	☒
214	03/06/19 16:23	Reinspection Photo	 Load JPG	☒
215	03/06/19 16:23	Reinspection Photo	 Load JPG	☒
216	03/06/19 16:23	Reinspection Photo	 Load JPG	☒
217	03/06/19 16:23	Reinspection Photo	 Load JPG	☒
218	03/06/19 16:23	Reinspection Photo	 Load JPG	☒
219	03/06/19 16:23	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/06/19 08:19	TP GIA REPORT	 Load PDF	
2	22/08/19 17:51	EMAIL TO OI	 Load PDF	
3	26/12/19 10:37	GIA SEARCH	 Load PDF	

Letters/Correspondences			1 per page ▼	✓
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
4	26/12/19 10:37	LOD		Load PDF
5	26/12/19 10:37	RENTAL RECEIPT		Load PDF
6	19/02/20 10:43	Authorisation to Act		Load PDF
7	19/02/20 10:43	Release Voucher		Load PDF
8	19/02/20 10:43	WORKSHOP INVOICE		Load PDF
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
1	04/06/19 10:02	OI GIA report		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLR6713A (Insd veh)	Model:	HYUNDAI AVANTE 1.6 HD (A)
	SJP5226E (TP veh)		
Date of Accident:	31/05/2019		

Global Sum Settlement	:	[] Yes	[X] No	
Repair Estimate	: \$			31,586.53
Final Repair Cost	: \$			12,626.00
Loss of Use	: \$			days at \$0.00 per day
Rental (if any)	: \$			800.00 8 days
LTA / GIA Search Fee	: \$			2.00
Others:	: \$			
	: \$			
Final Settlement Sum	: \$			13,428.00

Is Third Party Workshop GIA Registered?	[] YES	[X] NO	(Kindly indicate below)
A) For <u>Non GIA Registered Workshop</u> :	Agreed Liability _____ 100 _____ (%)		
B) For <u>GIA Registered Workshop</u> :	BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____ (%)	Assessed Liability (*): _____ 100 _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Kim Chwee Auto Pte Ltd	: \$	13,428.00
2)		: \$	
3)		: \$	

NUR SHAQILAH BTE ABDOL WAHAB

19 Feb
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19009742/UKA3S2

Date: 19/02/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 1700043771

Claimant Vehicle No : SJP5226E

Insured Vehicle No : SLR6713A

Date of Loss: 31/05/2019

Nature of Claim: TP

Claim No: 6936765385SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJP5226E

Make & Model: HYUNDAI AVANTE, 1.6 HD (A)

Engine No: G4FC9U622680

Reg. Date: 27/03/2009 (Man. Year: 2009)

Chassis No: KMHU41BR9U718674

Colour: Grey

Odometer: 0 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size:

195/65 R15

Front Left Side: Falken 6 mm

Rear Left Side:

Falken 6 mm

Front Right Side: Falken 6 mm

Rear Right Side:

Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,780.12	13,179.92	9,600.20	42.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,740.00	3,720.00	3,020.00	44.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	29,520.12	16,899.92	12,620.20	42.75
Approved Total (Overridden) (S\$)		11,800.00		
(S\$)	29,520.12	11,800.00	17,720.12	60.03
+ GST 7.00/7.00% (S\$)	2,066.41	826.00	1,240.41	60.03
Nett Amount (S\$)	31,586.53	12,626.00	18,960.53	60.03
+ Car Rental (8.0 x S\$100.00/day) (S\$)		800.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		13,428.00		

INSPECTION

Date of Assignment: 03/06/2019

Date Inspected: 03/06/2019 Inspected At:

Kim Chwee Auto Pte Ltd (HQ)

1 Kaki Bukit Avenue 6 #01-48, AutoBay@Kaki Bukit
Singapore 417883

Estimated Period of Repair: 12.0 days

Adjuster: MARCUS CHUA**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented / Bent	907.60 F	*907.60 FL
2	1		*BOOTLID REAR LOGO	Necessary	25.80 F	*25.80 FL
3	1		*BOOTLID AVANTE EMBLEM	Necessary	30.80 F	*30.80 FL
4	1		*BOOTLID S EMBLEM	Necessary	28.20 F	*28.20 FL
5	1		*BOOTLID INNER LOCK	Not Necessary	183.60 F	*- FL
6	1		*BOOTLID WEATHERSTRIPS	Twisted	165.30 F	*165.30 FL
7	2		*BOOTLID HINGES	Not Necessary	220.20 F	*- FL
8	2		*BOOTLID REFLECTORS	Not Necessary	379.20 F	*- FL
9	1		*BOOTLID INNER TRIM	Not Necessary	185.30 F	*- FL
10	1		*SET BOOTLID INNER TRIM CLIPS	Not Necessary	50.00 F	*- FL
11	1		*REAR BUMPER	Distorted	486.90 F	*486.90 FL
12	1		*REAR BUMPER REINFORCEMENT	Cracked	354.00 F	*354.00 FL
13	1		*REAR BUMPER REINFORCEMENT STAYS	O/s Bent	270.00 F	*135.00 FL
14	5		*REAR BUMPER REINFORCEMENT BRACKETS	Not Necessary	105.00 F	*- FL
15	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	91.00 F	*- FL
16	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
17	1		*REAR BUMPER SPONGE	Torn	145.30 F	*145.30 FL
18	2		*TAILLAMPS	Cracked	533.00 F	*533.00 FL
19	2		*TAILLAMPS HOUSING PANEL	Repair	370.20 F	*- FL
20	1		*REAR END PANEL	Badly Dented	637.90 F	*637.90 FL
21	1		*REAR END PANEL TOP GARNISH	Twisted	188.60 F	*188.60 FL
22	1		*REAR FLOOR PANEL	Repair	928.10 F	*- FL
23	1		*REAR FLOOR PANEL TOP BOARD	Serviceable	280.60 F	*- FL
24	1		*REAR EXHAUST	Repair	693.80 F	*- FL
25	2		*REAR EXHAUST MOUNTINGS	Not Necessary	90.00 F	*- FL
26	1		*BONNET	Buckled	1,102.00 F	*1,102.00 FL
27	1		*BONNET LOCK	Twisted	83.60 F	*83.60 FL
28	2		*BONNET HINGES	Bent	179.00 F	*179.00 FL
29	1		*BONNET INNER RUBBER	Necessary	42.00 F	*42.00 FL
30	1		*BONNET INSULATOR	Torn	266.30 F	*266.30 FL
31	1		*SET BONNET INSULATOR CLIPS	Necessary	50.00 F	*50.00 FL
32	2		*HEADLAMPS	Broken	1,163.20 F	*1,163.20 FL
33	1		*FRONT GRILLE	Broken	385.00 F	*385.00 FL
34	1		*FRONT GRILLE LOGO RS	Necessary	22.80 F	*22.80 FL
35	1		*FRONT BUMPER	Distorted	480.60 F	*480.60 FL
36	2		*FRONT BUMPER BRACKETS	Not Necessary	90.22 F	*- FL
37	1		*FRONT BUMPER SPONGE	Torn	145.80 F	*145.80 FL
38	1		*FRONT BUMPER LOWER GRILLE	Torn	105.20 F	*105.20 FL
39	1		*FRONT BUMPER REINFORCEMENT	Distorted	431.50 F	*431.50 FL
40	2		*FRONT BUMPER SIDE RETAINERS	Not Necessary	73.00 F	*- FL
41	2		*FRONT FENDERS	Bent / Buckled	810.60 F	*810.60 FL
42	2		*FRONT FENDER VVTI EMBLEM	Necessary	84.00 F	*84.00 FL
43	1		*FRONT SUPPORT PANEL	Broken	958.00 F	*958.00 FL
44	1		*HORN UNIT	Bent	90.00 F	*90.00 FL
45	2		*FRONT SUPPORT PANEL SIDE COVERS	Torn	91.00 F	*91.00 FL
46	1		*AIRCON CONDENSER	Distorted	950.00 F	*950.00 FL
47	1		*AIRCON SUCTION HOSE	Bent	295.00 F	*295.00 FL
48	1		*AIRCON DISCHARGE HOSE	Bent	305.00 F	*305.00 FL
49	1		*RADIATOR	Distorted	885.00 F	*885.00 FL
50	1		*RADIATOR FAN ASSY	Broken	685.00 F	*685.00 FL
51	1		*BATTERY TRAY	Cracked	162.50 F	*162.50 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*SET FRONT PANEL INNER SHIELD CLIPS O/S	Not Necessary	50.00 F	*- FL
53	1		*ALTERNATOR ASSY	Cracked	620.40 F	*620.40 FL
54	1		*AIR DUCT	Cracked	115.30 F	*115.30 FL
55	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
56	1		*REAR BUMPER LOWER SKIRTING	Not fitted	850.00 FS	*- FS
57	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
58	1		*REAR FLOOR PANEL INSULATOR	Not Necessary	200.00 FS	*- FS
59	1		*FRONT LICENCE PLATE	Broken	50.00 FS	*40.00 FS
60	1		*BOL RADIATOR COOLANT	Necessary	50.00 FS	*30.00 FS
61	1		*FRONT BUMPER LOWER SKIRTING	Not fitted	980.00 FS	*- FS
62	1		*SET FRONT HEADLAMP GARNISH	Not Necessary	120.00 FS	*- FS
63	1		*BATTERY	Broken	300.00 FS	*80.00 FS
64	1		*AIR CLEANER BOX	Broken	389.20 F	*389.20 FL
65	1		*THROTTLE BODY	Cracked	485.20 F	*485.20 FL
66	1		*INLET MANIFOLD	Cracked	688.30 F	*688.30 FL
67	1		*WASHER TANK	Deformed	215.00 F	*215.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	22,780.12	16,374.90
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	3,194.98
Total Parts (\$\$)	22,780.12	13,179.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING.	New	80.00	30.00
2	TO DISMANTLE & REPLACING REVERSE SENSOR.	New	80.00	50.00
3	TO DISMANTLE & REFIX SEAT CUSHION UPHOLSTERY.	New	150.00	80.00
4	TO DISMANTLE & REFIX REAR EXHAUST.	New	100.00	0.00
5	TO DISMANTLE & REFIX PETROL TANK.	New	100.00	0.00
6	TO DISMANTLE & REPLACING BOOTLID MECHANISM.	New	100.00	60.00
7	TO REFILL AIRCON GAS.	New	150.00	100.00
8	TO MOUNT VEHICLE ON CAR O-LINER.	New	380.00	0.00
9	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS.	New	2,800.00	1,600.00
10	TO PUTTY & SPRAY PAINTING.	New	2,800.00	1,800.00
Gross Labour Cost (S\$)			6,740.00	3,720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >