

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : SXXX2136J
NG CHUI LI
BLK 85A LORONG 4 TOA PAYOH
#06-310
SINGAPORE 311085
TEL : FAX :
PH : 93203985
ATTN :

LKK Auto Consultants hence notify
the Repairer of the following:
To resurvey before/after spray paint
To display damaged part(s) during survey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

ESTIMATE BILL

Number : EB00005396
Date : 20/01/2020
Case No : AD00010922
Vehicle No : SLU9400S
Chassis: KMHCU41BTJU403665
Year of Mfr 2017
Policy No 5097362274
Model : HYUNDAI ACCENT

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	REAR BUMPER - REPAIR <i>x repair</i>	1.0			
	Special Nett Price - Parts Sub Total				0.00
	Parts Total				0.00
2	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	150.00	0	150.00
3	SPRAY PAINT ON THE AFFECTED AREAS	1.0	300.00	0	300.00
4	ANTI-RUST COATING	1.0	50.00	0	50.00
5	TO REMOVE & REFIT REVERSE SENSOR	1.0	150.00	0	150.00
	Labour 1 Sub Total				650.00
					340.
SINGAPORE DOLLARS : SIX HUNDRED NINETY-FIVE AND CENTS FIFTY ONLY			Less Excess		0.00
			SUBTOTAL		650.00
			GST 7.00%		45.50
			TOTAL		695.50

2 Days.

P/P

After paint photos.

Que Qiang - 82889282

21/01/2020

Date of accident : 06/12/2018 08:10 AM. Place : PIE > CHANGI

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE