

AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE LTD
18 UBI ROAD 4
SINGAPORE 408623
TEL 6490 9668 FAX: 6346 7483

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/H/0298/19
DATE : 27-MAY-2019

ERGO INSURANCE PTE LTD
5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
S(038985)
TEL : 68299199
FAX : 68299247/9248
ATTN : CLAIM MANAGER

OWNER'S NAME : MR LOW HEE PENG
ADDRESS : BLK 260A SENGKANG EAST WAY
#15-482
S(541260)
TELEPHONE NO : 97548827

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : *
VEHICLE NO : SLF2188E
MODEL CODE : JDRNRRT32EWA-----
MODEL/YEAR : X-TRAIL 2.0L ALL MODE 4X4I
ENGINE NO : MR20890013B
CHASSIS NO : JN1JANT32Z0002327
MILEAGE : 84998 KM
DATE IN : 27/05/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : HAMZAH - 96450079
ACCIDENT DATE : 27/05/2019

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To resurvey damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary part(s) must be resurveyed and
is subject to the approval from Insurance Company
• To resurvey before/after spray painting
Acknowledged by the Repairer of the following:
Signature: _____
Date: _____

not Authorized
Low

Take photo before repair.

26/7/19

3 dy.

9/7/2332.52

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLF2188E

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 ZZ/001	LABOUR CHARGES TO REPAIR RADIATOR SUPPORT, RENEW FRONT BUMPER AND BONNET.	650.00	585
2 ZZ/002	CHARGES TO SPRAY PAINTING SAME.	650.00	500
3 ZZ/003	CHECK LIGHT SYSTEM AND FOCUS.	48.00	✓
4 ZZ/004	APPLY SEALANT TO BONNET.	100.00	✓
5 ZZ/005	SUPPLY FRONT LICENCE PLATE.		
	TOTAL LABOUR CHARGES	1448.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLF2188E

		DAMAGED PARTS & PRICES		
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST S/NETT REMARKS
1	SUNDRIES	NPN	11	40.00 X
2	FRT LICENCE PLATE	FLP	SCA	60.00 /
3	HEADLAMP LH	26060-4CA5D	11	2352.00 X
4	HEADLAMP RH	26010-4CA5D	11	2352.00 X
5	BONNET	F510M-4CCMA	12/100	901.90 /
6	EMBLEM RAD GRILLE	62890-4BA0A	11	59.70 X
7	GRILLE-RADIATOR	62310-4CE1B	SCR	390.30 2
8	FRT BUMPER LOWER MLDG	62072-4BA0A	11	153.10 X
9	FRT BUMPER STAY LH	62211-4CL0A	11	86.60 X
10	FRT BUMPER STAY RH	62210-4CL1A	11	86.60 X
11	FRT BUMPER REINFORCEMENT	62030-4CL0A	11	453.10 X
12	ENERGY ABSORBER FRONT BUMPER	62090-4CE0A	11	291.60 X
13	CLIP FRT BUMPER @ \$1.20 EACH	01553-10501	11	7.20 /
14	FRONT BUMPER FASCIA	62022-4CE0H	R	534.70 X
SUB TOTAL			7668.80	0.00 100.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			1533.76	0.00 0.00
GRAND TOTAL			6135.04	0.00 100.00
OVERALL TOTAL			6235.04	

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLF2188E

TOTAL LABOUR CHARGES	1448.00
TOTAL SPARE PARTS CHARGES	6235.04

GRAND TOTAL	7683.04 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

Marcus

AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 108623
TEL: 6496 9566 FAX: 6346 7483

FINALIZED : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/H/0298/19

DATE : 27-MAY-2019

ERGO INSURANCE PTE LTD
5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
S(038985)
TEL : 68299199
FAX : 68299247/9248
ATTN : CLAIM MANAGER

OWNER'S NAME : MR LOW HEE PENG
ADDRESS : BLK 260A SENGKANG EAST WAY
#15-482
S(541260)
TELEPHONE NO : 97548827

3 days

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : *
VEHICLE NO : SLF2188E
MODEL CODE : JDRNRRT32EWA-----
MODEL/YEAR : X-TRAIL 2.0L ALL MODE 4X4I
ENGINE NO : MR208900138
CHASSIS NO : JN1JANT32Z0002327
MILEAGE : 91394 KM
DATE IN : 27/05/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : HAMZAH
ACCIDENT DATE : 27/05/2019

- 96450079

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLF2188E

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOUR CHARGES TO REPAIR RADIATOR SUPPORT, FRONT BUMPER AND RENEW BONNET.	650.00	585.00
2	ZZ/002	CHARGES TO SPRAY PAINTING SAME.	650.00	500.00
3	ZZ/003	CHECK LIGHT SYSTEM AND FOCUS.	48.00	48.00
4	ZZ/004	APPLY SEALANT TO BONNET.	100.00	100.00
5	ZZ/005	SUPPLY FRONT LICENCE PLATE.		
TOTAL LABOUR CHARGES			1448.00	1233.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLF2188E

			DAMAGED PARTS & PRICES			
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	REMARKS
1	SUNDRIES	NPN			40.00	X
2	FRT LICENCE PLATE	FLP			60.00	OK
3	HEADLAMP LH	26060-4CA5D	2352.00			X
4	HEADLAMP RH	26010-4CA5D	2352.00			X
5	BONNET	F510M-4CCMA	901.90			OK
6	EMBLEM RAD GRILLE	62890-4BA0A	59.70			X
7	GRILLE-RADIATOR	62310-4CE1B	390.30			OK
8	FRT BUMPER LOWER MLDG	62072-4BA0A	153.10			X
9	FRT BUMPER STAY LH	62211-4CL0A	86.60			X
10	FRT BUMPER STAY RH	62210-4CL1A	86.60			X
11	FRT BUMPER REINFORCEMENT	62030-4CL0A	453.10			X
12	ENERGY ABSORBER FRONT BUMPER	62090-4CE0A	291.60			X
13	CLIP FRT BUMPER @ \$1.20 EACH	01553-10501	7.20			OK
14	FRONT BUMPER FASCIA	62022-4CE0H	534.70			X
SUB TOTAL			1299.40	0.00	60.00	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			259.88	0.00	0.00	
GRAND TOTAL			1039.52	0.00	60.00	
OVERALL TOTAL			1099.52			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SLF2188E

NETT ITEM	1299.40
LESS 20.00%)	-259.88
NETT AMOUNT	1039.52

LIST ITEM	0.00
LESS 30.00%)	0.00
LIST AMOUNT	0.00

SPECIAL NETT ITEM	60.00
LESS .00%)	0.00
SPECIAL NETT AMOUNT	60.00

TOTAL LABOUR CHARGES	1233.00
TOTAL SPARE PARTS CHARGES	1099.52

TOTAL CHARGES	2332.52
ADD 7 % GST	163.28

GRAND TOTAL	2495.80
-------------	---------
