



Cecilia

Case Details

Case Reference Number : TAX/05/19/2137
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB5850A

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-7097-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : EQ Insurance Company Ltd
 Accident Date and Time : 30/05/2019 12:15 AM
 Vehicle Age(In Months) : 17

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			COVER, FR BUMPER	1	495.50	495.50	25.00	371.63	Replace	1	0.00	Repair	✓ XR
One Time Key In	Main			FENDER SUB-ASSY, FR , RH	1	933.10	933.10	25.00	699.83	Replace	1	0.00	Repair	✓ XR
One Time Key In	Main			EMBLEM, SIDE PANEL (HYBRID)	1	52.90	52.90	25.00	39.67	Replace	1	39.67	Replace	✓ nel
One Time Key In	Main			LINER, FR FENDER, RH	1	198.40	198.40	25.00	148.80	Replace	0	0.00	Not Give	✓ uu
One Time Key In	Main			COVER SUB-ASSY, FRONT PILLAR , UPR RH	1	96.90	96.90	25.00	72.68	Replace	0	0.00	Not Give	✓ uu
One Time Key In	Main			MIRROR ASSY, OUTER REAR VIEW , RH	1	1,373.50	1,373.50	10.00	1,236.15	Replace	1	1,236.15	Replace	✓ CRD
One Time Key In	Main			COVER, OUTER MIRROR, RH	1	89.50	89.50	25.00	67.13	Replace	1	67.13	Replace	✓ mlf
Total Spare Part Cost									2,635.89	Surveyor Total			1,342.95	
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)			0.00	
Final Spare Part Cost									2,635.89	Final Sur Total			1,342.95	

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR RH PORTION	338.00	200.00 /	
Total:			338.00	200.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200.00 /	
2	Main	TO RESPRAY FRONT FENDER RH	378.00	200.00 /	
3	Main	TO RESPRAY VIEW MIRROR	180.00	50.00 /	
Total:			936.00	450.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20.00 /	NP
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00	
3	Main	TO REMOVE AND REFIX WING MIRROR	120.00	50.00 /	NP
4	Main	TO WASH AND VACUUM	60.00	0.00	
Total:			360.00	70.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	2,635.89	1,342.95
Total Labour Cost	338.00	200.00
Total Spray Painting	936.00	450.00
Other	360.00	70.00
Overall Total	4,269.89	2,062.95
Lump Sum Repair Option		
Lump Sum Total	0.00	2,062.95
Surveyor Approved Amount		2,062.95

5/31/2019

	Estimator Assessment(\$)	Surveyor Assessment(\$)
No of Repair Days*	3	2
Remarks		p/p repair, photo before paint.
Surveyor Name		Hwee Jie
Signature		
Survey Date	31/05/2019	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REQUEST FOR SUPPLYMENT PARTS

Contractor:		WEGA ENGINEERING PTE LTD	
Accident Case Number	75X/05/19/2137	Date of Collection	31/5/19
Vehicle No	SHB 5850 A	Date of Request	31/5/19
Vehicle Model	2007/12 PRIUS 4	Number of Days to Extend (If any)	120 DAYS


S/N	Part Number	Part Description	Quantity	Unit Price
	1533, 34, 35, 36	To Repair FRT RH DOOR		#250.00 \$200 /
	1537	To Respray FRT RH DOOR		#375.00 200 /
	1531, 32	To Respray FRT RH Rim		#150.00 \$50
		Sticker Decal SMRT (DOOR)		#60.00 / nee

<<<Please submit photographs for damaged parts>>>

I, (Name) CAIY

(Position)

Do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.



Signature of person making this declaration
[To be signed in front of an authorised witness]



I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission

Section A - Accident Details

Registration Number	SHB5850A
Case Reference Number	TAX/05/19/2137
Registration Date	12/12/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	FOO TEE CHYE SIMON
Type of Accident	Side Swipe
Accident Date and Time	30/5/2019 8:15 AM
Accident Reported Date and Time	30/5/2019 1:55 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	24101754
Special Instruction to ARC, if any	TP
Prepared Date and Time	31/5/2019 8:47 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



p/p

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$588.00	\$400.00
Total Spray Cost	\$1,494.00	\$700.00
Total Spare Part Cost	\$2,695.89	\$1,402.96
Total Other Cost	\$360.00	\$70.00
TOTAL COST	\$5,137.89	\$2,572.96 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	4.0	3.0
Prepared / Adjusted By	ARC Manager Team	Hwee Jie (LKK) / EQ
ARC / Surveyor Sign Off Date	31/05/2019 9:56 AM	31/05/2019 2:28 PM
Signature		
Remarks	p/p repair, photo before paint.	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1908-0100	Invoice Number	
Quotation Date	08.08.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	\$338.00	\$200.00 /
TO REPAIR FRONT DOOR RH	\$250.00	\$200.00 /
Total Labour	\$588.00	\$400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00 /
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00 /
TO RESPRAY VIEW MIRROR	\$180.00	\$50.00 /
TO RESPRAY FRONT DOOR RH	\$378.00	\$200.00 /
TO RESPRAY RIM	\$180.00	\$50.00 /
Total Spray Painting & Panel Beating	\$1,494.00	\$700.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO REMOVE AND REFIX WING MIRROR	\$120.00	\$50.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$360.00	\$70.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119479 62	COVER, FR BUMPER	1.00	\$495.50	100.00	\$0.00	Replace	Repair
		53801470 80	FENDER SUB-ASSY, FR, RH	1.00	\$933.10	100.00	\$0.00	Replace	Repair
		75374471 40	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$52.90	25.00	\$39.68	Replace	Replace
		53875470 70	LINER, FR FENDER, RH	0.00	\$198.40	0.00	\$0.00	Replace	Not Given
		60117470 20	COVER SUB-ASSY, FRONT PILLAR, UPR RH	0.00	\$96.90	0.00	\$0.00	Replace	Not Given
		87910474 50	MIRROR ASSY, OUTER REAR VIEW, RH	1.00	\$1,373.50	10.00	\$1,236.15	Replace	Replace
		87915470 70A1	COVER, OUTER MIRROR, RH	1.00	\$89.50	25.00	\$67.13	Replace	Replace
Total					\$3,239.80		\$1,342.96		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
			STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace
Total					60.00		60.00		

1402.96
+ 400.00
+ 770.00
2572.96