

INS. CASE OWNER:

JMS / Lau | CC 4 / HSM 1900 97SU / J 2007/4

IDAC:

119500

PREMISE:

HJ / Mans

DOI:

ASSIGNMENT

3/6/19

Date / Time:

3/6/2019

Registered in Meriton:

Pre-assign: CCU / FLE



Insured Vehicle No.:

SGH 2991B

Name of Insured:

PATRICIA LAU after Chen

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

9/5/2009

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SQ M 01 M Z 2



INSRS:

WSP:

Tel:

Liability:

RMKS:

Yew Tee



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

FBL6064J - X;

SGH 2991B - CC4/CT11700 079/PLU6302: 24/1/17

10/6/19

Confirm accident details inform TP claim.
letter send out. as was charge inconsiderate driving.

10/6/19

email workshop liability clear.

24/4/20 - PS letters

24/4/20 - 18th - MK truck

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PTR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days)

Reduction:

%

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

NIL

Repair Cost:

S\$

3156.50

Loss of Rental (LOR):

S\$

Loss of Use (LOU):

S\$

100.00

(525

x

4

days)

Loss of Income (LOI):

S\$

-

(5

x

-

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search:

S\$

2.00

Medical:

S\$

-

Disbursement:

S\$

-

Legal Cost:

S\$

-

(e.g. Tow/ Independent)

Total:

S\$

3258.50

Global Sum S\$:

3250.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

S\$

3250.00

Name 1:

Yew Tee Automobile Tech Pte Ltd

Payee 2: (Str: Do: JTL: &):

S\$

Name 2:

Payee 3: (Str: Do: JTL: &):

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

#350.00

COPY SENT 24/4/20

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 6500 check w Bryan

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: FBM60645 Yr Regn: 6 Jan 2014

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Sym c.c. 278Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RFGLNA701DS006309Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt or _____Brake: Inorder / Jammed / Leaked / Burnt or _____Modi: Nil / S/Rim / STD A/Rim or _____Tyre Size: F: 120/80-14R: 140/60-13BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. - mm L/Bal. - mmD.O.A. 9/5/19 D.O.I. 3/6/19Survey held at Yew tee AutoDes. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

US\$ 2950 (Red \$ 6469.50 / 69%).

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐ : Prel. Report
☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Block 6 Woodlands Road 399F, Yew Tee Industrial Estate
Singapore 678006

Tel: 67653373 Fax: 67604895 Email: YTHQ

INSURER : NTUC INCOME INSURANCE CO-OPERATIVE LTD

PARTICULARS OF CLAIM

Claim Type:	TP	Ref. No:	YTHQ/TP/1905/012
Policy No:	pvmc2019-00002197	Date of Loss:	09/05/2019
Vehicle Reg. No.:	FBM6064J	Driveable?	yes
Driver Age:	19-02-1990	Third Party Vehicle No.:	SGH2991B
Any Injuries?	yes	Contact No:	97981404
Insured/Claimant:	MUHAMMAD HAFIZ BIN IBRAHIM	Driver:	MUHAMMAD HAFIZ BIN IBRAHIM

Make/Model:	Yamaha, FJR1300 - JYARP13A00	Vehicle Reg. Date:	06/01/2014
Vehicle Colour:	GREY	Engine Number:	MK916293
Chassis No:	RFGLNA701DS006309	Odometer:	
Total Loss?	NO	Est. Duration of Repair(Day)	

Description of Accident/loss: COLLISION - HEAD ON COLLISION
Remarks:
Present Location: Yew Tee Automobile Tech Pte Ltd (HQ)-YTHQ

COST OF CLAIMS

	Amount
Parts	7,191.90
Miscellaneous Items	858.00
Labour	920.00
Paintwork Labour	450.00
Towing	0.00
Gross Total(S\$):	9,419.90
GST 7.00%(S\$):	659.39
Nett Amount(S\$):	10,079.29

This claim is handled by: Sky Toh T C

REPAIR DETAILS

Estimates On Parts

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	FRONT HEADLAMP <i>3mm</i>	0.00	900.00	-10.00	810.00
2	1	FRONT HEADLAMP FAIRING <i>CRA/</i>	0.00	450.00	-10.00	405.00
3	1	FRONT HEADLAMP FAIRING CENTRE <i>rec/</i> CHROME	0.00	95.00	-10.00	85.50
4	1	FRONT HEADLAMP CENTRE FAIRING <i>CRA/</i>	0.00	230.00	-10.00	207.00
5	1	FRONT HEADLAMP LOGO <i>rec/</i>	0.00	53.00	-10.00	47.70
6	1	FRONT HEADLAMP BRACKET <i>3mm</i>	0.00	83.00	-10.00	74.70
7	1	FRONT HEADLAMP INNER FAIRING <i>3mm</i>	0.00	430.00	-10.00	387.00
8	1	FRONT SIDE LAMP LH <i>3mm</i>	0.00	208.00	-10.00	187.20
9	1	FRONT SIDE LAMP RH <i>scr/</i>	0.00	208.00	-10.00	187.20
10	1	FRONT SIDE MIRROR LH <i>3mm</i>	0.00	130.00	-10.00	117.00
11	1	FRONT SIDE MIRROR RH <i>CRA/</i>	0.00	130.00	-10.00	117.00
12	1	FRONT SIDE MIRROR SIGNAL LAMP LH <i>3mm</i>	0.00	70.00	-10.00	63.00
13	1	FRONT SIDE MIRROR SIGNAL LAMP RH <i>CRA/</i>	0.00	70.00	-10.00	63.00
14	1	FRONT SIDE MIRROR GLASS RH <i>mis/</i>	0.00	87.00	-10.00	78.30
15	1	FRONT SIDE MIRROR GARNISH LH <i>3mm</i>	0.00	38.00	-10.00	34.20
16	1	FRONT SIDE MIRROR GARNISH RH <i>mis/</i>	0.00	38.00	-10.00	34.20
17	1	FRONT TOP VISOR <i>3mm</i>	0.00	160.00	-10.00	144.00
18	1	FRONT TOP VISOR LOWER FAIRING <i>scr/</i>	0.00	145.00	-10.00	130.50
19	1	FRONT FENDER <i>scr/</i>	0.00	180.00	-10.00	162.00
20	1	FRONT FORK LH <i>3mm</i>	0.00	280.00	-10.00	252.00
21	1	FRONT FORK RH <i>3mm</i>	0.00	280.00	-10.00	252.00
22	1	FRONT WHEEL DISC ROTOR <i>3mm</i>	0.00	265.00	-10.00	238.50
23	1	FRONT WHEEL BRAKE CALIPER <i>3mm</i>	0.00	380.00	-10.00	342.00
24	1	FRONT BALANCER RH <i>scr/</i>	0.00	25.00	-10.00	22.50
25	1	FRONT HANDLE BAR <i>3mm</i>	0.00	240.00	-10.00	216.00
26	1	FRONT STEERING STEM <i>3mm</i>	0.00	55.00	-10.00	49.50
27	1	FRONT BRAKE LEVER RH <i>scr/</i>	0.00	28.00	-10.00	25.20
28	1	FRONT CENTRE INNER FAIRING <i>CRA/</i>	0.00	480.00	-10.00	432.00
29	1	FRONT STEP GARNISH RH <i>3mm</i>	0.00	110.00	-10.00	99.00
30	1	FRONT RADIATOR FAIRING <i>CRA/</i>	0.00	420.00	-10.00	378.00
31	1	FRONT CENTRE LOWER FAIRING <i>3mm</i>	0.00	370.00	-10.00	333.00
32	1	RADIATOR <i>3mm</i>	0.00	445.00	-10.00	400.50
33	1	RADIATOR BRACKET <i>3mm</i>	0.00	78.00	-10.00	70.20
34	1	REAR EXHAUST PIPE PROTECTOR <i>scr/</i>	0.00	160.00	-10.00	144.00
35	1	REAR FAIRING RH <i>scr/</i>	0.00	320.00	-10.00	288.00
36	1	REAR HANDLE RH <i>scr/</i>	0.00	140.00	-10.00	126.00
37	1	FRONT SEAT TOP BACKING CUSHION <i>3mm</i>	0.00	210.00	-10.00	189.00
Total Parts (\$\$)						7,191.90

Estimates of Miscellaneous Items

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	FRONT WHEEL RIM <i>max</i>	0.00	353.00	0.00	353.00
2	1	FRONT NUMBER PLATE <i>rec/</i>	0.00	45.00	0.00	45.00
3	1	REAR BOX (METAL) <i>scr/</i>	0.00	380.00	0.00	380.00
4	1	REAR BOX BRACKET (1 SET) <i>max</i>	0.00	80.00	0.00	80.00
Sub Total (\$\$)						858.00

Estimates On Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	30.00	0.00	30.00 20
2	1	To Remove and Refit, Straighten and Re-adjust Exhaust Pipe and Rear Exhaust Silencer and Mountings.	180.00	180.00	0.00	180.00 50
3	1	To Pressure Test Air Con Condenser and Radiator For Leakage.	120.00	120.00	0.00	120.00 2
4	1	Towing Charges.	80.00	80.00	0.00	80.00 40
5	1	To Conduct Wheel Balancing	60.00	60.00	0.00	60.00 50
6	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	450.00	450.00	0.00	450.00 300

Gross Labour Cost (\$\$) 920.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	50.00	50.00	0.00	50.00 30
2	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	400.00	400.00	0.00	400.00 X

Gross Labour Cost (\$\$) 450.00

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Hwee Jie - LKK

3/6/19

4/5 4days.



Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Block 6 Woodlands Road 399F, Yew Tee Industrial Estate
Singapore 678006

Tel: 67653373 Fax: 67604895 Email: YTHQ

INSURER : NTUC INCOME INSURANCE CO-OPERATIVE LTD

PARTICULARS OF CLAIM

Claim Type:	TP	Ref. No:	YTHQ/TP/1905/012
Policy No:	pvmc2019-00002197	Date of Loss:	09/05/2019
Vehicle Reg. No.:	FBM6064J	Driveable?	yes
Driver Age:	19-02-1990	Third Party Vehicle No.:	SGH2991B
Any Injuries?	yes	Contact No:	97981404
Insured/Claimant:	MUHAMMAD HAFIZ BIN IBRAHIM	Driver:	MUHAMMAD HAFIZ BIN IBRAHIM

Make/Model:	Yamaha, FJR1300 - JYARP13A00	Vehicle Reg. Date:	06/01/2014
Vehicle Colour:	GREY	Engine Number:	MK916293
Chassis No:	RFGLNA701DS006309	Odometer:	
Total Loss?	NO	Est. Duration of Repair(Day)	

Description of Accident/loss: COLLISION - HEAD ON COLLISION
Remarks:
Present Location: Yew Tee Automobile Tech Pte Ltd (HQ)-YTHQ

COST OF CLAIMS

	Amount
Parts	7,191.90
Miscellaneous Items	858.00
Labour	920.00
Paintwork Labour	450.00
Towing	0.00

Gross Total(S\$):	9,419.90
GST 7.00%(S\$):	659.39
Nett Amount(S\$):	10,079.29

This claim is handled by: Sky Toh T C

Part = \$2933.10

Item = \$703.00

Labour = \$460.00

Paint = \$30.00

Total = \$4126.10

- 20% (Hump Sum)

= \$3300.88 ≈ \$3301.

REPAIR DETAILS

Estimates On Parts

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	FRONT HEADLAMP ?	0.00	900.00	-10.00	810.00
2	1	FRONT HEADLAMP FAIRING CRA ✓	0.00	450.00	-10.00	405.00
3	1	FRONT HEADLAMP FAIRING CENTRE rec ✓	0.00	95.00	-10.00	85.50
4	1	FRONT HEADLAMP CENTRE FAIRING CRA ✓	0.00	230.00	-10.00	207.00
5	1	FRONT HEADLAMP LOGO rec ✓	0.00	53.00	-10.00	47.70
6	1	FRONT HEADLAMP BRACKET ?	0.00	83.00	-10.00	74.70
7	1	FRONT HEADLAMP INNER FAIRING ?	0.00	430.00	-10.00	387.00
8	1	FRONT SIDE LAMP LH ?	0.00	208.00	-10.00	187.20
9	1	FRONT SIDE LAMP RH scr ✓	0.00	208.00	-10.00	187.20
10	1	FRONT SIDE MIRROR LH ?	0.00	130.00	-10.00	117.00
11	1	FRONT SIDE MIRROR RH CRA ✓	0.00	130.00	-10.00	117.00
12	1	FRONT SIDE MIRROR SIGNAL LAMP LH ?	0.00	70.00	-10.00	63.00
13	1	FRONT SIDE MIRROR SIGNAL LAMP RH CRA ✓	0.00	70.00	-10.00	63.00
14	1	FRONT SIDE MIRROR GLASS RH mis ✓	0.00	87.00	-10.00	78.30
15	1	FRONT SIDE MIRROR GARNISH LH ?	0.00	38.00	-10.00	34.20
16	1	FRONT SIDE MIRROR GARNISH RH mis ✓	0.00	38.00	-10.00	34.20
17	1	FRONT TOP VISOR ?	0.00	160.00	-10.00	144.00
18	1	FRONT TOP VISOR LOWER FAIRING scr ✓	0.00	145.00	-10.00	130.50
19	1	FRONT FENDER scr ✓	0.00	180.00	-10.00	162.00
20	1	FRONT FORK LH ?	0.00	280.00	-10.00	252.00
21	1	FRONT FORK RH ?	0.00	280.00	-10.00	252.00
22	1	FRONT WHEEL DISC ROTOR ?	0.00	265.00	-10.00	238.50
23	1	FRONT WHEEL BRAKE CALIPER ?	0.00	380.00	-10.00	342.00
24	1	FRONT BALANCER RH scr ✓	0.00	25.00	-10.00	22.50
25	1	FRONT HANDLE BAR ?	0.00	240.00	-10.00	216.00
26	1	FRONT STEERING STEM ?	0.00	55.00	-10.00	49.50
27	1	FRONT BRAKE LEVER RH scr ✓	0.00	28.00	-10.00	25.20
28	1	FRONT CENTRE INNER FAIRING CRA ✓	0.00	480.00	-10.00	432.00
29	1	FRONT STEP GARNISH RH ?	0.00	110.00	-10.00	99.00
30	1	FRONT RADIATOR FAIRING cra ✓	0.00	420.00	-10.00	378.00
31	1	FRONT CENTRE LOWER FAIRING ?	0.00	370.00	-10.00	333.00
32	1	RADIATOR ?	0.00	445.00	-10.00	400.50
33	1	RADIATOR BRACKET ?	0.00	78.00	-10.00	70.20
34	1	REAR EXHAUST PIPE PROTECTOR scr ✓	0.00	160.00	-10.00	144.00
35	1	REAR FAIRING RH scr ✓	0.00	320.00	-10.00	288.00
36	1	REAR HANDLE RH scr ✓	0.00	140.00	-10.00	126.00
37	1	FRONT SEAT TOP BACKING CUSHION ?	0.00	210.00	-10.00	189.00
				5259	-10%	4733.10
Total Parts (\$\$)						7,194.90

Estimates of Miscellaneous Items

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	FRONT WHEEL RIM nax	0.00	353.00	0.00	353.00
2	1	FRONT NUMBER PLATE rec ✓	0.00	45.00	0.00	45.00
3	1	REAR BOX (METAL) scr ✓	0.00	380.00	0.00	380.00
4	1	REAR BOX BRACKET (1 SET) nax	0.00	80.00	0.00	80.00
Sub Total (\$\$)						858.00

703

Estimates On Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	30.00	0.00	30.00 20
2	1	To Remove and Refit, Straighten and Re-adjust Exhaust Pipe and Rear Exhaust Silencer and Mountings.	180.00	180.00	0.00	180.00 50
3	1	To Pressure Test Air-Con Condenser and Radiator For Leakage.	120.00	120.00	0.00	120.00 ?
4	1	Towing Charges.	80.00	80.00	0.00	80.00 40
5	1	To Conduct Wheel Balancing	60.00	60.00	0.00	60.00 50
6	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	450.00	450.00	0.00	450.00 30

Gross Labour Cost (S\$) 920.00
460

Estimates On Paint Work Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	50.00	50.00	0.00	50.00 30
2	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	400.00	400.00	0.00	400.00 X

Gross Labour Cost (S\$) 450.00

< END OF ESTIMATES >

30

Hwee Jie - LKK

3/6/19

4/5 4days.



[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6904G
Vehicle Details	
Vehicle No.:	FBM6064J
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Jun 2019
Vehicle Make:	SYM
Vehicle Model:	JOYMAX 300I CVT
Primary Colour:	Grey
Manufacturing Year:	2013
Engine No.:	MK916293
Chassis No.:	RFGLNA701DS006309
Maximum Power Output:	-
Open Market Value:	\$3,925.00
Original Registration Date:	06 Jan 2014
First Registration Date:	06 Jan 2014
Transfer Count:	3
Actual ARF Paid:	\$589.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	05 Jan 2024
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$1,710.00
COE Rebate Amount:	\$830.00
Total Rebate Amount:	\$830.00

The information contained herein is correct as at 07 Jun 2019

OK



Service Request Details

Claim

S9M01MZ2

Reference

None 

Loss Date

9 May 2019

Report Date

15 May 2019 12:54:00 PM

Request Date

3 June 2019

Due Date

11 June 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

P: Vinnie

T: 11.53 a.m

V: In

E: ✓

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration

FBM6064J

PRODUCT

SYM JOYMAX 300I CVT GREY

Service Address

Primary Contact/Insured

LAW CHEOW CHIEN PATRICIA
5A SURIN AVENUE, ONE SURIN, 533924, Singapore
90222607
AVTFONG@GMAIL.COM

Claim Handler

TAN Jas
6568804844
jas.tan@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

Catherine Chong (LKK Auto)

From: YT(HQ) <info@yewteegroup.com>
Sent: Monday, 3 June, 2019 10:09 AM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Cc: YT(HQ); YT; YTKB
Subject: Accident involving FBM6064J & SGH2991B on 09.05.2019 (PRS)
Attachments: FBM6064J_09052019.pdf

Categories: Raghav

Hi Motor Claim Department,

Attached the report for your attention.

Kindly assist to arrange survey before repair at Yew Tee HQ.

Please lets us have the surveyor list and the liability too.

Thank you

Best Regards

Vinnie Lim



Yew Tee Automobile Tech Pte Ltd

HQ:
Blk 6 Woodlands Road 399F
Yew Tee Ind. Est
Singapore 678006
DID: 6765 3373 / 6762 2081 / 6764 9042 Fax: 6760 4895
Email: utauto@singnet.com.sg

Branch Office:
Synergy@KB, 25 Kaki Bukit Road
Unit No #01-60/61
Singapore 417800
DID: 6702 3113
Email: utauto2@singnet.com.sg

Branch Office:
39 Woodlands Close,
#01-12 Mega@Woodlands
Singapore 737856
DID: 62562081
Email: info@yewteegroup.com



please consider the environment before printing this email

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

Hsiao Tong (LKKAuto)

From: Mei Kwan (LKKAuto)
Sent: Monday, 4 November 2019 9:26 AM
To: Hsiao Tong (LKKAuto)
Subject: FW: New message for service request 119300, vehicle number FBM6064J

4/11/19 9:22 AM ***

Messagehi, please update. thanks. - TAN Jas

-----Original Message-----

From: jas.tan@axa.com.sg <jas.tan@axa.com.sg>
Sent: Monday, 4 November, 2019 9:23 AM
To: admin-d@lkkauto.com
Subject: New message for service request 119300, vehicle number FBM6064J

AXA Insurance has sent you a message for claim number S9M01MZ2.

Please click here <https://vp.smartclaims.axa.com.sg/claim-portal/> to view the message in Vendor Portal.

This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.



<TP - Mandate IA> - S9M01MZ2 [ACCIDENT INVOLVING SGH 2991B(OI) & FBM 6064J(TP) ON 09/05/2019]

Type

🔔 Question

Message

Liability: 100%. PIR shows that OID was being charged for Inconsiderate Driving. Inform OI about third party claim. Agreed to settle at best and aware NCD issue. We seek your mandate at \$3,313.95(all-in), TP-Mandate IA had been uploaded in Smartclaims. Kindly let us have your approval/instruction. Hsiao Tong - 5-Nov-19

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564312

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 5/11/2019

Survey Details:

Date of loss	9-May-19
Date of appointment	3-Jun-19
Date of survey	3-Jun-19
Location of survey	YEW TEE AUTOMOBILE TECH PL

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	FBM6064J
Make and Model	SYM JOYMAX 300I CVT
Date of registration	6-Jan-14
Parf Rebate	
Market Value	\$ 6,500.00
Parf Rebate	\$ 832.00
Nett Loss	\$ 5,668.00

Repair details:

Initial Estimate	9,419.90
------------------	----------

Proposed/Revised repair cost:

Parts	\$ 3,203.10
Check items (estimate)	NIL
Labour	\$ 490.00
Total	\$ 3,693.10
Lump Sum(if applicable)	\$ 2,950.00

Number of days for repair	4.0
---------------------------	-----



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 URAVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (665) 62563561 FAX : (665) 62564315

Remarks:

PIR shows that OID was being charged for Inconsiderate Driving.

Mandate:

Liability(TP)		100%
Proposed repair cost (w/GST)	\$	3,156.50
Loss of use	\$	150.00 (6days x \$25)
Loss of rental		NIL no. of days
Loss of income		NIL no. of days
LTA search fees	\$	7.45
Others		NIL
Proposed Total	\$	3,313.95

Hsiao Tong (LKKAuto)

From: Mei Kwan (LKKAuto)
Sent: Tuesday, 5 November 2019 11:24 AM
To: Hsiao Tong (LKKAuto)
Subject: FW: New message for service request 119300, vehicle number FBM6064J

5/11/19 8:57 AM *** please proceed - TAN Jas

-----Original Message-----

From: jas.tan@axa.com.sg <jas.tan@axa.com.sg>
Sent: Tuesday, 5 November, 2019 8:58 AM
To: admin-d@lkkauto.com
Subject: New message for service request 119300, vehicle number FBM6064J

AXA Insurance has sent you a message for claim number S9M01MZ2.
Please click here <https://vp.smartclaims.axa.com.sg/claim-portal/> to view the message in Vendor Portal.
This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

Hsiao Tong (LKKAuto)

From: YT(HQ) <info@yewteegroup.com>
Sent: Wednesday, 29 January 2020 9:58 AM
To: Hsiao Tong (LKKAuto)
Cc: 'YTHQ'
Subject: RE: FBM 6064 J FINALIZE //DOA: 09/05/2019// LKK REF: CC4/ASM19009750/Jpa3
Attachments: LOD.pdf

Hi Hsiao Tong,

Attached the full claim document for your kind attention,

The original copy will post to your good office soon,

Thank you.

Best Regards

SHUYI



Yew Tee Automobile Tech Pte Ltd

HQ:
Blk 6 Woodlands Road 399F
Yew Tee Ind. Est
Singapore 678006
DID: 6765 3373 /6764 9042 Fax: 6760 4895
Email: utauto@singnet.com.sg

Branch Office:
Synergy@KB, 25 Kaki Bukit Road
Unit No #01-60/61
Singapore 417800
DID: 6702 3113
Email: utauto2@singnet.com.sg

Branch Office:
39 Woodlands Close,
#01-12 Mega@Woodlands
Singapore 737856
DID:62562081
Email: info@yewteegroup.com



please consider the environment before printing this email

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

From: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Sent: Friday, 8 November 2019 10:18 am
To: YT(HQ) <info@yewteegroup.com>
Cc: 'YTHQ' <utauto@singnet.com.sg>
Subject: RE: FBM 6064 J FINALIZE //DOA: 09/05/2019// LKK REF: CC4/ASM19009750/Jpa3

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

For COR, recommended amount at **L/sum \$2,950.00**(before GST) with **04** repair days.

****Kindly forward your LOD with all the relevant documents(ie: final repair bill, authorisation to act, rental receipt) to us (LKK) for our necessary action.**

Please note that all the finalisation subject to insurer approval.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: YT(HQ) <info@yewteegroup.com>
Sent: Monday, 4 November 2019 7:52 PM
To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Cc: 'YTHQ' <utauto@singnet.com.sg>
Subject: FBM 6064 J FINALIZE

Hi,

Kindly find attached GIA REPORT,

Thank you.

Best Regards

SHUYI



Yew Tee Automobile Tech Pte Ltd

HQ:

Blk 6 Woodlands Road 399F

Yew Tee Ind. Est

Singapore 678006

DID: 6765 3373 /6764 9042 Fax: 6760 4895

Email: utauto@singnet.com.sg

Branch Office:

Synergy@KB, 25 Kaki Bukit Road

Unit No #01-60/61

Singapore 417800

DID: 6702 3113

Email: utauto2@singnet.com.sg

Branch Office:

39 Woodlands Close,

#01-12 Mega@Woodlands

Singapore 737856

DID:62562081

Email: info@yewteegroup.com



please consider the environment before printing this email

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

Hsiao Tong (LKKAuto)

From: YT(HQ) <info@yewteegroup.com>
Sent: Wednesday, 19 February 2020 2:19 PM
To: Hsiao Tong (LKKAuto)
Cc: 'YTHQ'
Subject: RE: FBM 6064 J FINALIZE //DOA: 09/05/2019// LKK REF: CC4/ASM19009750/Jpa3

Hi Hsiao Tong,

Ok accept \$3250/ all in,

Thank you.

Best Regards

SHUYI



Yew Tee Automobile Tech Pte Ltd

HQ:
Blk 6 Woodlands Road 399F
Yew Tee Ind. Est
Singapore 678006
DID: 6765 3373 /6764 9042 Fax: 6760 4895
Email: utauto@singnet.com.sg

Branch Office:
Synergy@KB, 25 Kaki Bukit Road
Unit No #01-60/61
Singapore 417800
DID: 6702 3113
Email: utauto2@singnet.com.sg

Branch Office:
39 Woodlands Close,
#01-12 Mega@Woodlands
Singapore 737856
DID:62562081
Email: info@yewteegroup.com

 please consider the environment before printing this email

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

From: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Sent: Wednesday, 29 January 2020 10:57 am
To: YT(HQ) <info@yewteegroup.com>
Cc: 'YTHQ' <utauto@singnet.com.sg>
Subject: RE: FBM 6064 J FINALIZE //DOA: 09/05/2019// LKK REF: CC4/ASM19009750/Jpa3

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement at a global sum of **\$3,250.00(all-in)**.

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

"Wishing you a Happy and Prosperous New Year"



Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: YT(HQ) <info@yewteegroup.com>
Sent: Wednesday, 29 January 2020 9:58 AM
To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Cc: 'YTHQ' <utauto@singnet.com.sg>
Subject: RE: FBM 6064 J FINALIZE //DOA: 09/05/2019// LKK REF: CC4/ASM19009750/Jpa3

Hi Hsiao Tong,

Attached the full claim document for your kind attention,

The original copy will post to your good office soon,

Thank you.

Best Regards

SHUYI



Yew Tee Automobile Tech Pte Ltd

HQ:

Blk 6 Woodlands Road 399F

Yew Tee Ind. Est

Singapore 678006

DID: 6765 3373 /6764 9042 Fax: 6760 4895

Email: utauto@singnet.com.sg

Branch Office:

Synergy@KB, 25 Kaki Bukit Road

Unit No #01-60/61

Singapore 417800

DID: 6702 3113

Email: utauto2@singnet.com.sg

Branch Office:

39 Woodlands Close,

#01-12 Mega@Woodlands

Singapore 737856

DID:62562081

Email: info@yewteegroup.com



please consider the environment before printing this email

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

From: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Sent: Friday, 8 November 2019 10:18 am

To: YT(HQ) <info@yewteegroup.com>

Cc: 'YTHQ' <utauto@singnet.com.sg>

Subject: RE: FBM 6064 J FINALIZE //DOA: 09/05/2019// LKK REF: CC4/ASM19009750/Jpa3

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

For COR, recommended amount at **L/sum \$2,950.00**(before GST) with **04** repair days.

****Kindly forward your LOD with all the relevant documents(ie: final repair bill, authorisation to act, rental receipt) to us (LKK) for our necessary action.**

Please note that all the finalisation subject to insurer approval.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: YT(HQ) <info@yewteegroup.com>
Sent: Monday, 4 November 2019 7:52 PM
To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Cc: 'YTHQ' <utauto@singnet.com.sg>
Subject: FBM 6064 J FINALIZE

Hi,

Kindly find attached GIA REPORT,

Thank you.

Best Regards

SHUYI



Yew Tee Automobile Tech Pte Ltd

HQ:

Blk 6 Woodlands Road 399F

Yew Tee Ind. Est

Singapore 678006

DID: 6765 3373 /6764 9042 Fax: 6760 4895

Email: utauto@singnet.com.sg

Branch Office:

Synergy@KB, 25 Kaki Bukit Road

Unit No #01-60/61

Singapore 417800

DID: 6702 3113

Email: utauto2@singnet.com.sg

Branch Office:
39 Woodlands Close,
#01-12 Mega@Woodlands
Singapore 737856
DID:62562081
Email: info@yewteegroup.com



please consider the environment before printing this email

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

28.1.2020

AXA Insurance Singapore
143 Cecil Street
#01-01 GB Building
Singapore 069542

Attn: Motor Claims Department

Dear Sirs,

ACCIDENT INVOLVING FBM6064J & SGH2991B on 09/05/2019

We are the authorized repair workshop for the owner of motor vehicle no: FBM6064J which was involved in the captioned accident with your insured vehicle: SGH2991B The vehicle owner has requested and authorized us to assist him in presenting his/her claim against the party responsible for the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving, we are submitting these claims for your consideration on behalf of the owner/claimant.

01)	LUMP SUM REPAIR	\$	2,950.00
02)	TP search fee	\$	1.87
		\$	2,951.87
	GST 7%	\$	206.63
03)	Loss of use \$50/per day x4days	\$	200.00
	Grand Total	\$	<u>3,358.50</u>

We enclosed herewith the following documents to support the claims:-

- a) Tax Invoice/ Letter of authorisation
- b) GIA report

Kindly look into the matter and let us hear from you on the settlement of our customer's claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

Thank you
Yours faithfully



**YEW TEE AUTOMOBILE TECH PTE LTD**

HQ: BLK 6 WOODLANDS ROAD 399-F YEW TEE IND EST S(678006)

BR: SYNERGY@KB, 25 KAKI BUKIT ROAD 4 #01-61 S(417800)

BR: MEGA@WOODLANDS, 39 WOODLANDS CLOSE #01-12 S(737856)

GST Reg No. 200311009C

Singapore

67653373 67023113

INFO@YEWTEEGROUP.COM

WWW.YEWTEEGROUP.COM

Company Registration No. 200311009C

ADDRESS

AXA INSURANCE SINGAPORE

PTE LTD

AXA INSURANCE SINGAPORE

PTE LTD

TP Tax Invoice MC2001007**DATE 28/01/2020****VEHICLE NO.**

FBM6064J

ACTIVITY	QTY	RATE	TAX	AMOUNT
LUMP SUM REPAIR	1	2,950.00	7% SR	2,950.00
Survey & Search fee	1	1.87	7% SR	1.87
Loss Of Use	4	50.00	Out of Scope	200.00

Cheque should be crossed & made payable to "YEW TEE AUTOMOBILE TECH PTE LTD" and strictly send to our HQ address.

SUBTOTAL

3,151.87

GST TOTAL

206.63

TOTAL**SGD 3,358.50**

Accepted By

Accepted Date



ISSUED BY STAFF

E. & O.E.

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19009750/Jpa3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 27-02-2020



ATTN: JAS TAN

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGH 2991B	Veh. Inspected	FBM 6064J
Policy No.	VPA/P1458638	Coverage (\$)	0.00
Claim No.	S9M01MZ2	Excess (\$)	0.00
Assign From		Assign Date	03/06/2019

2. Vehicle Particulars & Condition

Make & Model	SYM	c.c	278
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	RFGLNA701DS006309	Colour	SILVER
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	120/80-14	MICHELIN	6 mm
L/H Front Tyre			mm
R/H Rear Tyre	140/60-13	MICHELIN	6 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	09/05/2019	Inspection Date	03/06/2019
Survey held at	YEW TEE AUTOMOBILE TECH PL (HQ) BLK 6 WOODLANDS ROAD 399F YEW TEE IND. ESTATE SINGAPORE 678006		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBM 6064J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT HEADLAMP (CONSISTENT)	NOT NECESSARY	900.00	-
1	FRONT HEADLAMP FAIRING (CONSISTENT)	CRACKED	450.00	450.00
1	FRONT HEADLAMP FAIRING CENTRE CHROME (CONSISTENT)	NECESSARY	95.00	95.00
1	FRONT HEADLAMP CENTRE FAIRING (CONSISTENT)	CRACKED	230.00	230.00
1	FRONT HEADLAMP LOGO (CONSISTENT)	NECESSARY	53.00	53.00
1	FRONT HEADLAMP BRACKET (CONSISTENT)	NOT NECESSARY	83.00	-
1	FRONT HEADLAMP INNER FAIRING (CONSISTENT)	NOT NECESSARY	430.00	-
1	FRONT SIDE LAMP LH (CONSISTENT)	NOT NECESSARY	208.00	-
1	FRONT SIDE LAMP RH (CONSISTENT)	SCRATCHED	208.00	208.00
1	FRONT SIDE MIRROR LH (CONSISTENT)	NOT NECESSARY	130.00	-
1	FRONT SIDE MIRROR RH (CONSISTENT)	CRACKED	130.00	130.00
1	FRONT SIDE MIRROR SIGNAL LAMP LH (CONSISTENT)	NOT NECESSARY	70.00	-
1	FRONT SIDE MIRROR SIGNAL LAMP RH (CONSISTENT)	CRACKED	70.00	70.00
1	FRONT SIDE MIRROR GLASS RH (CONSISTENT)	MISSING	87.00	87.00
1	FRONT SIDE MIRROR GARNISH LH (CONSISTENT)	NOT NECESSARY	38.00	-
1	FRONT SIDE MIRROR GARNISH RH (CONSISTENT)	MISSING	38.00	38.00
1	FRONT TOP VISOR (CONSISTENT)	NOT NECESSARY	160.00	-
1	FRONT TOP VISOR LOWER FAIRING (CONSISTENT)	SCRATCHED	145.00	145.00
1	FRONT FENDER (CONSISTENT)	SCRATCHED	180.00	180.00
1	FRONT FORK LH (CONSISTENT)	NOT NECESSARY	280.00	-
1	FRONT FORK RH (CONSISTENT)	NOT NECESSARY	280.00	-
1	FRONT WHEEL DISC ROTOR (CONSISTENT)	NOT NECESSARY	265.00	-
1	FRONT WHEEL BRAKE CALIPER (CONSISTENT)	NOT NECESSARY	380.00	-
1	FRONT BALANCER RH (CONSISTENT)	SCRATCHED	25.00	25.00
1	FRONT HANDLE BAR (CONSISTENT)	NOT NECESSARY	240.00	-
1	FRONT STEERING STEM (CONSISTENT)	NOT NECESSARY	55.00	-
1	FRONT BRAKE LEVER RH (CONSISTENT)	SCRATCHED	28.00	28.00
1	FRONT CENTRE INNER FAIRING (CONSISTENT)	CRACKED	480.00	480.00
1	FRONT STEP GARNISH RH (CONSISTENT)	NOT NECESSARY	110.00	-
1	FRONT RADIATOR FAIRING (CONSISTENT)	CRACKED	420.00	420.00

Report Ref No. CC4/ASM19009750/Jpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT CENTRE LOWER FAIRING (CONSISTENT)	NOT NECESSARY	370.00	-
1	RADIATOR (CONSISTENT)	NOT NECESSARY	445.00	-
1	RADIATOR BRACKET (CONSISTENT)	NOT NECESSARY	78.00	-
1	REAR EXHAUST PIPE PROTECTOR (CONSISTENT)	SCRATCHED	160.00	160.00
1	REAR FAIRING RH (CONSISTENT)	SCRATCHED	320.00	320.00
1	REAR HANDLE RH (CONSISTENT)	SCRATCHED	140.00	140.00
1	FRONT SEAT TOP BACKING CUSHION (CONSISTENT)	NOT NECESSARY	210.00	-
	LESS 10% DISCOUNT		-799.10	-325.90
			7,191.90	2,933.10
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT WHEEL RIM (SN) (CONSISTENT)	NOT NECESSARY	353.00	-
1	FRONT NUMBER PLATE (SN) (CONSISTENT)	NECESSARY	45.00	20.00
1	REAR BOX (METAL) (SN) (CONSISTENT)	SCRATCHED	380.00	250.00
1	SET REAR BOX BRACKET (SN) (CONSISTENT)	NOT NECESSARY	80.00	-
			858.00	270.00
	<u>LABOUR</u>			
	TO DISCONNECT AND RECONNECT ,CHECK ELECTRICAL WIRING HARNESS WIRE ,SOCKETS ,REPLACE DAMAGED PARTS.		30.00	20.00
	TO REMOVE AND REFIT ,STRAIGHTEN AND RE-ADJUST EXHAUST PIPE AND REAR EXHAUST SILENCER AND MOUNTINGS.		180.00	50.00
	TO PRESSURE TEST AIR CON CONDENSER AND RADIATOR FOR LEAKAGE.	NOT NECESSARY	120.00	-
	TOWING CHARGES.		80.00	40.00
	TO CONDUCT WHEEL BALANCING.		60.00	50.00
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS ,STRAIGHTEN ,KNOCK OUT ,REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS .TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS.		450.00	300.00
	TO CARRY -OUT BODY CAVITY PRESERVATION .		50.00	30.00

Report Ref No. CC4/ASM19009750/Jpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SPRAY PAINTING ON THE REPLACED AND REPAIR PARTS ,PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER ,CLEANING AND SANDING OF SURFACES ,FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.	NOT NECESSARY	400.00	-
			1,370.00	490.00
GRAND TOTAL			9,419.90	3,693.10
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,950.00

Report Ref No. CC4/ASM19009750/Jpa3q2

ONG HWEЕ JIE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim	59M01MZZ
Reference	CC4/ASM19009750/Jaa302
Loss Date	9 May 2019
Report Date	15 May 2019 12:54:00 PM
Request Date	3 June 2019
Due Date	

Actions

Next Step

Wait for Approve Invoice

Add Invoice

Vehicle Information	
Incident Vehicle Registration #	FBM6064J
Make	TPVD SYM
Model	SYM JOYMAX 300I CVT GREY
Service Address	

...

Vendor Name	LK& AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Primary Contact/Insured	
LAW CHEOW CHIEN PATRICIA 5A SURIN AVENUE, ONE SURIN, S33924, Singapore 90222607 AVTEONG@GMAIL.COM	

Claim Handler

TAN Jia
6568804844
jia.tan@axa.com.sg

Additional Instructions

Messages	Invoices	History	Documents	Assessment	Metrics	Notes
----------	----------	---------	-----------	------------	---------	-------

Document Type

Document SubType

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LK&Invoice1 (4).pdf	Invoice	Surveyor/ Assessor expense	LK& AUTO CONSULTANTS PTE LTD (TP)	3 March 2020

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKK Inspection.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	3 March 2020
 LKK Adjustment 1a.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	3 March 2020
 GIA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	3 March 2020
 PAYMENT BREAKDOWN_EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	3 March 2020
 AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	3 March 2020
 LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	3 March 2020
 TP ESTIMATE_MARKED(FINAL).pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	5 November 2019
 LKK RESURVEY PHOTOS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	5 November 2019
 TP-MANDATE IA .dll.051119.pdf	Forms / Claim Documents	Assessment	LKK AUTO CONSULTANTS PTE LTD (TP)	5 November 2019
 LKK SURVEY PHOTO.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	18 June 2019
 TP - IA.pdf	Forms / Claim Documents	Assessment	LKK AUTO CONSULTANTS PTE LTD (TP)	18 June 2019
 TP ESTIMATE-MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	16 June 2019
 SGH429910 INSD GIA REPORT.PDF	Reports & Statement	GIA Report	DHAKAL Raghav	3 June 2019
 TP YEW TEE-PRI FROM WORKSHOP WITH GIA REPORT .msg	Letters and Correspondence	Workshop	DHAKAL Raghav	3 June 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 PIR.png	Evidence	Others	LAK AUTO CONSULTANTS PTE LTD (TP)	3 June 2019
 CIA FBMA044 TP.pdf	Reports & Statement	CIA Report	VISHNU BATHAM Shekhar	24 May 2019