



Case Details

Case Reference Number :

TAX/05/19/2138

Type of Repair : Accident Repair

Vehicle Registration Number :

SHD6303X

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-7099-ID

Assigned By : Taxi Claims Manager
Team

Insurance Company Name : India International Insurance Pte Ltd

Accident Date and Time : 29/05/2019 04:45 PM

Vehicle Age(In Months) : 35

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			DOOR FRT/LH	1	894.40	894.40	25.00	670.80	Replace	1	670.80	Replace ▾	BUC
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace ▾	neu
One Time Key In	Main			DOOR BELT FRT/LH	1	69.20	69.20	25.00	51.90	Replace	1	51.90	Replace ▾	cut
One Time Key In	Main			DOOR OUTER HANDLE FRT/LH	1	370.80	370.80	25.00	278.10	Replace	0	0	Not Give ▾	nm
One Time Key In	Main			MIRROR ASSY, LH	1	1,224.90	1,224.90	25.00	918.68	Replace	1	918.68	Replace ▾	CRA
One Time Key In	Main			MIRROR LAMP LH	1	65.30	65.30	10.00	58.77	Replace	1	58.77	Replace ▾	scr
One Time Key In	Main			MIRROR GLASS LH	1	142.50	142.50	25.00	106.88	Replace	0	0	Not Give ▾	nm
One Time Key In	Main			COVER, OUTER MIRROR, LH	1	107.40	107.40	25.00	80.55	Replace	1	0	Repair ▾	

Total Spare Part Cost	3,873.38	Surveyor Total	1,849.55
Lump Sum Discount (%)	0.00	Lump Sum Dis (%)	0
Final Spare Part Cost	3,710.31	Final Sur Total	1,849.55

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			DOOR RR/LH	1	954.50	954.50	25.00	715.88	Replace	1	0	Repair ▾	
One Time Key In	Main			DOOR BELT RR/LH	1	69.20	69.20	25.00	51.90	Replace	0	0	Not Give ▾	hh
One Time Key In	Main			DOOR OUTER HANDLE RR/LH	1	69.80	69.80	25.00	52.35	Replace	0	0	Not Give ▾	hh
One Time Key In	Main			PIXEL STICKER	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace ▾	nee
One Time Key In	Main			FENDER RR/LH	1	766.80	766.80	25.00	575.10	Replace	1	0	Repair ▾	
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace ▾	nee
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace ▾	nee
One Time Key In	Main			QUARTER GLASS RR/LH	1	168.10	168.10	25.00	126.07	Replace	0	0	Not Give ▾	nn
One Time Key In	Main			SEALANT W/SCREEN	1	37.00	37.00	0.00	37.00	Replace	0	0	Not Give ▾	nn
Total Spare Part Cost									3,873.38		Surveyor Total		1,849.55	
Lump Sum Discount (%)									0.00		Lump Sum Dis (%)		0	
Final Spare Part Cost									3,710.31		Final Sur Total		1,849.55	

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR LH PORTION	1,014.00	600	
Total:			1,014.00	600.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY FRONT DOOR LH	378.00	200	
Total:			1,314.00	650.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
2	Main	TO RESPRAY VIEW MIRROR	180.00	50	
3	Main	TO RESRAY REAR DOOR LH	378.00	200	
4	Main	TO RESPRAY REAR FENDER LH	378.00	200	
Total:			1,314.00	650.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TOWING CHARGE	84.00	0	
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	20	
3	Main	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	0	
4	Main	TO TRANSFER DOOR MECHANISM	240.00	50	
5	Main	TO REMOVE AND REFIX WING MIRROR	120.00	40	
6	Main	TO WASH AND VACUUM	60.00	0	
Total:			729.00	110.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	3,710.31	1,849.55
Total Labour Cost	1,014.00	600.00
Total Spray Painting	1,314.00	650.00
Other	729.00	110.00
Overall Total	6,767.31	3,209.55
Lump Sum Repair Option	☐	☐
Lump Sum Total	0.00	3,209.55
Surveyor Approved Amount		3,209.55
No of Repair Days*	7	5

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Remarks		p/p repair, photo before paint.
Surveyor Name		Hwee jie
Signature		
Survey Date	31/05/2019	Save Clear

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: