


Customer:		Date:	4/6/2019 10:12 AM
Company:		VIN	
License No:	SGG1320A	Technician:	
Odometer:		Order No.:	

Graphic Alignment Report



PRE-REPAIR INSPECTION REQUEST – SGG1320A vs SLS642E (OI) on D.O.A.: 01/06/2019

From: Hor, Yinrul
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Subramaniam, Divyashni; Tor
Sent: 6/3/2019 4:31:01 PM
Attachments:  [PRI Arrangement.pdf](#)

Hi,

Please refer to the enclosed request from **RICO 60 AUTO SERVICES PTE. LTD.**
Kindly carry out Policy coverage verification **first** before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.
Kindly assist to assign Marcus Chua as Single Joint Expert as requested.

Thanks & Regards,

Hor Yin Rul (Viviane)
AIG
Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Yinrul.Hor@aig.com | www.aig.sg

From: claims@rico60.com [mailto:claims@rico60.com]
Sent: Monday, June 03, 2019 4:02 PM
To: Hor, Yinrul
Cc: Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Subramaniam, Divyashni; Tong, Wahxin
Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLS642E AND SGG1320A ON 01/06/2019

Dear AIG,

Please have Marcus Chua from LKK survey the said vehicle.

From: Hor, Yinrul
Sent: Mon, 3 Jun 2019 07:04:02 +0000
To: claims@rico60.com
Cc: Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Subramaniam, Divyashni; Tong, Wahxin
Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLS642E AND SGG1320A ON 01/06/2019

Without Prejudice

Your Reference : SGG1320A
Our Reference : SLS642E

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Hor Yin Rui (Viviane)

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto

Yinui.Hor@aig.com | www.aig.sg

From: Rico 60 [<mailto:claims@rico60.com>]

Sent: Monday, June 03, 2019 2:55 PM

To: Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Chin, Lee-Ying; Abu Kassim, Noor Mariesa

Subject: [EXTERNAL] PRI Arrangement for SGG1320 A

This message is from an external sender; be cautious with links and attachments.

Dear All,

Kindly arrange PRI to survey the said vehicle as follows:

Our Client – SGG 1320 A

Your Insured – SL5 642 E

DOA – 01/06/2019

Thank you.

Best Regards,

Jin Hai



RICO 60 AUTO SERVICES PTE. LTD.

Co. & GST Reg. No.: 201807623M

8 Kaki Bukit Avenue 4, Premier @ Kaki Bukit

#02-24, Singapore 415875

Tel: +65 6286 6060 | Fax: +65 6286 7060

Email: claims@rico60.com

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

JOIN US (<https://www.police.gov.sg/join-us>)

FAQS (<https://va.ecitizen.gov.sg/cfp/CustomerPages/SPF/explorefaq.aspx>)

CONTACT US (<https://www.police.gov.sg/content/contact-us>)

E-FEEDBACK (</content/policehubefeedback/efeedback.html>)

SITEMAP (<https://www.police.gov.sg/sitemap>)

Privacy Statement (<https://www.police.gov.sg/content/privacy-statement>) | Terms of Use

(<https://www.police.gov.sg/content/terms-of-use>) | Rate this Service

(<https://form.gov.sg/forms/spf/5b90934f64567e000fb2d9a6>) . © 2019 Singapore Police Force. A Member of The Home Team (<https://www.mha.gov.sg>).

Print Received Message

This mail is associated with :

***SGG1320A (6627806807SG)**
[SLS642E]

TP

TAY HUNG YEONG

Jun 1 2019 9:00AM

[MR LUA WEIBIN JONATHAN]
RICO 60 AUTO SERVICES PTE LTD

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 16/08/2019 16:06 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$13976.49) - SGG1320A - Claim Handler: Chan, Kian-Meng

Approved:13976.49:Kindly settle at best.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Jun 2019 Edit Reg		03 Jun 2019 00:00 Edit Adj Rpt	S\$12,000.00 Edit Estimates	S\$12,000.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	MR LUA WEIBIN JONATHAN, ID: S9340947G		
Main Claimant:	TAY HUNG YEONG, ID: S6844986C		
Vehicle Reg. No.:	SGG1320A	Date of Loss:	01/06/2019 09:00 - :59 [39 Months and 8 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 6627806807SG	Policy/Cover Note No.:	(Comprehensive) Coverage: 05/09/2018 - 04/09/2019
Vehicle Reg. No. (Insured):	SLS642E	Policy No. (Claimant):	A28692537COMP
		Excess:	
Repairer:	RICO 60 AUTO SERVICES PTE LTD (HQ) 8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@alg.com		
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 19/06/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG_EXPRESS (16/08/2019): Alert - Adj Mandate Approved (S\$13976.49) - SGG1320A - Claim Handler: Chan, Kian...

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SGG1320A (6627806807SG)**
[SLS642E]
TP
TAY HUNG YEONG
Jun 1 2019 9:00AM
[MR LUA WEIBIN JONATHAN]
RICO 60 AUTO SERVICES PTE LTD

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View
[View in Browser](#)

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown		Edit	

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	01/07/19 08:29	Chassis Number		Load JPG	☒
2	01/07/19 08:29	Odometer Reading		Load JPG	☒
3	01/07/19 08:29	General View		Load JPG	☒
4	01/07/19 08:29	General View		Load JPG	☒
5	01/07/19 08:29	General View		Load JPG	☒
6	01/07/19 08:29	General View		Load JPG	☒
7	01/07/19 08:29	General View		Load JPG	☒
8	01/07/19 08:29	General View		Load JPG	☒
9	01/07/19 08:29	General View		Load JPG	☒
10	01/07/19 08:29	General View		Load JPG	☒
11	01/07/19 08:29	General View		Load JPG	☒
12	01/07/19 08:29	General View		Load JPG	☒
13	01/07/19 08:29	General View		Load JPG	☒
14	01/07/19 08:29	General View		Load JPG	☒
15	01/07/19 08:29	General View		Load JPG	☒
16	01/07/19 08:29	General View		Load JPG	☒
17	01/07/19 08:29	General View		Load JPG	☒
18	01/07/19 08:29	General View		Load JPG	☒
19	01/07/19 08:29	General View		Load JPG	☒
20	01/07/19 08:29	General View		Load JPG	☒
21	01/07/19 08:29	General View		Load JPG	☒
22	01/07/19 08:29	General View		Load JPG	☒
23	01/07/19 08:29	General View		Load JPG	☒
24	01/07/19 08:29	General View		Load JPG	☒
25	01/07/19 08:29	General View		Load JPG	☒
26	01/07/19 08:29	General View		Load JPG	☒
27	01/07/19 08:29	General View		Load JPG	☒
28	01/07/19 08:29	General View		Load JPG	☒
29	01/07/19 08:29	General View		Load JPG	☒
30	01/07/19 08:29	General View		Load JPG	☒
31	01/07/19 08:29	General View		Load JPG	☒
32	01/07/19 08:29	General View		Load JPG	☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
33	01/07/19 08:29	General View	 Load JPG	☒
34	01/07/19 08:29	General View	 Load JPG	☒
35	01/07/19 08:29	General View	 Load JPG	☒
36	01/07/19 08:29	General View	 Load JPG	☒
37	01/07/19 08:29	General View	 Load JPG	☒
38	01/07/19 08:29	General View	 Load JPG	☒
39	01/07/19 08:29	General View	 Load JPG	☒
40	01/07/19 08:29	General View	 Load JPG	☒
41	01/07/19 08:29	General View	 Load JPG	☒
42	01/07/19 08:29	General View	 Load JPG	☒
43	01/07/19 08:29	General View	 Load JPG	☒
44	01/07/19 08:29	General View	 Load JPG	☒
45	01/07/19 08:29	General View	 Load JPG	☒
46	01/07/19 08:29	General View	 Load JPG	☒
47	01/07/19 08:29	General View	 Load JPG	☒
48	01/07/19 08:29	General View	 Load JPG	☒
49	01/07/19 08:29	General View	 Load JPG	☒
50	01/07/19 08:29	General View	 Load JPG	☒
51	01/07/19 08:29	General View	 Load JPG	☒
52	01/07/19 08:29	General View	 Load JPG	☒
53	01/07/19 08:29	General View	 Load JPG	☒
54	01/07/19 08:29	General View	 Load JPG	☒
55	01/07/19 08:29	General View	 Load JPG	☒
56	01/07/19 08:29	General View	 Load JPG	☒
57	01/07/19 08:29	General View	 Load JPG	☒
58	01/07/19 08:29	General View	 Load JPG	☒
59	01/07/19 08:29	General View	 Load JPG	☒
60	01/07/19 08:29	General View	 Load JPG	☒
61	01/07/19 08:29	General View	 Load JPG	☒
62	01/07/19 08:29	General View	 Load JPG	☒
63	01/07/19 08:29	General View	 Load JPG	☒
64	01/07/19 08:29	General View	 Load JPG	☒
65	01/07/19 08:29	General View	 Load JPG	☒
66	01/07/19 08:29	General View	 Load JPG	☒
67	01/07/19 08:29	General View	 Load JPG	☒
68	01/07/19 08:29	General View	 Load JPG	☒
69	01/07/19 08:29	General View	 Load JPG	☒
70	01/07/19 08:29	General View	 Load JPG	☒
71	01/07/19 08:29	General View	 Load JPG	☒
72	01/07/19 08:29	General View	 Load JPG	☒
73	01/07/19 08:29	General View	 Load JPG	☒
74	01/07/19 08:29	General View	 Load JPG	☒
75	01/07/19 08:29	General View	 Load JPG	☒
76	01/07/19 08:29	General View	 Load JPG	☒
77	01/07/19 08:30	Reinspection Photo	 Load JPG	☒
78	01/07/19 08:30	Reinspection Photo	 Load JPG	☒
79	01/07/19 08:30	Reinspection Photo	 Load JPG	☒
80	01/07/19 08:30	Reinspection Photo	Load JPG	☒

Letters/Correspondences			1 per page ▼	✓
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
81	01/07/19 08:30	Reinspection Photo	 Load JPG	✓
82	01/07/19 08:30	Reinspection Photo	 Load JPG	✓
83	01/07/19 08:30	Reinspection Photo	 Load JPG	✓
84	01/07/19 08:30	Reinspection Photo	 Load JPG	✓
85	01/07/19 08:30	Reinspection Photo	 Load JPG	✓
86	01/07/19 08:30	Reinspection Photo	 Load JPG	✓
87	01/07/19 08:30	Reinspection Photo	 Load JPG	✓
88	01/07/19 08:30	Reinspection Photo	 Load JPG	✓
89	01/07/19 08:30	Reinspection Photo	 Load JPG	✓
90	01/07/19 08:30	Reinspection Photo	 Load JPG	✓
91	01/07/19 08:30	Reinspection Photo	 Load JPG	✓
92	01/07/19 08:30	Reinspection Photo	 Load JPG	✓
93	01/07/19 08:30	Reinspection Photo	 Load JPG	✓
94	01/07/19 08:30	Reinspection Photo	 Load JPG	✓
95	01/07/19 08:30	Reinspection Photo	 Load JPG	✓
96	01/07/19 08:30	Reinspection Photo	 Load JPG	✓
97	01/07/19 08:30	Reinspection Photo	 Load JPG	✓
98	01/07/19 08:30	Reinspection Photo	 Load JPG	✓
99	01/07/19 08:30	Reinspection Photo	 Load JPG	✓
100	01/07/19 08:30	Reinspection Photo	 Load JPG	✓
101	01/07/19 08:30	Reinspection Photo	 Load JPG	✓
102	01/07/19 08:30	Reinspection Photo	 Load JPG	✓
103	01/07/19 08:30	Reinspection Photo	 Load JPG	✓
104	01/07/19 08:30	Reinspection Photo	 Load JPG	✓
105	01/07/19 08:30	Reinspection Photo	 Load JPG	✓
106	01/07/19 08:30	Reinspection Photo	 Load JPG	✓
107	01/07/19 08:30	Reinspection Photo	 Load JPG	✓
108	01/07/19 08:30	Reinspection Photo	 Load JPG	✓
109	01/07/19 08:30	Reinspection Photo	 Load JPG	✓
110	01/07/19 08:30	Reinspection Photo	 Load JPG	✓
111	01/07/19 08:30	Reinspection Photo	 Load JPG	✓
112	01/07/19 08:30	Reinspection Photo	 Load JPG	✓
113	01/07/19 08:30	Reinspection Photo	 Load JPG	✓
114	01/07/19 08:30	Reinspection Photo	 Load JPG	✓
115	01/07/19 08:30	Reinspection Photo	 Load JPG	✓
116	01/07/19 08:30	Reinspection Photo	 Load JPG	✓
117	01/07/19 08:30	Reinspection Photo	 Load JPG	✓
118	01/07/19 08:30	Reinspection Photo	 Load JPG	✓
119	01/07/19 08:30	Reinspection Photo	 Load JPG	✓
120	01/07/19 08:30	Reinspection Photo	 Load JPG	✓
121	01/07/19 08:30	Reinspection Photo	 Load JPG	✓
122	01/07/19 08:30	Reinspection Photo	 Load JPG	✓
123	01/07/19 08:30	Reinspection Photo	 Load JPG	✓
124	01/07/19 08:30	Reinspection Photo	 Load JPG	✓
125	01/07/19 08:30	Reinspection Photo	 Load JPG	✓
126	01/07/19 08:30	Reinspection Photo	 Load JPG	✓
127	01/07/19 08:30	Reinspection Photo	 Load JPG	✓
128	01/07/19 08:30	Reinspection Photo	Load JPG	✓

Letters/Correspondences			1 per page	✓
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
129	01/07/19 08:30	Reinspection Photo	Load JPG	✓
130	01/07/19 08:30	Reinspection Photo	Load JPG	✓
131	01/07/19 08:30	Reinspection Photo	Load JPG	✓
132	01/07/19 08:30	Reinspection Photo	Load JPG	✓
133	01/07/19 08:30	Reinspection Photo	Load JPG	✓
134	01/07/19 08:30	Reinspection Photo	Load JPG	✓
135	01/07/19 08:30	Reinspection Photo	Load JPG	✓
136	01/07/19 08:30	Reinspection Photo	Load JPG	✓
137	01/07/19 08:30	Reinspection Photo	Load JPG	✓
138	01/07/19 08:30	Reinspection Photo	Load JPG	✓
139	01/07/19 08:30	Reinspection Photo	Load JPG	✓
140	01/07/19 08:30	Reinspection Photo	Load JPG	✓
141	01/07/19 08:30	Reinspection Photo	Load JPG	✓
Documentation			1 per page	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/06/19 19:58	TP GIA REPORT	Load PDF	
2	10/06/19 19:58	EMAIL FROM AIG DD 4.6.19	Load PDF	
3	10/06/19 19:58	ACKNOWLEDGEMENT EMAIL TO AIG DD 03.06.2019	Load PDF	
4	10/06/19 19:58	NOTIFICATION FROM WORKSHOP	Load PDF	
5	11/06/19 16:17	TP ESTIMATE - MARKED	Load PDF	
6	11/06/19 16:17	ALIGNMENT REPORT	Load PDF	
7	19/06/19 13:17	Letter to OI	Load PDF	
8	07/08/19 17:09	GIA LTA SEARCH	Load PDF	
9	07/08/19 17:09	RENTAL RECEIPT	Load PDF	
10	30/08/19 09:01	LOD	Load PDF	
11	30/08/19 09:01	AUTHORISATION TO ACT	Load PDF	
12	30/08/19 09:01	RELEASE VOUCHER	Load PDF	
13	30/08/19 09:01	WORKSHOP INVOICE	Load PDF	
14	30/08/19 09:03	RENTAL MILEAGE	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	12/06/19 10:23	OI GIA report	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLS642E (Insd veh)	Model:	VOLKSWAGEN TIGUAN 1.4 TSI
	SGG1320A (TP veh)		(A)
Date of Accident:	01/06/2019		

Global Sum Settlement	:	☒ [X] Yes	☐ [] No	
Repair Estimate	:	\$		79,026.18
Final Repair Cost	:	\$		
Loss of Use	:	\$		days at \$0.00 per day
Rental (if any)	:	\$		11 days
LTA / GIA Search Fee	:	\$		
Others:	:	\$		
	:	\$		
Final Settlement Sum (GLOBAL SUM)	:	\$		13,970.00

Is Third Party Workshop GIA Registered?	☐ [] YES	☒ [X] NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:	Agreed Liability _____ 100 _____ (%)		
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____ (%)	Assessed Liability (*): _____ 100 _____ (%)		
<i>* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.</i>			
Remarks _____			

Payment Instruction: Payee's Breakdown

1)	RICO 60 AUTO SERVICES PTE. LTD.	:	\$	13,970.00
2)		:	\$	
3)		:	\$	
4)		:	\$	

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

30 Aug
2019

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19009777/UHA3S2

Date: 30/08/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SGG1320A

Insured Vehicle No : SLS642E

Date of Loss: 01/06/2019

Nature of Claim: TP

Claim No: 6627806807SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGG1320A

Make & Model: VOLKSWAGEN TIGUAN, 1.4 TSI (A)

Engine No: CTH230378

Reg. Date: 24/02/2016 (Man. Year: 2015)

Chassis No: WVGZZZ5NZGW030898

Colour: Silver

Odometer: 54155 km

Engine Capacity: 1390 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes

Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/40R19

Rear Tyre Size:

255/40R19

Front Left Side: Dunlop 6 mm

Rear Left Side:

Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side:

Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	61,876.24	12,131.04	49,745.20	80.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,980.00	2,970.00	9,010.00	75.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	73,856.24	15,101.04	58,755.20	79.55
Approved Total (Overridden) (S\$)		12,000.00		
(S\$)	73,856.24	12,000.00	61,856.24	83.75
+ GST 7.00/7.00% (S\$)	5,169.94	840.00	4,329.94	83.75
Nett Amount (S\$)	79,026.18	12,840.00	66,186.18	83.75
+ Car Rental (11.0 x S\$100.00/day) (S\$)		1,100.00		
+ Doc/Search Fee (S\$)		36.49		
Nett Liability (S\$)		13,976.49		
Global Sum Settlement (S\$)		13,970.00		

INSPECTION

Date of Assignment: 03/06/2019

Date Inspected: 04/06/2019 Inspected At:

RICO 60 AUTO SERVICES PTE LTD (HQ)

8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT

Singapore 415875

Estimated Period of Repair: 10.0 days

Adjuster: MARCUS CHUA**Manager:** VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR WINDSCREEN MOULDING	Not Necessary	216.80 FL	*- FL
2	1	*TAILGATE	Repair	1,674.60 FL	*- FL
3	1	*TAILGATE SPOILER	Not Necessary	468.70 FL	*- FL
4	1	*TAILGATE THIRD BRAKE LAMP	Not Necessary	296.70 FL	*- FL
5	1	*TAILGATE WIPER	Not Necessary	86.30 FL	*- FL
6	1	*TAILGATE WIPER MOTOR	Not Necessary	216.70 FL	*- FL
7	1	*TAILGATE WIPER MOTOR COVER	Not Necessary	42.30 FL	*- FL
8	1	*TAILGATE LOGO (VOLKSWAGEN)	Not Necessary	130.90 FL	*- FL
9	1	*TAILGATE EMBLEM (TIGUAN)	Not Necessary	76.10 FL	*- FL
10	1	*TAILGATE EMBLEM (TSI)	Not Necessary	62.20 FL	*- FL
11	2	*TAILGATE LAMP (L+R)	Not Necessary	420.60 FL	*- FL
12	1	*TAILGATE LOCK	Not Necessary	248.10 FL	*- FL
13	1	*TAILGATE CATCH	Not Necessary	56.70 FL	*- FL
14	1	*TAILGATE HANDLE	Not Necessary	32.80 FL	*- FL
15	1	*REVERSE CAMERA	Not Necessary	1,064.30 FL	*- FL
16	2	*TAILGATE CARPLATE LAMP (L+R)	Not Necessary	121.40 FL	*- FL
17	1	*TAILGATE INNER TRIM	Not Necessary	425.70 FL	*- FL
18	2	*TAILGATE INNER TRIM (L+R)	Not Necessary	1,267.40 FL	*- FL
19	1	*TAILGATE INNER TRIM TOP	Not Necessary	128.40 FL	*- FL
20	1	*TAILGATE INNER BOARD (NPA)	Not Necessary	0.00 FL	*- FL
21	2	*TAILGATE DAMPER (L+R)	Not Necessary	426.60 FL	*- FL
22	2	*TAILGATE HINGE (L+R)	Not Necessary	226.20 FL	*- FL
23	2	*TAILGATE INNER WIPE PROTECTOR (L+R)	Not Necessary	186.20 FL	*- FL
24	1	*TAILGATE WEATHER STRIP	Not Necessary	816.80 FL	*- FL
25	1	*TAIL LAMP (L+R)	N/s Cracked	760.80 FL	*380.10 FL
26	2	*TAIL LAMP PANEL (L+R)	Repair	425.40 FL	*- FL
27	1	*REAR BUMPER	Distorted	1,041.50 FL	*1,041.50 FL
28	1	*REAR BUMPER RETAINER (L+R)	N/s Cracked	88.40 FL	*44.20 FL
29	1	*REAR BUMPER LOWER	Distorted	865.70 FL	*865.70 FL
30	1	*REAR BUMPER REFLECTOR (L+R)	N/s Broken	112.40 FL	*56.20 FL
31	2	*REAR BUMPER REFLECTOR LAMP (L+R)	Repeated	365.60 FL	*- FL
32	1	*REAR BUMPER TOW COVER	Not Necessary	42.10 FL	*- FL
33	1	*SET REAR BUMPER REVERSE SENSOR 6pcs	Shorted 2pcs Only	2,160.00 FL	*430.00 FL
34	1	*REAR BUMPER UNDERCOVER	Grazed	328.70 FL	*225.30 FL
35	1	*REAR BUMPER SIDE PROTECTOR (L+R)	N/s Distorted	216.40 FL	*108.20 FL
36	1	*REAR BUMPER REINFORCEMENT BAR	Not Necessary	639.80 FL	*- FL
37	1	*REAR BUMPER BEAM	Not Necessary	331.30 FL	*- FL
38	1	*REAR BUMPER SPONGE	No such part	321.70 FL	*- FL
39	1	*REAR BUMPER BRACKET (L+R)	N/s Cracked	86.40 FL	*43.20 FL
40	1	*REAR FENDER (L+R)	N/s Badly Dented / Buckled	4,860.40 FL	*1,866.00 FL
41	1	*REAR AIR VENT	Distorted	128.60 FL	*128.60 FL
42	2	*REAR FENDER QUARTER WINDOW MOULDING (L+R)	Not Necessary	631.80 FL	*- FL
43	2	*REAR FENDER INNER TRIM (L+R)	Not Necessary	867.40 FL	*- FL
44	1	*REAR FENDER COWLING (L+R)	N/s Torn	484.40 FL	*242.20 FL
45	1	*REAR WHEEL ARCH PROTECTOR (L+R)	N/s Torn	268.20 FL	*134.10 FL
46	1	*END PANEL	Badly Dented	648.90 FL	*648.90 FL
47	1	*END PANEL TOP GARNISH	Not Necessary	128.00 FL	*- FL
48	1	*SPARE WHEEL PANEL	Not Necessary	1,263.70 FL	*- FL
49	1	*SPARE WHEEL PANEL TOP BOARD	Not Necessary	216.10 FL	*- FL
50	1	*SPARE WHEEL PANEL INNER ACCESSORIES BOX	Not Necessary	144.70 FL	*- FL
51	1	*EXHAUST PIPE	Not Necessary	869.40 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
52	1	*EXHAUST GASKET	Not Necessary	156.70 FL	*- FL
53	2	*EXHAUST BRACKET (L+R)	Not Necessary	76.90 FL	*- FL
54	1	*EXHAUST HEAT SHIELD	Not Necessary	218.40 FL	*- FL
55	1	*REAR ABSORBER (LH)	Not Necessary	422.10 FL	*- FL
56	1	*REAR LOWER ARM (LH)	Not Necessary	907.40 FL	*- FL
57	1	*REAR KNUCKLE (LH)	Not Necessary	344.10 FL	*- FL
58	1	*REAR KNUCKLE BEARING (LH)	Not Necessary	297.30 FL	*- FL
59	1	*REAR BEARING HUB (LH)	Not Necessary	302.40 FL	*- FL
60	1	*REAR AXLE (NPA)	Not Necessary	0.00 FL	*- FL
61	1	*FRONT BONNET	Repair	1,268.70 FL	*- FL
62	1	*FRONT BONNET LOCK	Not Necessary	79.60 FL	*- FL
63	1	*FRONT BONNET CATCH	Not Necessary	52.90 FL	*- FL
64	1	*FRONT BONNET INNER TRIM	Not Necessary	7.10 FL	*- FL
65	4	*FRONT BONNET STOPPER (L+R)	Not Necessary	72.40 FL	*- FL
66	2	*FRONT BONNET INNER RUBBER STRIP (L+R)	Not Necessary	268.20 FL	*- FL
67	1	*FRONT CENTRE GRILLE CHROME	Not Necessary	418.40 FL	*- FL
68	1	*FRONT CENTRE LOGO CHROME (VOLKSWAGEN)	Not Necessary	141.70 FL	*- FL
69	1	*HEAD LAMP (L+R)	O/s Cracked	2,094.20 FL	*1,047.10 FL
70	2	*HEAD LAMP BRACKET (L+R)	Not Necessary	428.20 FL	*- FL
71	1	*FRONT BUMPER	Distorted	1,231.70 FL	*1,231.70 FL
72	1	*FRONT BUMPER RETAINER (L+R)	O/s Bent	89.60 FL	*49.80 FL
73	1	*FRONT BUMPER GRILLE	Not Necessary	218.70 FL	*- FL
74	1	*FRONT BUMPER FOG LAMP (L+R)	Not Necessary	25.60 FL	*- FL
75	1	*FRONT BUMPER FOG LAMP GARNISH (L+R)	O/s Scratched	682.40 FL	*255.00 FL
76	1	*SET FRONT BUMPER SENSOR 6pcs	Shorted 1pc Only	2,160.00 FL	*215.00 FL
77	1	*FRONT BUMPER NOZZLE CAP	Not Necessary	46.00 FL	*- FL
78	2	*FRONT BUMPER TOW COVER	Not Necessary	64.20 FL	*- FL
79	1	*FRONT BUMPER SIDE PROTECTOR (L+R)	O/s Distorted	248.40 FL	*124.20 FL
80	1	*FRONT FENDER (L+R)	O/s Dented	916.80 FL	*458.40 FL
81	1	*FRONT FENDER COWLING (L+R)	O/s Deformed	494.20 FL	*247.10 FL
82	2	*FRONT FENDER TOP GARNISH (L+R)	Not Necessary	188.40 FL	*- FL
83	1	*FRONT FENDER WHEEL ARCH PROTECTOR (L+R)	O/s Cut	280.60 FL	*140.30 FL
84	1	*FRONT SUPPORT PANEL	Not Necessary	1,269.70 FL	*- FL
85	1	*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	128.40 FL	*- FL
86	1	*A/C CONDENSER	Not Necessary	984.30 FL	*- FL
87	1	*HIGH PRESSURE HOSE	Not Necessary	216.20 FL	*- FL
88	1	*LOW PRESSURE HOSE	Not Necessary	219.80 FL	*- FL
89	1	*RADIATOR	Not Necessary	1,264.30 FL	*- FL
90	1	*DISCHARGE PIPE	Not Necessary	129.60 FL	*- FL
91	1	*SUCTION PIPE	Not Necessary	117.20 FL	*- FL
92	1	*RADIATOR FAN COWLING	Not Necessary	643.40 FL	*- FL
93	1	*RADIATOR FAN BLADE	Not Necessary	215.90 FL	*- FL
94	1	*RADIATOR FAN MOTOR	Not Necessary	269.60 FL	*- FL
95	1	*WIPER WASHER TANK	Not Necessary	248.00 FL	*- FL
96	1	*WIPER WASHER MOTOR	Not Necessary	129.80 FL	*- FL
97	1	*FRONT ABSORBER (RH)	Not Necessary	421.80 FL	*- FL
98	1	*FRONT LOWER ARM (RH)	Bent	899.70 FL	*669.00 FL
99	1	*FRONT KNUCKLE (RH)	Bent	316.10 FL	*316.10 FL
100	1	*FRONT KNUCKLE BEARING (RH)	Necessary	278.40 FL	*278.40 FL
101	1	*FRONT BEARING HUB (RH)	Bent	299.30 FL	*299.30 FL
102	1	*FRONT STEERING RACK AND PINION ASSY	Not Necessary	1,687.70 FL	*- FL
103	1	*FRONT CROSSMEMBER	Not Necessary	1,240.80 FL	*- FL
104	1	*REAR WINDSCREEN SEALANT	Not Necessary	120.00 FS	*- FS
105	1	*TAILGATE EMBLEM (BLUEMOTION)	Not Necessary	400.00 FS	*- FS
106	10	*TAILGATE INNER TRIM CLIP	Not Necessary	100.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
107	10		*TAIL LAMP CLIP	Not Necessary	100.00 FS	*- FS
108	1		*REAR CARPLATE	Not Necessary	120.00 FS	*- FS
109	10		*REAR BUMPER CLIP	Necessary	100.00 FS	*50.00 FS
110	10		*REAR BUMPER LOWER CLIP	Not Necessary	100.00 FS	*- FS
111	1		*REAR FENDER SEALANT	Necessary	120.00 FS	*40.00 FS
112	10		*REAR FENDER INNER TRIM CLIP	Not Necessary	100.00 FS	*- FS
113	10		*REAR FENDER COWLING CLIP	Not Necessary	100.00 FS	*- FS
114	1		*END PANEL SEALANT	Not Necessary	120.00 FS	*- FS
115	1		*SPARE WHEEL PANEL SEALANT	Not Necessary	120.00 FS	*- FS
116	1		*SPARE TIRE	Not Necessary	600.00 FS	*- FS
117	1		*SPARE TIRE RIM	Not Necessary	800.00 FS	*- FS
118	2		*FRONT TIRE	Not Necessary	1,600.00 FS	*- FS
119	2		*REAR TIRE	Not Necessary	1,600.00 FS	*- FS
120	1		*SET RIM (10PCS)	Cut 2pcs Only	8,000.00 FS	*1,600.00 FS
121	10		*FRONT BONNET INNER TRIM CLIP	Not Necessary	100.00 FS	*- FS
122	1		*FRONT CENTER GRILLE EMBLEM (R)	Not Necessary	400.00 FS	*- FS
123	1		*FRONT CARPLATE	Not Necessary	120.00 FS	*- FS
124	10		*FRONT BUMPER CLIP	Necessary	100.00 FS	*50.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (S\$)	67,093.60	13,285.60
- List Item Discount on L Items 10.00/10.00% (S\$)	5,217.36	1,154.56
Total Parts (S\$)	61,876.24	12,131.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RNR ACCIDENT DAMAGE PARTS, CUT / WELD, KNOCK & REALIGN.	New	5,200.00	1,200.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA.	New	3,200.00	1,400.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA.	New	250.00	60.00
4	TO RNR REAR WINDSCREEN.	New	400.00	0.00
5	TO RNR REAR BOOT MECHANISM.	New	200.00	0.00
6	TO RNR UPHOLSTERY, GARNISH AND ATTACHMENT PARTS.	New	400.00	80.00
7	TO RNR REVERSE SENSOR & CHECK FUNCTION.	New	150.00	50.00
8	TO RNR FRONT SENSOR AND CHECK FUNCTION.	New	150.00	30.00
9	TO RNR REVERSE CAMERA AND TEST FUNCTION.	New	120.00	0.00
10	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS.	New	250.00	0.00
11	TO RNR UNDERCARRIAGE SYSTEM.	New	250.00	0.00
12	TO CHECK WHEEL ALIGNMENT.	New	200.00	120.00
13	TO RNR A/C CONDENSER ASSY AND REFILL GAS.	New	120.00	0.00
14	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS.)	New	120.00	30.00
15	TO CHECK WIRING LAYOUT AND TAIL LAMP FUNCTION.)	New	120.00	0.00
16	TO RNR TYRE AND WHEEL BALANCING.	New	200.00	0.00
17	TO DO DIAGNOSIS AND RESET, REPROGRAM OR CODING FAULT CODE.	New	200.00	0.00
18	TO DO WATER LEAK TEST.	New	80.00	0.00
19	TO RNR RADIATOR ASSY AND HOSES TO ASSIST WORK LOAD.	New	120.00	0.00
20	TO RNR FUEL TANK TO ASSIST WORK LOAD.	New	250.00	0.00
Gross Labour Cost (S\$)			11,980.00	2,970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >