

Alu h

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

18/6/2019

M/S AIG

MNT RAB

DEAR SIR / MADAM

ESTIMATE REPAIR COST FOR SKW7051E

TO SUPPLY :

List Items

- | | | |
|-----|------|-------------------------------|
| 01) | 1 PC | FRONT BUMPER |
| 02) | 1 PC | FRONT BUMPER CLIPS |
| 03) | 1 PC | FRONT BUMPER SPONGE |
| 04) | 1 PC | FRONT BUMPER LH SIDE RETAINER |
| 05) | 1 PC | FRONT LH HEADLAMP |
| 06) | 1 PC | GRILLE |
| 07) | 1 PC | FRONT BUMPER REINFORCEMENT |

20/70.1	\$	492.00	—
20	\$	50.00	—
17	\$	213.00	X
17	\$	22.00	X
17	\$	745.00	—
17	\$	722.00	—
17	\$	512.00	X
17	\$	2,756.00	
LESS 10%	\$	(275.60)	
	\$	2,480.40	

Labour Charge :

- | | |
|-----|---|
| 08) | SPRAY PAINTING |
| 09) | CHECK WIRING |
| 10) | LABOUR CHARGE TO REMOVE AND RENEW PARTS |

\$	580.00	300
\$	25.00	20
\$	580.00	300
\$	2,835.00	

NETT TOTAL \$ 5,315.40

- 18)
19)
20)
21)
22)

23)
24)
25)
26)
27)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Not Acknowledged
11/6/19
1/5 \$1900
3 day.

2019