

SKIN 70512 NISSAN SYLPHY

MNTBBAB17200345

①	FRONT BUMPER	492.00 N	2e ✓
②	" " CLIP RD	5.00 N	m ✓
③	" " SPONGE	213.00 N	?
④	" " LH SIDE RETAINER	22.00 N	MX
⑤	" " LH HEADLAMP	745.00 N	?
⑥	" " GRILLE	722.00 N	me ✓
⑦	" " BUMPER REINFORCEMENT	512.00 N	RX
⑧	" " LH FENDER	REPAIR	RX

s/p xx \$.. 580 - 300
 L/b \$.. 480 - 300
 wiring \$.. 25 20

34

I/We, the undersigned, hereby notify the Repairer of the following:
 • To survey and/or repair spray painting
 • To disassemble and/or repair using resurvey
 • Parts may be sold and to be returned
 • That work is done on a "No Fault Prejudice" basis
 • If the repair is not approved, it is allowed
 • Supply and/or materials must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: