

15/2/11

INS. CASE OWNER:

SawThurs

CC 4 ASM
/AXA1900 9781, 1196352

LKK:

IDAC:

Surveyor:

cls

DOI:

ASSIGNMENT

3/6/11

Date / Time:

3/6/11

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKU 1426H

Name of Insured:

Vai Yung Wark

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

28/6/11

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

S7M02P3P/119280

Policy No.:

GA 766/83

Make / Model:

BMW

Place of Accident:

BANK RESERVOIR RD TO ROAD
NORTH AVE 3

If NO, Driver Name / Age:

Driver Tel No.:

(VL: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

INSRS:
WSP:
Tel:
Liability:
RMKS:

Admin.

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time:

JJ 57911

SKU 1426H - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Marcus

Repair Cost:

45

SS 4100.00

(7 days)

Reduction:

4528.67

%

57

FINAL SETTLEMENT

Date/Time:

21/8/11

12/15/11

Confirm with:

Admin

Email:

Cal:

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

27

Repair Cost:

(WGS)

SS

4389.00

Loss of Rental (LOR):

SS

1000.00

(10 days)

x

\$100

Loss of Use (LOU):

SS

-

(\$

x

days)

Loss of Income (LOI):

SS

-

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

SS

2.00

Medical:

SS

-

Disbursement:

SS

-

(e.g. Tow/ Independent)

Legal Cost

SS

-

Total:

SS

5389.00

Global Sum SS:

FINAL PAYMENT

Date/Time:

21/8/11

Confirm with:

Admin

Email:

Cal:

Payee 1:

SS

5389.00

Name 1:

Admin Service Pte Ltd

Payee 2: (Strike if N.A.)

SS

-

Name 2:

-

Payee 3: (Strike if N.A.)

SS

-

Name 3:

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

\$350/-

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

AXA

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

17-9-2023

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

LTA 13th 2 yrs 3m.

confirmed w/s \$4100 with AH hee.

(Red = \$5328.67 / 57%)

* 7 repair days + 2 PRS + 1 Sunday = 10 days.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

) \$ + RS, \$

) Photos

) Others

TOTAL

Veh No:

SJS-7516 Yr Regn: 9 108

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make:

Toyota corolla Axo c.c 1496

Colour:

Grey

A/C: Insured / Std / NI / NA

Sp. Reading

126260

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

N2E141 6072418

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

205/55-216

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

28/5/18

D.O.I.

3/6/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

ABWIN SERVICE PTE LTD

8 KAKI BUKIT AVENUE 4 - GATE 2

#07-48 PREMIER @ KAKI BUKIT SINGAPORE 415875

Tel: 67139400 Fax: 67138415

Email: servicecentre@abwin.com.sg Website: www.abwinm9.com

Company Reg. No: 201318685G GST Reg. No: 201318685G



Not Authorized
2/5
4100
3/6/19

QUOTATION: HQQ000003**SJJ5751L****ASLAM SYED****ZARRAR**

2 BEDOK RESERVOIR VIEW

#07-02479232

TEL : 91808142

DATE : 03-JUN-2019
 MAKE : TOYOTA
 MODEL : AXIO 1.5 XA
 CHASSIS NO : NZE1416072418
 ENGINE NO : 1NZC957503
 SERVICE ADVISOR : YVONNEWONG
 PAGE : 1 OF 2

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
LIST ITEM			
1	BOOT LID	2 721.50 X	
1	BOOT LID LOCK	11 94.50 X	
1	BOOT LID MOULDING	11 272.80 X	
1	BOOT LID LOGO	11 57.80 X	
1	BOOT LID EMBLEM AXIO	rec 48.17 /	
1	TAILLAMP LHS	11 359.40 X	
1	TAILLAMP RHS	CM 359.40 /	
1	TAILLAMP PANEL RH	11 18.40 /	
1	REAR BUMPER	11 454.20 /	
1	REAR BUMPER SIDE RETAINER RH	CM 96.60 /	
1	REAR BUMPER SIDE RETAINER LHS	11 96.60 X	
1	REAR BUMPER SPONGE	NS 180.00 X	
1	REAR BUMPER BRACKET RHS	11 650.00 /	
1	REAR BUMPER BRACKET LHS	11 0.00 X	
1	SPARE TYRE TOP BOARD	CM 562.50 /	
1	SPARE TYRE PANEL	cracked 820.90 /	
1	REAR END PANEL	Barly 513.20 /	
1	REAR END PANEL TOP GARNISH	11 198.90 /	
10	REAR BUMPER LOCK CATCH	11 184.00 X	
1	EXHAUST HEAT SHIELD	11 143.90 X	
1	EXHAUST MUFFLER	2 815.90 X	
Sub Total		5,998.67	

50%

3137.27
50%
1568.63
0.00

SPECIAL NETT

10	REAR END PANEL TOP GARNISH CLIPS	11 50.00 X	
10	REAR BUMPER CLIPS	rec 50.00 /	
1	REAR END PANEL SEALANT	rec 50.00 /	

ABWIN SERVICE PTE LTD

8 KAKI BUKIT AVENUE 4 - GATE 2
 #07-48 PREMIER @ KAKI BUKIT SINGAPORE 415875
 Tel: 67139400 Fax: 67138415
 Email: servicecentre@abwin.com.sg Website: www.abwinm9.com
 Company Reg. No: 201318685G GST Reg. No: 201318685G

**QUOTATION: HQQ000003**

SJJ5751L
ASLAM SYED
ZARRAR

2 BEDOK RESERVOIR VIEW
 #07-02479232
 TEL : 91808142

DATE : 03-JUN-2019
 MAKE : TOYOTA
 MODEL : AXIO 1.5 XA
 CHASSIS NO : NZE1416072418
 ENGINE NO : 1NZC957503
 SERVICE ADVISOR : YVONNEWONG
 PAGE : 2 OF 2

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
1	REVERSE SENSOR <i>1 set</i>	<i>shd</i> 250.00 <i>200</i>	
1	TAILLAMP INNER SEAL LH	<i>11</i> 50.00 <i>X</i>	
1	TAILLAMP INNER SEAL RHS	<i>11</i> 50.00 <i>X</i>	
1	BOOT LID SEALANT	<i>11</i> 50.00 <i>X</i>	
Sub Total		550.00	0.00

LABOUR

1	TO CHECK WIRING SYSTEM AFTER DISCONNECT AND CONNECT	100.00 <i>30</i>	
1	TO DISMANTLE & INSTALL BOOT LID COMPONENT	<i>11</i> 180.00 <i>X</i>	
1	TO DISMANTLE & INSTALL REVERSE SENSOR	100.00 <i>50</i>	
1	TO APPLY UNDERCOATING FOR RUSTPROOFING	100.00 <i>60</i>	
1	TO DISMANTLE & INSTALL EXHAUST PIPE AND ALIGNMENT	<i>11</i> 200.00 <i>X</i>	
1	TO PANEL BEATING AND STRAIGHTEN PARTS ON ACCIDENT AREA.	1,000.00 <i>✓</i>	
1	TO SPRAY PAINTING ON ACCIDENT AREA.	1,200.00 <i>1100</i>	
Sub Total		2,880.00	0.00

11K Auto Consultants hence notify the Repairer of the following:

- To not do before/after spray painting
- To not do any repair (s) during resurvey
- Parts must be subject to confirmation
- There is no "Without Prejudice" basis
- No insurance claim is allowed
- Survey (resurvey) must be resurveyed and is subject to final approval from Insurance Company

P-1568.63
S.N-300.00
Labour-2240.00
4108.63

Acknowledged by Repairer	SUB-TOTAL	9,428.67	0.00
Signature:	GST - 7 %	660.01	0.00
Date:	TOTAL	10,088.68	0.00

ABWIN SERVICE PTE LTD*9493.67*

Prepared By

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Foreign Identification Number
Owner ID:	5551X
Vehicle Details	
Vehicle No.:	SJJ5751L
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Jun 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA AXIO 1.5X A
Primary Colour:	Beige
Manufacturing Year:	2008
Engine No.:	1NZC957503
Chassis No.:	NZE1416072418
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$12,893.00
Original Registration Date:	18 Sep 2008
First Registration Date:	18 Sep 2008
Transfer Count:	2
Actual ARF Paid:	\$12,893.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	17 Sep 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$16,170.00
COE Rebate Amount:	\$13,852.00
Total Rebate Amount:	\$13,852.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 03 Jun 2019

OK

SGCARMART.COM

Login Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

Find out more



axio

Price Range

Depreciation

> 10 year

Vehicle Type

Submit

Advanced Search

Home » Used Cars » Direct Owners » Toyota Corolla Axio 1.5A X (COE till 08/2023)

Toyota Corolla Axio 1.5A X (COE till 08/2023)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

DIRECT OWNER

Price \$25,500

Depreciation \$6,050 /yr

Reg Date 20-Aug-2008
(4yrs 2mths 16days COE left)

Mileage 125,000 km (11.6k /yr)

Manufactured 2008

Road Tax \$750 /yr

Transmission Auto

Dereg Value \$14,410 as of today (change)

OMV \$11,675

COE \$17,099

ARF \$9,034

Engine Cap 1,496 cc

Power 81.0 kW (108 bhp)

Curb Weight 1,130 kg

No. of Owners 3

Type of Vehicle Mid-Sized Sedan

Features

1.5L DOHC VVT-I Engine Producing 108Bhp, CVT Auto Transmission. View specs of the Toyota Corolla Axio (2007-2012)

Accessories

Front And Back In-Car Cam Recorders, Solar Films, DVD Player With Reverse Camera And Sensors, Pivot Throttle Controller, RPM Meter, 17" Vossen Rims.

Description

New BC Racing V1 Coilovers, New Michelin PS4 Tyres, New Radiator, New Coils, New Water Piping. Well Maintained By Car Lover! No Wear And Tear Needed To Be Replaced. Only Use FK Massimo Engine Oil. Loan Can Be Arranged. Viewing Strictly By Appointment.

Category

COE Car, Direct Owner Sale

Status

Available

Resources




Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Car Valuation - Free

Find out the market value of your existing car for free. Get started



Shortlist

Compare

Add note

Report Error

More Actions

Seller Information

Contact Person(s) AC
Contact No. 88181155

ESSENTIAL TRANSACTION FORMS

- » Indemnity form
- » Sales agreement
- » Receipt
- » Hand-over form
- » Ownership Transfer



GET HELP WITH PAPERWORK



sgCarMart Connect handles your transaction paperwork - send us your completed Sales Agreement, and we'll help with Car Loans, Insurance, Payments & Ownership Transfer. FREE for all sgCarMart Advertised Vehicles.

Upload your Sales Agreement

Read our 8 Step Guide for Direct Buyers & Sellers

Posted on: 15-May-2019 | Last Updated on: 31-May-2019

Upfront Payment

» more Financial info

Transfer Fee \$25

Down Payment \$7,650 (change)

Maximum 70% Loan

1st Instalment \$413

Based on 3.75% interest rate

Compare

sgCARMART.COM

Login Sign up

New Cars Used Cars Sell My Car Directory Products Insurance Articles Forum Resources



CONNECTING CAR BUYERS & SELLERS.
We'll handle your loans, insurance & other paperwork for FREE.

Find out more


 Price Range Depreciation > 10 year Vehicle Type Advanced Search

Home > Used Cars > Direct Owners > Toyota Corolla Axio 1.5A X (COE till 10/2023)

Toyota Corolla Axio 1.5A X (COE till 10/2023)

Overview Financial Insurance Accessories Similar Research Photos Map

Price	\$25,888		
Depreciation <input type="button" value="v"/>	\$5,970 /yr	Reg Date	03-Oct-2008 (4yrs 3mths 29days COE left)
Mileage	N.A.	Manufactured <input type="button" value="v"/>	2008
Road Tax <input type="button" value="v"/>	\$750 /yr	Transmission	Auto
Dereg Value <input type="button" value="v"/>	\$13,126 as of today (change)	OMV <input type="button" value="v"/>	\$13,653
COE <input type="button" value="v"/>	\$15,142	ARF <input type="button" value="v"/>	\$13,653
Engine Cap	1,496 cc	Power	81.0 kW (108 bhp)
Curb Weight <input type="button" value="v"/>	1,130 kg	No. of Owners <input type="button" value="v"/>	2
Type of Vehicle	Mid-Sized Sedan		

Features

Rare Pearl White. Reliable And Fuel Efficient 1.5l 16 Valves 4 Cylinders Toyota VVTi DOHC Engine. Smooth CVT Auto Transmission, Low Fuel Consumption. View specs of the Toyota Corolla Axio (2007-2012)

Accessories

Leather Seats, Reverse Camera, Audio Systems, Sound Amplifier, Fog Light Installed. 16 Inch Rim. 205/55 Tyre.

Description

Only 1 Owner For The Last 10.5 Years, Accident-Free, Quiet Engine, Smooth Gearbox, Strong Acceleration. Recently Changed Suspension, Lower Arm, Engine Mounting, And Aircon Compressor. Clean And Well Maintained Car And Non-Smoking. Road Tax Till 2nd Oct 2019. Great Family Car And For Those Buying For Phv Purpose. You Will Love My Car! No Consignment Dealer, No Dealer Involved. DIY Buyer Only.

Category

COE Car, Direct Owner Sale

Status

Available

Resources



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Car Valuation - Free

Find out the market value of your existing car for free. Get started



Shortlist Report Error Compare More Actions Add note

Seller Information

Contact Person(s) Steven Ling
Contact No. 83228882

ESSENTIAL TRANSACTION FORMS

- * Indemnity form
- * Sales agreement
- * Receipt
- * Hand-over form
- * Ownership Transfer



GET HELP WITH
PAPERWORK



sgCarMart Connect handles your transaction paperwork - send us your completed Sales Agreement, and we'll help with **Car Loans, Insurance, Payments & Ownership Transfer**. FREE for all sgCarMart Advertised Vehicles.

Upload your Sales Agreement

Read our 8 Step Guide for Direct Buyers & Sellers

Posted on: 18-May-2019 | Last Updated on: 30-May-2019

Upfront Payment

» more Financial Info

Transfer Fee <input type="button" value="v"/>	\$25	
Down Payment <input type="button" value="v"/>	\$7,766 (change)	Maximum 70% Loan
1st Instalment <input type="button" value="v"/>	\$412	Based on 3.75% interest rate


Compare

<< Service Request Details

Claim

S9M01P3P

Reference

None 

Loss Date

28 May 2019

Report Date

3 Jun 2019 10:18:00 AM

Request Date

3 June 2019

Due Date

11 June 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

P. Yvonne

T: 10.52 a.m

V: 14

E: ✓

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SJJ5751L

MODEL

AXIO-1.5 X (A)

Service Address

...

Primary Contact/Insured

LAI YING CHEOK (LI YINGZHUO)

771 BEDOK RESERVOIR VIEW, #03-169, 470771, Singapore

90489432

chester_laiyc@yahoo.com.sg

Claim Handler

KHOR Saw Theng

6568804754

sawtheng.khor@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

Catherine Chong (LKK Auto)

From: AbwinM9 - Yvonne Wong <yvonnewong@AbwinM9.com>
Sent: Monday, 3 June, 2019 9:52 AM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Cc: lindaliao@AbwinM9.com
Subject: ACCIDENT INVOLVING SJJ5751L & YOUR INSURED: SKU1426H DOA: 28/05/2019

Categories: Raghav

Morning Motor Claims Dept

Please arrange surveyor to survey our vehicle.

We prefer LKK Survey Services


Thank you

Warmest regards,

ABWIN 論 輝
Service Centre

Yvonne Wong
Claims Department
DID +65 6713 9416

Abwin Service Pte Ltd
T +65 6713 9400 | F +65 6713 9415
No. 8 Kaki Bukit Avenue 4
#07-48 Premier @ Kaki Bukit Gate 2 Singapore 415875





Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 20/08/2019

Survey Details:

Date of loss	28-May-19
Date of appointment	3-Jun-19
Date of survey	3-Jun-19
Location of survey	ABWIN SERVICE PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SJJ 5751L
Make and Model	TOYOTA COROLLA AXIO 1.5X A
Date of registration	18/9/2008
Excess	
Market Value	\$24,000
Parf Rebate	\$13,852
Nett Loss	\$10,148

Repair details:

Initial Estimate	\$ 9,428.67
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 1,868.63
Check items (estimate)	\$ -
Labour	\$ 2,240.00
Total	\$ 4,108.63
Lump Sum(if applicable)	\$ 4,100.00

Number of days for repair	7
---------------------------	---



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

07 RECOMMENDED REPAIR DAYS + 2 PRS + 1 SUNDAY= 10 DAYS

Mandate:

Liability(TP)	100%	
Proposed repair cost	\$ 4,387.00	W/GST
Loss of use	\$ -	
Loss of rental	\$ 1,000.00	10days x \$100
Loss of income	\$ -	
LTA search fees	\$ 2.00	
Others	\$ -	
Proposed Total	\$ 5,389.00	



<MANDATE IA> - S9M01P3P {ACCIDENT INVOLVING SKU 1426H(OI) & SJJ 5751L(TP) ON 28/05/2019}

Type

🔗 Question

Message

LIABILITY: 100% BOLA S27: INFORMED OI ABOUT TP CLAIM AND NCD ISSUE. AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$5389.00(CLAIMING LOR). MANDATE IA HAS BEEN UPLOADED INTO SMARTCLAIM. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION. THANKS - CECILIA

Reply



**Re:<MANDATE IA> - S9M01P3P {ACCIDENT INVOLVING
SKU 1426H(OI) & SJJ 5751L(TP) ON 28/05/2019}**

Type

🔗 Question

Message

Pls proceed with your proposed mandate.

Reply

ABWIN SERVICE PTE LTD

8 KAKI BUKIT AVENUE 4 - GATE 2
#07-48 PREMIER @ KAKI BUKIT SINGAPORE 415875
Tel: 67139400 Fax: 67139415
Email: servicecentre@abwin.com.sg Website: www.abwinm9.com
Company Reg. No: 201318685G GST Reg. No: 201318685G



08-AUG-2019

AXA INSURANCE PTE LTD

8 SHENTON WAY #24-01 AXA TOWER
SINGAPORE 068811

Dear Sirs,

ACCIDENT ON 28-May-2019 INVOLVING SJJ5751L & SKU1426H AT BEDOK RESERVOIR ROAD SLIP ROAD

We are authorised repair workshop for the owner of vehicle, SJJ5751L, which was involved in the captioned accident with your insured's vehicle. The vehicle owner has requested and authorised us to assist him/her in presenting his claim against the party responsible for the damage to the vehicle.

As the accident was caused by the negligent act of your insured, SKU1426H, we are submitting these claims for your consideration on behalf of the owner/driver/claimant.

1. Cost of Repair	\$4,387.00
2. 10 days Car Rental x \$110.00	\$1,100.00
3. Loss Of Use	-
4. Survey Fees	-
5. LTA Fees	-
6. TP/GIA Fees	\$2.00
7. Medical Fees	-
8. Others	-
<hr/>	
(E&OE)	\$5,489.00

We enclosed the following documents to support the claims:-

<input type="checkbox"/> Repair/Excess Bill	<input type="checkbox"/> GIA/Police Report(s)	<input type="checkbox"/> Power of Attorney	<input type="checkbox"/> Medical Bill
<input type="checkbox"/> Surveyor Report	<input type="checkbox"/> GIA/TP Search	<input type="checkbox"/> Car Rental Bill	<input type="checkbox"/> Witness Statement
<input type="checkbox"/> Coloured Photographs	<input checked="" type="checkbox"/> Insurance Certificate	<input type="checkbox"/> Others : _____	

Kindly look into the matter and let us hear from you on the settlement of our client's claim as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/driver/claimant.

Yours faithfully,

ABWIN SERVICE PTE LTD

Claim Department

Email :



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19009781/Ugb3s2

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Date : 28-08-2019



ATTN: SAW THENG

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKU 1426H	Veh. Inspected	SJJ 5751L
Policy No.	GA366183	Coverage (\$)	0.00
Claim No.	S9M01P3P	Excess (\$)	0.00
Assign From	SAW THENG	Assign Date	03/06/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA COROLLA AXIO (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	NZE1416072418	Colour	BEIGE
Odometer	126260	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	MICHELIN	6 mm
L/H Front Tyre	205/55 R16	MICHELIN	6 mm
R/H Rear Tyre	205/55 R16	MICHELIN	6 mm
L/H Rear Tyre	205/55 R16	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	28/05/2019	Inspection Date	03/06/2019
Survey held at	ABWIN SERVICE PTE LTD No. 8 KAKI BUKIT AVENUE 4 #07-48 PREMIER@KAKI BUKIT GATE 2 SINGAPORE 415875		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **7 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJJ 5751L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BOOT LID (CONSISTENT)	TO REPAIR SEE LABOUR	721.50	-
1	BOOT LID LOCK (CONSISTENT)	NOT NECESSARY	94.50	-
1	BOOT LID MOULDING (CONSISTENT)	NOT NECESSARY	272.80	-
1	BOOT LID LOGO (CONSISTENT)	NOT NECESSARY	57.80	-
1	BOOT LID EMBLEM AXIO (CONSISTENT)	NECESSARY	48.17	48.17
1	TAILLAMP LHS (CONSISTENT)	NOT NECESSARY	359.40	-
1	TAILLAMP RHS (CONSISTENT)	CRACKED	359.40	359.40
1	TAILLAMP PANEL RH (CONSISTENT)	DENTED	18.40	18.40
1	REAR BUMPER (CONSISTENT)	DISTORTED	454.20	454.20
1	REAR BUMPER SIDE RETAINER RH (CONSISTENT)	CRACKED	96.60	96.60
1	REAR BUMPER SIDE RETAINER LHS (CONSISTENT)	NOT NECESSARY	96.60	-
1	REAR BUMPER SPONGE (CONSISTENT)	NO SUCH PARTS	180.00	-
1	REAR BUMPER BRACKET RHS (CONSISTENT)	DENTED	65.00	65.00
1	REAR BUMPER BRACKET LHS (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	SPARE TYRE TOP BOARD (CONSISTENT)	CRACKED	562.50	562.50
1	SPARE TYRE PANEL (CONSISTENT)	CRUMPLED	820.90	820.90
1	REAR END PANEL (CONSISTENT)	BADLY DENTED	513.20	513.20
1	REAR END PANEL TOP GARNISH (CONSISTENT)	TWISTED	198.90	198.90
10	REAR BUMPER LOCK CATCH (CONSISTENT)	NOT NECESSARY	184.00	-
1	EXHAUST HEAT SHIELD (CONSISTENT)	NOT NECESSARY	143.90	-
1	EXHAUST MUFFLER (CONSISTENT)	TO REPAIR SEE LABOUR	815.90	-
	LESS 50% DISCOUNT		-	-1,568.64
			6,063.67	1,568.63
<u>SPECIAL NETT ITEMS</u>				
10	REAR END PANEL TOP GARNISH CLIPS (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
10	REAR BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	50.00	50.00
1	REAR END PANEL SEALANT (SN) (CONSISTENT)	NECESSARY	50.00	50.00
1	SET REVERSE SENSOR (SN) (CONSISTENT)	SHORTED	250.00	200.00

Report Ref No. CC4/ASM19009781/Ugb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAILLAMP INNER SEAL LH (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
1	TAILLAMP INNER SEAL RHS (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
1	BOOT LID SEALANT (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
			550.00	300.00
	LABOUR			
	TO CHECK WIRING SYSTEM AFTER DISCONNECT AND CONNECT.		100.00	30.00
	TO DISMANTLE & INSTALL BOOT LID COMPONENT.	NOT NECESSARY	180.00	-
	TO DISMANTLE & INSTALL REVERSE SENSOR.		100.00	50.00
	TO APPLY UNDERCOATING FOR RUSTPROOFING.		100.00	60.00
	TO DISMANTLE & INSTALL EXHAUST PIPE AND ALIGNMENT.	NOT NECESSARY	200.00	-
	TO PANEL BEATING AND STRAIGHTEN PARTS ON ACCIDENT AREA. INCLUSIVE OF THE REPAIR OF BOOT LID AND EXHAUST MUFFLER.		1,000.00	1,000.00
	TO SPRAY PAINTING ON ACCIDENT AREA.		1,200.00	1,100.00
			2,880.00	2,240.00
GRAND TOTAL			9,493.67	4,108.63
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,100.00

Report Ref No. CC4/ASM19009781/Ugb3s2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.