

ASS. REC. BY:

REF: CS/C11190097331 Utd302

Special Instruction:

Survivor: ThamASSIGNMENT (Office)From (Person): Onn Chin Lat

of

CFIDate/Time: 3-6-2019 16:36 PM

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SGG 1320AInsured: GBF 1932Zat Workshop m/s Rico 60 Auto ServiceTel: 98163144of B Kati Bukit Muzne 4 / #02-24Policy No: DMVSA 301300/8022Claim No: SVM 19020246902

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 01/06/2019

CA / REV / REP. / REV 24 HRS

Date/Time: 3-6-19 2019Person Contacted: Jin Hai

H.O.D. Enforcement:

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SGG 1320A - CS/Alq 190097331 / Utd 3
	GBF 1932Z - X

D.O.A. - 01/06/2019

(08/11/13)

ASS. REC. BY:

REF

ASSIGNMENT

From:

Date:

04/6/19

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SGG 1320A

at Workshop m/s

RICO 60

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

81k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

10

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

LTA 53831

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SGG1320A

Yr Regn:

2116

Type: M-Car / M-Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA/

Make:

Volkswagen

Tiguan C.C.

1390

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

14155

T/Radio: Insured / Std / NI / NA

Eng/No:

WV 62225N 86W 030898

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

255/40R19

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

1169

mm

L/Bal.

6

mm

D.O.A.

1/6/19

D.O.I.

4/6/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt & Rear n/s &

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

byng Bulb plus. Day
CTI. 6351932 o/s Frt.
Aler 525642 Rear n/s

RECEIVED 2 JUL 2019

1/7/19 4/5 @ 12.000 car p. ins with John CRed: 60666.62 (83%).

Date/Time, File Pass to?

☐ : Prel. Report

☒ : Final Report

Date/Time, File Return to?

2)

Report Format :

TP

Lump Sum / I.B.I. (\$ 12,000)-

Days Of Repair:

10

Resurvey No. of Trip:

1

Add Fee:

☐ : Site Insp. (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation:

G + RS, SI

Photos

Others

TOTAL

220

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Jun 2019		03 Jun 2019 16:36 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All																				
CLAIM SUBFOLDER DETAILS		[Created by insurer]																						
Insured:	STARTECH COMMUNICATION ENGRG PTE LTD, Co. Reg. No.: 200916360G																							
Main Claimant:	TAY HUNG YEONG, ID: S6844986C																							
Vehicle Reg. No.:	SGG1320A	Date of Loss:	01/06/2019 09:00 - :59 [39 Months and 8 Days From LTA Reg Date (Man Yr)]																					
Claim Type:	TP / SNM19D202469C02	Policy/Cover Note No.:	DMCVSN30730018022																					
Vehicle Reg. No. (Insured):	GBF1932Z	Policy No. (Claimant):	A 28692537 COMP																					
		Excess:	S\$0.00																					
Repairer:	RICO 60 AUTO SERVICES PTE LTD (HQ) 8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel:																							
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]																							
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888																							
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 13/06/2019]																							
Adj Asg. Remarks:	to assign Mr Marcus Chua for SJE, please contact Jin Hai at 9816 3144 to arrange for survey. thank you																							
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail																						
There are no mail for this case.																								
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete <table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4986C
Vehicle Details	
Vehicle No.:	SGG1320A
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Jun 2019
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	TIGUAN 1.4 TSI AT BMT 5N22QY
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	CTH230378
Chassis No.:	WVGZZZ5NZGW030898
Maximum Power Output:	118.0 kW (158 bhp)
Open Market Value:	\$26,894.00
Original Registration Date:	24 Feb 2016
First Registration Date:	24 Feb 2016
Transfer Count:	0
Actual ARF Paid:	\$29,652.00 14826
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Feb 2026
PARF Rebate Amount:	\$22,239.00
Intended COE Rebate Details	
COE Expiry Date:	23 Feb 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,970.00
COE Rebate Amount:	\$31,592.00
Total Rebate Amount:	\$53,831.00

The information contained herein is correct as at 03 Jun 2019

OK

HIGH GLOSS, LESS MAINTENANCE, LAST LONGER

► Check out the list of Paint Protection Film services available here.

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Toyota Dyna 150 3.0



Low Mileage - 1.1k Approx
Genuine
Direct Owner - 1st hand



VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND

HOTLINE: 6741 9997

View More

Sort by Date Posted 20 results

3 vehicles

Volkswagen Tiguan

Reset Search

Price Any price

Depre Any depre

Reg Date 2015 to 2016

Eng Cap Any

Veh Type All types

Fuel Any fuel

Mileage Any

OMV Any

Gear Any Gear

Past Owners Any

Category All categories

Scheme All schemes

Dealer Any Dealer

Location Any

Status Available

Make & Model Price Depreciation Reg Date Eng Cap Mileage Veh Type St



Volkswagen Tiguan 1.4A TSI
BMT R-Line

\$80,800

\$9,930 /yr

22-Jan-2016

1,390 cc

-

SUV

A

"1 Owner" Unit, Flexible In-House Loan Available To Driveaway! Wear & Tear, Servicing Done. Original Parts Used & ACCIDENT FREE. A Perfect Sports SUV To Drive With Perfect Engine Condition. Call Now T...

ABWIN (1994) Pte Ltd

Posted: 30-May-2019

Tags: 2016 Volkswagen Tiguan, 2016 volkswagen tiguan, Volkswagen Tiguan, volkswagen tiguan, Volkswagen, Tiguan, tiguan, Used Volkswagen



Volkswagen Tiguan 1.4A TSI
BMT

\$83,800

\$10,290 /yr

04-Jul-2016

1,390 cc

26,500 km

SUV

A

Lady Owner, Genuine Low Mileage! Full Agent Servicing Till Date, Under Agent Warranty! Low Interest Rate, Up To 90% Loan Available, Well Taken Care By Previous Owner! 100% Accident Free! Trade In Welc...

Posted: 24-May-2019

Tags: 2016 Volkswagen Tiguan, 2016 volkswagen tiguan, Volkswagen Tiguan, volkswagen tiguan, Volkswagen, Tiguan, tiguan, Used Volkswagen



Volkswagen Tiguan 1.4A TSI
BMT R-Line

\$85,800

\$11,300 /yr

23-Sep-2015

1,390 cc

67,188 km

SUV

A

Owned By A Reputable Restaurant Boss As A Second Car! Worry-Free Transaction! Buy From A Case Trust Company With No Gimmicks And Add-On Price! Proven Performance With Responsive Engine/Smooth Cruising...

Car House Pte Ltd

Posted: 28-Apr-2019

Tags: 2015 Volkswagen Tiguan, 2015 volkswagen tiguan, Volkswagen Tiguan, volkswagen tiguan, Volkswagen, Tiguan, tiguan, Used Volkswagen

Make & Model Price Depreciation Reg Date Eng Cap Mileage Veh Type St

For old advertisements, view Expired ads

20 results

Home New Cars Used Cars Sell My Car Directory Products Insurance Article Forum Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sports cars or SUV, MPV, hatchback, to CDE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Used Volkswagen Tiguan, Volkswagen Tiguan Singapore, used Volkswagen Tiguan Singapore, used Volkswagen Tiguan, used vehicles Singapore or even buy used Volkswagen Tiguan. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotion partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & C.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	03/06/2019 12:52
Date Of Accident	01/06/2019 09:50
Exact Location Of Accident	JALAN BESAR / ROCHOR CANAL ROAD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SGG1320A
Insured/Policyholder	
Name Of Registered Owner	TAY HUNG YEONG
NRIC No	S6844986C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96831498
Alternative Phone No	OFFICE-96831498
Vehicle Particulars	
Manufacturer	VOLKSWAGEN
Model	TIGUAN 1.4 TSI AT BMT 5N22QY
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	
	NO
If No, Please state action to be taken	
	THIRD PARTY
Vehicle Category	
	PRIVATE CAR
Insurance Company	
Name of Insurance Company	
	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	
	COMPREHENSIVE
Fleet Policy	
	NO
Policy Number	
	A 28692537 COMP
Cover Note Number	
Driver	
Name of Driver	
	CHOW SOW WAI (ZHOU XIUHUI)
NRIC No	
	S7135117C
Date Of Birth	
	30/09/1971
Occupation	
	INDOOR
Date Of Driving Pass	
	12/03/1997
Driving Experience	
	22 YEARS AND 2 MONTHS
Gender	
	FEMALE
Mobile Number	
	(LOCAL) +65-96844633
Fax Number	
Contact Number	
Email Address	
	CHOWSOWWAI@YAHOO.COM

Address	BLK 552 ANG MO KIO AVENUE 10 #16-1978
Postcode	560552
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBF1932Z
Vehicle Make/Model/Colour	TOYOTA HIACE DX 3.0 M
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLS642E
-----------------------------	---------

Vehicle Make/Model/Colour	MAZDA3 SEDAN 1.5 AT LED EU6
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

[Signature]

Policyholder's Signature
Date & Time:

[Signature]


Driver's Signature
(If driver is not the policyholder)
Date & Time:

1 June - 3 JUN 2019

LDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4
Singapore 415933

Tel: 67416697 Fax: 67492305
Reporting Centre Personnel's Signature
Name: *[Signature]*
NIC/PIN No.:

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date and time, I vehicle A was travelling
second lane of an
on the stated venue. As I was turning right, vehicle B
went straight on a right-turn only lane, colliding into me
rear side of my vehicle. After which, vehicle C, tried to
avoid the accident by swerving left and collided into the
rear-left portion of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time: - 3 JUN 2019

LDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4
Singapore 415933
Tel: 65 6750 6000 Fax: 65 6750 2305
Email: yackb@singnet.com.sg
NOC/PIN No:



Rico 60 Auto Services Pte Ltd, Blk 8, Kaki Bukit Avenue 4, #02-24
Premier @ Kaki Bukit Singapore 415875, Email: claims@rico60.com
Tel: 6286 6060, FAX: 6286 7060

VEHICLE NUM: SGG 1320 A
MAKE & MODEL: VOLKSWAGEN TIGUAN
MILEAGE:
TYRE:
CHASSIS NUM: WVGT228N26W

ref Albul
nbar
1/5 \$12.000
10 hrs
4/1/19
Zh 1st bill up

ATTN	NO.	DESCRIPTION - PARTS	QTY	PRICE	
	1	REAR WINDSCREEN MOULDING 17X	1	\$26.80	X
	2	TAILGATE 12X	1	\$1674.60	X
	3	TAILGATE SPOILER 11X	1	\$468.70	X
	4	TAILGATE THIRD BRAKE LAMP 11X	1	\$296.70	X
	5	TAILGATE WIPER 11X	1	\$80.30	X
	6	TAILGATE WIPER MOTOR 11X	1	\$216.70	X
	7	TAILGATE WIPER MOTOR COVER 11X	1	\$42.30	X
	8	TAILGATE LOGO (VOLKSWAGEN) 11X	1	\$130.90	X
	9	TAILGATE EMBLEM (TIGUAN) 11X	1	\$76.10	X
	10	TAILGATE EMBLEM (TSI) 11X	1	\$62.20	X
	11	TAILGATE LAMP (L+R) 11X	2	\$420.60	X
	12	TAILGATE LOCK 11X	1	\$248.10	X
	13	TAILGATE CATCH 11X	1	\$30.70	X
	14	TAILGATE HANDLE 11X	1	\$32.30	X
	15	REVERSE CAMERA 11X	1	\$1064.30	X
	16	TAILGATE CARPLATE LAMP (L+R) 11X	2	\$121.40	X
	17	TAILGATE INNER TRIM 11X	1	\$425.70	X
	18	TAILGATE INNER TRIM (L+R) 11X	2	\$267.40	X
	19	TAILGATE INNER TRIM TOP 11X	1	\$128.40	X
	20	TAILGATE INNER BOARD 11X	1	NIL	X
	21	TAILGATE DAMPER (L+R) 11X	2	\$436.60	X
	22	TAILGATE HINGE (L+R) 11X	2	\$326.20	X
	23	TAILGATE INNER WIRE PROTECTOR (L+R) 11X	2	\$136.20	X
	24	TAILGATE WEATHER STRIP 11X	1	\$816.80	X
	25	TAIL LAMP (L+R) 21/5 crs 17C 38010	2	\$760.10	1PC
	26	TAIL LAMP PANEL (L+R) 12X	2	\$425.40	X
	27	REAR BUMPER 115	1	\$1041.50	—
	28	REAR BUMPER RETAINER (L+R) 115 crs 17C	2	\$98.40	1PC
	29	REAR BUMPER LOWER 115	1	\$865.70	—
	30	REAR BUMPER REFLECTOR (L+R) 115 320 17C	2	\$112.40	1PC
	31	REAR BUMPER REFLECTOR LAMP (L+R) 115 320 17C	2	\$365.60	X
	32	REAR BUMPER TOW COVER 11X	1	\$42.10	X
	33	REAR BUMPER REVERSE SENSOR SET 115 320 17C	6	\$2160.00	2pcs 430
	34	REAR BUMPER UNDERCOVER 115 320 17C	1	\$328.20	—
	35	REAR BUMPER SIDE PROTECTOR (L+R) 115 320 17C	2	\$216.40	1PC
	36	REAR BUMPER REINFORCEMENT BAR 11X	1	\$679.80	X
	37	REAR BUMPER BEAM 11X	1	\$321.30	X
	38	REAR BUMPER SPONGE 115	1	\$321.70	X
	39	REAR BUMPER BRACKET (L+R) 115 320 17C	2	\$86.40	1PC
	40	REAR FENDER (L+R) 115 body d/buc 17C	2	\$4860.40	1PC
		Rear air vent 115	1	\$48.60	—

20 bill 60

41	REAR FENDER QUARTER WINDOW MOULDING (L+R)	11 X	2	\$681.80	X
42	REAR FENDER INNER TRIM (L+R)	11 X	2	\$767.40	X
43	REAR FENDER COWLING (L+R)	242-20 N/S 70.1 1/2 C \$212.20	2	\$484.40	1/2 C
44	REAR WHEEL ARCH PROTECTOR (L+R)	N/S 70.1 1/2 C \$134.10	2	\$268.20	1/2 C
45	END PANEL	2 badly dd	1	\$648.90	X
46	END PANEL TOP GARNISH	11 X	1	\$128.00	X
47	SPAREWHEEL PANEL	11 X	1	\$1263.70	X
48	SPAREWHEEL PANEL TOP BOARD	11 X	1	\$216.10	X
49	SPAREWHEEL PANEL INNER ACCESSORIES BOX	11 X	1	\$144.70	X
50	EXHAUST PIPE	11 X	1	\$869.40	X
51	EXHAUST GASKET	11 X	1	\$156.70	X
52	EXHAUST BRACKET (L+R)	11 X	2	\$36.90	X
53	EXHAUST HEAT SHIELD	11 X	1	\$218.40	X
54	REAR ABSORBER (LH)	11 X	1	\$422.10	X
55	REAR LOWER ARM (LH)	11 X	1	\$207.40	X
56	REAR KNUCKLE (LH)	11 X	1	\$344.10	X
57	REAR KNUCKLE BEARING (LH)	11 X	1	\$217.30	X
58	REAR BEARING HUB (LH)	11 X	1	\$302.40	X
59	REAR AXLE	11 X	1	NIL	X
60	FRONT BONNET	11 X	1	\$1268.70	X
61	FRONT BONNET LOCK	11 X	1	\$79.60	X
62	FRONT BONNET CATCH	11 X	1	\$52.90	X
63	FRONT BONNET INNER TRIM	11 X	1	\$71.10	X
64	FRONT BONNET STOPPER (L+R)	11 X	4	\$72.40	X
65	FRONT BONNET INNER RUBBER STRIP (L+R)	11 X	2	\$268.20	X
66	FRONT CENTER GRILLE CHROME	11 X	1	\$418.40	X
67	FRONT CENTER LOGO CHROME (VOLKSWAGEN)	11 X	1	\$141.70	X
68	HEAD LAMP (L+R)	0/5 cm 7/2 C 1047.10 \$1047.10	2	\$2094.20	1/2 C
69	HEAD LAMP BRACKET (L+R)	11 X	2	\$428.20	X
70	FRONT BUMPER	D.S	1	\$1231.70	X
71	FRONT BUMPER RETAINER (L+R)	0/5 3/4 1/2 C \$49.80	2	\$89.60	1/2 C
72	FRONT BUMPER GRILLE	11 X	1	\$218.70	X
73	FRONT BUMPER FOG LAMP (L+R)	11 X	2	\$525.60	X
74	FRONT BUMPER FOG LAMP GARNISH (L+R)	0/5 5/2 1/2 C \$316.20	2	\$632.40	1/2 C
75	FRONT BUMPER SENSOR SET	3/2 1/2 1/2 C 215 \$360	6	\$2160.00	1/2 C
76	FRONT BUMPER NOZZLE CAP	11 X	1	\$46.00	X
77	FRONT BUMPER TOW COVER	11 X	2	\$64.20	X
78	FRONT BUMPER SIDE PROTECTOR (L+R)	124 0/5 D.S 1/2 C \$124.40	2	\$248.80	1/2 C 12
79	FRONT FENDER (L+R)	0/5 1/2 1/2 C \$458.40	2	\$916.80	1/2 C
80	FRONT FENDER COWLING (L+R)	0/5 2/2 1/2 C 247.10 \$247.10	2	\$494.20	1/2 C
81	FRONT FENDER TOP GARNISH (L+R)	11 X	2	\$88.40	X
82	FRONT FENDER WHEEL ARCH PROTECTOR (L+R)	0/5 1/2 1/2 C \$110.50	2	\$221.00	1/2 C
83	FRONT SUPPORT PANEL	11 X	1	\$131.70	X
84	FRONT SUPPORT PANEL TOP GARNISH	11 X	1	\$128.40	X
85	AIR CON CONDENSOR	11 X	1	\$984.70	X
86	HIGH PRESSURE HOSE	11 X	1	\$216.20	X
87	LOW PRESSURE HOSE	11 X	1	\$219.80	X
88	RADIATOR	11 X	1	\$1264.70	X

9907.60

24731.60

[illegible]



Rico 60 Auto Services Pte Ltd. D18, KAM BUKIT AVENUE 4, #01-27
Premier @ Kaki Bukit Singapore 415875, Email: claims@rico60.com
Tel: 6286 6060, FAX: 6286 7060
VEHICLE NUM: SGG 1320 A
MAKE & MODEL: VOLKSWAGEN TIGUAN
MILEAGE:
TYRE:
CHASSIS NUM:

not Alfred
1/5 9
19 Jan
4/6/19
The 7th - 11th Apr

APIN	NO.	DESCRIPTION - PARTS	QTY	PRICE
	1	REAR WINDSCREEN MOULDING 17 X	1	
	2	TAILGATE 17 X	1	
	3	TAILGATE SPOILER 17 X	1	
	4	TAILGATE THIRD BRAKE LAMP 17 X	1	
	5	TAILGATE WIPER 17 X	1	
	6	TAILGATE WIPER MOTOR 17 X	1	
	7	TAILGATE WIPER MOTOR COVER 17 X	1	
	8	TAILGATE LOGO (VOLKSWAGEN) 17 X	1	
	9	TAILGATE EMBLEM (TIGUAN) 17 X	1	
	10	TAILGATE EMBLEM (TSI) 17 X	1	
	11	TAILGATE LAMP (L+R) 17 X	2	
	12	TAILGATE LOCK 17 X	1	
	13	TAILGATE CATCH 17 X	1	
	14	TAILGATE HANDLE 17 X	1	
	15	REVERSE CAMERA 17 X	1	
	16	TAILGATE CARPLATE LAMP (L+R) 17 X	2	
	17	TAILGATE INNER TRIM 17 X	1	
	18	TAILGATE INNER TRIM (L+R) 17 X	2	
	19	TAILGATE INNER TRIM TOP 17 X	1	
	20	TAILGATE INNER BOARD 17 X	1	
	21	TAILGATE DAMPER (L+R) 17 X	2	
	22	TAILGATE HINGE (L+R) 17 X	2	
	23	TAILGATE INNER WIRE PROTECTOR (L+R) 17 X	2	
	24	TAILGATE WEATHER STRIP 17 X	1	
	25	TAIL LAMP (L+R) 21/5 CNE 1PC	2	
	26	TAIL LAMP PANEL (L+R) R X	2	
	27	REAR BUMPER D15	1	
	28	REAR BUMPER RETAINER (L+R) 1/5 CNE 1PC	2	
	29	REAR BUMPER LOWER D15	1	
	30	REAR BUMPER REFLECTOR (L+R) 1/5 520 1PC	2	
	31	REAR BUMPER REFLECTOR LAMP (L+R) 17 X	2	
	32	REAR BUMPER TOW COVER 17 X	1	
	33	REAR BUMPER REVERSE SENSOR SET 17 X	6	
	34	REAR BUMPER UNDERCOVER 17 X	1	
	35	REAR BUMPER SIDE PROTECTOR (L+R) 1/5 D15 1PC	2	
	36	REAR BUMPER REINFORCEMENT BAR 17 X	1	
	37	REAR BUMPER BEAM 17 X	1	
	38	REAR BUMPER SPONGE 17 X	1	
	39	REAR BUMPER BRACKET (L+R) 21/5 CNE 1PC	2	
	40	REAR FENDER (L+R) 1/5 100/100 1PC	2	

Rear air vent 1/5 CNE ✓

41	REAR FENDER QUARTER WINDOW MOULDING (L+R)	11 X	2
42	REAR FENDER INNER TRIM (L+R)	11 X	2
43	REAR FENDER COWLING (L+R)	M/S Toon 12C	2
44	REAR WHEEL ARCH PROTECTOR (L+R)	M/S Toon 12C	2
45	END PANEL	Body 20 —	1
46	END PANEL TOP GARNISH	11 X	1
47	SPAREWHEEL PANEL	11 X	1
48	SPAREWHEEL PANEL TOP BOARD	11 X	1
49	SPAREWHEEL PANEL INNER ACCESSORIES BOX	11 X	1
50	EXHAUST PIPE	11 X	1
51	EXHAUST GASKET	11 X	1
52	EXHAUST BRACKET (L+R)	11 X	2
53	EXHAUST HEAT SHIELD	11 X	1
54	REAR ABSORBER (LH)	11 X	1
55	REAR LOWER ARM (LH)	11 X	1
56	REAR KNUCKLE (LH)	11 X	1
57	REAR KNUCKLE BEARING (LH)	11 X	1
58	REAR BEARING HUB (LH)	11 X	1
59	REAR AXLE	11 X	1
60	FRONT BONNET	12 X	1
61	FRONT BONNET LOCK	11 X	1
62	FRONT BONNET CATCH	11 X	1
63	FRONT BONNET INNER TRIM	11 X	1
64	FRONT BONNET STOPPER (L+R)	11 X	4
65	FRONT BONNET INNER RUBBER STRIP (L+R)	11 X	2
66	FRONT CENTER GRILLE CHROME	11 X	1
67	FRONT CENTER LOGO CHROME (VOLKSWAGEN)	11 X	1
68	HEAD LAMP (L+R)	0/5 Sene 12C	2
69	HEAD LAMP BRACKET (L+R)	11 X	2
70	FRONT BUMPER	D.S. —	1
71	FRONT BUMPER RETAINER (L+R)	0/5 Bt 12C	2
72	FRONT BUMPER GRILLE	11 X	1
73	FRONT BUMPER FOG LAMP (L+R)	11 X	2
74	FRONT BUMPER FOG LAMP GARNISH (L+R)	0/5 Sene 12C	2
75	FRONT BUMPER SENSOR SET	3200 12C	6
76	FRONT BUMPER NOZZLE CAP	11 X	1
77	FRONT BUMPER TOW COVER	11 X	2
78	FRONT BUMPER SIDE PROTECTOR (L+R)	0/5 D.S. 12C	2
79	FRONT FENDER (L+R)	0/5 DD 12C	2
80	FRONT FENDER COWLING (L+R)	0/5 Qe 12C	2
81	FRONT FENDER TOP GARNISH (L+R)	11 X	2
82	FRONT FENDER WHEEL ARCH PROTECTOR (L+R)	0/5 Cut 12C	2
83	FRONT SUPPORT PANEL	11 X	1
84	FRONT SUPPORT PANEL TOP GARNISH	11 X	1
85	AIR CON CONDENSOR	11 X	1
86	HIGH PRESSURE HOSE	11 X	1
87	LOW PRESSURE HOSE	11 X	1
88	RADIATOR	11 X	1

89	DISCHARGE PIPE	✓		1	
90	SUCTION PIPE	✓		1	
91	RADIATOR FAN COWLING	✓		1	
92	RADIATOR FAN BLADE	✓		1	
93	RADIATOR FAN MOTOR	✓		1	
94	WIPER WASHER TANK	✓		1	
95	WIPER WASHER MOTOR	✓		1	
96	FRONT ABSORBER (RH)	✓		1	
97	FRONT LOWER ARM (RH)	sent ✓		1	
98	FRONT KNUCKLE (RH)	sent ✓		1	
99	FRONT KNUCKLE BEARING (RH)	new ✓		1	
100	FRONT BEARING HUB (RH)	sent ✓		1	
101	FRONT STEERING RACK AND PINION ASSY	✓		1	
102	FRONT CROSSMEMBER	✓		1	
			SUBTOTAL	\$	-
			LESS 10%	\$	-
			PARTS TOTAL	\$	-
			SPECIAL NETT	QTY	PRICE
1	REAR WINDSCREEN SEALANT	✓	1	\$	120.00
2	TAILGATE EMBLEM (BLUEMOTION)	✓	1	\$	400.00
3	TAILGATE INNER TRIM CLIP	✓	10	\$	100.00
4	TAIL LAMP CLIP	✓	10	\$	100.00
5	REAR CARPLATE	✓	1	\$	120.00
6	REAR BUMPER CLIP	new 50	10	\$	100.00
7	REAR BUMPER LOWER CLIP	✓	10	\$	100.00
8	REAR FENDER SEALANT	new 40	1	\$	120.00
9	REAR FENDER INNER TRIM CLIP	✓	10	\$	100.00
10	REAR FENDER COWLING CLIP	✓	10	\$	100.00
11	END PANEL SEALANT	✓	1	\$	120.00
12	SPAREWHEEL PANEL SEALANT	✓	1	\$	120.00
13	SPARE TIRE	✓	1	\$	600.00
14	SPARE TIRE RIM	✓	1	\$	800.00
15	FRONT TIRE	✓	2	\$	1,600.00
16	REAR TIRE	✓	2	\$	1,600.00
17	RIM SET	entire set 1600	1SET	\$	8,000.00
18	FRONT BONNET INNER TRIM CLIP	✓	10	\$	100.00
19	FRONT CENTER GRILLE EMBLEM (R)	✓	1	\$	400.00
20	FRONT CARPLATE	✓	1	\$	120.00
21	FRONT BUMPER CLIP	new 50	10	\$	100.00
			SPECIAL NETT TOTAL	\$	14,920.00
			LABOUR	QTY	PRICE
1	TO RNR ACCIDENT DAMAGE PARTS, CUT/WELD, KNOCK&REALIGN	1100	1	\$	5,200.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	1400	1	\$	3,200.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA	60	1	\$	250.00
4	TO RNR REAR WINDSCREEN	✓	1	\$	400.00
5	TO RNR REAR BOOT MECHANISM	✓	1	\$	200.00

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Jun 2019		03 Jun 2019 16:36 Edit Adj Rpt	S\$12,000.00 Edit Estimates	S\$12,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	STARTECH COMMUNICATION ENGRG PTE LTD, Co. Reg. No.: 200916360G								
Main Claimant:	TAY HUNG YEONG, ID: S6844986C								
Vehicle Reg. No.:	SGG1320A	Date of Loss:	01/06/2019 09:00 - :59 [39 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D202469C02	Policy/Cover Note No.:	DMCVSN30730018022						
Vehicle Reg. No. (Insured):	GBF1932Z	Policy No. (Claimant):	A 28692537 COMP						
		Excess:	S\$0.00						
Repairer:	RICO 60 AUTO SERVICES PTE LTD (HQ) 8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 13/06/2019]								
Adj Asg. Remarks:	to assign Mr Marcus Chua for SJE. please contact Jin Hai at 9816 3144 to arrange for survey. thank you								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SGG1320A (SNM19D202469C02)**
[GBF1932Z]
TP
TAY HUNG YEONG
Jun 1 2019 9:00AM
[STARTECH COMMUNICATION ENGRG PTE LTD]
RICO 60 AUTO SERVICES PTE LTD

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		☒	
No	Finalized On	VAC (Kaki Bukit)					Thumbnail	Print		
1	03/06/19 12:56	Accident Statement					1 Load HTM			
Photos/Images							3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print		
1	04/06/19 19:35	Chassis Number					1 Load JPG	☒		
2	04/06/19 19:36	Odometer Reading					1 Load JPG	☒		
3	04/06/19 19:36	General View					1 Load JPG	☒		
4	04/06/19 19:36	General View					1 Load JPG	☒		
5	04/06/19 19:36	General View					1 Load JPG	☒		
6	04/06/19 19:36	General View					1 Load JPG	☒		
7	04/06/19 19:36	General View					1 Load JPG	☒		
8	04/06/19 19:36	General View					1 Load JPG	☒		
9	04/06/19 19:36	General View					1 Load JPG	☒		
10	04/06/19 19:36	General View					1 Load JPG	☒		
11	04/06/19 19:36	General View					1 Load JPG	☒		
12	04/06/19 19:36	General View					1 Load JPG	☒		
13	04/06/19 19:36	General View					1 Load JPG	☒		
14	04/06/19 19:36	General View					1 Load JPG	☒		
15	04/06/19 19:36	General View					1 Load JPG	☒		
16	04/06/19 19:36	General View					1 Load JPG	☒		
17	04/06/19 19:36	General View					1 Load JPG	☒		
18	04/06/19 19:36	General View					1 Load JPG	☒		
19	04/06/19 19:36	General View					1 Load JPG	☒		
20	04/06/19 19:36	General View					1 Load JPG	☒		
21	04/06/19 19:36	General View					1 Load JPG	☒		
22	04/06/19 19:36	General View					1 Load JPG	☒		
23	04/06/19 19:36	General View					1 Load JPG	☒		
24	04/06/19 19:36	General View					1 Load JPG	☒		
25	04/06/19 19:36	General View					1 Load JPG	☒		
26	04/06/19 19:36	General View					1 Load JPG	☒		
27	04/06/19 19:36	General View					1 Load JPG	☒		
28	04/06/19 19:36	General View					1 Load JPG	☒		
29	04/06/19 19:36	General View					1 Load JPG	☒		
30	04/06/19 19:36	General View					1 Load JPG	☒		
31	04/06/19 19:36	General View					1 Load JPG	☒		
32	04/06/19 19:36	General View					1 Load JPG	☒		
33	04/06/19 19:36	General View					1 Load JPG	☒		
34	04/06/19 19:36	General View					1 Load JPG	☒		

Assessment Reports			1 per page	☒
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
				☒
35	04/06/19 19:36	General View	 Load JPG	☒
36	04/06/19 19:36	General View	 Load JPG	☒
37	04/06/19 19:36	General View	 Load JPG	☒
38	04/06/19 19:36	General View	 Load JPG	☒
39	04/06/19 19:36	General View	 Load JPG	☒
40	04/06/19 19:36	General View	 Load JPG	☒
41	04/06/19 19:36	General View	 Load JPG	☒
42	04/06/19 19:37	General View	 Load JPG	☒
43	04/06/19 19:37	General View	 Load JPG	☒
44	04/06/19 19:37	General View	 Load JPG	☒
45	04/06/19 19:37	General View	 Load JPG	☒
46	04/06/19 19:37	General View	 Load JPG	☒
47	04/06/19 19:37	General View	 Load JPG	☒
48	04/06/19 19:37	General View	 Load JPG	☒
49	04/06/19 19:37	General View	 Load JPG	☒
50	04/06/19 19:37	General View	 Load JPG	☒
51	04/06/19 19:37	General View	 Load JPG	☒
52	04/06/19 19:37	General View	 Load JPG	☒
53	04/06/19 19:37	General View	 Load JPG	☒
54	04/06/19 19:37	General View	 Load JPG	☒
55	04/06/19 19:37	General View	 Load JPG	☒
56	04/06/19 19:37	General View	 Load JPG	☒
57	04/06/19 19:37	General View	 Load JPG	☒
58	04/06/19 19:37	General View	 Load JPG	☒
59	04/06/19 19:37	General View	 Load JPG	☒
60	04/06/19 19:37	General View	 Load JPG	☒
61	04/06/19 19:37	General View	 Load JPG	☒
62	04/06/19 19:37	General View	 Load JPG	☒
63	04/06/19 19:37	General View	 Load JPG	☒
64	04/06/19 19:37	General View	 Load JPG	☒
65	04/06/19 19:37	General View	 Load JPG	☒
66	04/06/19 19:37	General View	 Load JPG	☒
67	04/06/19 19:37	General View	 Load JPG	☒
68	04/06/19 19:37	General View	 Load JPG	☒
69	04/06/19 19:37	General View	 Load JPG	☒
70	04/06/19 19:37	General View	 Load JPG	☒
71	04/06/19 19:37	General View	 Load JPG	☒
72	04/06/19 19:37	General View	 Load JPG	☒
73	04/06/19 19:37	General View	 Load JPG	☒
74	04/06/19 19:37	General View	 Load JPG	☒
75	04/06/19 19:37	General View	 Load JPG	☒
76	04/06/19 19:37	General View	 Load JPG	☒
77	04/06/19 19:37	Reinspection Photo	 Load JPG	☒
78	04/06/19 19:37	Reinspection Photo	 Load JPG	☒
79	04/06/19 19:37	Reinspection Photo	 Load JPG	☒
80	04/06/19 19:37	Reinspection Photo	 Load JPG	☒
81	04/06/19 19:37	Reinspection Photo	 Load JPG	☒
82	04/06/19 19:37	Reinspection Photo	 Load JPG	☒
83	04/06/19 19:37	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
84	04/06/19 19:37	Reinspection Photo	 Load JPG	☒
85	04/06/19 19:37	Reinspection Photo	 Load JPG	☒
86	04/06/19 19:37	Reinspection Photo	 Load JPG	☒
87	04/06/19 19:37	Reinspection Photo	 Load JPG	☒
88	04/06/19 19:37	Reinspection Photo	 Load JPG	☒
89	04/06/19 19:37	Reinspection Photo	 Load JPG	☒
90	04/06/19 19:37	Reinspection Photo	 Load JPG	☒
91	04/06/19 19:37	Reinspection Photo	 Load JPG	☒
92	04/06/19 19:37	Reinspection Photo	 Load JPG	☒
93	04/06/19 19:37	Reinspection Photo	 Load JPG	☒
94	04/06/19 19:37	Reinspection Photo	 Load JPG	☒
95	04/06/19 19:37	Reinspection Photo	 Load JPG	☒
96	04/06/19 19:37	Reinspection Photo	 Load JPG	☒
97	04/06/19 19:37	Reinspection Photo	 Load JPG	☒
98	04/06/19 19:37	Reinspection Photo	 Load JPG	☒
99	04/06/19 19:37	Reinspection Photo	 Load JPG	☒
100	04/06/19 19:37	Reinspection Photo	 Load JPG	☒
101	04/06/19 19:37	Reinspection Photo	 Load JPG	☒
102	04/06/19 19:37	Reinspection Photo	 Load JPG	☒
103	04/06/19 19:37	Reinspection Photo	 Load JPG	☒
104	04/06/19 19:37	Reinspection Photo	 Load JPG	☒
105	04/06/19 19:37	Reinspection Photo	 Load JPG	☒
106	04/06/19 19:37	Reinspection Photo	 Load JPG	☒
107	04/06/19 19:37	Reinspection Photo	 Load JPG	☒
108	04/06/19 19:37	Reinspection Photo	 Load JPG	☒
109	04/06/19 19:37	Reinspection Photo	 Load JPG	☒
110	04/06/19 19:37	Reinspection Photo	 Load JPG	☒
111	04/06/19 19:37	Reinspection Photo	 Load JPG	☒
112	04/06/19 19:37	Reinspection Photo	 Load JPG	☒
113	04/06/19 19:37	Reinspection Photo	 Load JPG	☒
114	04/06/19 19:37	Reinspection Photo	 Load JPG	☒
115	04/06/19 19:37	Reinspection Photo	 Load JPG	☒
116	04/06/19 19:37	Reinspection Photo	 Load JPG	☒
117	04/06/19 19:37	Reinspection Photo	 Load JPG	☒
118	04/06/19 19:37	Reinspection Photo	 Load JPG	☒
119	04/06/19 19:37	Reinspection Photo	 Load JPG	☒
120	04/06/19 19:37	Reinspection Photo	 Load JPG	☒
121	04/06/19 19:37	Reinspection Photo	 Load JPG	☒
122	04/06/19 19:37	Reinspection Photo	 Load JPG	☒
123	04/06/19 19:37	Reinspection Photo	 Load JPG	☒
124	04/06/19 19:37	Reinspection Photo	 Load JPG	☒
125	04/06/19 19:37	Reinspection Photo	 Load JPG	☒
126	04/06/19 19:37	Reinspection Photo	 Load JPG	☒
127	04/06/19 19:37	Reinspection Photo	 Load JPG	☒
128	04/06/19 19:37	Reinspection Photo	 Load JPG	☒
129	04/06/19 19:37	Reinspection Photo	 Load JPG	☒
130	04/06/19 19:37	Reinspection Photo	 Load JPG	☒
131	04/06/19 19:37	Reinspection Photo	 Load JPG	☒
132	04/06/19 19:37	Reinspection Photo	 Load JPG	☒
133	04/06/19 19:37	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
134	04/06/19 19:37	Reinspection Photo	 Load JPG	☒
135	04/06/19 19:37	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	03/06/19 16:35	PRS	 Load PDF	

Linked Accident Report Documents

			View	View in Browser
Assessment Reports			1 per page	☒
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	03/06/19 12:56	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	03/06/19 12:56	Accident Photo	 Load JPG	☒
2	03/06/19 12:56	Accident Photo	 Load JPG	☒
3	03/06/19 12:56	Accident Photo	 Load JPG	☒
4	03/06/19 12:56	Accident Photo	 Load JPG	☒
5	03/06/19 12:56	Accident Photo	 Load JPG	☒
6	03/06/19 12:56	Accident Photo	 Load JPG	☒
7	03/06/19 12:56	Accident Photo	 Load JPG	☒
8	03/06/19 12:56	Accident Photo	 Load JPG	☒
9	03/06/19 12:56	Accident Photo	 Load JPG	☒
10	03/06/19 12:56	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	03/06/19 12:55	Sketch Plan	 Load TIF	
2	03/06/19 12:55	Sketch Plan #2	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) 			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119009783/UTD3E2

Date: 10/07/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN30730018022

Claimant Vehicle
No: SGG1320AInsured Vehicle
No: GBF1932Z

Date of Loss: 01/06/2019

Nature of Claim: TP

Claim
No: SNM19D202469C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGG1320A

Make & Model: VOLKSWAGEN TIGUAN, 1.4 TSI BMT (5N22SY)
(A)

Engine No: CTH230378

Reg. Date: 24/02/2016 (Man. Year: 2015)

Chassis No: WVGZZZ5NZGW030898

Colour: Silver

Odometer: 54155 km

Engine Capacity: 1390 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/40 R19

Rear Tyre Size: 255/40 R19

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	60,857.26	12,130.86	48,726.40	80.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,980.00	2,970.00	9,010.00	75.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	72,837.26	15,100.86	57,736.40	79.27
Approved Total (Overridden) (S\$)		12,000.00		
(S\$)	72,837.26	12,000.00	60,837.26	83.52
+ GST 7.00/7.00% (S\$)	5,098.61	840.00	4,258.61	83.52
Nett Amount (S\$)	77,935.87	12,840.00	65,095.87	83.52

INSPECTION

Date of Assignment: 03/06/2019

Date Inspected: 04/06/2019 Inspected At:

RICO 60 AUTO SERVICES PTE LTD (HQ)
8, KAKI BUKIT AVENUE 4, #02-24,

PREMIER @ KAKI BUKIT
Singapore 415875

Estimated Period of Repair: 10.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Jul 2019)
Parts:	M1-SUV	VOLKSWAGEN TIGUAN 1.4 TSI BMT (5N22SY) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGG1320A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Not Necessary	216.80 FL	*- FL
2	1		*TAILGATE	Repair	1,674.60 FL	*- FL
3	1		*TAILGATE SPOILER	Not Necessary	463.70 FL	*- FL
4	1		*TAILGATE THIRD BRAKE LAMP	Not Necessary	296.70 FL	*- FL
5	1		*TAILGATE WIPER	Not Necessary	86.30 FL	*- FL
6	1		*TAILGATE WIPER MOTOR	Not Necessary	216.70 FL	*- FL
7	1		*TAILGATE WIPER MOTOR COVER	Not Necessary	42.30 FL	*- FL
8	1		*TAILGATE LOGO (VOLKSWAGEN)	Not Necessary	130.90 FL	*- FL
9	1		*TAILGATE EMBLEM (TIGUAN)	Not Necessary	76.10 FL	*- FL
10	1		*TAILGATE EMBLEM (TSI)	Not Necessary	62.20 FL	*- FL
11	2		*TAILGATE LAMP (L+R)	Not Necessary	420.60 FL	*- FL
12	1		*TAILGATE LOCK	Not Necessary	248.10 FL	*- FL
13	1		*TAILGATE CATCH	Not Necessary	56.70 FL	*- FL
14	1		*TAILGATE HANDLE	Not Necessary	32.30 FL	*- FL
15	1		*REVERSE CAMERA	Not Necessary	1,064.30 FL	*- FL
16	2		*TAILGATE CARPLATE LAMP (L+R)	Not Necessary	121.40 FL	*- FL
17	1		*TAILGATE INNER TRIM	Not Necessary	425.70 FL	*- FL
18	2		*TAILGATE INNER TRIM (L+R)	Not Necessary	267.40 FL	*- FL
19	1		*TAILGATE INNER TRIM TOP	Not Necessary	128.40 FL	*- FL
20	1		*TAILGATE INNER BOARD (NPA)	Not Necessary	0.00 FL	*- FL
21	2		*TAILGATE DAMPER (L+R)	Not Necessary	426.60 FL	*- FL
22	2		*TAILGATE HINGE (L+R)	Not Necessary	226.20 FL	*- FL
23	2		*TAILGATE INNER WIRE PROTECTOR (L+R)	Not Necessary	136.20 FL	*- FL
24	1		*TAILGATE WEATHER STRIP	Not Necessary	816.80 FL	*- FL
25	1		*TAIL LAMP (L+R)	N/s Cracked	760.20 FL	*380.10 FL
26	2		*TAIL LAMP PANEL (L+R)	Repair	425.40 FL	*- FL
27	1		*REAR BUMPER	Distorted	1,041.50 FL	*1,041.50 FL
28	1		*REAR BUMPER RETAINER (L+R)	N/s Cracked	88.40 FL	*44.20 FL
29	1		*REAR BUMPER LOWER	Distorted	865.70 FL	*865.70 FL
30	1		*REAR BUMPER REFLECTOR (L+R)	N/s Broken	112.40 FL	*56.20 FL
31	2		*REAR BUMPER REFLECTOR LAMP (L+R)	Repeated	365.60 FL	*- FL
32	1		*REAR BUMPER TOW COVER	Not Necessary	42.10 FL	*- FL
33	1		*SET REAR BUMPER REVERSE SENSOR (6 Pcs)	Shorted - 2 Pcs only	2,160.00 FL	*430.00 FL
34	1		*REAR BUMPER UNDERCOVER	Grazed	328.70 FL	*225.30 FL
35	1		*REAR BUMPER SIDE PROTECTOR (L+R)	N/s Distorted	216.40 FL	*108.20 FL
36	1		*REAR BUMPER REINFORCEMENT BAR	Not Necessary	639.80 FL	*- FL
37	1		*REAR BUMPER BEAM	Not Necessary	331.30 FL	*- FL
38	1		*REAR BUMPER SPONGE	No such part	321.70 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
39	1		*REAR BUMPER BRACKET (L+R)	N/s Cracked	86.40 FL	*43.20 FL
40	1		*REAR FENDER (L+R)	N/s Badly Dented/Buckled	4,860.40 FL	*1,866.00 FL
41	1		*REAR AIR VENT	Distorted	128.60 FL	*128.60 FL
42	2		*REAR FENDER QUARTER WINDOW MOULDING (L+R)	Not Necessary	631.80 FL	*- FL
43	2		*REAR FENDER INNER TRIM (L+R)	Not Necessary	867.40 FL	*- FL
44	1		*REAR FENDER COWLING (L+R)	N/S Torn	484.40 FL	*242.20 FL
45	1		*REAR WHEEL ARCH PROTECTOR (L+R)	N/S Torn	268.20 FL	*134.10 FL
46	1		*END PANEL	Badly Dented	648.90 FL	*648.90 FL
47	1		*END PANEL TOP GARNISH	Not Necessary	128.60 FL	*- FL
48	1		*SPARE WHEEL PANEL	Not Necessary	1,263.70 FL	*- FL
49	1		*SPARE WHEEL PANEL TOP BOARD	Not Necessary	216.10 FL	*- FL
50	1		*SPARE WHEEL PANEL INNER ACCESSORIES BOX	Not Necessary	144.70 FL	*- FL
51	1		*EXHAUST PIPE	Not Necessary	869.40 FL	*- FL
52	1		*EXHAUST GASKET	Not Necessary	156.70 FL	*- FL
53	2		*EXHAUST BRACKET (L+R)	Not Necessary	76.90 FL	*- FL
54	1		*EXHAUST HEAT SHIELD	Not Necessary	218.40 FL	*- FL
55	1		*REAR ABSORBER (LH)	Not Necessary	422.10 FL	*- FL
56	1		*REAR LOWER ARM (LH)	Not Necessary	907.40 FL	*- FL
57	1		*REAR KNUCKLE (LH)	Not Necessary	344.10 FL	*- FL
58	1		*REAR KNUCKLE BEARING (LH)	Not Necessary	297.30 FL	*- FL
59	1		*REAR BEARING HUB (LH)	Not Necessary	302.40 FL	*- FL
60	1		*REAR AXLE (NPA)	Not Necessary	0.00 FL	*- FL
61	1		*FRONT BONNET	Repair	1,268.70 FL	*- FL
62	1		*FRONT BONNET LOCK	Not Necessary	79.60 FL	*- FL
63	1		*FRONT BONNET CATCH	Not Necessary	52.90 FL	*- FL
64	1		*FRONT BONNET INNER TRIM	Not Necessary	79.10 FL	*- FL
65	4		*FRONT BONNET STOPPER (L+R)	Not Necessary	72.40 FL	*- FL
66	1		*FRONT CENTER GRILLE CHROME	Not Necessary	418.40 FL	*- FL
67	1		*FRONT CENTER LOGO CHROME (VOLKSWAGEN)	Not Necessary	141.70 FL	*- FL
68	1		*HEAD LAMP (L+R)	O/S Cracked	2,094.20 FL	*1,047.10 FL
69	2		*HEAD LAMP BRACKET (L+R)	Not Necessary	428.20 FL	*- FL
70	1		*FRONT BUMPER	Distorted	1,231.70 FL	*1,231.70 FL
71	1		*FRONT BUMPER RETAINER (L+R)	O/S Bent	89.60 FL	*49.80 FL
72	1		*FRONT BUMPER GRILLE	Not Necessary	218.70 FL	*- FL
73	2		*FRONT BUMPER FOG LAMP (L+R)	Not Necessary	25.60 FL	*- FL
74	1		*FRONT BUMPER FOG LAMP GARNISH (L+R)	O/S Scratched	632.40 FL	*255.00 FL
75	1		*SET FRONT BUMPER SENSOR (6 Pcs)	Shorted - 1Pc only	2,160.00 FL	*215.00 FL
76	1		*FRONT BUMPER NOZZLE CAP	Not Necessary	46.00 FL	*- FL
77	2		*FRONT BUMPER TOW COVER	Not Necessary	64.20 FL	*- FL
78	1		*FRONT BUMPER SIDE PROTECTOR (L+R)	O/S Distorted	248.40 FL	*124.00 FL
79	1		*FRONT FENDER (L+R)	O/S Dented	916.80 FL	*458.40 FL
80	1		*FRONT FENDER COWLING (L+R)	O/S Deformed	494.20 FL	*247.10 FL
81	2		*FRONT FENDER TOP GARNISH (L+R)	Not Necessary	88.40 FL	*- FL
82	1		*FRONT FENDER WHEEL ARCH PROTECTOR (L+R)	O/S Cut	280.60 FL	*140.30 FL
83	1		*FRONT SUPPORT PANEL	Not Necessary	1,269.70 FL	*- FL
84	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	128.40 FL	*- FL
85	1		*AIR CON CONDENSOR	Not Necessary	984.70 FL	*- FL
86	1		*HIGH PRESSURE HOSE	Not Necessary	216.20 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
87	1		*LOW PRESSURE HOSE	Not Necessary	219.80 FL	*- FL
88	1		*RADIATOR	Not Necessary	1,264.30 FL	*- FL
89	1		*DISCHARGE PIPE	Not Necessary	129.60 FL	*- FL
90	1		*SUCTION PIPE	Not Necessary	117.20 FL	*- FL
91	1		*RADIATOR FAN COWLING	Not Necessary	643.40 FL	*- FL
92	1		*RADIATOR FAN BLADE	Not Necessary	215.90 FL	*- FL
93	1		*RADIATOR FAN MOTOR	Not Necessary	269.60 FL	*- FL
94	1		*WIPER WASHER TANK	Not Necessary	248.90 FL	*- FL
95	1		*WIPER WASHER MOTOR	Not Necessary	129.80 FL	*- FL
96	1		*FRONT ABSORBER (RH)	Not Necessary	421.80 FL	*- FL
97	1		*FRONT LOWER ARM (RH)	Bent	899.70 FL	*669.00 FL
98	1		*FRONT KNUCKLE (RH)	Bent	316.10 FL	*316.10 FL
99	1		*FRONT KNUCKLE BEARING (RH)	Necessary	278.40 FL	*278.40 FL
100	1		*FRONT BEARING HUB (RH)	Bent	299.30 FL	*299.30 FL
101	1		*FRONT STEERING RACK AND PINION ASSY	Not Necessary	1,687.70 FL	*- FL
102	1		*FRONT CROSSMEMBER	Not Necessary	1,240.80 FL	*- FL
103	1		*REAR WINDSCREEN SEALANT	Not Necessary	120.00 FS	*- FS
104	1		*TAILGATE EMBLEM (BLUEMOTION)	Not Necessary	400.00 FS	*- FS
105	10		*TAILGATE INNER TRIM CLIP	Not Necessary	100.00 FS	*- FS
106	10		*TAIL LAMP CLIP	Not Necessary	100.00 FS	*- FS
107	1		*REAR CARPLATE	Not Necessary	120.00 FS	*- FS
108	10		*REAR BUMPER CLIP	Necessary	100.00 FS	*50.00 FS
109	10		*REAR BUMPER LOWER CLIP	Not Necessary	100.00 FS	*- FS
110	1		*REAR FENDER SEALANT	Necessary	120.00 FS	*40.00 FS
111	10		*REAR FENDER INNER TRIM CLIP	Not Necessary	100.00 FS	*- FS
112	10		*REAR FENDER COWLING CLIP	Not Necessary	100.00 FS	*- FS
113	1		*END PANEL SEALANT	Not Necessary	120.00 FS	*- FS
114	1		*SPAREWHEEL PANEL SEALANT	Not Necessary	120.00 FS	*- FS
115	1		*SPARE TIRE	Not Necessary	600.00 FS	*- FS
116	1		*SPARE TIRE RIM	Not Necessary	800.00 FS	*- FS
117	2		*FRONT TIRE	Not Necessary	1,600.00 FS	*- FS
118	2		*REAR TIRE	Not Necessary	1,600.00 FS	*- FS
119	1		*SET RIM	Cut	8,000.00 FS	*1,600.00 FS
120	10		*FRONT BONNET INNER TRIM CLIP	Not Necessary	100.00 FS	*- FS
121	1		*FRONT CENTER GRILLE EMBLEM (R)	Not Necessary	400.00 FS	*- FS
122	1		*FRONT CARPLATE	Not Necessary	120.00 FS	*- FS
123	10		*FRONT BUMPER CLIP	Necessary	100.00 FS	*50.00 FS
124	2		*FRONT BONNET INNER RUBBER STRIP (L+R)	Not Necessary	268.20 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 65,961.40 13,285.40
 - List Item Discount on L Items 10.00/10.00% (\$\$) 5,104.14 1,154.54

Total Parts (\$\$) 60,857.26 12,130.86

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RNR ACCIDENT DAMAGE PARTS, CUT / WELD, KNOCK & REALIGN	New	5,200.00	1,200.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	New	3,200.00	1,400.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA	New	250.00	60.00
4	TO RNR REAR WINDSCREEN	New	400.00	0.00
5	TO RNR REAR BOOT MECHANISM	New	200.00	0.00
6	TO RNR UPHOLSTERY, GARNISH AND ATTACHMENT PARTS	New	400.00	80.00
7	TO RNR REVERSE SENSOR & CHECK FUNCTION	New	150.00	50.00
8	TO RNR FRONT SENSOR AND CHECK FUNCTION	New	150.00	30.00
9	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	New	250.00	0.00
10	TO RNR UNDERCARRIAGE SYSTEM	New	250.00	0.00
11	TO CHECK WHEEL ALIGNMENT	New	200.00	120.00
12	TO RNR A/C CONDENSOR ASSY AND REFILL GAS	New	120.00	0.00
13	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS }	New	120.00	30.00
14	TO CHECK WIRING LAYOUT AND TAIL LAMP FUNCTION }	New	120.00	0.00
15	TO RNR TYRE AND WHEEL BALANCING	New	200.00	0.00
16	TO DO DIAGNOSIS AND RESET, REPROGRAM OR CODING FAULT CODE	New	200.00	0.00
17	TO DO WATER LEAK TEST	New	80.00	0.00
18	TO RNR FUEL TANK TO ASSIST WORK LOAD	New	250.00	0.00
19	TO RNR REVERSE CAMERA AND TEST FUNCTION	New	120.00	0.00
20	TO RNR RADIATOR ASSY AND HOSES TO ASSIST WORK LOAD	New	120.00	0.00
Gross Labour Cost (S\$)			11,980.00	2,970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >