

INSURER

INS. CASE OWNER:

Winnie

CC 4 ASM AXA 1900

9784, K 8639

LKR
IDAC

ASSIGNMENT

Surveyor:

KSC

DOI:

3/6/2019

Date / Time:

3/6/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKK 8200Z

Name of Insured:

LEONG YEW KEE

Insured Tel No.:

HP:

71/5/19

Excess Sec II :SS

D.O.A.:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: LEONG TIM HAO

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

SGM02PAT/11A756

Policy No.:

CN 022231

Make / Model:

TR402A

Place of Accident:

MARY MOUNT RD

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

% Final? Yes / No

SHE 15544



INSRS:
WSP:
Tel:
Liability:
RMKS:

Soon Hock



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time

20/6/19

Called OZ to inform TP claim

6/7/19

Seek mandate via SMART.

16/7/19

Mandate approve via SMART.

STAGE

DATE / PIC

Non-Reporting hr (1st)

Non-Reporting hr (2nd)

Non-Reporting hr (Final)

Notification hr (if non-pickup):

Call OI:

After call hr to OI: 20/06/19 - Jimmy

Documentation Check List: Handler Typist

Notification hr (if non-pickup)

After call hr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with William

Email

Call

Final Liability:

%

100 (Agreed / Assessed) BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

SS 5000.00

Loss of Rental (LOR):

SS

(days)

Loss of Use (LOU):

SS 720.00

(5120 x 6 days)

Loss of Income (LOI):

SS

(5 x days)

LOR only

LOU only

LOR + LOU

LOR + LO

(Tick only one)

GIA/LTA Search:

SS 2.00

Medical:

SS

Disbursement:

SS

(e.g. Tow/Independent)

Legal Cost:

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

SS 5720.00

Global Sum SS: 5700

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS 5700.00

Name 1:

Soon Hock Motor Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

ASS. REC. BY:

REF:

AXA/

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: Pr

225/65R17

R: Rondo

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

File pass to

4/7/19

Confirm US \$5000.00 with 6 working days

(Pd) = \$3848.98
44.1%

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

KW

SOON HOCK MOTOR PTE LTD

01/06/19

QUOTATION FOR VEHICLE SHF 1559 Y

PARTS				
1	1	REAR BUMPER	\$ B ₁ 996.72	✓
2	1	REAR BUMPER SIDE REFLECTOR (RED)	\$ S ₁ 43.20	X
3	1	REAR BUMPER SIDE REFLECTOR CHROME	\$ S ₁ 16.20	X
4	2	REAR BUMPER SENSOR	\$ 421.24	LT
5	4	REAR BUMPER SENSOR BRACKET	\$ S ₁ 73.60	X
6	1	REAR BUMPER CENTRE GRILLE	\$ CM 199.63	✓
7	1	REAR BUMPER TOWING COVER	\$ H ₁ 26.57	✓
8	1	REAR BUMPER REINFORCEMENT	\$ R ₁ 605.22	✓
9	2	REAR BUMPER REINFORCEMENT BRACKET (RH/LH)	\$ B ₁ 360.00	LT
10	2	REAR TAILLAMP (RH/LH)	\$ N ₁ 1,066.96	LT
11	1	REAR FENDER SHIELD (LH)	\$ CM 197.28	✓
12	1	REAR END PANEL	\$ R ₁ 1,151.95	✓
13	1	REAR END PANEL TOP GARNISH	\$ S ₁ 69.24	X
14	1	REAR SPARE TYRE PANEL	\$ R ₁ 1,023.36	X
15	1	REAR SPARE TYRE HOLDER	\$ R ₁ 265.20	✓
16	1	REAR SPARE TYRE SPONGE	\$ R ₁ 426.94	✓
SUB TOTAL			\$ 6,943.31	
LESS 10%			\$ 694.33	
DISCOUNTED SUB TOTAL			\$ 6,248.98	
S/NETT				
1	1	REAR BUMPER ADVERTISEMENT LOGO	\$ R ₁ 100.00	60sm
SUB TOTAL			\$ 100.00	
LABOUR				
1		PANEL BEATING	\$ 1,000.00	900
2		SPRAYPAINTING CHARGES	\$ 800.00	750
3		WIRING CHARGES	\$ 40.00	20
4		DASHBOARD WIRING DIAGNOSTIC	\$ 400.00	180
5		TUFF KOTE	\$ 100.00	30
6		REMOVE/REFIX REAR BUMPER SENSOR	\$ 80.00	60
7		REMOVE/REFIX BATTERY CONTROLLER	\$ 80.00	X
SUB TOTAL			\$ 2,500.00	
GRAND TOTAL			\$ 8,848.98	

PLEASE NOTE THAT THE ABOVE IS ONLY AN ESTIMATE. THEREFORE SHOULD THERE BE ANY ADDITIONAL PARTS REQUIRE OR DISCOVER DAMAGE DURING OUR COURSE OF REPAIRS. WE WOULD INFORM YOU ACCORDINGLY FOR THE NECESSARY ACTIONS. PRICES OF PARTS QUOTED ARE SUBJECT TO CHANGE WITHOUT NOTICE.

Not Authorized
 61 Emp & 5000
 Preserving After Paint
 6 days

SOON HOCK MOTOR PTE LTD
 89, 10, 400, 143, 144, 145, 146, 147, 148, 149, 150, 151, 152, 153, 154, 155, 156, 157, 158, 159, 160, 161, 162, 163, 164, 165, 166, 167, 168, 169, 170, 171, 172, 173, 174, 175, 176, 177, 178, 179, 180, 181, 182, 183, 184, 185, 186, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, 216, 217, 218, 219, 220, 221, 222, 223, 224, 225, 226, 227, 228, 229, 230, 231, 232, 233, 234, 235, 236, 237, 238, 239, 240, 241, 242, 243, 244, 245, 246, 247, 248, 249, 250, 251, 252, 253, 254, 255, 256, 257, 258, 259, 260, 261, 262, 263, 264, 265, 266, 267, 268, 269, 270, 271, 272, 273, 274, 275, 276, 277, 278, 279, 280, 281, 282, 283, 284, 285, 286, 287, 288, 289, 290, 291, 292, 293, 294, 295, 296, 297, 298, 299, 300, 301, 302, 303, 304, 305, 306, 307, 308, 309, 310, 311, 312, 313, 314, 315, 316, 317, 318, 319, 320, 321, 322, 323, 324, 325, 326, 327, 328, 329, 330, 331, 332, 333, 334, 335, 336, 337, 338, 339, 340, 341, 342, 343, 344, 345, 346, 347, 348, 349, 350, 351, 352, 353, 354, 355, 356, 357, 358, 359, 360, 361, 362, 363, 364, 365, 366, 367, 368, 369, 370, 371, 372, 373, 374, 375, 376, 377, 378, 379, 380, 381, 382, 383, 384, 385, 386, 387, 388, 389, 390, 391, 392, 393, 394, 395, 396, 397, 398, 399, 400, 401, 402, 403, 404, 405, 406, 407, 408, 409, 410, 411, 412, 413, 414, 415, 416, 417, 418, 419, 420, 421, 422, 423, 424, 425, 426, 427, 428, 429, 430, 431, 432, 433, 434, 435, 436, 437, 438, 439, 440, 441, 442, 443, 444, 445, 446, 447, 448, 449, 450, 451, 452, 453, 454, 455, 456, 457, 458, 459, 460, 461, 462, 463, 464, 465, 466, 467, 468, 469, 470, 471, 472, 473, 474, 475, 476, 477, 478, 479, 480, 481, 482, 483, 484, 485, 486, 487, 488, 489, 490, 491, 492, 493, 494, 495, 496, 497, 498, 499, 500, 501, 502, 503, 504, 505, 506, 507, 508, 509, 510, 511, 512, 513, 514, 515, 516, 517, 518, 519, 520, 521, 522, 523, 524, 525, 526, 527, 528, 529, 530, 531, 532, 533, 534, 535, 536, 537, 538, 539, 540, 541, 542, 543, 544, 545, 546, 547, 548, 549, 550, 551, 552, 553, 554, 555, 556, 557, 558, 559, 560, 561, 562, 563, 564, 565, 566, 567, 568, 569, 570, 571, 572, 573, 574, 575, 576, 577, 578, 579, 580, 581, 582, 583, 584, 585, 586, 587, 588, 589, 590, 591, 592, 593, 594, 595, 596, 597, 598, 599, 600, 601, 602, 603, 604, 605, 606, 607, 608, 609, 610, 611, 612, 613, 614, 615, 616, 617, 618, 619, 620, 621, 622, 623, 624, 625, 626, 627, 628, 629, 630, 631, 632, 633, 634, 635, 636, 637, 638, 639, 640, 641, 642, 643, 644, 645, 646, 647, 648, 649, 650, 651, 652, 653, 654, 655, 656, 657, 658, 659, 660, 661, 662, 663, 664, 665, 666, 667, 668, 669, 670, 671, 672, 673, 674, 675, 676, 677, 678, 679, 680, 681, 682, 683, 684, 685, 686, 687, 688, 689, 690, 691, 692, 693, 694, 695, 696, 697, 698, 699, 700, 701, 702, 703, 704, 705, 706, 707, 708, 709, 710, 711, 712, 713, 714, 715, 716, 717, 718, 719, 720, 721, 722, 723, 724, 725, 726, 727, 728, 729, 730, 731, 732, 733, 734, 735, 736, 737, 738, 739, 740, 741, 742, 743, 744, 745, 746, 747, 748, 749, 750, 751, 752, 753, 754, 755, 756, 757, 758, 759, 760, 761, 762, 763, 764, 765, 766, 767, 768, 769, 770, 771, 772, 773, 774, 775, 776, 777, 778, 779, 780, 781, 782, 783, 784, 785, 786, 787, 788, 789, 790, 791, 792, 793, 794, 795, 796, 797, 798, 799, 800, 801, 802, 803, 804, 805, 806, 807, 808, 809, 810, 811, 812, 813, 814, 815, 816, 817, 818, 819, 820, 821, 822, 823, 824, 825, 826, 827, 828, 829, 830, 831, 832, 833, 834, 835, 836, 837, 838, 839, 840, 841, 842, 843, 844, 845, 846, 847, 848, 849, 850, 851, 852, 853, 854, 855, 856, 857, 858, 859, 860, 861, 862, 863, 864, 865, 866, 867, 868, 869, 870, 871, 872, 873, 874, 875, 876, 877, 878, 879, 880, 881, 882, 883, 884, 885, 886, 887, 888, 889, 890, 891, 892, 893, 894, 895, 896, 897, 898, 899, 900, 901, 902, 903, 904, 905, 906, 907, 908, 909, 910, 911, 912, 913, 914, 915, 916, 917, 918, 919, 920, 921, 922, 923, 924, 925, 926, 927, 928, 929, 930, 931, 932, 933, 934, 935, 936, 937, 938, 939, 940, 941, 942, 943, 944, 945, 946, 947, 948, 949, 950, 951, 952, 953, 954, 955, 956, 957, 958, 959, 960, 961, 962, 963, 964, 965, 966, 967, 968, 969, 970, 971, 972, 973, 974, 975, 976, 977, 978, 979, 980, 981, 982, 983, 984, 985, 986, 987, 988, 989, 990, 991, 992, 993, 994, 995, 996, 997, 998, 999, 1000.

L&S Auto Consultants hereby notify the Repairer of the following:

- To survey before any painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary demand must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:

QUOTATION FOR VEHICLE SHF 1559 Y

PARTS				
1	1	REAR BUMPER	\$	996.72 ✓
2	1	REAR BUMPER SIDE REFLECTOR (RED)	\$	43.20 X
3	1	REAR BUMPER SIDE REFLECTOR CHROME	\$	16.20 X
4	2	REAR BUMPER SENSOR	\$	421.24 LTT
5	4	REAR BUMPER SENSOR BRACKET	\$	73.60 X
6	1	REAR BUMPER CENTRE GRILLE	\$	199.63 ✓
7	1	REAR BUMPER TOWING COVER	\$	26.57 ✓
8	1	REAR BUMPER REINFORCEMENT	\$	605.22 ✓
9	2	REAR BUMPER REINFORCEMENT BRACKET (RH/LH)	\$	360.00 LTT
10	2	REAR TAILLAMP (RH/LH)	\$	1,066.96 LTT
11	1	REAR FENDER SHIELD (LH)	\$	197.28 ✓
12	1	REAR END PANEL	\$	1,151.95 ✓
13	1	REAR END PANEL TOP GARNISH	\$	69.24 X
14	1	REAR SPARE TYRE PANEL	\$	1,023.36 X
15	1	REAR SPARE TYRE HOLDER	\$	265.20 ✓
16	1	REAR SPARE TYRE SPONGE	\$	426.94 ✓
		SUB TOTAL	\$	6,943.31
		LESS 10%	\$	694.33
		DISCOUNTED SUB TOTAL	\$	6,248.98
S/NETT				
1	1	REAR BUMPER ADVERTISEMENT LOGO	\$	100.00 60sm
		SUB TOTAL	\$	100.00
LABOUR				
1		PANEL BEATING	\$	1,000.00 900
2		SPRAYPAINTING CHARGES	\$	800.00 750
3		WIRING CHARGES	\$	40.00 20
4		DASHBOARD WIRING DIAGNOSTIC	\$	400.00 180
5		TUFF KOTE	\$	100.00 30
6		REMOVE/REFIX REAR BUMPER SENSOR	\$	80.00 60
7		REMOVE/REFIX BATTERY CONTROLLER	\$	80.00 ?
		SUB TOTAL	\$	2,500.00
		GRAND TOTAL	\$	8,848.98

PLEASE NOTE THAT THE ABOVE IS ONLY AN ESTIMATE. THEREFORE SHOULD THERE BE ANY ADDITIONAL PARTS REQUIRE OR DISCOVER DAMAGE DURING OUR COURSE OF REPAIRS. WE WOULD INFORM YOU ACCORDINGLY FOR THE NECESSARY ACTIONS. PRICES OF PARTS QUOTED ARE SUBJECT TO CHANGE WITHOUT NOTICE.

Not Notional
11 Imp & 7
Presony After Paint
6 days

SOON HOCK MOTOR PTE LTD
811 To Ang Mo Kio Road, Block 2, #01-15/16, Singapore 569547
Singapore 569547
569547 (T) 569547 Fax: 569547
Email: shm@shmotor.com.sg

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:



Service Request Details

Claim

S9M01PAT

Reference

None

Loss Date

31 May 2019

Report Date

31 May 2019 2:11:26 PM

Request Date

3 June 2019

Due Date

11 June 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

P: William

T: 10.344.17

V: In

E: ✓

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SHF1559Y

(F100000)

E6H-(A)

Service Address

...

Primary Contact/Insured

LEONG YEW KEE

419 ANG MO KIO AVENUE 2, 567865, Singapore

Claim Handler

NG Stacey

6568804351

stacey.ng@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

Catherine Chong (LKK Auto)

From: Soon Hock Motor Pte Ltd <soonhockmotor@yahoo.com.sg>
Sent: Saturday, 1 June, 2019 11:01 AM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Subject: Accident involving SHF 1559 Y & SKK8200Z along Marymount Rd on 31/05/19.
Attachments: 01062019105717.pdf

Categories: Raghav

We refer to the above cited accident.

Investigation reveals that you are the insurer of SKK 8200 Z at the material time

Kindly appoint your surveyor to survey our client's vehicle SHF 1559 Y at our premises urgently.

We enclose the following documents:

- 1) GIA Report & Police Report
- 2) Quotation for SHF 1559 Y
- 3) LTA Search
- 4) Certificate of Insurance

Please note that our client reserves the right to reject the contents/findings of the survey report as they deem fit.

Regards
Claims Department

Soon Hock Motor Pte Ltd
Blk 10 Ang Mo Kio Industrial Park 2A
#01-06 AMK Autopoint
Singapore 568047

Tel: 6483 6016
Fax: 64836015



TP MANDATE IA-S9M01PAT

Type

🔔 Question

Message

Hi Vivian, COR - \$5,000.00 - proceed Loss of Revenue - propose 6 days X \$120 per day, up to max \$150 days LTA search fees \$2.00 - proceed Tks

Reply



SOON HOCK MOTOR PTE LTD

Our Ref: MTP/5078/19

Your Ref: SKK 8200 Z

Date: 29 Jun 2019

WITHOUT PREJUDICE

The Motor Claims Department
LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Ind Park
Singapore 408933

Dear Sir/Madam

RE: ACCIDENT INVOLVING SHF 1559 Y & SKK 8200 Z ALONG MARYMOUNT RD
ON 31 MAY 2019.

We are authorised by the owner of motor vehicle/taxi, SHF 1559 Y, which was involved in the above-mentioned accident to claim damages against you.

The motor vehicle/taxi was surveyed by your appointed appraiser at the premises of M/s Soon Hock Motor Pte Ltd. The accident was caused by your insured's negligent driving and/or management of his vehicle. Therefore, we are claiming property damages and losses sustained by our client against you in connection with the accident based on the appraiser's recommendation

Our claim is as follows:

1) Cost of Repair	S\$ 5,000.00
2) Loss of Revenue	S\$ 1,750.00
3) LTA Search	S\$ 2.00
	<u>S\$ 6,752.00</u>

We enclose herewith the following relevant supporting documents:

- Authorisation Letter
- Final Repair Bill
- GIA Report & Police Report
- LTA Search
- Certificate of Insurance

Any settlement is limited to the aforesaid claim only and does not prejudice our hirer's rights to any personal injury claims and/or losses in future should such a claim arises.

Yours faithfully,



20 June, 2019

LEONG YEW KEE
419 ANG MO KIO AVE 2
SINGAPORE 567865

Dear Sir,

OUR REF : CC4/ASM19009784/Kwb3
YOUR REF : SKK8200Z
ACCIDENT INVOLVING SKK8200Z & SHF1559Y ALONG MARYMOUNT ROAD RIGHT
BEFORE BUSSTOP 53139 ON 31/05/2019

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a third-party claim(s) from **SOON HOCK MOTOR PTE LTD** acting on behalf of the owner of **SHF1559Y** against your motor insurance policy.

Please be informed that your No Claim Discount (NCD) may be affected because of the claim against your policy.

As Insurers, they shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter. Your intent must be formally expressed to AXA and acknowledged by AXA.

Your full co-operation in the handling of the claim is required and kindly submit the following to vicalpeh@lkkauto.com within 7 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Copy of the letter of authorization
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim.

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives or make any compromise or settlement without our prior knowledge and consent. If you receive any correspondence or legal document such as a Writ of Summons in connection with this accident, please forward it to us immediately. You may email it to cst@axa.com.sg or deliver it by hand to AXA Customer Care Centre.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

In the event of receiving and handling of any third-party injury claim(s), we shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6841 2928 or vicalpeh@lkkauto.com. Please quote our claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Jimmy
Case Handler
DID: 6841 2928
Email: vicalpeh@lkkauto.com

c.c. AXA Insurance Pte Ltd (AXA)
(Motor Claims Dept)



HDT SINGAPORE TAXI PTE LTD

REGISTRATION NO. 201609494H

Letter of Authority

To: Whom it may concern,

Accident involving SHP 1559 Y & SKIC 8200 Z
along MAYAMOUNT RD on 21/05/19

We, HDT Singapore Taxi Pte Ltd, Company Registration No.201609494H, located at 47, Jalan Pemimpin #03-05 Singapore 577200, owner of motor vehicle registration No. SHP 1559 Y Insured by MS First Capital Insurance Ltd under Policy No. D-18091940 MFSH/55 do hereby authorize M/s Soon Hock Motor Pte Ltd as our authorized representative to write, negotiate and settle claims on our behalf in our claim against the owner and/or motor vehicle registration No. SKIC 8200 Z in respect of the above-mentioned accident. We also hereby authorize that the agreed settlement sum (cost of repair, loss of use, earnings & rental, survey report fee, LTA fee and GIA report fee) be made in favour of our representative, M/s Soon Hock Motor Pte Ltd and that the said payment be forwarded to them as full and final discharge of our claim.

Date: 31/05/19

Signature: _____

Company stamp if applicable



Address: 47 Jalan Pemimpin Halcyon 2 #03-05 Singapore 577200
Main Line: 6715 3760, Fax: 6258 0774



AXA THIRD PARTY DIRECT SETTLEMENT

Vehicle No:	SKK 8200Z (Insd veh)	Model: BYD E6H
	SHF 1559Y (TP veh)	
Date of Accident/ Time:	31/05/2019	

Repair Estimate	: \$	8,848.98	
Final Repair Cost	: \$	5,000.00	
Loss of Use	: \$	720.00	06 days at \$120.00 per day
Rental (if any)	: \$		days at \$ per day:
LTA / GIA Search Fee	: \$		
Others:	: \$	2.00	
	: \$		
Final Settlement Sum (GLOBAL SUM)	: \$	5,700.00	

Payee Name : SOON HOCK MOTOR PTE LTD

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A)	For Non GIA Registered Workshop:	Agreed Liability: <u>100</u> (%)
B)	For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: _____
	BOLA Liability: _____ (%)	Assessed Liability (*): _____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.		
Remarks:		

NOTE:

- PLEASE EXPRESSLY RESERVE YOUR CLIENT'S RIGHTS IF SO REQUIRED IN THIS SETTLEMENT DOCUMENT.
- THIS SETTLEMENT IS ON A WITHOUT PREJUDICE BASIS AND SHOULD NOT CONSTRUED AS AN ADMISSION OF LIABILITY ON AXA AND THEIR CLIENT/TORTFEASOR IN ANY MANNER WHATSOEVER.
- AXA RESERVES THEIR RIGHTS UNDER THE POLICY TERMS & CONDITIONS AS WELL AS THEIR RIGHTS IN LAW.

Only applicable to rental claim - All document are to be submitted with this settlement confirmation. In the event, rental agreement / invoices are **not received within 7 days** of this signed confirmation, we will automatically revert to loss of use claim per the NIMA rates.

We/I confirmed that this is a **full and final settlement** that we and or our client have/had/has against you (AXA and their policyholder/authorised driver/tortfeasor) for any and all losses (past/present/future) arising from this accident.

We confirmed that we have the authority of our client to act for and on their behalf in this accident.




SOON HOCK MOTOR PTE LTD
 Blk 10 Ang Mo Kio Industrial Park 2
 #01-0500 AMK Singapore
 Singapore 60004
 Tel: 67611111 Fax: 67611111
 Reg. No. 199804869H

Signature of workshop representative / Workshop stamp
 Name of Representative: Chen Yan Feng
 Date:

Signature of Witness / Workshop stamp (if applicable)
 Name of Witness: William
 Date:

Signature of AXA's surveyor/representative:
 Name of AXA's surveyor/Representative:
 Date:



"The contents of this document apply to vehicle damages only. All personal injuries and damages arising therefrom are excluded from the ambit and application of this document."



SOON HOCK MOTOR PTE LTD

HDT SINGAPORE TAXI PTE LTD NO. 47 JALAN PEMIMPIN HALCYON 2 #03-05 SINGAPORE 577200	VEHICLE NO
	SHF 1559 Y
	DATE
	22/06/2019
	INVOICE NO
	005026
	ACC DATE/TIME
	31.05.2019 @ 08:00 HRS

Cost of Repair \$ 5,000.00

TOTAL \$ 5,000.00

(SGD DOLLARS: FIVE THOUSAND ONLY)

Kindly arrange for payment as soon as possible. All cheques must be crossed and made payable to **SOON HOCK MOTOR PTE LTD**.





RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-19-087058

Date of Request: 01/06/2019

Your Ref No:

Online Purchase

Soon Hock Motor Pte Ltd
Blk 10 Ang Mo Kio Industrial Park 2A
#01-05/06 AMK Autopoint
Singapore 568047

Dear Sir/Madam,

Enquiry Date: 01/06/2019
Enquiry By: Chris Lim Gan Koon
TP Vehicle No.: SKK8200Z
Accident Date: 31/05/2019

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SKK8200Z	AXA Insurance Pte Ltd	22/11/2018-21/11/2019	6338 7288

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**
6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-19-087058
Date of Request: 01/06/2019
Your Ref No: Online Purchase

Soon Hock Motor Pte Ltd
Blk 10 Ang Mo Kio Industrial Park 2A
#01-05/06 AMK Autopoint
Singapore 568047

Dear Sir/Madam,

Enquiry Date 01/06/2019
Enquiry By Chris Lim Gan Koon
TP Vehicle No. SKK8200Z
Accident Date 31/05/2019

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.
This is a computer generated document and requires no signature.

For GIARMC Official use:
Date:
☒ GIRO ☐ Cash ☐ Cheque



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM19009784/Kwb3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:WINNIE			Date : 01-08-2019	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKK 8200Z	Veh. Inspected	SHF 1559Y	
Policy No.	CN022230	Coverage (\$)	0.00	
Claim No.	S9M01PAT	Excess (\$)	0.00	
Assign From		Assign Date	03/06/2019	
2. Vehicle Particulars & Condition				
Make & Model	BYD E6H (A)	c.c	0	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	LC0CE4DB2H1006914	Colour	WHITE/GREEN	
Odometer	196909	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/65 R17	PIRELLI	8 mm	
L/H Front Tyre	225/65 R17	PIRELLI	8 mm	
R/H Rear Tyre	225/65 R17	ROVELO	9 mm	
L/H Rear Tyre	225/65 R17	ROVELO	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	31/05/2019	Inspection Date	03/06/2019	
Survey held at	SOON HOCK MOTOR PTE LTD BLK 10 ANG MO KIO INDUSTRIAL PK 2A #01-05/06 AMK AUTOPOINT , SINGAPORE 568047			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHF 1559Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (CONSISTENT)	BENT	996.72	996.72
1	REAR BUMPER SIDE REFLECTOR (RED) (CONSISTENT)	SERVICEABLE	43.20	-
1	REAR BUMPER SIDE REFLECTOR CHROME (CONSISTENT)	SERVICEABLE	16.20	-
4	REAR BUMPER SENSOR (CONSISTENT)	DENTED / SHORTED (2 PCS ONLY)	421.24	210.62
4	REAR BUMPER SENSOR BRACKET (CONSISTENT)	SERVICEABLE	73.60	-
1	REAR BUMPER CENTRE GRILLE (CONSISTENT)	CRACKED	199.63	199.63
1	REAR BUMPER TOWING COVER (CONSISTENT)	MISSING	26.57	26.57
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	BENT	605.22	605.22
2	REAR BUMPER REINFORCEMENT BRACKET (LH/RH) (CONSISTENT)	N/S BENT	360.00	180.00
2	REAR TAILLAMP (RH/LH) (CONSISTENT)	N/S MTG CRACKED	1,066.96	533.48
1	REAR FENDER SHIELD (LH) (CONSISTENT)	CRACKED	197.28	197.28
1	REAR END PANEL (CONSISTENT)	BENT	1,151.95	1,151.95
1	REAR END PANEL TOP GARNISH (CONSISTENT)	SERVICEABLE	69.24	-
1	REAR SPARE TYRE PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	1,023.36	-
1	REAR SPARE TYRE HOLDER (CONSISTENT)	CRACKED	265.20	265.20
1	REAR SPARE TYRE SPONGE (CONSISTENT)	DEFORMED	426.94	426.94
	LESS 10% DISCOUNT		-694.33	-479.36
			6,248.98	4,314.25
SPECIAL NETT ITEMS				
1	REAR BUMPER ADVERTISEMENT LOGO (SN) (CONSISTENT)	NECESSARY	100.00	60.00
			100.00	60.00
LABOUR				
	PANEL BEATING.		1,000.00	900.00
	SPRAYPAINTING CHARGES.		800.00	750.00
	WIRING CHARGES.		40.00	20.00
	DASHBOARD WIRING DIAGNOSTIC.		400.00	180.00

Report Ref No. CC4/ASM19009784/Kwb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TUFF KOTE.		100.00	30.00
	REMOVE/REFIX REAR BUMPER SENSOR .		80.00	60.00
	REMOVE/REFIX BATTERY CONTROLLER.	NOT NECESSARY	80.00	-
			2,500.00	1,940.00
GRAND TOTAL			8,848.98	6,314.25
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,000.00

Report Ref No. CC4/ASM19009784/Kwb3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.


No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part does so at his or her own risk.

Service Request Details

Actions
Next Step
Wait for Approve Invoice
Add Invoice

Claim	59M01/PAT	Actions	
Reference	CC6/ASM190097B4/KwB3a2 	Next Steps	Wait for Approve Invoice
Loss Date	31 May 2019	<div>Add Invoice</div>	
Report Date	31 May 2019 2:11:26 PM		
Request Date	3 June 2019		
Due Date			
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)		
Type of Loss	Third Party Vehicle Damage		
Services	Pending verification - Direct Settlement		

Additional Instructions

Messages	Inventory	History	Documents	Assessment	Metrics	Notes
<div>Document Type <input type="text" value="Document Subtype"/></div> <div> <input type="button" value="Upload Document"/> </div>						
NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED		
 L00Invoice1 (3).pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TIN)	7 August 2019		

