

Mon 10/06 @ 10am
P&R

SMG 697Z

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601
64796624

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company



Acknowledged by Repairer

Signature:

Date:

Steve (LKK) WH 10/6/19, 11am

4-5 days GST REG. NO : M2 - 0020081 - X

03 JUN 2019

ESTIMATE

Estimate No. : **b1 51388**
Date Estimated : **03/06/2019**
Prepared By : **Han Kwan Yong**

Page No. : **1 of 4**

- ESTIMATE REPAIR FOR -

Tan Lau Ming
18 Choa Chu Kang Grove
#10-46

Singapore 688211

- ACCOUNT - **40000**

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMG697Z	WE60338	28/09/2018	520i	0

DESCRIPTION

To replace front bumper including to knock out dented area caused by the accident

1338.75 1487.50 2,550.00

To respray front bumper and front right fender

1557.90 1731 1,923.00

To replace right headlight.

367.20 408 481.00

To check electrical wiring systems at the front section for proper function including adjustments of headlights.

135.00 150 177.00

Sundries.

80 150.00

Total Labour 1: **5,281.00**

DESCRIPTION

C CLIP FOR PLASTIC NUT

QTY 14 PRIC 1.00 VALUE 14.00

RH FOG LAMP SUPPORT

1 64.70 64.70

RH BUMPER GUIDE

1 16.15 16.15

FRT BUMPER PANEL PRIMED (PMA/PDC)

1 1,348.75 1,348.75

LETTERING (LUXURY LINE)

1 46.30 46.30

EXPANDING RIVET D=8MM

10 1.05 10.50

RIGHT HEADLIGHT LED

1 4,855.25 4,855.25

Claim Settlement

Regn No. Claim No.

Date & Time Excess \$

Total Parts : **6,355.65**

Surveyor's Name Sign

Surveyor's Tel Authorised Yes / No

Authorised Date Time

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail

No. of Working Days Recommend

Labour 1 : **5,281.00**

Parts : **6,355.65**

Labour 2 : **0.00**

Excess : **0.00**

Total GST @ 7% : **814.57**

Grand Total : **12,451.22**

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 51388
Date Estimated : 03/06/2019
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -
Tan Lau Ming
18 Choa Chu Kang Grove
#10-46

- ACCOUNT - 238
AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

Singapore 688211

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMG697Z	WE60338	28/09/2018	520i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# ADJUSTABLE BLIND RIVET * <i>npc ✓</i>	3.15	3.00	3.00	9.17 ✓
# EXPANDING RIVET L=11MM * <i>npc ✓</i>	0.90	3.00	3.00	2.62 ✓

Total Labour :	0.00
Total Parts :	11.79
Total Labour & Parts :	11.79