Performance Motors Limited

A member of the Sime Darby Group Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. :

b1 51400

Page No.:

Date Estimated :

03/06/2019

Prepared By : Inthiran A/L Thurasamy

REPAIR FOR -

- ACCOUNT -

121

Tan Boon Yew 2 Jubilee Road AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way

#08-16 Chartis Building

Singapore 079120

Singapore 128523

REGN. NO.

DESCRIPTION

CHASSIS NO.

REGN. DATE

MODEL

MILEAGE

SJP2S

AG14184

21/09/2018

420i/2

DISC. %

To transfer lock mechanism from old to new door include

ORIGINAL PRICE

NETT

conducting checks on new door power window system for proper function

451.00

451.00 ML

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EXPANDING NUT *	2.00	2.00		4.00 mg
# ADJUSTABLE BLIND RIVET *	3.15	2.00		
# EXPANDING RIVET L=11MM *	0.90	3.00		2.70 New
# EXPANDING RIVET L=11MM *	0.90	1.00		0.90 ner
# EXPANDING NUT 7X7 MM *	1.00	3.00		3.00 me

Total Labour:	451.00
Total Parts:	16.90
Total Labour & Parts:	467.90

Performance Motors Limited

A member of the Sime Darby Group Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

Page No.:

Estimate No. : b1 51400

Date Estimated : 03/06/2019

Prepared By : Inthiran A/L Thurasamy

REPAIR FOR -

- ACCOUNT -

Tan Boon Yew 2 Jubilee Road AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way

#08-16 Chartis Building

Singapore 079120

Singapore 128523

REGN. NO.

CHASSIS NO.

REGN. DATE

MODEL

MILEAGE

SJP2S AG14184 21/09/2018 420i/2

-				
	DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
	To replace front RH door and attachments, front RH fender and attachments include making good the rear RH fender, RH side skirting and knocking out dents caused by the accident	2975.00		2,975.00
	To spray paint front RH fender, front RH door, rear RH fender and RH side skirting	3133.00		3,133.00
	To check electrical wiring systems and lightings at the RH section for proper function	150.00		150.00
	To carry out body cavity preservation (2x) (Per panel)	200.00		200.00
#	To transfer lock mechanism from old to new door include conducting checks on new door power window system for proper function	451.00		451.00
	Sundries	80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EXPANDING NUT *	2.00	2.00		4.00
# ADJUSTABLE BLIND RIVET *	3.15	2.00		6.30
# EXPANDING RIVET L=11MM *	0.90	3.00		2.70
# EXPANDING RIVET L=11MM *	0.90	1.00		0.90
FRT RH DOOR	1,584.35	1.00		1,584.35
FRT RH SIDE PANEL	702.65	1.00		702.65
EMBLEM (M)	81.90	1.00		81.90
FRT RH DOOR JOINT SEAL	42.25	1.00		42.25
FRT RH AIR DUCT SIDE PANEL PRIMED	55.95	1.00		55.95
# EXPANDING NUT 7X7 MM *	1.00	3.00		3.00

SUPPLEMENTARY ITEMS

Total Labour:

6,989.00

Performance Motors Limited

A member of the Sime Darby Group Co, Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

Total Parts:	2,484.00
Total Labour & Parts:	9,473.00
Deduction for Excess:	0.00
Total Repair Costs less Excess:	9,473.00
GST @7%:	663.11
Grand Total:	10,136.11

Vic (LKKAuto)

From:

PBSP <pml-pbsp@simedarby.com.sg> Wednesday, 17 July, 2019 4:31 PM

Sent: To:

Taufikh (LKKAuto); Vic (LKKAuto); CS A Team

Subject:

FINAL REPORT/ SJP2S

Attachments:

Final Report SJP2S.pdf; Final Report SJP2S_2.pdf

Dear Sirs

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 6,989.00 Total Parts : 2,484.00

Total Labour & Parts: 9,473.00

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."