

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : **b1 51400**
Date Estimated : **03/06/2019**
Prepared By : **Inthiran A/L Thurasamy**

Page No. :

REPAIR FOR -
Tan Boon Yew
2 Jubilee Road

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 128523

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJP2S	AG14184	21/09/2018	420i/2	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace front RH door and attachments, front RH fender and attachments include making good the rear RH fender, RH side skirting and knocking out dents caused by the accident	2975.00		2,975.00
To spray paint front RH fender, front RH door, rear RH fender and RH side skirting	3133.00		3,133.00
To check electrical wiring systems and lightings at the RH section for proper function	150.00		150.00
To carry out body cavity preservation (2x) (Per panel)	200.00		200.00
# To transfer lock mechanism from old to new door include conducting checks on new door power window system for proper function	451.00		451.00
Sundries	80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EXPANDING NUT *	2.00	2.00		4.00
# ADJUSTABLE BLIND RIVET *	3.15	2.00		6.30
# EXPANDING RIVET L=11MM *	0.90	3.00		2.70
# EXPANDING RIVET L=11MM *	0.90	1.00		0.90
FRT RH DOOR	1,584.35	1.00		1,584.35
FRT RH SIDE PANEL	702.65	1.00		702.65
EMBLEM (M)	81.90	1.00		81.90
FRT RH DOOR JOINT SEAL	42.25	1.00		42.25
FRT RH AIR DUCT SIDE PANEL PRIMED	55.95	1.00		55.95
# EXPANDING NUT 7X7 MM *	1.00	3.00		3.00

SUPPLEMENTARY ITEMS

Total Labour : 6,989.00

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

Total Parts :	2,484.00
Total Labour & Parts :	9,473.00
Deduction for Excess :	0.00
Total Repair Costs less Excess:	9,473.00
GST @7%:	663.11
Grand Total :	10,136.11