



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLP 5544 M

Parts	(a) Cost / List Price Items	\$	18,217.22
	Plus/Less 25%	\$	4,554.31
	Total of Cost / List	\$	13,662.92
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	350.00
Total Parts Cost		\$	14,012.92
Labour		\$	4,130.00
Total		\$	18,142.92

The above total will be subjected to 7% G.S.T.

*Not Authorized
Repair Repair*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Name of Surveyor : Kennerth
Company : LKK
Survey conducted on : 4/6/19 at _____

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 09 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$ _____

(e) Signature of surveyor : Le Date: 4/6/19



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. :
Make & Model :
Chassis No. :

SLP 5544 M

TOYOTA PRIUS

JTDKB3FU103559523

Submit By :
Year Manufacture :
Engine No. :

Carmen Lim

2017

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front support panel LH	1	\$213.50		?
2	Headlamp panel LH	1	\$89.20		?
3	Support panel lower	1	\$387.95		?
4	Headlamp LH	1	\$2,531.60		✓
5	Front bumper	1	\$450.80		✓
6	Front bumper clip	10	\$40.00		✓
7	Front bumper reinforcement - upper	1	\$711.50		?
8	Front bumper reinforcement - lower	1	\$245.30		?
9	Front bumper side retainer RH	1	\$107.20		X
10	Front bumper side retainer LH	1	\$107.20		✓
11	Front bumper upper grille	1	\$321.90		✓
12	Front bumper lower grille	1	\$148.60		✓
13	Front bumper emblem	1	\$87.10		✓
14	Front bumper tow cover LH	1	\$25.70		?
15	Front bumper sponge - upper	1	\$89.81		?
16	Front bumper sponge - lower	1	\$135.70		?
17	Fog lamp LH	1	\$910.70		?
18	Engine under cover	1	\$198.30		?
19	Engine under cover clip	10	\$35.00		?
20	LH front fender	1	\$868.70		✓
21	LH front fender undershield	1	\$195.60		✓
22	LH front fender undershield clip	10	\$25.00		✓
23	LHF fender wording "HYBRID"	1	\$44.17		✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SLP 5544 M** Submit By : **Carmen Lim**
Make & Model : **TOYOTA PRIUS** Year of Manufacture : **2017**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (FRONT BUMPER,BONNET,SUPPORT PANEL, LHF FENDER,LHF DOOR,LHR DOOR,LH SIDE SKIRT)	\$1,600.00	800 - 1100
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (FRONT BUMPER,BONNET,SUPPORT PANEL, LHF FENDER,LHF DOOR,LHR DOOR,LH SIDE SKIRT)	\$1,600.00	1400
3	To remove & refit radiator, condenser to assist work load, to top up A/C gas.	\$150.00	?
4	To remove & refit undercarriage to assist work load.	\$250.00	200
5	To do wheel alignment.	\$150.00	60
6	To remove & refit Door trim, door glass, window regulator, door lock to assist work load.	\$150.00	60
7	To check wiring & focus headlamp	\$50.00	20
8	To tuff coat	\$180.00	60

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.