

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

INDIA

1206L

3105/19

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/LAW/0280/2019
DATE : 29-MAY-2019

DIRECT SETTLEMENT
OWNER CLAIMING LOSS OF USE / RENTAL
CAR AT WORKSHOP / CAR NOT AT WORKSHOP
KINDLY REVERT TO ME ASAP
EMAIL : lawrenceteo@tanchong.com
H/P : 94568832 FAX : 64697472

INDIA INT'L INSURANCE PTE LTD
64 CECIL STREET
#04-05 IOB BUILDING
S(049711)
TEL : 63476100
FAX : 62244174
ATTN:MOTOR CLAIM MANAGER

OWNER'S NAME : GAN CHEE KONG
ADDRESS : 75 BURGUNDY CRESCENT
S(658787)
TELEPHONE NO : 98386966

Lee

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-SHA4994E
VEHICLE NO : SDQ2388G
MODEL CODE : FRLARDWJ11USA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2 MY2017
ENGINE NO : HRA2563930A
CHASSIS NO : SJNFEAJ11U2180341
MILEAGE : 1 KM
DATE IN : 29/05/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : LAWRENCE
ACCIDENT DATE : 28/05/2019

Tanjin 97495749
wp
13/6/19 @ 1115.
Resurvey before paint.
4 days
Tanjin @ 1115 on

Apr
13/06/19.
1115.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SDQ2388G

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	✓
2	RS	SUPPLY & INSTALL REVERSE SENSOR	110.00	✓
3	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	X
4	ZZ/001	REPAIR END PANEL, LH REAR FENDER AND RENEW REAR BUMPER <i>* plus to end panel & Ren LH fender.</i>	1200.00	780. 390 250
5	ZZ/002	S/PAINT REAR BUMPER(2 TONE), END PANEL AND LH REAR FENDER	1500.00	850.
TOTAL LABOUR CHARGES			3030.00	

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SDQ2388G

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
		NETT	LIST	S/NETT	
1 FENDER LH REAR ARC	93829-4EA0A	966.00	?		
2 CANOE RIVET \$6.50 EA X 2	76882-0M000	13.00	?		
3 CLIP BUMPER \$1.20 EA X 02	01553-05933	2.40	new		
4 GROMMET BUMPER \$2.20 EA X 02	01281-00111				4.40 new
5 STAY ASSY-REAR RH	H5210-4EAMA	126.00	?		
6 STAY ASSY-REAR LH	H5211-4EAMA	126.00	?		
7 REINF-BUMPER RR	H5030-4EAMA	619.20	?		
8 ENERGY ABSORBER	85090-HV00A	126.40	?		
9 BRACKET-BUMPER RH	85220-4EA0A	35.90	X		
10 BRACKET-BUMPER LH	85221-4EA0A	35.90	new		
11 RETAINER-BUMPER RH	79184-4EA0A	23.80	X		
12 RETAINER-BUMPER LH	79185-4EA0A	23.80	new		
13 CLIP BUMPER \$7.40 EA X 03	85284-JD00A	22.20	new		
14 FINISHER-REAR BUMPER TOW	85071-HV00A	16.80	X		
15 FASCIA BUMPER	85022-HV30H	717.00	de		
16 SUNDRIES	NPN				20 100.00
17 REVERSE SENSOR(J11 & T32)	SENSOR-TE5140				new 210.00
SUB TOTAL		2854.40	0.00	314.40	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		570.88	0.00	0.00	
GRAND TOTAL		2283.52	0.00	314.40	
OVERALL TOTAL		2597.92			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SDQ2388G

TOTAL LABOUR CHARGES	3030.00
TOTAL SPARE PARTS CHARGES	2597.92

GRAND TOTAL	5627.92 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.