

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

AIM

Automobile Integrated Management Pte Ltd
(Business Reg no. 201605297G)
Office: 28 Sin Ming Lane #07-147
Midview City Singapore 573972
Workshop: 23 Kaki Bukit Ave 4 #04-01 (south wing) Singapore 415933
Email: automim.claim@gmail.com

Acknowledged by Repairer

Signature:

Date:

ESTIMATE

Our Ref: AC2019014/TP/GBF7984J - 24.05.2019

VEHICLE NO :GBF7984J TOYOTA DYNA

ITEMS QTY PARTICULAR

- | | | | |
|---|---|---------------------|---------|
| 1 | 1 | TAIL GATE | |
| 2 | 1 | SIDE GATE RH | 2101.00 |
| 3 | 1 | TAIL GATE HANDLE RH | |
| 4 | 1 | TAIL GATE LOCK RH | |
| 5 | 1 | REAR FENDER RH | |

AMOUNT S\$

2,100.00	X
2,560.00	
195.00	
210.00	
210.00	
\$ 5,275.00	
\$ 1,318.75	
\$ 3,956.25	

LESS 25%

SPECIAL NETT ITEMS

- | | | | |
|---|---|--------------------------------|----------------|
| 6 | 1 | TAIL GATE COMPANY NAME STICKER | |
| 7 | 1 | SIDE GATE COMPANY NAME STICKER | |
| 8 | 1 | TRUCK STICKER | 70/400 sticker |

AMOUNT S\$

280.00	250
320.00	300
25.00	10
\$ 625.00	

LABOUR & MISCELLANEOUS:

- | | | | |
|----|--|----------|-----|
| 9 | To remove damaged body parts with all necessary components/attachments apply hot-works where necessary repair, reshape body dented panels in accordance with factory specifications replace new parts refit and align into position refit all necessary components/attachments | 1,000.00 | 400 |
| 10 | To spray paint replaced/repared body parts inclusive of preparatory works and painting materials | 800.00 | 600 |
| 11 | To remove,refix rear cargo box aluminium panels | 200.00 | 50 |

\$ 2,000.00

not added
also
To be paid after rep-
4/6/19
Hdn

L/S \$ 2650

P-2311
25%
P-1737-25
S.N-560.00
Calm-1050.02
3343.2
202
267