

12/01/2003

ASS. REC. BY:

REF:

CS/F0119009834/Ked3 n2

Special Instruction:

SUPERVISOR:

ASSIGNMENT (Office)

From (Person):

Karen (COS)

of

FBI

Date/Time:

3/6/2019 6:48pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

8JV924SS

Insured:

8HC1326T

at Workshop m/s

K Kim Hin

Tel:

64522018

of

160 S/W #02-20

Policy No:

Claim No:

D19003560MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

3/5/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time

Action/Instruction ()

Estimate

8JV924SS-X

8HC1326T-X

04/06/19 @ 16:50 pm

revised PA to Karen via email

ASS. REC. BY:

REF: *FCV*

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: *822k*

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: *10* days Res.: Yes or NoLum Sum: *20* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: *STV 9245*Yr Regn: *02, 10*

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: *Honda*Colour: *White*Sp. Reading: *139979*

Eng/No: _____

C/No: *JH MRN 6860 95200800*Gen. Cond: *Good* / Fair / Poor / BurntSteering: *In order* / Jammed / Leaked / Burnt orBrake: *In order* / Jammed / Leaked / Burnt orMod: *NII* / S/Rlm / STD A/Rlm orTyre Size: *F Achilles 205/55R16*R: *mic*BS / DUN / EXNOVA / GY / FS / LIZA / *WIC* / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

R/Bal. *9* mmL/Bal. *9* mmD.O.A. *27/5/19*

Survey held at _____

Rear

R/Bal. *8* mmL/Bal. *8* mmD.O.I. *31/5/19*

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The *WIC* / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 File pass to*3/6* L/Sy @ Fk Confirm Prices*(\$ 17,598.48 Red-72%)**MV - \$ 22k**LTA - \$ 14,411.00**NCH - \$ 7,589.00*

RECEIVED 17 OCT 2019

Date/Time, File Pass to?

17/10/19☐ : Prell. Report☒ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: *10* / confirm with shirleyResurvey No. of Trip: *1*Survey Fee: *170 + 225*Transportation: *50*

S + R.S. \$

Fees: *32*

Others

TOTAL

477

Report Format :

Lump Sum / I.B.I. (\$) *7,000/- 45*Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)*15x15=225*



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19003560MFSH

Date: 04 June 2019

Our Ref: CS/FCI19009834/Ksd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SJV 9245S

Please be informed that we had conducted the inspection of the abovementioned vehicle on 31/05/2019 at the premises of M/s K.Kim Hin Automotive Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ 24,598.48
Revised Estimate Amount	: S\$ 13,078.12
"Check" Items Amount	: S\$ 9,815.28
Total	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the front o/s portion.



Comments/ Present Status:

Damages Consistent.

Repair days: 10 days

Yours faithfully,
Kenneth Kong
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	29-05-2019	Our Ref No. D19003560MFSH
Accident Date	27-05-2019	Claim Type. Third Party
Insured Vehicle	SHC1326T	Third Party Vehicle. SJV9245S
Survey Location	160 SIN MING DRIVE #02-20SIN MING AUTOCITY	
Contact Person.	SANDRA	
Contact No.	64527018/ 96222116	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	K. KIM HIN AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Tuesday, 4 June 2019 4:50 PM
To: 'Karen Tan'; 'CWS Motor Claims'
Cc: assignments; SUR
Subject: RE: SURVEY ASSESSMENT - D19003560MFSH/1
Attachments: SJV 9245S - Preli Advise .pdf

Dear Karen,

Enclosed preliminary revised of vehicle SJV 9245S.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Tuesday, 4 June 2019 10:07 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19003560MFSH/1

Dear Sir/Madam,

Thank you for the assignment.

Best Regards,

Shiau Chan on behalf of G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Monday, 3 June 2019 6:48 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Karen Tan <karentan@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19003560MFSH/1

Dear Sir/Mdm,

We refer to the above reference.


Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

BMW PREMIUM SELECTION.

CERTIFIED PRE-OWNED BY PERFORMANCE PREMIUM SELECTION.

[Find out more](#)


Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

Jaguar XF 2.2 Diesel at \$101,800



Beautiful condition
StarAd



Browse by Category ▼

Sort by Date Posted ▼ 20 results/page ▼

3 vehicles

Honda Stream

Advanced Search:

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection								
Honda Stream		Any	Any	2010	Any	Any	Any	Available
	Honda Stream 1.8A	\$21,800	\$12,790 /yr	14-Jan-2010	1,799 cc	-	MPV	Available
One Owner Unit. Practical And Good Fuel Efficiency Family Car Ideal For Daily Drives. Car Is In Good Condition. Good For COE Extension. Must View. Selling Cheap! Hurry! View Now. Flexible Loan And Hig...								
Car Empire Automobiles Pte Ltd								
Posted: 02-Jun-2019 Tags: 2010 Honda Stream, 2010 honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used Honda								
	Honda Stream 1.8A X	\$26,800	\$11,820 /yr	12-Oct-2010	1,799 cc	96,000 km	MPV	Available
New 5 Years Or 10 Years COE Available. Immaculate Condition Coupled With Well Maintained. Good For Drivers With Kids Or Big Families. 100% Loan Available Coupled With Competitive Interest Rates. Do Ca...								
Posted: 01-Jun-2019 Tags: 2010 Honda Stream, 2010 honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used Honda								
	Honda Stream 1.8A (New 5-yr COE)	\$39,800	\$7,950 /yr	19-Jan-2010	1,799 cc	124,462 km	MPV	Available
Options To Renew COE 10 Years At \$59800! Well Maintained, Excellent Condition, Accident Free, Bank And In House Loan Available, Trade In Are Welcome, Powerful Engine And Smooth Transmission, Buy With ...								
Posted: 31-May-2019 Tags: 2010 Honda Stream, 2010 honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used Honda								

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view Expired ads

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Honda Stream, Honda Stream Singapore, used Honda Stream Singapore, used Honda Stream, used vehicles Singapore or even buy used Honda Stream Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow [sgCarMart.com](#)
[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

Compare

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1551H
Vehicle Details	
Vehicle No.:	SJV9245S
Vehicle to be Exported:	No
Intended Deregistration Date:	28 May 2019
Vehicle Make:	HONDA
Vehicle Model:	STREAM 1.8L A
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	R18A13800805
Chassis No.:	JHMRN68609S200800
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$25,402.00
Original Registration Date:	23 Feb 2010
First Registration Date:	23 Feb 2010
Transfer Count:	4
Actual ARF Paid:	\$25,402.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Feb 2020
PARF Rebate Amount:	\$12,701.00
Intended COE Rebate Details	
COE Expiry Date:	22 Feb 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$23,180.00
COE Rebate Amount:	\$1,710.00
Total Rebate Amount:	\$14,411.00

The information contained herein is correct as at 28 May 2019

OK

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

No. : 30478

Vehicle Insured : SHC 1326 T
Accident Date : 27-May-2019

Date : 28-May-2019

Our Ref : 190282 () / SANDRA

PAGE : 1

ZHENG FU(MDM)
Singapore

Not Ashore
Resurvey After Paint
L/Sing B?

ESTIMATED COST OF REPAIR FOR HONDA STREAM 1.8L A (2010) SJV9245S

1 pc	front bumper			<i>Pr</i>	635.60	—
2 pcs	front bumper side retainer (LH/RH)	@ S\$ 20.50		<i>Pr</i>	41.00	—
10 pcs	front bumper clips	@ S\$ 3.90		<i>Pr</i>	39.00	—
1 pc	o/s front bumper fog cover			<i>Pr</i>	24.40	X
1 pc	front bumper reinforcement			<i>Pr</i>	218.80	—
1 pc	front grille			<i>CM</i>	218.10	—
1 pc	front grille outer chrome				210.30	?
1 pc	front grille logo				23.40	?
8 pcs	front grille clips	@ S\$ 3.90		<i>Pr</i>	31.20	—
1 pc	front grille top garnish			<i>Pr</i>	48.60	X
10 pcs	front grille top garnish clips	@ S\$ 3.90		<i>Pr</i>	39.00	X
2 pcs	headlamp assy (LH/RH) <i>o/c CM</i>	@ S\$ 603.80			1,207.60	4
2 pcs	headlamp lower bracket (LH/RH)	@ S\$ 36.50		<i>o/c CM</i>	73.00	4
1 pc	o/s front fender			<i>Pr</i>	486.20	—
1 pc	o/s front fender inner shield			<i>Pr</i>	82.70	X
8 pcs	o/s front fender inner shield clips	@ S\$ 3.50		<i>Pr</i>	28.00	X
1 pc	o/s front fender inner top garnish			<i>Pr</i>	36.50	—
3 pcs	o/s front fender inner top garnish clips	@ S\$ 3.50		<i>Pr</i>	10.50	—
1 pc	o/s front fender inner bracket			<i>Pr</i>	15.00	X
1 pc	o/s front fender inner panel			<i>Pr</i>	81.80	X
1 pc	o/s front wheel housing			<i>Pr</i>	472.40	X
1 pc	o/s front chassis member			<i>Pr</i>	587.80	X
1 pc	front support panel			<i>Pr</i>	496.20	—
1 pc	bonnet			<i>Pr</i>	638.90	—
2 pcs	bonnet hinges (LH/RH)	@ S\$ 38.90		<i>Pr</i>	77.80	—
1 pc	bonnet lock			<i>Pr</i>	85.10	X

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurer's Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Vehicle Insured : SHC 1326 T
Our Ref : 190282

Page : 2
No. : 30478

1 pc	bonnet lock cover	15.00	X
1 pc	horn wireharness	2,100.00	?
1 pc	air con condenser	840.10	?
1 pc	air con condenser liquid pipe	197.00	?
1 pc	air con condenser discharge pipe	235.90	?
1 pc	air con condenser suction pipe	105.00	?
1 pc	air con compressor	1,089.40	?
1 pc	alternator	1,580.40	?
1 pc	radiator	1,507.00	?
2 pcs	centre pillar inner trim-lower @ S\$180.00 (LH/RH)	360.00	?
1 pc	driver seat belt	694.00	✓
1 pc	driver seat frame with mechanism	1,500.00	?
1 pc	steering air bag	1,880.90	✓
1 pc	steering clock spring	300.00	✓
1 pc	air con control unit	952.80	✓
1 pc	o/s front crash sensor	189.00	✓
1 pc	front passenger air bag	2,236.80	✓
1 pc	front passenger seat belt	694.00	✓
1 pc	dashboard	768.80	✓
1 pc	engine mounting - LH	230.40	?
1 pc	engine mounting - RH	291.70	?
1 pc	engine mounting - top	107.80	?
1 pc	engine mounting - rear	92.10	?
1 pc	wiper washer tank	48.60	?
		23,925.60	
Less 20% :		-4,785.12	
		19,140.48	
1 pc	front number plate	40.00	sn ✓
1 pc	radiator coolant	48.00	sn

1100 1,800.00

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

Vehicle Insured : SHC 1326 T
Our Ref : 190282

Page : 3
No. : 30478

To focus headlamps. To check front wiring and lighting operation.

50.00 200

To remove and refit front seat assy trim board and carpet to facilitate repairing works

180.00 7

To remove aircon condenser, pipes and driers. Vacuum and recharge gas

100.00 ✓

To apply undersealing

120.00 900

To remove and renew front instrument panel assy, to rewiring and transfer instrument fittings.

280.00 ?

To remove and renew air bag sensors seat belts assy, to rewiring and re-setting program

300.00 2400

To remove and refit engine assy in order to facilitate repairing works

300.00 ?

To dismantle and check front under-carriages. To replace affected portions.

240.00 ?

To conduct front wheel alignment test.

100.00 ?

To check and realignment on chassis member.

300.00 ?

To putty and respray on affected portions.

1,600.00 12000

Total : S\$24,598.48

Singapore Dollars Twenty Four Thousand Five Hundred and Ninety Eight and Cents Forty Eight Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

No. : 30478

Vehicle Insured : SHC 1326 T
Accident Date : 27-May-2019

Date : 28-May-2019

Our Ref : 190282 () / SANDRA

PAGE : 1

ZHENG FU(MDM)
Singapore

Not Authorised
Recovery After Repair
L/Lamp & ?

ESTIMATED COST OF REPAIR FOR HONDA STREAM 1.8L A (2010) SJV9245S

1 pc	front bumper			<i>By</i>	635.60	—
2 pcs	front bumper side retainer (LH/RH)	@ S\$ 20.50	<i>DIY</i>	41.00	—	
10 pcs	front bumper clips	@ S\$ 3.90	<i>By</i>	39.00	—	
1 pc	o/s front bumper fog cover		<i>By</i>	24.40	X	
1 pc	front bumper reinforcement		<i>By</i>	218.80	—	
1 pc	front grille		<i>CM</i>	218.10	—	
1 pc	front grille outer chrome /		<i>By</i>	210.30	—	
1 pc	front grille logo /		<i>By</i>	23.40	—	
8 pcs	front grille clips	@ S\$ 3.90	<i>By</i>	31.20	—	
1 pc	front grille top garnish /		<i>By</i>	48.60	X	
10 pcs	front grille top garnish clips	@ S\$ 3.90	<i>By</i>	39.00	X	
2 pcs	headlamp assy (LH/RH) / <i>o/s CM</i>	@ S\$ 603.80		1,207.60	—	2 pcs <i>By</i>
2 pcs	headlamp lower bracket (LH/RH)	@ S\$ 36.50	<i>By</i>	73.00	—	2 pcs <i>By</i>
1 pc	o/s front fender		<i>By</i>	486.20	—	
1 pc	o/s front fender inner shield		<i>By</i>	82.70	X	
8 pcs	o/s front fender inner shield clips	@ S\$ 3.50	<i>By</i>	28.00	X	
1 pc	o/s front fender inner top garnish		<i>DIY</i>	36.50	—	
3 pcs	o/s front fender inner top garnish clips	@ S\$ 3.50	<i>By</i>	10.50	—	
1 pc	o/s front fender inner bracket		<i>n</i>	15.00	X	
1 pc	o/s front fender inner panel		<i>n</i>	81.80	X	
1 pc	o/s front wheel housing		<i>n</i>	472.40	X	
1 pc	o/s front chassis member		<i>n</i>	587.80	X	
1 pc	front support panel		<i>By</i>	496.20	—	
1 pc	bonnet		<i>By</i>	638.90	—	
2 pcs	bonnet hinges (LH/RH)	@ S\$ 38.90	<i>DIY</i>	77.80	—	
1 pc	bonnet lock		<i>n</i>	85.10	X	

12 days
Limit \$7k

Con't Page 2 ...

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Vehicle Insured : SHC 1326 T
Our Ref : 190282

Page : 2
No. : 30478

1 pc	bonnet lock cover	sn 15.00	X
1 pc	horn wireharness	R 2,100.00	X local repair
1 pc	air con condenser	TTIPu 840.10	✓
1 pc	air con condenser liquid pipe	nd 197.00	✓
1 pc	air con condenser discharge pipe	Ru 235.90	✓
1 pc	air con condenser suction pipe	R 105.00	✓
1 pc	air con compressor	nd/Tu 1,089.40	✓
1 pc	alternator	sn 1,580.40	X
1 pc	radiator	R 1,507.00	✓
2 pcs	centre pillar inner trim-lower @ S\$180.00 (LH/RH)	sn 360.00	X
1 pc	driver seat belt	Tu 694.00	✓
1 pc	driver seat frame with mechanism	sn 1,500.00	X
1 pc	steering air bag	Ru 1,880.90	✓
1 pc	steering clock spring	sn 300.00	✓
1 pc	air con control unit	nd 952.80	✓
1 pc	o/s front crash sensor	nd 189.00	✓
1 pc	front passenger air bag	Ru 2,236.80	✓
1 pc	front passenger seat belt	Tu 694.00	✓
1 pc	dashboard	Tu 768.80	✓
1 pc	engine mounting - LH	sn 230.40	X
1 pc	engine mounting - RH	sn 291.70	X
1 pc	engine mounting - top	sn 107.80	X
1 pc	engine mounting - rear	sn 92.10	X
1 pc	wiper washer tank	nd 48.60	✓

23,925.60
Less 20% : -4,785.12
----- 19,140.48

1 pc front number plate
1 pc radiator coolant

nd 40.00 sn
R 201.00 sn

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

1100 1,800.00

Supplies

1pc Engine Sub-Frame - 1118.70 Bu

1pc Fan Belt. 132.00 Gr 508sn

Con't Page 3 ...

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Vehicle Insured : SHC 1326 T
Our Ref : 190282

Page : 3
No. : 30478

To focus headlamps. To check front wiring and lighting operation.

50.00 201

To remove and refit front seat assy trim board and carpet to facilitate repairing works

nn 180.00 X

To remove aircon condenser, pipes and driers. Vaccum and recharge gas

100.00 ✓

To apply undersealing

120.00 901

To remove and renew front instrument panel assy, to rewiring and transfer instrument fittings.

ave 280.00 2001

To remove and renew air bag sensors seat belts assy, to rewiring and re-setting program

300.00 2401

To remove and refit engine assy in order to facilitate repairing works

300.00 2501

To dismantle and check front under-carriages. To replace affected portions.

240.00 1801

To conduct front wheel alignment test.

100.00 601

To check and realignment on chassis member.

300.00 2501

To putty and respray on affected portions.

1,600.00 12001

Total : S\$24,598.48

25625.44

Singapore Dollars Twenty Four Thousand Five Hundred and Ninety Eight and Cents Forty Eight Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19009834/Ksd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 21-10-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 1326T	Veh. Inspected	SVJ 9245S	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19003560MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	03/06/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA STREAM (A)	c.c	1799	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	JHMRN68609S200800	Colour	WHITE	
Odometer	139979	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	ACHILLES	9 mm	
L/H Front Tyre	205/55 R16	ACHILLES	9 mm	
R/H Rear Tyre	205/55 R16	MICHELIN	8 mm	
L/H Rear Tyre	205/55 R16	MICHELIN	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.THE CHASSIS FRAME AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/05/2019	Inspection Date	03/06/2019	
Survey held at	K KIM HIN AUTOMOTIVE PTE LTD 160 SIN MING DRIVE #02-20 SIN MING AUTO CITY SINGAPORE 575722			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJV 9245S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	BENT	635.60	635.60
2	FRONT BUMPER SIDE RETAINER (LH/RH) @\$20.50	DISTORTED	41.00	41.00
10	FRONT BUMPER CLIPS @\$3.90	NECESSARY	39.00	39.00
1	O/S FRONT BUMPER FOG COVER	SERVICEABLE	24.40	-
1	FRONT BUMPER REINFORCEMENT	BENT	218.80	218.80
1	FRONT GRILLE	CRACKED	218.10	218.10
1	FRONT GRILLE OUTER CHROME	MTG CRACKED	210.30	210.30
1	FRONT GRILLE LOGO	NECESSARY	23.40	23.40
8	FRONT GRILLE CLIPS @\$3.90	NECESSARY	31.20	31.20
1	FRONT GRILLE TOP GARNISH	DENTED	48.60	48.60
10	FRONT GRILLE TOP GARNISH CLIPS @\$3.90	NECESSARY	39.00	39.00
2	HEADLAMP ASSY (LH/RH) @\$603.80	O/S CRACKED / N/S MTG CRACKED	1,207.60	1,207.60
2	HEADLAMP LOWER BRACKET (LH/RH) @\$36.50	CRACKED	73.00	73.00
1	O/S FRONT FENDER	BUCKLED	486.20	486.20
1	O/S FRONT FENDER INNER SHIELD	SERVICEABLE	82.70	-
8	O/S FRONT FENDER INNER SHIELD CLIPS @\$3.50	NOT NECESSARY	28.00	-
1	O/S FRONT FENDER INNER TOP GARNISH	DISTORTED	36.50	36.50
3	O/S FRONT FENDER INNER TOP GARNISH CLIPS @\$3.50	NECESSARY	10.50	10.50
1	O/S FRONT FENDER INNER BRACKET	TO REPAIR SEE LABOUR	15.00	-
1	O/S FRONT FENDER INNER PANEL	TO REPAIR SEE LABOUR	81.80	-
1	O/S FRONT WHEEL HOUSING	TO REPAIR SEE LABOUR	472.40	-
1	O/S FRONT CHASSIS MEMBER	TO REPAIR SEE LABOUR	587.80	-
1	FRONT SUPPORT PANEL	BENT	496.20	496.20
1	BONNET	BENT	638.90	638.90
2	BONNET HINGES (LH/RH) @\$38.90	DISTORTED	77.80	77.80
1	BONNET LOCK	TO REPAIR SEE LABOUR	85.10	-
1	BONNET LOCK COVER	SERVICEABLE	15.00	-

Report Ref No. CS/FCI19009834/Ksd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	HORN WIREHARNESS	TO REPAIR SEE LABOUR	2,100.00	-
1	AIR CON CONDENSER	TWISTED / PUNCTURE	840.10	840.10
1	AIR CON CONDENSER LIQUID PIPE	DENTED	197.00	197.00
1	AIR CON CONDENSER DISCHARGE PIPE	PUNCTURE	235.90	235.90
1	AIR CON CONDENSER SUCTION PIPE	BENT	105.00	105.00
1	AIR CON COMPRESSOR	DENTED / JAMMED	1,089.40	1,089.40
1	ALTERNATOR	SERVICEABLE	1,580.40	-
1	RADIATOR	BENT	1,507.00	1,507.00
2	CENTRE PILLAR INNER TRIM-LOWER (LH/RH) @\$180.00	SERVICEABLE	360.00	-
1	DRIVER SEAT BELT	JAMMED	694.00	694.00
1	DRIVER SEAT FRAME WITH MECHANISM	SERVICEABLE	1,500.00	-
1	STEERING AIR BAG	BURST	1,880.90	1,880.90
1	STEERING CLOCK SPRING	NECESSARY	300.00	300.00
1	AIR CON CONTROL UNIT	NECESSARY	952.80	952.80
1	O/S FRONT CRASH SENSOR	NECESSARY	189.00	189.00
1	FRONT PASSENGER AIR BAG	BURST	2,236.80	2,236.80
1	FRONT PASSENGER SEAT BELT	JAMMED	694.00	694.00
1	DASHBOARD	TORN	768.80	768.80
1	ENGINE MOUNTING-LH	SERVICEABLE	230.40	-
1	ENGINE MOUNTING-RH	SERVICEABLE	291.70	-
1	ENGINE MOUNTING-TOP	SERVICEABLE	107.80	-
1	ENGINE MOUNTING-REAR	SERVICEABLE	92.10	-
1	WIPER WASHER TANK	DENTED	48.60	48.60
1	ENGINE SUB FRAME (ADDITIONAL)	BUCKLED	1,118.70	1,118.70
	LESS 20% DISCOUNT		-5,008.86	-3,477.94
			20,035.44	13,911.76
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE (SN)	DENTED	40.00	40.00
1	RADIATOR COOLANT (SN)	NECESSARY	48.00	20.00
1	FAN BELT (ADDITIONAL)(50%)(SN)	CUT	132.00	66.00
			220.00	126.00

Report Ref No. CS/FCI19009834/Ksd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REMOVE,CUT OUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW AFFECTED PARTS.INCLUSIVE OF THE REPAIR OF O/S FRONT FENDER INNER BRACKET,O/S FRONT FENDER INNER PANEL,O/S FRONT WHEEL HOUSING,O/S FRONT CHASSIS MEMBER,BONNET LOCK AND HORN WIREHARNES.		1,800.00	1,100.00
	TO FOCUS.TO CHECK FRONT WIRING AND LIGHTING OPERATION.		50.00	20.00
	TO REMOVE AND REFIT FRONT SEAT ASSY TRIM BOARD AND CARPET TO FACILITATE REPAIRING WORKS.	NOT NECESSARY	180.00	-
	TO REMOVE AIRCON CONDENSER,PIPES AND DRIERS.VACCUM AND RECHARGE GAS.		100.00	100.00
	TO APPLY UNDERSEALING.		120.00	90.00
	TO REMOVE AND RENEW FRONT INSTRUMENT PANEL ASSY,TO REWIRING AND TRANSFER INSTRUMENT FITTINGS.		280.00	200.00
	TO REMOVE AND RENEW AIR BAG SENSORS SEAT BELTS ASSY,TO REWIRING AND RE-SETTING PROGRAM.		300.00	240.00
	TO REMOVE AND REFIT ENGINE ASSY IN ORDER TO FACILITATE REPAIRING WORKS.		300.00	250.00
	TO DISMANTLE AND CHECK FRONT UNDER-CARRIAGES.TO REPLACE AFFECTED PORTIONS.		240.00	180.00
	TO CONDUCT FRONT WHEEL ALIGNMENT TEST.		100.00	60.00
	TO CHECK AND REALIGNMENT ON CHASSIS MEMBER.		300.00	250.00
	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.		1,600.00	1,200.00
			5,370.00	3,690.00
	GRAND TOTAL		25,625.44	17,727.76
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			7,000.00

Report Ref No. CS/FCI19009834/Ksd3n2

MARKET VALUE: \$22,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$14,411.00=NETT VALUE: \$7,589.00

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.