

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Vehicle Insured : SHC 1326 T
Our Ref : 190282

Page : 2
No. : 30478

- 1 pc bonnet lock cover
- 1 pc horn wireharness
- 1 pc air con condenser ✓
- 1 pc air con condenser liquid pipe ✓
- 1 pc air con condenser discharge pipe ✓
- 1 pc air con condenser suction pipe ✓
- 1 pc air con compressor ✓
- 1 pc alternator x
- 1 pc radiator ✓
- 2 pcs centre pillar inner trim-lower @ S\$180.00 (LH/RH) x
- 1 pc driver seat belt
- 1 pc driver seat frame with mechanism
- 1 pc steering air bag
- 1 pc steering clock spring
- 1 pc air con control unit
- 1 pc o/s front crash sensor
- 1 pc front passenger air bag
- 1 pc front passenger seat belt
- 1 pc dashboard
- 1 pc engine mounting - LH ✓
- 1 pc engine mounting - RH x
- 1 pc engine mounting - top ✓
- 1 pc engine mounting - rear x
- 1 pc wiper washer tank ✓

sn 15.00 x
R 2,100.00 x Local Repair
T-TIPu 840.10 ✓
Rd 197.00 ✓
Rn 235.90 ✓
Rn 105.00 ✓
Rd/Tm 1,089.40 ✓
Rn 1,580.40 x
Rn 1,507.00 ✓
Rn 360.00 x
Tm 694.00 ✓
Rn 1,500.00 x
Rn 1,880.90 ✓
Rn 300.00 ✓
Rn 952.80 ✓
Rn 189.00 ✓
Rn 2,236.80 ✓
Tm 694.00 ✓
Tn 768.80 ✓
Rn 230.40 x
Rn 291.70 x
Rn 107.80 x
Rn 92.10 x
Rd 48.60 ✓

23,925.60

Less 20% : -4,785.12

19,140.48

- 1 pc front number plate
- 1 pc radiator coolant

Rd 40.00 sn
Rn 201n 48.00 sn

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

1100 1,800.00

Supplement

1pc Engine Sub-Frame - 1118.70 Bn

1pc Fan Belt. 132.00 Cn 509sn

Con't Page 3 ...