

ASS. REC. BY:

REF:

09/FCI(9009845/49d3) n2

Special Instructions:

Surveyor:

Karon

ASSIGNMENT (Office)

From (Person):

Karen Tan

of

FCI

Date/Time:

03/6/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLJ 96560

Insured:

SHA 1486A

at Workshop n/s

Zoom Automobiles

Tel:

94507920 Elin Cai

of

120 Bedok Reservoir Rd # 08-1339

Policy No:

Claim No:

019003582MESH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

29/5/19

(Client's Record)

wpi

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle:

IN/OUT

Date/Time	Action/Instruction
	ishmall ()
	SLJ 96560 x
	SHA 1486A x
06/6/19 @ 11am	informed Karen Tan, we are pending for estimate from repairer.
19/6/19 @ 2.45pm	revised to Karen Tan by email.

(06/11/13) wef

ASS. REC. BY: Marcus

REF:

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: S L J 9 6 5 8 6

at Workshop m/s 2000

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 27k.

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: ☒ Consistent? : Yes or No

Est. Repairs: 4 days Res: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

31/1/2023

Vehicle: IN / OUT

Date: Person Contacted:

Date / Time Action / Instruction

L1A18927

nett 873
3y5. Sub.

Veh No: SLJ96586 Yr Regn: 2, 08

Type: M.C. / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make: mer Benz C180K c.c 1796

Colour: red A/C: Insured / Std / NI / NA

Sp. Reading 195331 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 29/5/19 D.O.I. 4/6/19

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date / Time

Action / Instruction

19/6/19 d/s 7100 confirmed with sls. (Red 12204.57, 63%)

RECEIVED 19 JUN 2019

mv: 27k

LTA: 18,927.00

nett: 8,073.00

Date/Time, File Pass to?

☐

Preli. Report

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format:

Lump Sum / I.B.I. (\$

TOTAL

9x15: 135

170+135

50

50+50

69

524



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19003582MFSH

Date: 19 June 2019

Our Ref: CS/FCI19009845/Uqd3

The Motor Claims Department
MS First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLJ 9656D .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 04/06/2019 at the premises of M/s ZOOM AUTOWERKS, and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 19,304.57</u> .
Revised Estimate Amount	: <u>S\$ 7,100.00 (Lump Sum)</u> .
"Check" Items Amount	: <u>S\$ -</u> .
Market Value	: <u>S\$ -</u> .
LTA Reimbursement Value	: <u>S\$ -</u> .
Nett Value	: <u>S\$ -</u> .

Description of Damage:

The vehicle sustained damages at the n/s front portion. The undercarriage affected due to collision.



Yours faithfully

CHUA KANG SENG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	30-05-2019	Our Ref No. D19003582MFSH
Accident Date	29-05-2019	Claim Type. Third Party
Insured Vehicle	SHA1486A	Third Party Vehicle. SLJ9656D
Survey Location	130 BEDOK RESERVOIR ROAD#08-1339	
Contact Person.	ELIN CAI	
Contact No.	01 94507920	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

(1/1)
Mawu

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	ZOOM AUTOWERKS PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 19 June 2019 2:49 PM
To: 'CWS Motor Claims'; assignments
Cc: 'Karen Tan'; SUR
Subject: RE: SURVEY ASSESSMENT - D19003582MFSH/1
Attachments: CSFCI19009845Uqd3.pdf

Dear Karen,

Enclosed herewith preliminary advice of SLJ 9656D.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 6 June 2019 11:11 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19003582MFSH/1

Dear Karen,

Please be informed that we have inspected the vehicle SLJ 9656D on 04/06/2019.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 4 June 2019 10:00 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19003582MFSH/1

Dear Sir/Madam,

Thank you for the assignment.

Best Regards,

Shiau Chan on behalf of G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 6 June 2019 11:11 AM
To: 'CWS Motor Claims'; assignments
Cc: 'Karen Tan'; SUR
Subject: RE: SURVEY ASSESSMENT - D19003582MFSH/1

Dear Karen,

Please be informed that we have inspected the vehicle SLI 9656D on 04/06/2019.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sjewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 4 June 2019 10:00 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19003582MFSH/1

Dear Sir/Madam,

Thank you for the assignment.

Best Regards,

Shiau Chan on behalf of G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 3 June 2019 5:53 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Karen Tan <karentan@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19003582MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.



AVIVA

c180

Price Range

Depreciation

> 10 year(s)

Vehicle Type

Home » Used Cars » SQ Car Credit » Mercedes-Benz C-Class C180K (COE till 03/2023)

Mercedes-Benz C-Class C180K (COE till 03/2023)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Price	\$55,800		
Depreciation	\$14,780 /yr	Reg Date	27-Mar-2008 (3yrs 9mths 9days COE left)
Mileage	148,686 km (13.2k /yr)	Manufactured	2007
Road Tax	\$1,071 /yr	Transmission	Auto
Dereg Value	\$16,988 as of today (change)	OMV	\$36,768
COE	\$22,499	ARF	\$36,768
Engine Cap	1,796 cc	Power	115.0 kW (154 bhp)
Curb Weight	1,485 kg	No. of Owners	2
Type of Vehicle	Luxury Sedan		



Features

1.8L Inline 4 Supercharged Engine At 154 Bhp, 5 Speed Auto Transmission, Cruise Control, Auto Headlights, Multi-Function Steering, Dual Auto Seats. View specs of the Mercedes-Benz C-Class Saloon (2002-2006)

Accessories

Factory Fitted Audio Systems Bluetooth Interface With 6 CDs Changer, Memory Seats, Fog Lamps, Parking Assist, Leather Seats, Auto Climate Aircon.

Description

Up To 90% Loan. Excellent Low Fuel Consumption, Easy Handling. Well Maintained And Serviced Regularly. Trade In Are Welcome. Contact Our Experience Consultant For A Non Obligation Advise.

Category

COE Car, Premium Ad Car

Status

Available

Re: [Compare](#)

Shortlist

Compare

Report Error

M

Seller Information

Company	SQ Car Credit
Address	18 Siew
Location	Midv
Office No	6335
Contact Person(s)	Ken



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)



Home » Used Cars » Direct Owners » Mercedes-Benz C-Class C180K (COE till 04/2023)

Mercedes-Benz C-Class C180K (COE till 04/2023)

[Overview](#)
[Financial](#)
[Insurance](#)
[Accessories](#)
[Similar](#)
[Research](#)
[Photos](#)
[Map](#)

Price \$49,800

Depreciation \$13,000 /yr

Reg Date 16-Apr-2008
(3yrs 9mths 29days COE left)

Mileage N.A.

Manufactured 2007

Road Tax \$1,071 /yr

Transmission Auto

Dereg Value \$15,658 as of today (change)

OMV \$36,767

COE \$20,441

ARF \$36,767

Engine Cap 1,796 cc

Power 115.0 kW (154 bhp)

Curb Weight 1,485 kg

No. of Owners 3

Type of Vehicle Luxury Sedan

Features

Powerful 1.8l 4 Cylinder 16 Valve Engine. Multi Function Steering Control And Cruise Control. View specs of the Mercedes-Benz C-Class Saloon (2002-2006)

Accessories

Factory Fitted Audio System Bluetooth Interface. Retractable Side Mirrors, Black Leather Seats, Auto Climate Aircon, Electric Seat.

Description

Service Regularly. Good Condition. Direct Owner. Price Negotiable.

Category

COE Car, Direct Owner Sale

Status

Available

Resourc

[Compare](#)



Preferred Viewing Area

[Shortlist](#)
[Com](#)
[Report Error](#)
[M](#)

Seller Information

Contact Person(s)

Contact No.

Enquiry

ESSENTIAL TRANSACTION

» Indemnity form

» Receipt

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 6868J

Vehicle Details

Vehicle No.: SLJ9656D
Vehicle to be Exported: No
Intended Deregistration Date: 17 Jun 2019
Vehicle Make: MERCEDES BENZ
Vehicle Model: C180K
Primary Colour: Silver
Manufacturing Year: 2007
Engine No.: 27195230997386
Chassis No.: WDD2040462A093114
Maximum Power Output: 115.0 kW (154 bhp)
Open Market Value: \$36,779.00
Original Registration Date: 01 Feb 2008
First Registration Date: 01 Feb 2008
Transfer Count: 3
Actual ARF Paid: \$40,457.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 31 Jan 2023
COE Category: E - Open Category
COE Period(Years): 5
PQP Paid: \$26,136.00
COE Rebate Amount: \$18,927.00
Total Rebate Amount: \$18,927.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 17 Jun 2019

OK



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com

ACCIDENT DATE : 29 May 2019

13 June 2019

OWNER : TIERRA GOH PEI YING

REG NO. : SLJ 9656 D

MAKE/MODEL : MERCEDES BENZ C180

Not Allegant
Hok
4/6/19 L/S \$7100/
Take the other 4/6/19

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
	<u>LIST ITEMS</u>	
1	Front headlamp -L/H 1795.00	\$ (neg 3,617.00 ✓
1	Front grille	\$ 17 485.00 X
1	Front grille logo	\$ 17 52.00 X
1	Front bumper 1365.00	\$ 715 1,887.00 ✓
1	Front bumper inner frame	\$ 17 199.00 X
1	Front bumper clip (1 set)	\$ 22 65.00 ✓
1	Front bumper side chrome moulding	\$ 22 125.00 ✓
1	Front bumper fog lamp	\$ 17 290.00 X
1	Front bumper fog lamp cover	\$ 17 142.00 X
1	Front bumper inner sponge	\$ 1m 155.00 X
1	Front bumper reinforcement	\$ 17 522.00 X
1	Front bumper reinforcement stay bracket	\$ 17 277.00 X
1	Front fender -L/H 915.32	\$ 10/30 1,085.00 ✓
1	Front fender inner shield	\$ 17 185.00 X
1	Front wheel rim 980.00	\$ 10/30 1,550.00 ✓
1	Front wheel hub with bearing	\$ 30 587.50 ✓
1	Front shock absorber	\$ 30 820.00 X
1	Front knuckle arm	\$ 30 1,135.00 ✓
1	Front knuckle arm bearing	\$ 30 481.00 X
1	Front lower arm 465.35	\$ 30 1,038.00 ✓
1	Front top arm	\$ 17 479.20 X
1	Front control arm 366.50	\$ 30 437.00 ✓
1	Front top arm ball joint	\$ 17 185.00 X
1	Front tie rod	\$ 17 278.60 X
		\$ 16,077.30
	Less 10%	\$ 1,607.73
		\$ 14,469.57

7799.67

102
7019.70

SPECIAL NETT ITEMS

- 1 Front fender inner shield clip (1 set)
1 Front tyre *7/5 4P 250*

\$	<i>RM</i>	45.00	✓
\$	<i>C47</i>	500.00	<i>6% 150</i>
\$		545.00	

S/N LABOUR CHARGES

- 1 To check wiring and reset headlamps focusing.
2 To remove and refit front undercarriage.
3 To conduct wheel alignment.
4 To apply undercoating.
5 Panel beating.
6 To re-spray painting on the affected areas.

\$	80.00	<i>30</i>
\$	450.00	<i>120</i>
\$	180.00	<i>120</i>
\$	180.00	<i>30</i>
\$	1,800.00	<i>600</i>
\$	1,600.00	<i>800</i>
\$	4,290.00	

GRAND TOTAL :

\$	19,304.57
----	------------------

Auto Consultants hence notify the Repairer of the following:

- To inspect & advise after spray painting
- To advise if damaged parts/using resurvey
- Parts prices are subject to confirmation
- Third party claim is on a "Without Prejudice" basis
- All (third party) is allowed
- Supplementary items must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P - 7018-70
S.N - 1951
John - 1700

Customer: SJL9656D
 Company:
 License NO:
 Odometer:

Date: 06-Jun-19 10:03AM
 VIN:
 Technician:
 Order NO:

VEHICLE ALIGNMENT REPORT

Primary Angles

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	---	---	---	---
		Right	---	---	---	
	Camber	Left	-1.9	---	---	-1.9
		Right	-0.5	---	---	-0.5
	Toe	Left	0.80	---	---	0.80
		Right	0.10	---	---	0.10
Total		0.90	---	---	0.90	
Rear	Camber	Left	-1.5	---	---	-1.5
		Right	-1.3	---	---	-1.3
	Toe	Left	0.15	---	---	0.15
		Right	0.10	---	---	0.10
		Total	0.25	---	---	0.25
	Max Thrust Angle			---		

Secondary Angles

			Initial	Specifications		Final
				Min.	Max.	
		Total	---	---	---	---
Rear	Camber	Left	---	---	---	---
		Right	---	---	---	---
	Toe	Left	---	---	---	---
		Right	---	---	---	---
		Total	---	---	---	---
	Max Thrust Angle		---	---		---

Secondary Angles

Secondary Angles		Initial	Specifications		Final
			Min.	Max.	
SAI	Left	-----	-----	-----	-----
	Right	-----	-----	-----	-----
Included Angle	Left	-----	-----	-----	-----
	Right	-----	-----	-----	-----
Toe Out On Turns	Left	-----	-----	-----	-----
	Right	-----	-----	-----	-----
Max Turn Inside	Left	-----	-----	-----	-----
	Right	-----	-----	-----	-----
Toe Curve Change	Left	-----	-----	-----	-----
	Right	-----	-----	-----	-----
Setback	Front	-----	-----	-----	-----
	Rear	-----	-----	-----	-----
Track Width Diff		-----			-----
Wheel Base Diff		-----			-----
Front Ride Height	Left	-----	-----	-----	-----
	Right	-----	-----	-----	-----
Rear Ride Height	Left	-----	-----	-----	-----
	Right	-----	-----	-----	-----
Frame Angle					-----

Customer: SLJ9656D
 Company:
 License NO:
 Odometer:

Date: 12-Jun-19 2:01PM
 VIN:
 Technician:
 Order NO:

VEHICLE ALIGNMENT REPORT

Primary Angles

			Initial	Specifications		Final
				Min	Max	
Front	Caster	Left	---	---	---	---
		Right	---	---	---	---
	Camber	Left	-0.8	---	---	-0.8
		Right	-0.5	---	---	-0.5
	Toe	Left	0.15	---	---	0.05
		Right	0.10	---	---	0.05
		Total	0.25	---	---	0.10
Rear	Camber	Left	-1.5	---	---	-1.5
		Right	-1.3	---	---	-1.3
	Toe	Left	0.15	---	---	0.10
		Right	0.10	---	---	0.10
		Total	0.25	---	---	0.20
	Max Thrust Angle		---	---	---	---

Secondary Angles

			Initial	Specifications		Final
				Min	Max	
		Total	---	---	---	---
Rear	Camber	Left	---	---	---	---
		Right	---	---	---	---
	Toe	Left	---	---	---	---
		Right	---	---	---	---
		Total	---	---	---	---
	Max Thrust Angle		---	---	---	---

Secondary Angles

Secondary Angles		Initial	Specifications		Final
			Min	Max	
SAI	Left	----	----	----	----
	Right	----	----	----	----
Included Angle	Left	----	----	----	----
	Right	----	----	----	----
Toe Out On Turns	Left	----	----	----	----
	Right	----	----	----	----
Max Turn Inside	Left	----	----	----	----
	Right	----	----	----	----
Toe Curve Change	Left	----	----	----	----
	Right	----	----	----	----
Setback	Front	----	----	----	----
	Rear	----	----	----	----
Track Width Diff.		----			----
Wheel Base Diff.		----			----
Front Ride Height	Left	----	----	----	----
	Right	----	----	----	----
Rear Ride Height	Left	----	----	----	----
	Right	----	----	----	----
Frame Angle					----



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19009845/Uqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 20-06-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 1486A	Veh. Inspected	SLJ 9656D	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19003582MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	03/06/2019	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ C180K (A)	c.c	1796	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	WDD2040462A093114	Colour	RED	
Odometer	195331	Steering	AFFECTED	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/45 ZR17	MICHELIN	6 mm	
L/H Front Tyre	215/45 ZR17	MICHELIN	6 mm	
R/H Rear Tyre	215/45 ZR17	MICHELIN	6 mm	
L/H Rear Tyre	215/45 ZR17	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/05/2019	Inspection Date	04/06/2019	
Survey held at	130 BEDOK RESERVIOR ROAD #08-1339			
Repairer	ZOOM AUTOWERKS PTE LTD			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 9656D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT HEADLAMP - L/H	CRACKED	3,617.00	1,795.00
1	FRONT GRILLE	NOT NECESSARY	485.00	-
1	FRONT GRILLE LOGO	NOT NECESSARY	52.00	-
1	FRONT BUMPER	DISTORTED	1,887.00	1,365.00
1	FRONT BUMPER INNER FRAME	NOT NECESSARY	199.00	-
1	SET FRONT BUMPER CLIP	NECESSARY	65.00	65.00
1	FRONT BUMPER SIDE CHROME MOULDING	NECESSARY	125.00	125.00
1	FRONT BUMPER FOG LAMP	NOT NECESSARY	290.00	-
1	FRONT BUMPER FOG LAMP COVER	NOT NECESSARY	142.00	-
1	FRONT BUMPER INNER SPONGE	NOT NECESSARY	155.00	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	522.00	-
1	FRONT BUMPER REINFORCEMENT STAY BRACKET	NOT NECESSARY	277.00	-
1	FRONT FENDER L/H	DENTED / BENT	1,085.00	915.32
1	FRONT FENDER INNER SHIELD	NOT NECESSARY	185.00	-
1	FRONT WHEEL RIM	DENTED / BENT	1,550.00	980.00
1	FRONT WHEEL HUB WITH BEARING	BENT	587.50	587.50
1	FRONT SHOCK ABSORBER	SERVICEABLE	820.00	-
1	FRONT KNUCKLE ARM	BENT	1,135.00	1,135.00
1	FRONT KNUCKLE ARM BEARING	REPEATED	481.00	-
1	FRONT LOWER ARM	BENT	1,038.00	465.35
1	FRONT TOP ARM	NOT NECESSARY	479.20	-
1	FRONT CONTROL ARM	BENT	437.00	366.50
1	FRONT TOP ARM BALL JOINT	NOT NECESSARY	185.00	-
1	FRONT TIE ROD	NOT NECESSARY	278.60	-
	LESS 10% DISCOUNT		-1,607.73	-779.97
			14,469.57	7,019.70
SPECIAL NETT ITEMS				
1	SET FRONT FENDER INNER SHIELD CLIP (SN)	NECESSARY	45.00	45.00
1	FRONT TYRE N/S (LOCAL PURCHASE)(\$250.00)(60%)(SN)	CUT	500.00	150.00
			545.00	195.00

Report Ref No. CS/FCI19009845/Uqd3n2