

XIN HUA WORKSHOP PTE. LTD.

23 Kaki Bukit Avenue 4, #04-01 (South Wing) Singapore 415933

Tel : 6844-1985 Fax : 6844-5185

Reg : 201838521G

Repair Estimate

Date :01/06/2019

Reference: RENAULT

Make: GRAND SCENIC

To Whom It May Concern

Dear Sir,

RE: VEHICLE : SMH5980S

CHASSIS NO.: VF1RFA00X61789268

ENGINE NO.: K9KF649D059534

Name of insured :BIS MOTORING PTE LTD

Date of accident.: 31/05/2019

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	RR BUMPER <i>Torn</i>	\$ 1,766.00
2	1	RR BUMPER LOW <i>new</i>	\$ 784.00
3	1	RR BUMPER SIDE RETAINER RH <i>new</i>	\$ 368.30
4	1	RR BUMPER REFLECTOR RH <i>new</i>	\$ 532.00
5	1	FRT DOOR RH <i>new</i>	\$ 2,166.00
6	1	RR DOOR RH <i>Distorted</i>	2186.00 \$ 2,480.00
7	1	RR DOOR PROTECTOR RH <i>Del d</i>	\$ 562.00
8	1	RR DOOR PROTECTOR CHROME MLDG RH <i>new</i>	\$ 281.00
9	1	RR DOOR HINGE UPP RH <i>new</i>	\$ 160.00
10	1	RR DOOR HINGE LOW RH <i>new</i>	\$ 146.00
11	1	RR DOOR CHECKER RH	\$ 142.00
12	1	RR DOOR LOCK RH <i>new</i>	\$ 242.00
13	1	RR DOOR LOCK CATCHER RH <i>new</i>	\$ 84.00
14	1	RR DOOR INNER TRIM RH <i>Del d</i>	1132.00 \$ 1,280.00
15	1	RR DOOR RUBBER BEADING RH <i>new new</i>	\$ 208.00
16	1	RR DOOR WEATHER STRIP RH <i>new</i>	\$ 252.00
17	1	RR DOOR OUTER HANDLE RH <i>new</i>	\$ 304.00
18	1	RR DOOR OUTER HANDLE KNOB RH <i>new</i>	\$ 132.00
19	1	RR DOOR HANDLE INNER BASE RH <i>new</i>	\$ 194.00
20	1	RR DOOR BLACK STICKER RH <i>new</i>	\$ 110.00
21	1	RR DOOR GLASS OUTER MLDG RH <i>new</i>	\$ 198.00
22	1	RR DOOR GLASS RUNCHANNEL RUBBER BEADING <i>new</i>	\$ 270.00
23	1	RR DOOR POWER WINDOW REGULATOR ASSY RH <i>new</i>	\$ 732.00
24	1	RR FENDER RH <i>new</i>	\$ 2,504.00
25	1	RR FENDER AIR DUCT RH <i>new</i>	\$ 140.00
26	1	RR FENDER INNERSHIELD RH <i>Del d</i>	\$ 150.00
27	1	RR FENDER OUTER QUARTER GLASS RH <i>new</i>	\$ 304.00
28	1	RR RIM RH <i>new</i>	\$ 1,200.00
29	1	RR WHEEL BEARING RH <i>new</i>	\$ 496.00
30	1	RR SHOCK ABSORBER RH <i>new</i>	\$ 368.00

680(SW)

SMH 59805

31	1	RR AXLE BEAM ASSY <i>Ren</i>		\$	3,029.00	+
32	1	RH ROCKER PANEL RH <i>1/2 hr</i>		\$	1,220.00	+
33	1	RH ROCKER PANEL GARNISH RH <i>Detd</i>	587.00	\$	873.00	✓

8126.3

7313.67

Parts Total: \$ 23,677.30

Less 10%: \$ 2,367.73

Total: \$ 21,309.57

LabourLabour Description

No.			Price (SGD)	
1		To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$ 1,600.00	900
2		Carry out spray painting on affected area, RR BUMPER, RR FENDER RH, RR DOOR RH, RH ROCKER PANEL GARNISH, RH ROCKER PANEL, FRT DOOR RH	\$ 1,600.00	1000
3		To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 180.00	30
4		Remove and refix seat cushion/upholstery & roof lining to facilitate repairs	\$ 200.00	80
5		To remove and refix reverse sensor and conduct test	\$ 120.00	50
6		To conduct 4 wheel alignment	\$ 180.00	80
7		To conduct reset of engine light on	\$ 350.00	+
8		Transfer of internal mechanism from old door panel to new door panel	\$ 250.00	80
9		Remove and replace RHR under carriage parts	\$ 300.00	+
10		To remove and refit fuel tank to facilitate accident repair	\$ 250.00	+
11		To remove and refix rear quarter glass	\$ 120.00	+

2220

Labour Total: \$ 5,150.00

OthersOther Description

No.			Price (SGD)	
1	10	RR BUMPER CLIP <i>Ren</i>	\$ 60.00	30
2	1	RR QUARTER GLASS SEALANT RH <i>3 hr</i>	\$ 65.00	+
3	1	RR QUARTER GLASS INNER SEAL RH <i>3 hr</i>	\$ 40.00	+
4	10	RR FENDER INNERSHIELD CLIP RH <i>Ren</i>	\$ 40.00	30
5	1	RR TYRE RH <i>Ren</i>	\$ 400.00	+

6 RH Rim RH

Other Total: \$ 605.00

740

SMH 59805

TOTAL: \$ 27,064.57

GRAND TOTAL : \$ 27,064.57

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully

Service Advisor
Kelvin Chew
HP: 8292 5595 Fax: 68445185

Adrian Lj
H/s 04/06/19.

06 Aug

10,273.67

- L/s \$8200.00 ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: