

Date: 01.06.2019
Vehicle No: SLS2179M
Model: MERCEDES BENZ E200
Chassis: WDD2130422A111838 - 2016
Reg.Year: 2017

Third Party Insurer: INDIA INTER'L
Third Party Veh No: SHA5985A
Date of Accident: 15.03.2019

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER REVERSE SENSOR SET RH	1	\$250.00	<i>P</i> \$250.00
SUB TOTAL				\$250.00
LESS 10%				-\$25.00
PARTS TOTAL				\$225.00

ESTIMATE

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE & READJUST, REPAIR REAR BUMPER & ETC BACK TO ORIGINAL CONDITIONS

\$200.00 *150*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINTS & FURNISHING MATERIAL

\$350.00 ✓

TO REMOVE & REPLACED REAR BUMPER REVERSE SENSOR & CHECK WIRING & ETC

~ \$60.00 X

LABOUR TOTAL \$610.00

ONG

TOTAL \$835.00

Not maintain
2 days
\$500

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: