Not Authorised

Helle

4/6/19

1/5 # (12)

FASTECH AUTO PTE LTD BLK1 KAKI BUKIT AVE 6 #01-46,48,50 AUTOBAY SINGAPORE 417883

	0 AUTOBAY			1	San
SINGAPORI	E 417883				
VEHICLE NO:	SKW 5961S				
QTY	PARTICULAR				
1 PCS	REAR WINDSCREEN MOULDING 66:50			nec	\$161.10
PCS	TAILGATE //25			3061,00	\$1,266.30
PCS	TAILGATE 'H' LOGO			11	
PCS	TAILGATE MOBILIO EMBLEM			n	
PCS	TAILGATE 'RS' EMBLEM			ser	
PCS	TAILGATE 'IVTEC' EMBLEM			ser	
PCS	TAILGATE REFLECTORS @\$488.10 204 · 20	V2=410	40	cn	\$976.20 -
PCS	TAILGATE OUTER GARNISH	70		11.	\$385.40
PCS	TAILGATE INNER LOCK			m/stud	\$266.20
PCS	TAILGATE WEATHERSTRIP			tul	\$266.10
PCS	TAILGATE INNER LOCK SENSOR			11	\$285.50 X
PCS	TAILGATE INNER LOCK BUZZER			17	\$208.30
PCS	TAILGATE INNER TRIM BOARD			11	\$488.10 0
SET	TAILAGTE INNER TRIM BOARD CLIPS			11	\$50.00
PCS	REAR WINDSCREEN			11	\$1,480.10
PCS	REAR WIPER ARM			11	\$165.50
PCS	REAR WIPER MOTOR			11	\$499.00
PCS	REAR BUMPER 463.70			ne	\$845.10
PCS	REAR BUMPER CHROME MOULDING			rec/sin	\$288.50
PCS	REAR BUMPER SIDE RETAINERS @\$39.00			11	
SET	REAR BUMPER CLIPS			ne	
PCS	REAR BUMPER REFLECTORS @\$68.00			11	
PCS	REAR BUMPER SPONGES @\$155.00 95 x L	-180		70,1	
PCS	REAR END PANEL 3(4.)0	- 170		m/zert	
PCS	REAR END PANEL TOP GARNISH (09.30			Relini	\$208.60
PCS	REAR FENDERS @\$1050.00			n	\$2,100.00 ×
PCS	REAR FENDER INNER BOARDS @\$480.00 3/3	x2=626		chi	\$960.00
PCS	REAR EXHAUST	70-0		na	\$899.20
PCS	REAR EXHAUST MOUNTINGS @\$35.00	1		17	
PCS	TAILLAMPS@\$680.10 350.50 × 2	= 19.11	701.0	and the second s	\$1,360.20
PCS	TAILLAMP HOUSING PANELS@\$255.00	= (202,		1	\$510.00 X
PCS	REAR SPARE TYRE BRACKET			11	\$292.30 ×
PCS	REAR FLOOR PANEL TOP BOARD				\$665.00
11.00		(0)/1 2			\$16,060.50
	S.NETT	50/0.2		meneración inform	\$10,000.50
SET	REAR BUMPER REVERSE SENSOR	4008.16		Shoted	\$280.00 2
PCS	REAR END PANEL SEALANT			received and the second second	
PCS	REAR WINDSCREEN SEALANT			ne	
PCS	REAR LICENCE PLATE W/HOLDER			w	2/
PCS	REAR EXHAUST CHROME PIPE			11	-
SET	REAR REVERSE CAMERA				and have been proportionally and the second
JEI	REAR REVERSE CAMERA			11	\$480.00
	LABOUR CHARGES				
	TO CHECK WIRING				\$80.00
	TO DISMANTLE & REPLACING REVERSE SENSOR	l l			\$80.00
	TO DISMANTLE & REFIX REAR WINDSCREEN				\$150.00

	TOTAL \$20,860.50
TO PUTTY & SPRAY PAINTING	\$1,500.00
LABOUR FOR PANEL BEATING & REPLACING PARTS	\$1,500.00
TO SPRAY RUST PROOFING	\$100.00
The state of the s	<b>ハヘ \$100.00</b>
TO DISMANTLE & REFIX REAR EXHAUST	\$100.00
TO TRANSFER TAILGATE MECHANISM	The second secon
TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTREY	\$120.00
TO DISMANTLE & REFIX REAR CAMERA	\$80.00

8578.16 5250

## LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis.
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: