

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5179A**AAD1905-281***Not Authorised
11 Sep 8 2850*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHC 5179A

VF1ABL15AUC276845

RENAULT

LATITUDE

30.5.19

AIG

14/1/2014

PART			LIST		
1	1	BUMPER COVER REAR	\$	<i>Bu</i> 1,108.46	✓
2	1	BUMPER LOWER REAR	\$	<i>OUTDIV</i> 768.84	✓
3	1	BUMPER BRACKET CTR REAR	\$	<i>SL</i> 113.47	X
4	1	BUMPER BRACKET SIDE RH REAR	\$	<i>SL</i> 135.97	X
5	1	BUMPER RETAINER RH REAR	\$	<i>SL</i> 44.99	X
6	1	BUMPER REFLECTOR RH	\$	<i>SL</i> 43.61	X
7	1	BUMPER BRACKET SIDE LH REAR	\$	<i>SL</i> 135.97	X
8	1	BUMPER RETAINER LH REAR	\$	<i>SL</i> 44.99	X
9	1	BUMPER REFLECTOR LH	\$	<i>CMF</i> 43.61	✓
10	1	BUMPER BEAM REAR	\$	<i>B</i> 777.52	✓
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>B</i> 225.95	✓
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>K</i> 225.95	X
13	1	OUTER PANEL REAR (End Panel)	\$	<i>K</i> 1,471.77	X
14	1	OUTER PANEL REAR (End Panel)TRIM	\$	<i>SL</i> 404.56	X
15	1	TAILLAMP RH	\$	<i>SL</i> 552.55	X
16	1	TAILLAMP PANEL RH	\$	<i>K</i> 986.70	X
17	1	TAILLAMP LH	\$	<i>SL</i> 552.55	X
18	1	TAILLAMP PANEL LH	\$	<i>K</i> 986.70	X
19	1	BOOT REAR	\$	<i>N-2</i> (N-2) 2,872.68	X
20	1	BOOT FINISHER	\$	<i>SL</i> 470.06	} X
21	1	BOOT WHEATERSTRIP	\$	<i>SL</i> 323.05	
22	1	BOOT REFLECTOR LAMP LH	\$	<i>SL</i> 493.35	
23	1	BOOT REFLECTOR LAMP RH	\$	<i>SL</i> 493.35	
24	1	BOOT BADGE 'RENAULT'	\$	<i>N-2</i> 225.36	
25	1	BOOT BADGE	\$	<i>N-2</i> 225.36	
26	1	BOOT STRUT LH	\$	<i>SL</i> 276.08	
27	1	BOOT STRUT RH	\$	<i>SL</i> 276.08	
28	1	BOOT HINGE LH	\$	<i>K</i> 367.84	}
29	1	BOOT HINGE RH	\$	<i>K</i> 367.84	

Trans-cab Auto Services Pte Ltd**AAD1905-281**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5179A

- 30 1 BOOT INNER TRIM
- 31 1 BOOT SWITCH
- 32 1 BOOT LOCK
- 33 1 BOOT LOCK CATCH

\$	<i>Sn</i>	586.45	X
\$	<i>Sn</i>	168.13	X
\$	<i>R</i>	202.67	/
\$	<i>R</i>	74.40	X
TOTAL	\$	16,046.87	
10%	\$	1,604.69	
	\$	14,442.19	

Special Nett

- 1 1SET PARKING AID
- 2 1SET REAR BUMPER CLIP
- 3 1SET BUMPER BRACKET CTR CLIP
- 4 1SET BUMPER BRACKET SIDE CLIP RH RR
- 5 1SET BUMPER RETAINER RH CLIP RR
- 6 1SET BUMPER BRACKET SIDE CLIP LH RR
- 7 1SET BUMPER RETAINER CLIP LH RR
- 8 1SET BUMPER LOWER REAR RIVET
- 9 1SET BUMPER LOWER REAR CLIP
- 10 1 BOOT STICKER "Trans-cab"
- 11 1 BOOT STICKER "6555-3333"
- 12 1 EXHAUST MOUNTING REAR
- 13 2 REAR WINDSCREEN SEALANT
- 14 1 WINDSCREEN MOULDING
- 15 1 REAR WINDSCREEN INNER SPONGE SEAL
- 16 1 BOOT INNER TRIM CLIP
- 17 1SET BOOT FINISHER CLIP
- 18 1 TAILLAMP CLIP LH
- 19 1 TAILLAMP CLIP RH

\$	<i>Sn</i>	700.00	X
\$	<i>nn</i>	66.00	✓
\$	<i>nn</i>	33.00	✓
\$	<i>nn</i>	10.00	X
\$	<i>nn</i>	20.00	X
\$	<i>nn</i>	10.00	X
\$	<i>nn</i>	20.00	X
\$	<i>nn</i>	22.00	X
\$	<i>nn</i>	66.00	✓
\$	<i>nn</i>	30.00	} X
\$	<i>nn</i>	30.00	
\$	<i>nn</i>	17.82	
\$	<i>nn</i>	80.00	
\$	<i>nn</i>	100.00	
\$	<i>nn</i>	100.00	
\$	<i>nn</i>	45.00	
\$	<i>nn</i>	24.20	}
\$	<i>nn</i>	5.00	
\$	<i>nn</i>	5.00	
TOTAL	\$	1,384.02	

TOTAL PARTS \$ 15,826.21**LABOUR**

To Check Electrical Lighting Concerned.	\$	170.00	<i>15/</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00	X
To Rust-Proofing Of The Affected Areas.	\$	<i>nn</i> 170.00	X

Trans-cab Auto Services Pte Ltd**AAD1905-281**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5179A

To reinstall rear bumper parking sensor.	\$	170.00	601
Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	2201
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn 170.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	2001
To repair and realign rear exhaust pipe.	\$	nn 170.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	4 380.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	4 170.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	4 170.00	X
To check steering geometry and computer wheel alignment	\$	4 220.00	X
To apply paint protection system (PPS) maintain and enhancement	\$	4 380.00	X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	4 380.00	X

TOTAL \$ 9,100.00**Over All Total \$ 24,926.21****LUMP SUM (REPAIR DAY)****10 DAYS**
2 days

KKK Auto Services Pte Ltd to notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: