

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICE

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: CU0049113 / INDIA
 Chassis No: JHMGK3850JX222656
 License No: SMA3502P
 Mileage: 34499
 Engine No: L13B11030741

Document No: SVO19040319
 Printed By: ANIKKALAI
 Order Date: 25. June 2019
 Order Time: 2:24:46 PM
 Service Advisor: ANIKKA LAI SWEE KAM

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount Includ GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: CHUA BENG HOCK OWNER INSURER: AVIVA LTD ACC DATE: 31/05/2019 SURVEYED BY: HWEE JIE / LKK DATE: REF NO: TP INSURER: INDIA TP VEH: SHD3373M						
68100-T5A-U10ZZ	TAIL GATE COMP	1	730.60	25	547.95	38.36	586.31
74440-T5A-003	WEATHERSTRIPTAILGATE	1	92.30	25	69.22	4.85	74.07
75722-T5L-T01	EMBLEMRR.	1	10.90	25	8.17	0.57	8.74
04715-T5A-J50ZZ	FACE,RR.BUMPER	1	492.70	25	369.52	25.87	395.39
71505-T5A-J50	GARNISH,RR.BUMPER	1	38.30	25	28.72	2.01	30.73
71593-T5A-J50	SPACER,R.RR.BUMPER SIDE	1	16.90	25	12.67	0.89	13.56
71598-T5A-J50	SPACER,L.RR.BUMPER SIDE	1	16.90	25	12.67	0.89	13.56
91505-TM8-003	CLIP,BUMPER	7	2.30	25	12.07	0.84	12.91
66100-TAR-T00ZZ	PANEL COMPRR.	1	320.40	25	240.30	16.82	257.12
73127-TY0-000	RUBBER CWINDOWSHIELD DAMPER	1	11.40	25	8.55	0.60	9.15
73214-T5A-013	RUBBERWINDOWSHIELD DAMPER	2	6.50	25	9.75	0.68	10.43
73226-SZW-000	DAMPERSTD 5X5	1	8.50	25	6.37	0.45	6.82
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00		320.00	22.40	342.40
	SUM PARTS:				1,705.96	119.43	1,825.39
BG02R	REPLACE RR. WINDSCREEN.(N)	1	560.00		560.00	39.20	599.20
BOSUN	0701 SUNDRIES	1	30.00		30.00	2.10	32.10
BA02R	1729 REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	120.00		120.00	8.40	128.40
BC012R	1729 RESET VEHICLE SMART ENTRY SYSTEM	1	280.00		280.00	19.60	299.60
BC011R	1729 REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	280.00		280.00	19.60	299.60
BKTG02R	1729 REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1	320.00		320.00	22.40	342.40
BMI03D	1438 REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)	1	560.00		560.00	39.20	599.20
BOJSE	1718 BODY JOINT SEALANT.	1	80.00		80.00	5.60	85.60
BML02I	1438 INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	120.00		120.00	8.40	128.40



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer:	CU0049113 / INDIA	Document No:	SVO19040319
Chassis No:	JHMGK3850JX222656	Printed By:	ANIKKALAI
License No:	SMA3502P	Order Date:	25. June 2019
Mileage:	34499	Order Time:	2:24:46 PM
Engine No:	L13B11030741	Service Advisor:	ANIKKA LAI SWEE KAM
BKRP02M	1729 CUT OFF & RENEW RR PANEL. Tailgate, rear bumper STRAIGHTEN ALIGN FLOOR PANEL INCLUDING FITTINGS ON ATTACHMENT ITEM	1 1,120.00	1,120.00 78.40 1,198.40
BOBC	1718 BODY UNDERSIDE COATING (N)	1 100.00	100.00 7.00 107.00
BODAMKIT	0701 WINDSCREEN DAM KIT.	1 80.00	80.00 5.60 85.60
BP05R	1/18 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(5P) Tailgate, Rear bumper	1 900.00	900.00 63.00 963.00
BKRP02M	CUT OFF & RENEW RR PANEL. Rear panel (Supp labour) STRAIGHTEN ALIGN FLOOR PANEL INCLUDING FITTINGS ON ATTACHMENT ITEM	1 1,120.00	1,120.00 78.40 1,198.40
BP03R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(3P) (Supp painting)	1 1,350.00	1,350.00 94.50 1,444.50
SUM LABOUR:		7,020.00	491.40 7,511.40
TOTAL SGD		8,725.96	610.83 9,336.79
Total Payable (SGD)			9,336.79

GST Amount is calculated from individual line(s)

P- 1795.96

L- 7020

8725.96

6 repair days