

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

**QUOTATION**

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

<b>Customer</b>	: INDIA INTERNATIONAL INSURANCE PTE 64 CECIL STREET #04-00 & #05-00 IOB BUILDING SINGAPORE 049711	<b>Document No.</b>	: SQT19002409	<b>Page</b>	1
<b>Registration No</b>	: SMA3502P	<b>Date</b>	: 3. Jun 2019		
<b>Chassis No</b>	: JHMGK3850JX222656	<b>Customer No.</b>	: WZI007		
<b>Model</b>	: JAZZ 1.3LXR CVT 18YM (EURO 6)	<b>Svc Advisor</b>	: IVAN TEO BOON KIAT		
<b>Owner's Name</b>	: CHUA BENG HOCK	<b>Engine No</b>	: L13B11030741		
<b>Ins Policy No.</b>	:	<b>Date   Time</b>	: 3. Jun 2019 9:31:00 AM		
<b>Date of Accident</b>	: 31/5/2019	<b>Surveyor Name</b>	:		
		<b>Survey Date</b>	:		
		<b>Authorisation Date</b>	:		

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: ) OWNER: CHUA BENG HOCK OWNER INSURER: AVIVA LTD ACC DATE: 31/05/2019 SURVEYED BY: DATE: REF NO: TP INSURER: INDIA TP VEH: SHD3373M						
68100-TAR-U10ZZ	TAILGATE COMP	1	730.60	25	547.95	38.36	586.31
74440-T5A-003	WEATHERSTRIPTAILGATE	1	92.30	25	69.22	4.85	74.07
74890-T5A-A11	GARNISH ASSY,RR LICENCE	1	105.50	25	79.12	5.54	84.66
75722-T5L-T01	EMBLEMRR.	1	10.90	25	8.17	0.57	8.74
04715-T5A-J50ZZ	FACE,RR.BUMPER	1	492.70	25	369.52	25.87	395.39
71502-T5A-J60	COVER,R.RR.BUMPER	1	20.70	25	15.52	1.09	16.61
71507-T5A-J60	COVER,L.RR.BUMPER	1	20.70	25	15.52	1.09	16.61
71505-T5A-J50	GARNISH,RR.BUMPER	1	38.30	25	28.72	2.01	30.73
71503-T5A-J50	COVER,RR.EXPI FIN	1	9.30	25	6.97	0.49	7.46
71593-T5A-J50	SPACER,R.RR.BUMPER SIDE	1	16.90	25	12.67	0.89	13.56
71598-T5A-J50	SPACER,L.RR.BUMPER SIDE	1	16.90	25	12.67	0.89	13.56
91505-TM8-003	CLIP,BUMPER	7	2.30	25	12.07	0.84	12.91
33500-T5A-J02	TAILLIGHT ASSY,R.	1	223.90	25	167.92	11.75	179.67
33550-T5A-J02	TAILLIGHT ASSYL.	1	223.90	25	167.92	11.75	179.67
34150-T5A-J01	LIGHT ASSYR.LID	1	81.70	25	61.27	4.29	65.56
34155-T5A-J01	LIGHT ASSYL.LID	1	81.70	25	61.27	4.29	65.56
66100-TAR-T00ZZ	PANEL COMPRR.	1	320.40	25	240.30	16.82	257.12
73127-TY0-000	RUBBER CWINDOWSHIELD DAMPER	1	11.40	25	8.55	0.60	9.15
73214-T5A-013	RUBBERWINDOWSHIELD DAMPER	2	6.50	25	9.75	0.68	10.43

**Printed on 3/6/2019 12:14:09 PM**

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

**QUOTATION**

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

<b>Customer</b>	: INDIA INTERNATIONAL INSURANCE PTE 64 CECIL STREET #04-00 & #05-00 IOB BUILDING SINGAPORE 049711	<b>Document No.</b>	: SQT19002409	<b>Page</b>	2
<b>Registration No</b>	: SMA3502P	<b>Date</b>	: 3. Jun 2019		
<b>Chassis No</b>	: JHMGK3850JX222656	<b>Customer No.</b>	: WZI007		
<b>Model</b>	: JAZZ 1.3LXR CVT 18YM (EURO 6)	<b>Svc Advisor</b>	: IVAN TEO BOON KIAT		
<b>Owner's Name</b>	: CHUA BENG HOCK	<b>Engine No</b>	: L13B11030741		
<b>Ins Policy No.</b>	:	<b>Date   Time</b>	: 3. Jun 2019 9:31:00 AM		
<b>Date of Accident</b>	: 31/5/2019	<b>Surveyor Name</b>	:		
		<b>Survey Date</b>	:		
		<b>Authorisation Date</b>	:		

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
73226-SZW-000	DAMPERSTD 5X5	1	8.50	25	6.37	0.45	6.82
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00		320.00	22.40	342.40
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	1	45.00		45.00	3.15	48.15
Sum Item					<b>2326.47</b>	<b>162.87</b>	<b>2,489.34</b>
BG02R	REPLACE RR. WINDSCREEN.(N)	1	560.00		560.00	39.20	599.20
BOSUN	SUNDRIES	1	100.00		100.00	7.00	107.00
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00		180.00	12.60	192.60
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	450.00		450.00	31.50	481.50
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	450.00		450.00	31.50	481.50
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	560.00		560.00	39.20	599.20
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	560.00		560.00	39.20	599.20
BOJSE	BODY JOINT SEALANT.	1	180.00		180.00	12.60	192.60
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00		180.00	12.60	192.60
BKRP02M	CUT OFF & RENEW RR PANEL. STRAIGHTEN ALIGN	1	2800.00		2800.00	196.00	2996.00
BOBC	BODY UNDERSIDE COATING (N)	1	180.00		180.00	12.60	192.60
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	560.00		560.00	39.20	599.20
BODAMKIT	WINDSCREEN DAM KIT.	1	100.00		100.00	7.00	107.00
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(5P)	1	2700.00		2700.00	189.00	2889.00
Sum Labor					<b>9560.00</b>	<b>669.20</b>	<b>10,229.20</b>

Survey By	_____				
Date & Time	_____	<b>Total Amount</b>	11,886.47	832.07	12,718.54
Excess	_____	<b>Total (Inclusive of GST)</b>			<b>12,718.54</b>
Status	_____				
Signature	_____				

**Printed on 3/6/2019 12:14:09 PM**

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

**QUOTATION**

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

<b>Customer</b>	: INDIA INTERNATIONAL INSURANCE PTE 64 CECIL STREET #04-00 & #05-00 IOB BUILDING SINGAPORE 049711	<b>Document No.</b>	: SQT19002409	<b>Page</b>	3
<b>Registration No</b>	: SMA3502P	<b>Date</b>	: 3. Jun 2019		
<b>Chassis No</b>	: JHMGK3850JX222656	<b>Customer No.</b>	: WZI007		
<b>Model</b>	: JAZZ 1.3LXR CVT 18YM (EURO 6)	<b>Svc Advisor</b>	: IVAN TEO BOON KIAT		
<b>Owner's Name</b>	: CHUA BENG HOCK	<b>Engine No</b>	: L13B11030741		
<b>Ins Policy No.</b>	:	<b>Date   Time</b>	: 3. Jun 2019 9:31:00 AM		
<b>Date of Accident</b>	: 31/5/2019	<b>Surveyor Name</b>	:		
		<b>Survey Date</b>	:		
		<b>Authorisation Date</b>	:		

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incl GST
------	-------------	-----	------------	--------	--------	------------------	--------------------

**Printed on 3/6/2019 12:14:09 PM**

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.